



Ref No: HIL/LHD/GM (GEO)/MoEF/74

Date: 27.05.2019

To,
The Additional Principal Chief Conservator of Forest (C)
Ministry of Environment, Forests and Climate Changes
Regional Office (ECZ), Ranchi-834002.

Sub: Compliance Report of EC conditions for Pakhar (8.09 ha) Bauxite Mining project of M/s Hindalco Industries Limited located in Lohardaga, Jharkhand for the period October'18 to March'19.

Ref: Environmental Clearance letter no J-11015/135/2006-IA II (M) dated 24th January 2007

Sir,

With reference to the above, we are submitting herewith the Compliance status report of EC conditions for **Pakhar (8.09 ha)** Bauxite Mining project of **M/s Hindalco Industries Limited** located in Lohardaga, Jharkhand for the period October'18 to March'19.

Hope you will find the same in order.

Thanking You

Yours Sincerely
FOR HINDALCO INDUSTRIES LIMITED

(Basudev Gangopadhyay)
GM (Geology & Environment)

Enclosure: - As Above

Copy to: Member Secretary, JSPCB, Ranchi
RO, JSPCB, Ranchi
CPCB, Zonal Office, Kolkata
<mef@ori.nic.in>, <mef@nic.in>, <mef.or@nic.in>, mef.or@nic.in

Compliance of conditions laid down in Environmental Clearance
PAKHAR (8.09 ha) BAUXITE MINES

Period: October'18- March'19

J-11015/135 /2006-IA.II (M) Dated 24.1.2007

Sl No	Specific Conditions	Compliance Status
1	All the conditions stipulated by SPCB in their NOC shall be effectively implemented.	The Mine is not in operation since Nov 2014. During operation of mine implementations of the stipulated condition were full filled.
2	The environmental clearance is subject to approval of the state land use Department, Government of Jharkhand for diversion of agricultural land for non-agricultural use.	The Mine is not in operation since Nov 2014. During operation of the mine land acquisition has been done following due procedure of law.
3	Mining shall not intersect groundwater. The mine working shall be restricted to ground water table. Prior approval of the Ministry of Environment & Forests and Central Ground Water Authority shall be obtained for mining below water table.	The Mine is not in operation since Nov 2014. Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. Final Mine closure Plan has been approved by Indian Bureau of Mines. We are in process of implementation of Final Mine closure.
4	The project proponent shall ensure that no natural watercourse shall be obstructed due to any mining operation.	No natural water course was obstructed during mining in past. Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. Mine is not in operation since Nov 2014.
5	Top soil shall be stacked properly with proper slope with adequate measures and should be used for reclamation and rehabilitation of mined out areas.	The Mine is not in operation since Nov 2014. Winning of bauxite operation not carried out in this lease during financial year 2018-19 due to exhaustion of mineral reserve.
6	The waste generated shall be concurrently backfilled in the mined out area. There shall be no external OB dump. Monitoring and management of rehabilitated areas should continue until the vegetation becomes self-sustaining. Compliance status should be submitted to the Ministry of Environment & Forest on six monthly basis.	Mine is not in operation since Nov 2014. Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. No external OB dump is in mine lease area.

7	<p>Catch drains and siltation ponds of appropriate size should be constructed to arrest silt and sediment flows from mine working. The water so collected should be utilized for watering the mine area, roads, green belt development etc. The drains should be regularly desilted particularly after monsoon and maintained properly.</p> <p>Garland drain (size, gradient and length) shall be constructed for mine pit and sump capacity should be designed keeping 50% safety margin over and above peak sudden rainfall (based on 50 years data) and maximum discharge in the area adjoining the mine site. Sump capacity should also provide adequate retention period to allow proper setting of silt material. Sedimentation pits should be constructed at the corners of the garland drains and desilted at regular intervals.</p>	<p>Winning of bauxite operation not carried out in this lease during financial year 2018-19 due to exhaustion of mineral reserve.</p> <p>The Mine is not in operation since Nov 2014.</p>
8	<p>Plantation shall be raised in an area of 6.35 ha including a green belt of adequate width by planting the native species around the ML area, roads, reclaimed area etc. in consultation with the local DFO / Agriculture Department. The density of the trees should be around 1500 plants per ha.</p>	<p>Mine is not in operation since Nov 2014 due to exhaustion of reserves. FMCP approved by IBM. Final Mine closure activity are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created. Plantation done/Agriculture activity is going on reclaimed land. Entire land is utilized for meaningful purpose.</p>
9	<p>The project authority should implement suitable conservation measures to augment ground water resources in the area in consultation with the Regional Director, Central Ground Water Board.</p>	<p>Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. Mine is not in operation since Nov 2014 due to exhaustion of reserves. FMCP approved by IBM. Final Mine closure activity are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created.</p>
10	<p>Regular monitoring of ground water level and quality should be carried out by establishing a network of existing wells and constructing new piezometers during the mining operation. The monitoring should be carried out four times in a year – pre-monsoon (April-May), monsoon (August), post-monsoon (November) and winter (January) and the data thus collected may be sent regularly to MOEF, Central Ground water Authority and Regional Director Central Ground Water Board.</p>	<p>Mine is not in operation since Nov 2014 due to exhaustion of reserves. FMCP approved by IBM. Final Mine closure activity are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created.</p>

11	Prior permission from the competent authority should be obtained for drawl of water from the surface water bodies.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014.
12	Vehicular emissions should be kept under control and regularly monitored. Measures shall be taken for maintenance of vehicles used in mining operations and transportation of mineral. The vehicles should be covered with a tarpaulin and shall not be overloaded.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014. FMCP approved by IBM. Final Mine closure activity are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created.
13	Drills should either be operated with dust extractors or should be equipped with water injection system.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014. FMCP approved by IBM. Final Mine closure activity are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created.
14	Blasting operation should be carried out only during the daytime. Controlled blasting should be practiced. The mitigative measures for control of ground vibration and to arrest fly rocks and boulders should be implemented.	Winning of bauxite operation not carried out in this lease during financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014. FMCP approved by IBM. Final Mine closure activity are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created.
15	Consent to operate should be obtained from SPCB prior to start of enhanced production from the mine.	The Mine is not in operation since Nov 2014. Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. FMCP approved by IBM. Final Mine closure activity are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created.

16	Sewage treatment plant should be installed for the colony. ETP should also be provided for workshop and wastewater generated from mining operations.	The Mine is not in operation since Nov 2014. Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. FMCP approved by IBM. Final Mine closure activities are completed. Mine Voids are reclaimed and rehabilitated. Water body is also created.
17	The project proponent should take all precautionary measures during mining operation for conservation and protection of endangered fauna such as Indian Python etc. Spotted in the study area. Action plan for conservation of flora and fauna shall be prepared and implemented in consultation with the State Forest and Wildlife Department. Necessary allocation of funds for implementation of the conservation plan shall be made and the funds so allocated shall be included in the project cost. Copy of action plan may be submitted to the Ministry and its Regional Office within 3 months.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014.
18	A Final Mine Closure plan along with details of Corpus Fund should be submitted to the Ministry of Environment & Forest 5 years in advance of final mine closure for approval.	Approval letter of Final Mine closure plan duly approved by Indian Bureau of Mines is hereby attached as annexure-5.

General Conditions.

S1 No	Conditions	Compliance Status
1	No change in mining technology and scope of working should be made without prior approval of the Ministry of Environment & Forest	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014.
2	No change in the calendar plan including excavation, quantum of mineral bauxite and waste should be made.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014.
3	Four ambient air quality-monitoring station should be established in the core zone as well as in the buffer zone for RPM, SPM, SO ₂ , NO _x monitoring. Location of the stations should be decided based on the metrological data, topographical features and environmentally and ecologically sensitive targets and frequency of monitoring should be undertaken	Monitoring Reports is enclosed. Annexure 1

	in consultation with the State Pollution Control Board.	
4	Data on ambient air quality (RPM, SPM, SO ₂ , and NO _x) should be regularly submitted to the Ministry including its Regional office located at Bhubneshwar and the State Pollution Control Board / Central pollution Control Board once in six months.	Monitoring Reports is enclosed in Annexure-1.
5	Fugitive dust emission from all the sources should be controlled regularly. Water spraying arrangements on haul roads, loading and unloading and at transfer points should be provided and properly maintained.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014. Water spraying is being done around Mine Lease in dust prone areas.
6	Measures should be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operation of HEMM, etc. should be provided with ear plug / muffs.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014.
7	Industrial waste water (workshops and waste water from the mine) Should be properly collected, treated so as to conform to the standards prescribed under GSR 422 (E) dated 19 th May, 1993 and 31 st December, 1993 or as amended from time to time. Oil and grease trap should be installed before discharge of workshop effluents.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014.
8	Personnel working in dusty areas should wear protective respiratory devices and they should also provided with adequate training and information on safety and health aspects. Occupational health surveillance program of the workers should be undertaken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014.
9	A separate environmental management cell with suitable qualified personnel should be set-up under the control of a Senior Executive, who will report directly to the Head of the Organization.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014. We have Environment Management Cell for our Pakhar Group of Mines. The same is looking after Environment issues of this Mine. Annexure-3.

10	The project authorities should inform to the Regional Office located at Bhubneshwar regarding date of financial closures and final approval of the project by the concerned authorities and the date of start of land development work.	Winning of bauxite operation not carried out in this lease during the financial year 2018-19 due to exhaustion of mineral reserve. The Mine is not in operation since Nov 2014. This was an operational mine and hence provision related to financial closure not applicable.
11	The funds earmarked for environmental protection measures should be kept in separate account and should not be diverted for other purpose. Year wise expenditure should be reported to the Ministry and its Regional Office located at Bhubneshwar.	Statement of budgetary provision and actual expenses for environmental protection measure is enclosed as Annexure-2. Currently, the Regional Office is located at Ranchi.
12	The Regional Office of this Ministry located at Bhubneshwar shall monitor compliance of the stipulated conditions. The project authorities should extend full cooperation to the officer (s) of the Regional Office by furnishing the requisite data / information / monitoring reports.	Agreed.
13	A copy of clearance letter will be marked to concerned Panchayat / local NGO, if any, from whom suggestion / representation has been received while processing the proposal.	Complied
14	State Pollution Control Board should display a copy of the clearance letter at the Regional office, District Industry Center and Collector's office / Tehsildar's Office for 30 days.	Displayed.
15	The project authorities should advertise at least in two local newspapers widely circulated, one of which locality concerned, within 7 days of the issue of the clearance letter informing that the project has been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution Control Board and also at web site of the Ministry of Environment and Forests at http://envfor.nic.in and a copy of the same should be forwarded to the Regional Office of this Ministry located Bhubneshwar.	Complied. Copies, of the advertisement made in the local newspapers, have already been submitted to the Regional Office.



Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Portugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC,
District – Ranchi 834009

PAKHAR PLATEAU- ENVIRONMENTAL MONITORING REPORT

OCTOBER TO DECEMBER 2018

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,

Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

OCTOBER – DECEMBER 2018

CONTENT

	LOCATION
	AMBIENT AIR QUALITY
1	Pakhar Plateau-Near Weigh Bridge
2	Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4
3	Pakhar Plateau- Near Office
4	Pakhar Plateau- Pakhar Quarry (109.507 ha. Near Shed)
5	Pakhar Plateau Pakhar Mines(109.507 ha. Yatri Shed)
6	Pakhar Plateau- Pakhar Loading Area (109.507 ha.)





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

OCTOBER – DECEMBER 2018

Report no: MEEPL/JAN0157/2018-19	Date: 30 th January, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau-Near Weigh Bridge	
Sample collected on: 14.12.2018	

LOCATION / IDENTIFICATION: Pakhar Plateau-Near Weigh Bridge				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	80
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	39
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	4.4
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	4.5
05.	Ammonia (NH ₃)	µg/m ³	400	7.2
06.	Ozone (O ₃)	µg/m ³	180	10.7
07.	Carbon Monoxide (CO)	mg/m ³	02	0.32
08.	Lead (Pb)	µg/m ³	1.0	0.03
09.	Nickel (Ni)	ng/m ³	20	2.4
10.	Arsenic (As)	ng/m ³	06	2.0
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.2
12.	Benzo (a) Pyrene	µg/m ³	01	0.40

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

OCTOBER – DECEMBER 2018

Report no: MEEPL/JAN0158/2018-19	Date: 30 th January, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4	
Sample collected on: 14.12.2018	

LOCATION / IDENTIFICATION: Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	86
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	41
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	3.9
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	5.3
05.	Ammonia (NH ₃)	µg/m ³	400	6.1
06.	Ozone (O ₃)	µg/m ³	180	10.9
07.	Carbon Monoxide (CO)	mg/m ³	02	0.31
08.	Lead (Pb)	µg/m ³	1.0	0.03
09.	Nickel (Ni)	ng/m ³	20	2.6
10.	Arsenic (As)	ng/m ³	06	2.0
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.1
12.	Benzo (a) Pyrene	µg/m ³	01	0.40

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

OCTOBER – DECEMBER 2018

Report no: MEEPL/JAN0159/2018-19	Date: 30 th January, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau-Near Office	
Sample collected on: 14.12.2018	

LOCATION / IDENTIFICATION: Pakhar Plateau-Near Office				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	84
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	38
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	3.4
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	4.2
05.	Ammonia (NH ₃)	µg/m ³	400	5.9
06.	Ozone (O ₃)	µg/m ³	180	11.5
07.	Carbon Monoxide (CO)	mg/m ³	02	0.28
08.	Lead (Pb)	µg/m ³	1.0	0.02
09.	Nickel (Ni)	ng/m ³	20	2.2
10.	Arsenic (As)	ng/m ³	06	2.3
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.1
12.	Benzo (a) Pyrene	µg/m ³	01	0.35

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalaranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

OCTOBER – DECEMBER 2018

Report no: MEEPL/JAN0160/2018-19	Date: 30 th January, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Near Shed)	
Sample collected on: 15.12.2018	

LOCATION / IDENTIFICATION: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Near Shed)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	72
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	34
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	3.7
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	4.1
05.	Ammonia (NH ₃)	µg/m ³	400	6.6
06.	Ozone (O ₃)	µg/m ³	180	9.1
07.	Carbon Monoxide (CO)	mg/m ³	02	0.33
08.	Lead (Pb)	µg/m ³	1.0	0.03
09.	Nickel (Ni)	ng/m ³	20	2.7
10.	Arsenic (As)	ng/m ³	06	2.0
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.1
12.	Benzo (a) Pyrene	µg/m ³	01	0.4

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,

Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalaranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

OCTOBER – DECEMBER 2018

Report no: MEEPL/JAN0161/2018-19	Date: 30 th January, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Yatri Shed)	
Sample collected on: 15.12.2018	

LOCATION / IDENTIFICATION: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Yatri Shed)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	70
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	36
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	2.3
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	3.9
05.	Ammonia (NH ₃)	µg/m ³	400	5.3
06.	Ozone (O ₃)	µg/m ³	180	10.8
07.	Carbon Monoxide (CO)	mg/m ³	02	0.29
08.	Lead (Pb)	µg/m ³	1.0	0.03
09.	Nickel (Ni)	ng/m ³	20	1.5
10.	Arsenic (As)	ng/m ³	06	2.0
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.3
12.	Benzo (a) Pyrene	µg/m ³	01	0.40

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalaranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

OCTOBER – DECEMBER 2018

Report no: MEEPL/JAN0162/2018-19	Date: 30 th January, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- 109.507 ha. Loading Area.	
Sample collected on: 15.12.2018	

LOCATION / IDENTIFICATION: Pakhar Plateau- 109.507 ha. Loading Area.

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	88
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	46
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	4.5
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	5.2
05.	Ammonia (NH ₃)	µg/m ³	400	7.6
06.	Ozone (O ₃)	µg/m ³	180	10.3
07.	Carbon Monoxide (CO)	mg/m ³	02	0.41
08.	Lead (Pb)	µg/m ³	1.0	0.03
09.	Nickel (Ni)	ng/m ³	20	2.5
10.	Arsenic (As)	ng/m ³	06	1.7
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.10
12.	Benzo (a) Pyrene	µg/m ³	01	0.41

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Portugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC,
District – Ranchi 834009

PAKHAR PLATEAU- ENVIRONMENTAL MONITORING REPORT

JANUARY TO MARCH 2019

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,

Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalaranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

CONTENT

	LOCATION
	AMBIENT AIR QUALITY
1	Pakhar Plateau-Near Weigh Bridge
2	Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4
3	Pakhar Plateau- Near Office
4	Pakhar Plateau- Pakhar Quarry (109.507 ha. Near Shed)
5	Pakhar Plateau Pakhar Mines(109.507 ha. Yatri Shed)
6	Pakhar Plateau- Pakhar Loading Area (109.507 ha.)
	NOISE LEVEL
1	Pakhar Near Office.
2	Pakhar Mine (115.13 ha.) Pakhar Plateau
3	Pakhar Mine (109.507 ha. Loading Area) Pakhar Plateau
4	Pakhar Mine (109.507 Ha Yatri Shed) Pakhar Plateau
5	Pakhar Quarry (Near Shed)
	SPOT NOISE LEVEL
1	Near Poclairn at Pakhar Mine (115.13 ha.)
2	Loading point near Dumper at Pakhar Mines (109.507 ha. Minerals & Minerals)





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0176/2019-20	Date: 21 st May, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau-Near Weigh Bridge	
Sample collected on: 08.03.2019	

LOCATION / IDENTIFICATION: Pakhar Plateau-Near Weigh Bridge				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	84.3
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	42.2
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	4.1
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	3.6
05.	Ammonia (NH ₃)	µg/m ³	400	5.2
06.	Ozone (O ₃)	µg/m ³	180	9.4
07.	Carbon Monoxide (CO)	mg/m ³	02	0.30
08.	Lead (Pb)	µg/m ³	1.0	0.04
09.	Nickel (Ni)	ng/m ³	20	2.2
10.	Arsenic (As)	ng/m ³	06	1.7
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.0
12.	Benzo (a) Pyrene	µg/m ³	01	0.25

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0177/2019-20	Date: 21 st May, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4	
Sample collected on: 08.03.2019	

LOCATION / IDENTIFICATION: Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	79.8
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	37.5
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	3.1
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	4.2
05.	Ammonia (NH ₃)	µg/m ³	400	4.9
06.	Ozone (O ₃)	µg/m ³	180	8.8
07.	Carbon Monoxide (CO)	mg/m ³	02	0.34
08.	Lead (Pb)	µg/m ³	1.0	0.02
09.	Nickel (Ni)	ng/m ³	20	2.8
10.	Arsenic (As)	ng/m ³	06	1.4
11.	Benzene (C ₆ H ₆)	µg/m ³	05	1.8
12.	Benzo (a) Pyrene	µg/m ³	01	0.33

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,

Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0178/2019-20	Date: 21 st May, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau-Near Office	
Sample collected on: 08.03.2019	

LOCATION / IDENTIFICATION: Pakhar Plateau-Near Office				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	88.5
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	34.8
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	2.3
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	3.7
05.	Ammonia (NH ₃)	µg/m ³	400	2.5
06.	Ozone (O ₃)	µg/m ³	180	10.1
07.	Carbon Monoxide (CO)	mg/m ³	02	0.26
08.	Lead (Pb)	µg/m ³	1.0	0.03
09.	Nickel (Ni)	ng/m ³	20	2.0
10.	Arsenic (As)	ng/m ³	06	2.5
11.	Benzene (C ₆ H ₆)	µg/m ³	05	1.4
12.	Benzo (a) Pyrene	µg/m ³	01	0.28

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalaranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0179/2019-20	Date: 21 st May, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Near Shed)	
Sample collected on: 08.03.2019	

LOCATION / IDENTIFICATION: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Near Shed)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	76.2
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	38.3
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	3.3
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	2.7
05.	Ammonia (NH ₃)	µg/m ³	400	3.0
06.	Ozone (O ₃)	µg/m ³	180	8.9
07.	Carbon Monoxide (CO)	mg/m ³	02	0.31
08.	Lead (Pb)	µg/m ³	1.0	0.04
09.	Nickel (Ni)	ng/m ³	20	2.3
10.	Arsenic (As)	ng/m ³	06	1.4
11.	Benzene (C ₆ H ₆)	µg/m ³	05	1.7
12.	Benzo (a) Pyrene	µg/m ³	01	0.3

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0180/2019-20	Date: 21 st May, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Yatri Shed)	
Sample collected on: 08.03.2019	

LOCATION / IDENTIFICATION: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Yatri Shed)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	65.4
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	31.9
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	2.0
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	3.4
05.	Ammonia (NH ₃)	µg/m ³	400	2.9
06.	Ozone (O ₃)	µg/m ³	180	9.3
07.	Carbon Monoxide (CO)	mg/m ³	02	0.26
08.	Lead (Pb)	µg/m ³	1.0	0.01
09.	Nickel (Ni)	ng/m ³	20	1.3
10.	Arsenic (As)	ng/m ³	06	1.9
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.2
12.	Benzo (a) Pyrene	µg/m ³	01	0.21

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0181/2019-20	Date: 21 st May, 2019
Sample described by customer: AMBIENT AIR QUALITY MONITORING	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample type: AMBIENT AIR QUALITY MONITORING	
Marks on Sample: Location: Pakhar Plateau- 109.507 ha. Loading Area.	
Sample collected on: 08.03.2019	

LOCATION / IDENTIFICATION: Pakhar Plateau- 109.507 ha. Loading Area.

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m ³	100	83.9
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	µg/m ³	60	49.3
03.	Sulphur Dioxide (SO ₂)	µg/m ³	80	3.1
04.	Nitrogen Dioxide (NO ₂)	µg/m ³	80	2.9
05.	Ammonia (NH ₃)	µg/m ³	400	4.3
06.	Ozone (O ₃)	µg/m ³	180	8.5
07.	Carbon Monoxide (CO)	mg/m ³	02	0.32
08.	Lead (Pb)	µg/m ³	1.0	0.04
09.	Nickel (Ni)	ng/m ³	20	2.4
10.	Arsenic (As)	ng/m ³	06	1.5
11.	Benzene (C ₆ H ₆)	µg/m ³	05	2.3
12.	Benzo (a) Pyrene	µg/m ³	01	0.32

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0182/2019-20	Date: 21 st May, 2019
Sample described by customer: Measurement of Noise	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample Description: Measurement of Noise	
Sampling Method: Instrumental, using Sound level Metter	
Data Collection Date: 08.03.2019	

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result
Pakhar Near Office	dB (A) L_{eq}	75	63.7	70	56.2

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0183/2019-20	Date: 21st May, 2019
Sample described by customer: Measurement of Noise	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample Description: Measurement of Noise	
Sampling Method: Instrumental, using Sound level Metter	
Data Collection Date: 08.03.2019	

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result
Pakhar Mines (115.13 ha.)	dB (A) L_{eq}	75	61.4	70	54.5

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0184/2019-20	Date: 21 st May, 2019
Sample described by customer: Measurement of Noise	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample Description: Measurement of Noise	
Sampling Method: Instrumental, using Sound level Metter	
Data Collection Date: 08.03.2019	

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result
Pakhar Mines (109.507 ha. Loading Area)	dB (A) L_{eq}	75	66.0	70	50.9

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0185/2019-20	Date: 21st May, 2019
Sample described by customer: Measurement of Noise	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample Description: Measurement of Noise	
Sampling Method: Instrumental, using Sound level Metter	
Data Collection Date: 08.03.2019	

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result
Pakhar Mines (109.507 ha. of Yatri Shed)	dB (A) L_{eq}	75	58.6	70	52.1

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0186/2019-20	Date: 21st May, 2019
Sample described by customer: Measurement of Noise	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample Description: Measurement of Noise	
Sampling Method: Instrumental, using Sound level Metter	
Data Collection Date: 08.03.2019	

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result
Pakhar Quarry (Near Shed)	dB (A) L_{eq}	75	60.2	70	48.4

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalanranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0187/2019-20	Date: 21 st May, 2019
Sample described by customer: Measurement of Spot Noise	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample Description: Measurement of Spot Noise	
Sampling Method: Instrumental, using Sound level Metter	
Data Collection Date: 08.03.2019	

Location/Identification	Unit	Limit (day)	Result
Near Poklen at Pakhar Mines (115.13 ha.)	dB (A) L_{eq}	75	68.1

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009,
Mobile No: +91 9431.102.102 / +91 9955.358.262,
E-mail: mahabalranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JANUARY – MARCH 2019

Report no: MEEPL/MAY0188/2019-20	Date: 21 st May, 2019
Sample described by customer: Measurement of Spot Noise	
Client Name: Hindalco Industries Limited	
Client Address: Lohardaga	
Postal Code: 835203	
State: Jharkhand	
Country: India	
Sample Description: Measurement of Spot Noise	
Sampling Method: Instrumental, using Sound level Metter	
Data Collection Date: 08.03.2019	

Location/Identification	Unit	Limit (day)	Result
Pakhar Mines (109.507 ha. of Minerals & Minerals) Loading point near Dumper	dB (A) L_{eq}	75	69.6

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey
SENIOR EXECUTIVE



Annexure-2

BREAK UP THE COST OF ENVIRONMENTAL MEASURES DURING THE YEAR 2018-19


The composite cost during the year 2018-19 for environmental protection & pollution control by Jharkhand Mines division of M/s Hindalco Industries Ltd & M/s Minerals & Minerals Ltd for implementation of the suggested measures in EC at our all the operating mines in the state of Jharkhand-namely Pakhar (115,13 Ha), Pakhar (15.58 Ha), Pakhar (109.507 Ha), Pakhar (8.09 Ha), Pakhar (35.12Ha), Serengdag (140.06 Ha), Serengdag (155.81 Ha), Jalim & Sanai (12.14 Ha), Gurdari (584.19 Ha), Amtipani (190.95 Ha), Kujam I (80.97 Ha) Kujam II (157.38 Ha), Bagru (75.41 Ha), Hisri New (14.55 Ha), Chiro kukud (152.57 ha), Orsa pat (196.36 Ha), Bhusar (65.31 Ha) and Bimarla Bauxite Mines (134.52 Ha).

S. No	Description	Budget (in Rupees) FY 2018-19	Actual (in Rupees) FY 2018-19 (from April'18 to Sep'18)	Actual (in Rupees) FY 2018-19 (from October'18 to March'19)
1	Pollution Control & Environment monitoring	15,21,000	8,82,300.00	8,43,969.95
2	Reclamation/ Back filing & Rehabilitation**	2,92,00,000	1,49,78,461.39	2,94,16,735.87
3	Green belt, Plantation & Water spraying arrangement	45,00,256	25,38,864.95	47,17,862.62
4	Rural Development	2,60,25,236	1,32,42,312.42	6,26,47,100.13

**Part of OB removed cost.



(Basudev Gangopadhyay)
Convenor (Quality & Environment)



Annexure - 3

Date: 10.01.19

Office Order

Environmental Cell has been re-constituted at Pakhar Bauxite Mines (Area 8.09 Ha) comprising below mentioned team members. The team will ensure compliance of Environment Act, Regulation & Rule in respect of the said mines of Hindalco Industries Limited.

1. Mr. Kiran Shankar Singh- Manager (Coordinator)
2. Mr. Ramnath Bhagat (Mining Mate)-Member
3. Mr. Gaurang Agrawal (Mining Engineer) - Member
4. Mr. Sunil Kumar Pandey (Fore Man) - Member

Basudev Gangopadhyay
Convenor (Quality & Environment)

Annexure 4

Production, Mined Out, Back Filled and Over Burden removal from April'18 to March'19

S No	Name of the Mines	Mining lease area (ha)	Production Capacity (MT)*	Lease Period*	Production (MT)	Mined out area (ha)	Back filled area (ha)	Over burden (Cu.M)
1	Bagru bauxite Mine	75.41	85000	22.01.1974 to 31.03.2030	Mining operation is stopped due to legal problem			
2	Bhusar Bauxite Mine	65.31	280000	11.07.1981 to 31.03.2030	190078	1.638	5.19	335972
3	Hisri (New) Bauxite Mine	14.55	100000	19.07.1981 to 31.03.2030	90674	1.366	0.457	46704
4	Kujam - I Bauxite Mine	80.87	150000	13.03.2006 to 12.03.2056	131115	4.36	4.76	156020.91
5	Kujam - II Bauxite Mine	157.38	300000	24.03.2006 to 23.03.2056	260995	14.29	23.08	499904.89
6	Amtipani Bauxite Mine	190.95	150000	13.03.2006 to 12.03.2056	144670	8.38	3.91	276790.63
7	Gurdari Bauxite Mine	584.19	325000	23.03.1985 to 22.03.2035	322340	13.57	13.68	649920.067
8	Shrengdag A Bauxite Mine	155.81	260000	16.10.1974 to 31.03.2030	255430	3.65	3.20	655460
9	Shrengdag B Bauxite Mine	140.07	100000	04.10.1978 to 31.03.2030	73190	1.04	0.45	159667.5
10	Jalim& Sanai Bauxite Mine	12.14	50000	16.10.1974 to 31.03.2030	40395	1.04	0.45	42125

Annexure 4

11	Orsapat Bauxite Mine	196.36	200000	17.07.1986 to 16.07.2036	1470	0.00	0.00	2185.422	
12	Chiro Kukud bauxite Mine	152.57	100000	29.01.1985 to 28.01.2035	1970	0.113	0.00	13168.924	
13	Pakhar (8.09)	8.09	80000	16.05.1973 to 31.03.2030	Nil	Nil	Nil	Nil	
14	Pakhar (35.12)	35.12	200000	17.04.1975 to 31.03.2030	Nil	Nil	Nil	Nil	
15	Pakhar (115.13)	115.13	300000	19.07.1996 to 31.03.2030	294000	3.31	2.43	521370	
Minerals & Minerals Limited									
16	Pakhar (15.58)	15.58	60000	28.04.1965 to 31.03.2030	35500	0.65	0.92	93116	
17	Pakhar (109.507)	109.507	280000	26.07.2008 to 25.07.2058	247130	2.37	2.82	378979	
18	Birmarla Bauxite Mine	134.526	300000	18.07.2009 to 17.07.2059	185715	8.09	8.65	409391.00	

*Static information about the mines included in the above table



Basudev Gangopadhyay
Convenor (Quality & Environment)



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES**

Telephone: (0651) 2242889
(0651) 2242903
Fax: (0651) 2242903
E-mail: ro.ranchi@ibm.gov.in

No.: RAN/LOH/BX/FMCP-03/2014-15

318-B, Road No.- 3,
Ashok Nagar,
Ranchi – 834 002,
Date: 15/05/2015

To: **Shri A. K. Agarwal,**
Director cum Nominated Owner
M/s HINDALCO Industries Ltd.,
Court Road, Lohardaga - 835 302 (Jharkhand).

Sub: **Approval of Final Mine Closure Plan in respect of PAKHAR Bauxite Mines of M/s HINDALCO Industries Ltd. over an area of 8.09 hectares in village-Pakhar, Lohardaga district of Jharkhand State submitted under Rule 23C of MCDR, 1988.**

Ref: Your A.G.M. (Geology) letters no.(1)HIL/LHD/BX/IBM/926(I) Dated 25/09/2014
(2)HIL/LHD/BX/IBM/ Dated 06/04/2015

This office letter no. रांची/लोहरदगा/बाक्साइट/एफ.एम.सी पी.-03/2014-15,दिनांक:13/03/2015

Sir,

In exercise of the powers conferred by the sub-rule 2 of Rule 23C of Mineral Conservation & Development Rules, 1988; I hereby **approve** the above said Final Mine Closure Plan in respect of PAKHAR Bauxite mines of M/s HINDALCO Industries Ltd. over an area of 8.09 hectares in village-Pakhar, Lohardaga district of Jharkhand State, submitted under Rule 23C of MCDR, 1988. This approval is subject to the following conditions: -


- (i) that the Final Mine Closure Plan is approved without prejudice to any other laws applicable to the mine/lease area from time to time whether made by the Central Government, State Government or any other Authority.
- (ii) that this approval of the Final Mine Closure Plan does not, in any way, imply the approval of the Government in terms of any other provisions of the Mines & Minerals (Development & Regulation) Act, 1957 or the Mineral Concession Rules, 1960 and any other laws including Forest (Conservation) Act, 1980, Environment (Protection) Act, 1986 and the rules made there under.
- (iii) that the Final Mine Closure Plan is approved without prejudice to any order or direction from any court of competent jurisdiction.
- (iv) that the Regional Office, Indian Bureau of Mines, Ranchi shall be informed after completion of activities of final mine closure as per proposal of the Final Mine Closure Plan.
- (v) that the Yearly report as required under Rule 23E(2) of MCDR, 1988 setting forth the extent of protection and rehabilitation works carried out as envisaged in the approved final mine closure plan and if there is any deviations, reasons thereof shall be submitted before 1st July of every year to the Regional office, Indian Bureau of Mines, Ranchi.

No.: RAN/LOH/BX/FMCP-03/2014-15.

- (iv) The financial assurance submitted for Rs.2,00,000/- (Two lacs only) is valid up to 31/03/2017. A new bank guarantee is to be submitted on or before its expiry i.e. 31/03/2017, if the rehabilitation proposal not completed by the time.

Encl.: One copy of approved
Final Mine Closure Plan.

Yours faithfully


(R. Purohit)

Regional Controller of Mines

Copy forwarded for information to: -

1. **The Director (Mines),**
Directorate of Mines and Geology,
Government of Jharkhand,
Nepal House Area, Doranda,
Ranchi - 834 002. (Jharkhand), along with a copy of approved Final Mine Closure Plan. **It is requested to ensure that the determination of aforesaid lease is not accepted unless and until a certificate issued by the Indian Bureau of Mines under Rule 29A (2) of Mineral Concession Rules, 1960 to the effect that protective, reclamation and rehabilitative works as envisaged in the approved Final Mine Closure Plan are carried out.**
2. **The Director of Mines Safety**
Ranchi Region
CMPDIL-Campus
3rd Floor, Old Building
Kanke Road, Ranchi-834008
along with a copy of approved Final Mine Closure Plan.
3. **Shri B.K.Mahapatra, RQP,**
HINDALCO Industries Ltd.
Court Road
LOHARDAGA - 835 302.


(R. Purohit)

Regional Controller of Mines