



Hindalco-Industries Ltd, Muri Fugitive Dust Emission Results

| S.NO. | DATE | Location | Maximum Permissible Limit | RESULTS |
|-------|------------|------------------------|----------------------------------|----------------------------------|
| | | | SPM ($\mu\text{g}/\text{M}^3$) | SPM ($\mu\text{g}/\text{M}^3$) |
| 1 | 30.01.2017 | RED MUD 3#4 | 1200 | 710 |
| 2 | 30.01.2017 | Bauxite conveying Area | 1200 | 622 |
| 3 | 29.01.2017 | Coal Handling | 1200 | 685 |

| S.NO. | DATE | Location | Maximum Permissible Limit | RESULTS |
|-------|------------|---------------------|--------------------------------|--------------------------------|
| | | | SPM (mg/M^3) | SPM (mg/M^3) |
| 1 | 31.01.2017 | Bauxite Yard | 10 | 6.4 |
| 2 | 31.01.2017 | Coal Rake Unloading | 10 | 7.8 |

Signature of Analyst