



Ref.:AA/E&S/BMW/2018/361

Date: 16/06/2018

To

The Regional Officer
State Pollution Control Board,
Plot No.1070, Hospital Road, Modipara
Sambalpur - 768002

Sub.: Submission of Annual Report under Biomedical Waste Management Rule 2016 for the period January 2017 to December - 2017.

Ref.: BMW Auth. Letter No.730/IV-BMW-44/15-16, dated 16.02.2017.

Dear Sir,

With reference to the above subject, please find attached herewith Annual Report under Biomedical Waste Management Rules, 2016 in Form-IV for the year 2017 (Jan - 2017 to Dec - 2017).

Please acknowledge receipt of the letter.

Thanking you,

Yours faithfully,
For Aditya Aluminium

A handwritten signature in black ink, appearing to read "K. N. Pandey".

(K. N. Pandey)
President & Unit Head

Encl.: As above

Copy to : The Member Secretary, State Pollution Control Board Odisha.

Hindalco Industries Limited

Aditya Aluminium: At/P.O.: Lapanga - 768 212, District: Sambalpur, Odisha, India
T: +91 663 2536 247 | Fax: +91 663 2536 499 | E: hindalco@adityabirla.com | W: www.hindalco.com
Registered Office: Ahura Centre, 1st Floor, B-Wing, Mahakali Caves Road, Andheri (East), Mumbai 400 093
Tel: +91 22 6691 7000 | Fax: + 91 222 6691 7001
Corporate ID No.: L27020MH1958PLC011238

Form – IV**(See rule 13)****ANNUAL REPORT**

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier of health care facility (HCF) or common bio-medical waste treatment facility (CBWTF)]

Sl. No.	Particulars	
1	Particulars of the Occupier	
	(i) Name of the authorised person (occupier or operator of facility)	Mr. Kailash Nath Pandey
	(ii) Name of HCF or CBMWTF	First-Aid Centre
	(iii) Address for Correspondence	Hindalco Industries Limited (Unit- Aditya Aluminium), At/Po- Lapanga, Dist-Sambalpur, Pin- 756 212, State-Odisha.
	(iv) Address of Facility	Hindalco Industries Limited (Unit- Aditya Aluminium), At/Po- Lapanga, Dist-Sambalpur, Pin- 756 212, State-Odisha.
	(v) Tel. No, Fax. No	Tel. No. +91663 2536247/ Fax:+91 663 2536499
	(vi) E-mail ID	shankar.sarkar@adityabirla.com
	(vii) URL of Website	www.hindalco.com
	(viii) GPS coordinates of HCF or CBMWTF	Latitude- 21° 44'08"N Longitude- 84° 03'18" E
	(ix) Ownership of HCF or CBMWTF	Aditya Aluminium
	(x). Status of Authorisation under the Bio-Medical Waste (Management and Handling) Rules	Authorisation Order No. 29, Vide letter No.: 730/IV-BMW-44/15-16 dated 16.02.2017, valid till further order of SPCB.
	(xi). Status of Consents under Water Act and Air Act	Valid up to: 31.03.2023
2	Type of Health Care Facility	First-Aid Centre
	(i) Bedded Hospital	No. of Beds- Nil
	(ii) Non-bedded hospital (Clinic or Blood Bank or Clinical Laboratory or Research Institute or Veterinary Hospital or any other)	Non- Bedded, First-Aid Centre
	(iii) License number and its date of expiry	Factory License No. SB 332, Date of Expiry- 31.12.2018
3	Details of CBMWTF	Not Applicable
	(i) Number healthcare facilities covered by CBMWTF	Not Applicable
	(ii) No of beds covered by CBMWTF	
	(iii) Installed treatment and disposal capacity of CBMWTF:	
	(iv) Quantity of biomedical waste treated or disposed by CBMWTF	

	minutes of the meetings held during the reporting period	
7	Details trainings conducted on BMW	Quarterly Conducted
	(i) Number of trainings conducted on BMW Management.	04/Year
	(ii) number of personnel trained	06 (Six)
	(iii) number of personnel trained at the time of induction	All new joinees
	(iv) number of personnel not undergone any training so far	Not Applicable
	(v) Whether standard manual for training is available?	Yes
	(vi) any other information)	
8	Details of the accident occurred during the year	Nil
	(i) Number of Accidents occurred	Nil
	(ii) Number of the persons affected	Nil
	(iii) Remedial Action taken (Please attach details if any)	Not Applicable
	(iv) Any Fatality occurred, details	Nil
9	Are you meeting the standards of air Pollution from the incinerator? How many times in last year could not met the standards?	Not Applicable
	Details of Continuous online emission monitoring systems installed	Not Applicable
10	Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year?	A very few quantity liquid waste generated, that's disinfected by 10% hypochlorite solution.
11	Is the disinfection method or sterilization meeting the log 4 standards? How many times you have not met the standards in a year?	Yes, we meet the log 4 standard at all times.
12	Any other relevant information	It is a first aid center inside the factory premises of Aditya Aluminium, the biomedical waste generated is being treated and disposed into the deep burial pit established near the First Aid Centre at a higher elevated place and fenced from outside and locked to restrict people movement.

Certified that the above report is for the period from:- 01/01/2017 to 31/12/2017.


Dr. S. Sankar 14/6/18

Name and Signature of the Head of the Institution

Date: 14-6-18

Place—Lapanga

Medical Officer
ADITYA ALUMINIUM
(A Division of Hindalco Industries Ltd.)
Lapanga, Sambalpur
Pin-768212 (Odisha)