

HIL/LHD/ENV/MoEF/60

Date: 24.05.2021

To,
The Additional Principal Chief Conservator of Forest (C)
Ministry of Environment, Forests and Climate Changes
Regional Office (ECZ), Ranchi-834002.

**Sub:** Compliance Report of EC conditions for Orsa (196.36ha) Bauxite Mining project of M/s Hindalco Industries Limited located in Gumla, Jharkhand for the period October'20 to March'21.

Ref: Environmental Clearance letter no J-11015/241/2006-IA II (M) dated 17<sup>th</sup> May 2007

Sir,

With reference to the above, we are submitting herewith the Compliance status report of EC conditions for **Orsa (196.36 ha)** Bauxite mining project of M/s Hindalco Industries Limited located in Gumla, Jharkhand for the period October'20 to March'21. The lease detail is as below.

ease area (ha) Production Capacity (MT)	y (MT) Lease Period	
196.36 200000	17.07.1986 to 16.07.2036	

Hope you will find the same in order.

Thanking You

Yours Sincerely

FOR HINDALCO INDUSTRIES LIMITED

(Basudev Gangopadhyay)

GM (Geology & Environment)

Enclosure: - As Above

CC: ro.ranchi-mef@gov.in, mef@ori.nic.in, mef@nic.in, mef.or@nic.in, mscb.cpcb@nic.in, zokolkatta.cpcb@nic.in, ranchijspcb@gmail.com, roranchi47@gmail.com

Name of the Project

: Orsa Bauxite Mine (196.38 ha) M/s Hindalco Industries Limited

Environment Clearance No. & date : J-11015/241/2006-IA.II(M), dated 17.05.2007

Period of compliance Report : From 1st October 2020 to 31st March 2021

S No	Conditions	Compliance Status
	Specific Conditions	
1	Environmental Clearance is subject to final order of the Hon'ble Supreme Court of India in the matter of Goa foundation Vs Union of India in write petition (civil) no 460 of 2004, as may be applicable to this project	Noted.
2.	Environmental Clearance is subject to obtaining clearance from Wildlife (Protection) Act '1972 from the competent authority.	The Mine is not is operation since 20 April 2018 and this matter is subjudice.
3.	All the conditions stipulated by SPCB in their NOC shall be effectively implemented.	Noted and Agreed. The Mine is not in operation since 20 April 2018. Mine was operational for very limited period of 4-5 month. As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
4	The environmental clearance is subject to approval of the state land use Department, Government of Jharkhand for diversion of agricultural land for non-agricultural use.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month.
5	Mining shall not intersect groundwater. The mine working shall be restricted to above ground water table. Prior approval of the Ministry of Environment & Forests and Central Ground Water Authority shall be obtained for mining below water table.	Noted. Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month during which also it was above ground water level. Post resumption of mining operation compliance to the said conditions will be implemented. In future also, working zone will be restricted to above ground water table.  We undertake that no mining is/was carried out below ground water table and the same status will be maintained in future also.

6	The project proponent shall ensure that the mining shall be carried out in small blocks and at a given point of time active mining shall not be more than 2.0 ha.	Noted. The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month.  As on date mine is not operational. Post
		resumption of mining operation compliance to the said conditions will be implemented.
7.	The project proponent shall ensure that no natural water course shall be obstructed due to any mining operations.	Noted.  The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with. As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
8	Top soil, if any, shall be stacked properly with proper slope with adequate measures and should be used for reclamation and rehabilitation of mined out areas.	Noted.  The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month. As on date, mine is not operational and this condition was complied with. As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
9.	The overburden generated during the initial year shall be kept as temporary dump. Concurrent backfilling starts from the 2 <sup>nd</sup> year onwards and there shall be no external dump at the end of the mine life.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with. As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
10.	The entire excavated area of 155 ha shall be reclaimed, out of which 131 ha land shall be returned to raiyats for agricultural purpose and in 24 ha plantation shall be raised. Monitoring and management of rehabilitated areas should continue until the vegetation becomes self-sustaining. Compliance status should be submitted to the Ministry of Environment & Forest on six month basis.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month.  Post resumption of mining operation compliance to the said conditions will be implemented.

11	Catch drains and siltation ponds of appropriate	The Mine is not in operation since 20 April
	size should be constructed to arrest silt and sediment flows from mine working. The water	2018.
	so collected should be utilized for watering the mine area, roads, green belt development etc.	Prior to this, Mine was operational for very limited period of 4-5 months.
	The drains should be regularly desilted particularly after monsoon and maintained properly.	As on date mine is not operational. Post resumption of mining operation compliance
	Garland drain (size, gradient and length) shall be constructed for mine pit and sump capacity should be designed keeping 50% safety margin over and above peak sudden rainfall (based on 50 years data) and maximum discharge in the area adjoining the mine site. Sump capacity	to the said conditions will be implemented.
	should also provide adequate retention period to allow proper setting of silt material. Sedimentation pits should be constructed at the corners of the garland drains and desilted at regular intervals.	
12	Dimension of the retaining wall at the OB benches within the mine to check run-off and siltation should be based on rainfall data.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 months.  As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
13	Plantation shall be raised in an area of 24.0 ha including a green belt of adequate width by planting the native species around the ML area, roads, reclaimed area etc. in consultation with the local DFO / Agriculture Department. The	The Mine is not in operation since 20 April 2018. Total 0.13 ha have been planted till date.
	density of the trees should be around 1500 plants per ha.	Prior to this, Mine was operational for very limited period of 4-5 month.  As on date mine is not operational. Post resumption of mining operation compliance
14	The project authority should implement suitable conservation measures to augment ground water resources in the area in consultation with the Regional Director, Central Ground Water Board.	to the said conditions will be implemented.  The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month.
		As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented. It may be noted that, there is no chance to intersect ground water table during mining operation.

15	Regular monitoring of ground water level and quality should be carried out by establishing a network of existing wells and constructing new piezometers during the mining operation. The monitoring should be carried out four times in a year — pre-monsoon (April-May), monsoon (August), post-monsoon (November) and winter (January) and the data thus collected may be sent regularly to MOEF, Central Ground water Authority and Regional Director Central Ground Water Board.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month.  Monitoring of water quality report is enclosed as Annexure-1.
16	Prior permission from the competent authority should be obtained for drawl of water from the surface water bodies.	Noted. As on date, mine is not operational
17	Vehicular emissions should be kept under control and regularly monitored. Measures shall be taken for maintenance of vehicles used in mining operations and transportation of mineral. The vehicles should be covered with a tarpaulin and shall not be overloaded.	The Mine is not in operation since 20 April 2018. Mine was operational for very limited period of 4-5 month and this condition was complied with. Post resumption of mining operation compliance to the said conditions will be implemented.
18	Drills should either be operated with dust extractors or should be equipped with water injection system.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with as on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
19	Blasting operation should be carried out only during the daytime. Controlled blasting should be practiced. The mitigative measures for control of ground vibration and to arrest fly rocks and boulders should be implemented.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with as on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
20	Consent to operate should be obtained from SPCB prior to start of enhanced production from the mine.	There is no proposal for enhancement of production. As on date, mine is not operational.
21	Sewage treatment plant should be installed for the colony. ETP should also be provided for workshop and wastewater generated from mining operations.	Noted. As on date, mine is not operational.
22	The project proponent should take all precautionary measures during mining operation for conservation and protection of endangered fauna such as Leopard, Indian Wolf, Indian elephant, Indian small civet, Indian Python, etc. Spotted in the study area. Action plan for conservation of flora and fauna shall be prepared	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month. Wildlife conservation plan has already been approved by PCCF, Ranchi. However, a fresh wildlife conservation plan has already been submitted to PCCF, Ranchi for its

and implemented in consultation with the State Forest and Wildlife Department. Necessary allocation of funds for implementation of the conservation plan shall be made and the funds so allocated shall be included in the project cost. Copy of action plan may be submitted to the Ministry and its Regional Office within 3 months.	
A Final Mine Closure plan along with details of Corpus Fund should be submitted to the Ministry of Environment & Forest 5 years in advance of final mine closure for approval.	2018. Prior to this, Mine was operational for

#### GENERAL CONDITIONS

S No	Conditions	Compliance Status
1	No change in mining technology and scope of working should be made without prior approval of the Ministry of Environment & Forest	
2	No change in the calendar plan including excavation, quantum of mineral bauxite and waste should be made.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with. As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.

3	Four ambient air quality-monitoring station should be established in the core zone as well as in the buffer zone for RPM, SPM, SO <sub>2</sub> . NO <sub>x</sub> monitoring. Location of the stations should be decided based on the metrological data, topographical features and environmentally and ecologically sensitive targets and frequency of monitoring should be undertaken in consultation with the State Pollution Control Board.	We have already established four ambient air quality monitoring stations in core zone as well as buffer zone. Monitoring is being carried out and reported to concern authorities. Report is attached as Annexure 1.
4	Data on ambient air quality (RPM, SPM, SO <sub>2</sub> , and NOx) should be regularly submitted to the Ministry including its Regional office located at Bhubneshwar and the State Pollution Control Board / Central pollution Control Board once in six months.	Monitoring Reports is attached as Annexure- 1.
5	Fugitive dust emission from all the sources should be controlled regularly. Water spraying arrangements on haul roads, loading and unloading and at transfer points should be provided and properly maintained.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with. As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.
6	Measures should be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operation of HEMM, etc. should be provided with ear plug / muffs.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with.  As on date mine is not operational. Post resumption of mining operation compliance
7	Industrial waste water (workshops and waste water from the mine) Should be properly collected, treated so as to conform to the standards prescribed under GSR 422 (E) dated 19 <sup>th</sup> May, 1993 and 31 <sup>st</sup> December, 1993 or as amended from time to time. Oil and grease trap should be installed before discharge of workshop effluents.	to the said conditions will be implemented.  There was no generation of wastewater from the mine as of now. The compliance to this condition will be adhered to as applicable. As on date, mine is not operational.
8	Personnel working in dusty areas should wear protective respiratory devices and they should also provided with adequate training and information on safety and health aspects.  Occupational health surveillance program of the workers should be undertaken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed.	The Mine is not in operation since 20 April 2018. Prior to this, Mine was operational for very limited period of 4-5 month and this condition was complied with.  As on date mine is not operational. Post resumption of mining operation compliance to the said conditions will be implemented.

9	A separate environmental management cell with suitable qualified personnel should be set-up under the control of a Senior Executive, who will report directly to the Head of the Organization.	A suitable environmental management cell has been developed with qualified personnel. Copy is enclosed as Annexure- 3.
10	The project authorities should inform to the Regional Office located at Bhubneshwar regarding date of financial closures and final approval of the project by the concerned	Provisions related to financial closure not applicable.  Now Regional office is at Ranchi.
	authorities and the date of start of land development work.	
11	The funds earmarked for environmental protection measures should be kept in separate account and should not be diverted for other purpose. Year wise expenditure should be reported to the Ministry and its Regional Office located at Bhubneshwar.	Cost of Environmental protection measures is attached as Annexure-2.  Now Regional office is at Ranchi.
12	The Regional Office of this Ministry located at Bhubneshwar shall monitor compliance of the stipulated conditions. The project authorities should extend full cooperation to the officer (s) of the Regional Office by furnishing the requisite data / information / monitoring reports.	Agreed. Now Regional office is at Ranchi.
13	The project proponent shall submit six monthly report on the status of the implementation of the stipulated environmental safeguards to the Ministry of Environment and Forests its Regional Office, Bhubneshwar CPCB and State Pollution Control Board.	Duly submitted. Now Regional office is at Ranchi
14	A copy of clearance letter will be marked to concerned Panchayat / local NGO, if any, from whom suggestion / representation has been received while processing the proposal.	Complied.
15	State Pollution Control Board should display a copy of the clearance letter at the Regional office, District Industry Center and Collector's office / Tehsildar's Office for 30 days.	Displayed.
16	The project authorities should advertise at least in two local newspapers widely circulated, one of which locality concerned, within 7days of the issue of the clearance letter informing that the project has been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution Control Board and also at web site of the Ministry of Environment and Forests at <a href="http://envfor.nic.in">http://envfor.nic.in</a> and a copy of the same should be forwarded to the Regional Office of this Ministry located	Already done and copies submitted.

Bhubneshwar.	

Signature



# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: <u>ecoventures.mumbai@qmail.com</u> /<u>ecoventures@eco-ventures.in</u>

### Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

# ORSAPAT BAUXITE MINE – ENVIRONMENTAL MONITORING REPORT OCTOBER 2020

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

#### CONTENT

	LOCATION – ORSAPAT	
A.	AMBIENT AIR QUALITY - CORE ZONE	
1	Orsa Village – Near Mine Area	
2	Orsa Village – Southern Part of Orsa Lease	
3	New Mine Office – Near Weigh Bridge	
4	Orsa Village – Northern Part of Orsa Lease	
B.	AMBIENT AIR QUALITY – BUFFER ZONE	
1	Amtahi Village – Near Tailoring Centre	
2	Ambakona village	
C.	AMBIENT NOISE	
D.	SPOT NOISE	
E.	DRINKING WATER ANALYSIS	



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/**NOV/0523/2020-21 **Date:** 30th November, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Near Mine Area

Sample collected on: 16.10.2020

	LOCATION / IDENTIFICATION: Orsa Village - Near Mine Area				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	67.2	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	29.7	
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.6	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	4.3	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.5	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.0	
07.	Carbon Monoxide (CO)	mg/m³	02	0.25	
08.	Lead (Pb)	µg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	2.4	
10.	Arsenic (As)	ng/m³	06	2.8	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.4	
12.	Benzo (a) Pyrene	µg/m³	01	0.31	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/**NOV/0524/2020-21 **Date:** 30th November, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Southern Part of Orsa Lease

Sample collected on: 16.10.2020

	LOCATION / IDENTIFICATION: Orsa Village - Southern Part of Orsa Lease						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	73.5			
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	38.2			
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.8			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	5.1			
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.3			
06.	Ozone (O <sub>3</sub> )	µg/m³	180	10.8			
07.	Carbon Monoxide (CO)	mg/m³	02	0.29			
08.	Lead (Pb)	µg/m³	1.0	0.04			
09.	Nickel (Ni)	ng/m³	20	2.7			
10.	Arsenic (As)	ng/m³	06	2.4			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	3.3			
12.	Benzo (a) Pyrene	µg/m³	01	0.25			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/**NOV/0525/2020-21 **Date:** 30th November, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: New Mine Office - Near Weigh Bridge

Sample collected on: 16.10.2020

	LOCATION / IDENTIFICATION: New Mine Office - Near Weigh Bridge						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	77.1			
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	39.5			
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	4.2			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	5.1			
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.7			
06.	Ozone (O <sub>3</sub> )	µg/m³	180	10.5			
07.	Carbon Monoxide (CO)	mg/m³	02	0.32			
08.	Lead (Pb)	µg/m³	1.0	0.04			
09.	Nickel (Ni)	ng/m³	20	2.7			
10.	Arsenic (As)	ng/m³	06	2.3			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.8			
12.	Benzo (a) Pyrene	μg/m³	01	0.39			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/NOV/0526/2020-21 Date: 30th November, 2020** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

**Client Name:** Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

**State:** Jharkhand **Country:** India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Nothern Part of Orsa Lease

Sample collected on: 16.10.2020

	LOCATION / IDENTIFICATION: Orsa Village - Northern Part of Orsa Lease						
Sl. No.	PARAMETERS UNIT		Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	54.0			
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	27.5			
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	2.6			
04.	Nitrogen Dioxide (NO2)	µg/m³	80	3.1			
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.4			
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.7			
07.	Carbon Monoxide (CO)	mg/m³	02	0.25			
08.	Lead (Pb)	µg/m³	1.0	0.03			
09.	Nickel (Ni)	ng/m³	20	2.7			
10.	Arsenic (As)	ng/m³	06	2.4			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.4			
12.	Benzo (a) Pyrene	μg/m³	01	0.33			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/**NOV/0527/2020-21 **Date:** 30th November, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Amtahi Village - Near Tailoring Centre

Sample collected on: 16.10.2020

	LOCATION / IDENTIFICATION: Amtahi Village - Near Tailoring Centre						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	55.0			
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	27.9			
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.3			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.8			
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.0			
06.	Ozone (O <sub>3</sub> )	µg/m³	180	10.4			
07.	Carbon Monoxide (CO)	mg/m³	02	0.26			
08.	Lead (Pb)	µg/m³	1.0	0.03			
09.	Nickel (Ni)	ng/m³	20	3.7			
10.	Arsenic (As)	ng/m³	06	2.4			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	3.2			
12.	Benzo (a) Pyrene	μg/m³	01	0.33			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/NOV/0528/2020-21** 

Date: 30th November, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

**Sample type:** AMBIENT AIR QUALITY MONITORING **Marks on Sample:** Location: Ambakona Village

Sample collected on: 16.10.2020

	LOCATION / IDENTIFICATION: Ambakona Village						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	66.1			
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	32.7			
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	5.1			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.7			
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.2			
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.0			
07.	Carbon Monoxide (CO)	mg/m³	02	0.35			
08.	Lead (Pb)	μg/m³	1.0	0.03			
09.	Nickel (Ni)	ng/m³	20	1.4			
10.	Arsenic (As)	ng/m³	06	2.1			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.0			
12.	Benzo (a) Pyrene	µg/m³	01	0.30			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/NOV/0529/2020-21 Date:** 30th November, 2020

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 16.10.2020

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result
Orsa Village – Near Mining Area	dB (A) L <sub>eq</sub>	75	65.7	70	52.9

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/**NOV/0530/2020-21 **Date:** 30th November, 2020

Sample described by customer: Measurement of Spot Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample Description: Measurement of Spot Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 16.10.2020

Location/Identification	Unit	Limit (day)	Result
Near Weigh Bridge	dB (A) L <sub>eq</sub>	75	70.1

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

Date: 30th November, 2020

**Report No.: MEEPL/NOV/0531/2020-21** 

Sample described by customer: DRINKING WATER

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample Type: DRINKING WATER

Marks on Sample: Location: ORSA VILLAGE - DRINKING WATER

Sample collected on:16.10.2020

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
1	Colour	Hazen	<1	5 Max	APHA 22 <sup>nd</sup> Ed. 2012, 2120-B, 2-6
2	Odour		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
3	Taste		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
4	Turbidity	NTU	0.2	1 Max	APHA 22 <sup>nd</sup> Ed. 2012, 2130-B, 2-13
5	рН		6.8	6.5-8.5	APHA 22 <sup>nd</sup> Ed. 2012, 4500-H+-B, 4-92
6	Free Chlorides (Residual)	mg/l	<0.5	0.2 min	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CI-G, 4-69
7	Total Dissolved Solids	mg/l	165	500 max	IS 3025 (Part 16): 1984, Reaffirmed 2006
8	Monochloramines	mg/l	< 0.05		APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
9	Dichioramines	mg/l	<0.05		APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
10	Total hardness (as CaCO3)	mg/l	25.6	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
11	Alkalinirty Total (as CaCO3)	mg/l	31.1	200 max	IS 3025 (Part 237): 1986, Reaffirmed 2009
12	Chloride (as CI)	mg/l	5.3	250 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CI-b, 4-72
13	Sulphate (as SO4)	mg/l	4.1	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-so4-e, 4- 190



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

#### Continuation Sheet MEEPL/NOV/0531/2020-21

	T	1	I	Acceptable	T
Sl.	B	11	D		** .1 1 6
No.	Parameters	Unit	Result	Limit	Method reference
				(IS10500:2012)	
14	Nitrate (as NO3)	mg/l	1.4	45 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-NO3-E,
					4-125
15	Fluoride (as F)	mg/l	0.13	1 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-FB & D,
	, ,	Ū			4-84, 4-87
16	Boron (as B)	mg/l	0.10	0.5 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-BB, 4-25
17	Calcium (as Ca)	mg/l	30	75 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Ca-B, 3-
.,	Salisiani (as say	111971		70 max	67
18	Magnesium (as Mg)	mg/l	1.4	30 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Mg-B, 3-
		111971		oo max	84
19	Ammonical Nitrogen/Total	mg/l	<0.1		APHA 22 <sup>nd</sup> Ed. 2012, 4500-NH3-F,
	Ammonia				4-115
20	Iron (as Fe)	mg/l	0.17	0.3 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
21	Manganese (as Mn)	mg/l	N.D	0.1 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
22	Aluminium (as AI)	mg/l	0.01	0.03 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-AI-B, 3-
	, ,	Ū			61
23	Cadmium (as Cd)	mg/l	N.D	0.003 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
24	Chromium Total (as Cr)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
25	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
26	Lead (as Pb)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
27	Zinc (as Zn)	mg/l	0.02	5 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
28	Arsenic (as As)	mg/l	<0.01	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
29	Selenium (as Se)	mg/l	N.D	0.001 max	APHA 22 <sup>nd</sup> Ed. 2012, 3112-B, 3-18
30	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
31	Nickel (as Ni)	mg/l	<0.02	0.02 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
32	Mineral Oil	ma /l	N.D	0.5 max	IS 3025 (Part 39): 1991, Reaffirmed
32	Willier at Oil	mg/l	IN.D	U.S ITIAX	2003: ed. 2.1
33	Cyanida (as CN)	ma /l	N.D	0.05 max	APHA 22 <sup>nd</sup> ED. 2012, 4500-CN.C &
33	Cyanide (as CN)	mg/l	N.D	U.US Max	4-39 & 4-44
2.4	Amiania datamenta ao MDAC	ma er /1	.0.1	0.2 may	APHA 22 <sup>nd</sup> ED. 2012, 5540-C.C & 5-
34	Anionic detergents as MBAS	mg/l	<0.1	0.2 max	53
25	Phenolic compounds (as	ma m /l	ND	0.001 2204	APHA 22 <sup>nd</sup> ED. 2012, 5530-B & C 5-
35	C6H5OH)	mg/l	N.D	0.001 max	4753
27	Polynuclear aromatic	ma -: /1	ND	0.0001	
36	hydrocarbons (PAH)	mg/l	N.D	0.0001 max	APHA 22 <sup>nd</sup> ED. 2012, 6440, 6-93
27	Polychlorinated Biphenyls	m~ /l	ND	0.000E may	LISEDA Method 0000
37	(PCBs)	mg/l	N.D	0.0005 max	USEPA Method 8082
20	Sulphide (ec.S)	m~ /l	ND	0.0E may	APHA 22 <sup>nd</sup> ED. 2012, 4500-S2-C 4-
38	Sulphide (as S)	mg/l	N.D	0.05 max	175 & F 4-178



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

OCTOBER 2020

Continuation Sheet MEEPL/NOV/0531/2020-21

Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method Reference
ogical Analysis	<u> </u>	<u> </u>		
al Colliforms	MPN/ 100 mL	N.D	<1.1	APHA 22nd Ed. 2012, 9221–B & C, 9-66, 9-69
oli	MPN/ 100 mL	N.D	Absent	APHA 22nd Ed. 2012, 9221– B, C & G, 9-66, 9-69 and 9-76
Residues	•			
DDT	μg/L	N.D	1	US EPA 508-1995
DDT	μg/L	N.D	1	US EPA 508-1995
DDE	μg/L	N.D	1	US EPA 508-1995
DDE	μg/L	N.D	1	US EPA 508-1995
DDD	μg/L	N.D	1	US EPA 508-1995
DDD	μg/L	N.D	1	US EPA 508-1995
CH (Lindane)	μg/L	<0.01	2	US EPA 508-1995
CH	μg/L	<0.01	0.02	US EPA 508-1995
СН	μg/L	N.D	0.03	US EPA 508-1995
HCH	μg/L	N.D	0.03	US EPA 508-1995
achlor	μg/L	N.D	120	US EPA 508-1995
chlor	μg/L	N.D	20	US EPA 508-1995
azine	μg/L	N.D	2.1	US EPA 532-2000
ndosulfan	μg/L	N.D	0.4	US EPA 508-1995
ndosulfan	μg/L	N.D	0.4	US EPA 508-1995
losulfan Sulphate	μg/L	N.D	0.3	US EPA 508-1995
ion	μg/L	N.D	3	US EPA 8141A-1994
athion	μg/L	N.D	185	US EPA 8141A -1994
hyl Parathion	μg/L	N.D	0.4	US EPA 8141A -1994
nocrotophos	μg/L	N.D	1	US EPA 8141A-1994
rate	μg/L	N.D	2	US EPA 8141A -1994
orpyrifos	μg/L	N.D	26	US EPA 8141A -1994
rin	μg/L	N.D	0.03	US EPA 508-1995
ldrin	μg/L	N.D	0.03	US EPA 508-1995
orp rin Idr	oyrifos I	$\begin{array}{ccc} & & & \mu g/L \\ & & \mu g/L \\ & & \mu g/L \\ & & & \mu g/L \end{array}$	$\begin{array}{ccc} & \mu g/L & \text{N.D} \\ \end{array}$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$

**Conclusion:** The Physical & Chemical Analysis report indicates that water is not contaminated.

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/**NOV/0536/2020-21 **Date:** 30th November, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Kudag Village - Near Hindalco Campus

Sample collected on: 17.10.2020

]	LOCATION / IDENTIFICATION: Near Chiro Kudag Village – Near Hindalco Campus						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	59.2			
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	31.8			
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.9			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.2			
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	5.6			
06.	Ozone (O <sub>3</sub> )	µg/m³	180	10.5			
07.	Carbon Monoxide (CO)	mg/m³	02	0.33			
08.	Lead (Pb)	µg/m³	1.0	0.04			
09.	Nickel (Ni)	ng/m³	20	3.3			
10.	Arsenic (As)	ng/m³	06	2.3			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	3.4			
12.	Benzo (a) Pyrene	μg/m³	01	0.32			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

OCTOBER 2020

**Report No.: MEEPL/**NOV/0537/2020-21 **Date:** 30<sup>th</sup> November, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Jaljali Village - Near Shiv Temple Sabag Road

Sample collected on: 17.10.2020

	LOCATION / IDENTIFICATION: Jaljali Village – Near Shiv Temple Sabag Road						
Sl. No.	PARAMETERS UNIT		Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	66.5			
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	31.7			
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	2.9			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	3.2			
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.0			
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.1			
07.	Carbon Monoxide (CO)	mg/m³	02	0.33			
08.	Lead (Pb)	µg/m³	1.0	0.03			
09.	Nickel (Ni)	ng/m³	20	2.6			
10.	Arsenic (As)	ng/m³	06	4.4			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.34			
12.	Benzo (a) Pyrene	μg/m³	01	0.34			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: <u>ecoventures.mumbai@qmail.com</u> /<u>ecoventures@eco-ventures.in</u>

### Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

#### ORSAPAT BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

#### **NOVEMBER 2020**

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsa & Chiro

**Environmental Monitoring Report** 

NOVEMBER 2020

#### CONTENT

	LOCATION – ORSAPAT
	AMBIENT AIR QUALITY - CORE ZONE
1	Orsa Village – Near Mine Area
2	Orsa Village – Southern Part of Orsa Lease
3	New Mine Office – Near Weigh Bridge
4	Orsa Village – Northern Part of Orsa Lease
B.	AMBIENT AIR QUALITY - BUFFER ZONE
1	Amtahi Village – Near Tailoring Centre
2	Ambakona village



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsa & Chiro

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL/DEC/0466/2020-21 Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Near Mine Area

Sample collected on: 17.11.2020

	LOCATION / IDENTIFICATION: Orsa Village - Near Mine Area			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	67.1
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	32.8
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	4.9
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.6
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.8
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.2
07.	Carbon Monoxide (CO)	mg/m³	02	0.27
08.	Lead (Pb)	µg/m³	1.0	0.01
09.	Nickel (Ni)	ng/m³	20	1.2
10.	Arsenic (As)	ng/m³	06	1.8
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.3
12.	Benzo (a) Pyrene	μg/m³	01	0.36

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsa & Chiro

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL**/DEC/0467/2020-21 **Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Southern Part of Orsa Lease

Sample collected on: 17.11.2020

	LOCATION / IDENTIFICATION: Orsa Village - Southern Part of Orsa Lease			
SI. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	55.9
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	27.5
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.0
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.8
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	3.9
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.5
07.	Carbon Monoxide (CO)	mg/m³	02	0.23
08.	Lead (Pb)	µg/m³	1.0	0.02
09.	Nickel (Ni)	ng/m³	20	1.1
10.	Arsenic (As)	ng/m³	06	2.0
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.1
12.	Benzo (a) Pyrene	μg/m³	01	0.23

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsa & Chiro

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL/DEC/0468/2020-21 Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: New Mine Office - Near Weigh Bridge

Sample collected on: 17.11.2020

	LOCATION / IDENTIFICATION: New Mine Office - Near Weigh Bridge			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	70.5
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	37.0
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	6.8
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.0
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	7.1
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.5
07.	Carbon Monoxide (CO)	mg/m³	02	0.31
08.	Lead (Pb)	µg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	1.1
10.	Arsenic (As)	ng/m³	06	2.1
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.5
12.	Benzo (a) Pyrene	μg/m³	01	0.26

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsa & Chiro

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL**/DEC/0469/2020-21 **Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

**Client Name:** Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Northern Part of Orsa Lease

Sample collected on: 17.11.2020

	LOCATION / IDENTIFICATION: Orsa Village - Northern Part of Orsa Lease			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	64.8
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	30.6
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	4.0
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.4
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	4.9
06.	Ozone (O <sub>3</sub> )	μg/m³	180	6.1
07.	Carbon Monoxide (CO)	mg/m³	02	0.24
08.	Lead (Pb)	μg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	1.6
10.	Arsenic (As)	ng/m³	06	1.3
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.1
12.	Benzo (a) Pyrene	μg/m³	01	0.25

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsa & Chiro

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL**/DEC/0470/2020-21 **Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Amtahi Village - Near Tailoring Centre

Sample collected on: 17.11.2020

	LOCATION / IDENTIFICATION: Amtahi Village - Near Tailoring Centre			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	49.5
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	27.7
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.0
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.1
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	4.8
06.	Ozone (O <sub>3</sub> )	µg/m³	180	5.5
07.	Carbon Monoxide (CO)	mg/m³	02	0.20
08.	Lead (Pb)	µg/m³	1.0	0.02
09.	Nickel (Ni)	ng/m³	20	1.3
10.	Arsenic (As)	ng/m³	06	0.2
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.1
12.	Benzo (a) Pyrene	μg/m³	01	0.17

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsa & Chiro

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL**/DEC/0471/2020-21 **Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India
Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Ambakona Village

Sample collected on: 17.11.2020

	LOCATION / IDENTIFICATION: Ambakona Village			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	43.9
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	20.7
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.9
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	2.5
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.8
06.	Ozone (O <sub>3</sub> )	µg/m³	180	5.3
07.	Carbon Monoxide (CO)	mg/m³	02	0.25
08.	Lead (Pb)	µg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	1.5
10.	Arsenic (As)	ng/m³	06	0.83
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.2
12.	Benzo (a) Pyrene	µg/m³	01	0.18

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL/DEC/0476/2020-21 Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Kudag Village - Near Hindalco Campus

Sample collected on: 18.11.2020

]	LOCATION / IDENTIFICATION: Near Chiro Kudag Village – Near Hindalco Campus			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	53.5
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	25.8
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	5.1
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.5
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.2
06.	Ozone (O <sub>3</sub> )	µg/m³	180	6.6
07.	Carbon Monoxide (CO)	mg/m³	02	0.34
08.	Lead (Pb)	µg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	1.3
10.	Arsenic (As)	ng/m³	06	0.9
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.5
12.	Benzo (a) Pyrene	μg/m³	01	0.29

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

NOVEMBER 2020

**Report no: MEEPL**/DEC/0477/2020-21 **Date:** 28th December, 2020

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Jaljali Village - Near Shiv Temple Sabag Road

Sample collected on: 18.11.2020

	LOCATION / IDENTIFICATION: Jaljali Village – Near Shiv Temple Sabag Road			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	57.0
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	25.9
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.8
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	2.5
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.9
06.	Ozone (O <sub>3</sub> )	µg/m³	180	4.0
07.	Carbon Monoxide (CO)	mg/m³	02	0.24
08.	Lead (Pb)	µg/m³	1.0	0.02
09.	Nickel (Ni)	ng/m³	20	1.1
10.	Arsenic (As)	ng/m³	06	0.75
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.4
12.	Benzo (a) Pyrene	µg/m³	01	0.22

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi -110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: <u>ecoventures.mumbai@qmail.com</u> /<u>ecoventures@eco-ventures.in</u>

### Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

### ORSAPAT BAUXITE MINE – ENVIRONMENTAL MONITORING REPORT

**DECEMBER 2020** 

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

DECEMBER 2020

#### CONTENT

	LOCATION – ORSAPAT
A.	AMBIENT AIR QUALITY - CORE ZONE
1	Orsa Village – Near Mine Area
2	Orsa Village – Southern Part of Orsa Lease
3	New Mine Office – Near Weigh Bridge
4	Orsa Village – Nothern Part of Orsa Lease
B.	AMBIENT AIR QUALITY - BUFFER ZONE
1.	Amtahi Village – Near Tailoring Centre
2.	Ambakona village



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

DECEMBER 2020

Date: 25th January, 2021

Report No.: MEEPL/JAN/0366/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Near Mine Area

Sample collected on: 15.12.2020

	LOCATION / IDENTIFICATION: Orsa Village - Near Mine Area				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	58.1	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	31.7	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.9	
04.	Nitrogen Dioxide (NO2)	µg/m³	80	4.1	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.3	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.27	
08.	Lead (Pb)	µg/m³	1.0	0.02	
09.	Nickel (Ni)	ng/m³	20	2.2	
10.	Arsenic (As)	ng/m³	06	2.3	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.5	
12.	Benzo (a) Pyrene	µg/m³	01	0.22	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

DECEMBER 2020

Date: 25th January, 2021

**Report No.: MEEPL/JAN/0367/2020-21** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Southern Part of Orsa Lease

Sample collected on: 15.12.2020

	LOCATION / IDENTIFICATION: Orsa Village - Southern Part of Orsa Lease				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	66.4	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	35.7	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.5	
04.	Nitrogen Dioxide (NO2)	μg/m³	80	4.2	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.9	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	10.2	
07.	Carbon Monoxide (CO)	mg/m³	02	0.27	
08.	Lead (Pb)	µg/m³	1.0	0.02	
09.	Nickel (Ni)	ng/m³	20	2.1	
10.	Arsenic (As)	ng/m³	06	1.4	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.5	
12.	Benzo (a) Pyrene	μg/m³	01	0.17	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

DECEMBER 2020

**Report No. : MEEPL**/JAN/0368/2020-21 **Date:** 25th January, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

**Client Name:** Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: New Mine Office - Near Weigh Bridge

Sample collected on: 15.12.2020

	LOCATION / IDENTIFICATION: New Mine Office - Near Weigh Bridge				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	79.3	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	41.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	7.9	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.2	
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	8.4	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	10.8	
07.	Carbon Monoxide (CO)	mg/m³	02	0.33	
08.	Lead (Pb)	μg/m³	1.0	0.02	
09.	Nickel (Ni)	ng/m³	20	2.4	
10.	Arsenic (As)	ng/m³	06	1.8	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.2	
12.	Benzo (a) Pyrene	μg/m³	01	0.25	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

DECEMBER 2020

**Report No. : MEEPL**/JAN/0369/2020-21 **Date:** 25th January, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

**Client Name:** Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Northern Part of Orsa Lease

Sample collected on: 15.12.2020

LOCATION / IDENTIFICATION: Orsa Village – Northern Part of Orsa Lease				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	60.7
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	28.1
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.5
04.	Nitrogen Dioxide (NO2)	µg/m³	80	4.2
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.7
06.	Ozone (O <sub>3</sub> )	µg/m³	180	10.4
07.	Carbon Monoxide (CO)	mg/m³	02	0.26
08.	Lead (Pb)	µg/m³	1.0	0.02
09.	Nickel (Ni)	ng/m³	20	2.0
10.	Arsenic (As)	ng/m³	06	1.6
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.9
12.	Benzo (a) Pyrene	μg/m³	01	0.12

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

DECEMBER 2020

Date: 25th January, 2021

**Report No.: MEEPL/JAN/0370/2020-21** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Amtahi Village - Near Tailoring Centre

Sample collected on: 15.12.2020

	LOCATION / IDENTIFICATION: Amtahi Village - Near Tailoring Centre				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	42.5	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	25.9	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.4	
04.	Nitrogen Dioxide (NO2)	μg/m³	80	1.7	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.9	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.1	
07.	Carbon Monoxide (CO)	mg/m³	02	0.05	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	0.9	
10.	Arsenic (As)	ng/m³	06	1.5	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.3	
12.	Benzo (a) Pyrene	µg/m³	01	0.18	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

DECEMBER 2020

Date: 25th January, 2021

Report No.: MEEPL/JAN/0371/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203
State: Jharkhand
Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Ambakona Village

Sample collected on: 15.12.2020

	LOCATION / IDENTIFICATION: Ambakona Village				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	49.2	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	26.0	
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	2.1	
04.	Nitrogen Dioxide (NO2)	µg/m³	80	1.8	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.3	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.17	
08.	Lead (Pb)	µg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	1.8	
10.	Arsenic (As)	ng/m³	06	0.6	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	0.9	
12.	Benzo (a) Pyrene	μg/m³	01	0.17	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

DECEMBER 2020

**Report No. : MEEPL/JAN/0376/2020-21 Date:** 25th January, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Kudag Village - Near Hindalco Campus

Sample collected on: 16.12.2020

]	LOCATION / IDENTIFICATION: Near Chiro Kudag Village – Near Hindalco Campus				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	41.0	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	23.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.0	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	1.9	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.6	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.1	
07.	Carbon Monoxide (CO)	mg/m³	02	0.20	
08.	Lead (Pb)	µg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	1.8	
10.	Arsenic (As)	ng/m³	06	1.6	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	0.7	
12.	Benzo (a) Pyrene	μg/m³	01	0.22	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

DECEMBER 2020

Date: 25th January, 2021

Report No.: MEEPL/JAN/0377/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Jaljali Village - Near Shiv Temple Sabag Road

Sample collected on: 16.12.2020

	LOCATION / IDENTIFICATION: Jaljali Village – Near Shiv Temple Sabag Road				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	46.6	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	22.0	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.3	
04.	Nitrogen Dioxide (NO2)	μg/m³	80	2.1	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.7	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	6.9	
07.	Carbon Monoxide (CO)	mg/m³	02	0.22	
08.	Lead (Pb)	µg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	1.4	
10.	Arsenic (As)	ng/m³	06	1.8	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.9	
12.	Benzo (a) Pyrene	μg/m³	01	0.25	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: <u>ecoventures.mumbai@qmail.com</u> /<u>ecoventures@eco-ventures.in</u>

### Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

# ORSAPAT BAUXITE MINE – ENVIRONMENTAL MONITORING REPORT JANUARY 2021

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

#### CONTENT

	LOCATION – ORSAPAT
A.	AMBIENT AIR QUALITY - CORE ZONE
1	Orsa Village – Near Mine Area
2	Orsa Village – Southern Part of Orsa Lease
3	New Mine Office – Near Weigh Bridge
4	Orsa Village – Northern Part of Orsa Lease
B.	AMBIENT AIR QUALITY – BUFFER ZONE
1	Amtahi Village – Near Tailoring Centre
2	Ambakona village
C.	DRINKING WATER ANALYSIS



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

Report No.: MEEPL/FEB/0372/2020-21 Date: 10th February, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

**Client Address**: Lohardaga **Postal Code:** 835203

**State:** Jharkhand **Country:** India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Near Mine Area

Sample collected on: 16.01.2021

	LOCATION / IDENTIFICATION: Orsa Village – Near Mine Area				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	50.5	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	27.2	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.1	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.5	
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	5.0	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.3	
07.	Carbon Monoxide (CO)	mg/m³	02	0.21	
08.	Lead (Pb)	µg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	2.0	
10.	Arsenic (As)	ng/m³	06	1.2	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.7	
12.	Benzo (a) Pyrene	μg/m³	01	0.30	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

**Report No.: MEEPL/**FEB/0373/2020-21 **Date:** 10<sup>th</sup> February, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Southern Part of Orsa Lease

Sample collected on: 16.01.2021

	LOCATION / IDENTIFICATION: Orsa Village - Southern Part of Orsa Lease				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	68	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	35	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.2	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.0	
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	3.7	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.30	
08.	Lead (Pb)	µg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	2.1	
10.	Arsenic (As)	ng/m³	06	1.5	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.0	
12.	Benzo (a) Pyrene	μg/m³	01	0.22	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

**Report No.: MEEPL/**FEB/0374/2020-21 **Date:** 10<sup>th</sup> February, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: New Mine Office - Near Weigh Bridge

Sample collected on: 16.01.2021

	LOCATION / IDENTIFICATION: New Mine Office - Near Weigh Bridge				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	71.0	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	35.2	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.0	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.4	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.2	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.6	
07.	Carbon Monoxide (CO)	mg/m³	02	0.35	
08.	Lead (Pb)	µg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	2.0	
10.	Arsenic (As)	ng/m³	06	1.7	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.4	
12.	Benzo (a) Pyrene	μg/m³	01	0.32	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

**Report No.: MEEPL/FEB/0375/2020-21 Date:** 10th February, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Nothern Part of Orsa Lease

Sample collected on: 16.01.2021

	LOCATION / IDENTIFICATION: Orsa Village - Northern Part of Orsa Lease					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	58		
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	30		
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	2.2		
04.	Nitrogen Dioxide (NO2)	µg/m³	80	3.5		
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.0		
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.1		
07.	Carbon Monoxide (CO)	mg/m³	02	0.28		
08.	Lead (Pb)	µg/m³	1.0	0.03		
09.	Nickel (Ni)	ng/m³	20	2.0		
10.	Arsenic (As)	ng/m³	06	1.5		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.2		
12.	Benzo (a) Pyrene	μg/m³	01	0.30		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

**Report No.: MEEPL/**FEB/0376/2020-21 **Date:** 10<sup>th</sup> February, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

**Client Address**: Lohardaga **Postal Code:** 835203 **State:** Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Amtahi Village - Near Tailoring Centre

Sample collected on: 16.01.2021

	LOCATION / IDENTIFICATION: Amtahi Village - Near Tailoring Centre					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	53		
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	27		
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.0		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	2.8		
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.0		
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.5		
07.	Carbon Monoxide (CO)	mg/m³	02	0.29		
08.	Lead (Pb)	µg/m³	1.0	0.03		
09.	Nickel (Ni)	ng/m³	20	2.5		
10.	Arsenic (As)	ng/m³	06	2.0		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.2		
12.	Benzo (a) Pyrene	μg/m³	01	0.27		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

**Report No.: MEEPL/**FEB/0377/2020-21 **Date:** 10<sup>th</sup> February, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India
Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Ambakona Village

Sample collected on: 16.01.2021

	LOCATION / IDENTIFICATION: Ambakona Village				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	64	
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	31	
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	4.8	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	3.5	
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.1	
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.37	
08.	Lead (Pb)	µg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	1.9	
10.	Arsenic (As)	ng/m³	06	1.5	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.0	
12.	Benzo (a) Pyrene	µg/m³	01	0.32	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

**Report No.: MEEPL/**FEB/0378/2020-21 **Date:** 10<sup>th</sup> February, 2021

Sample described by customer: DRINKING WATER

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample Type: DRINKING WATER

Marks on Sample: Location: ORSA VILLAGE - DRINKING WATER

Sample collected on:16.01.2021

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
1	Colour	Hazen	<1	5 Max	APHA 22 <sup>nd</sup> Ed. 2012, 2120-B, 2-6
2	Odour		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
3	Taste		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
4	Turbidity	NTU	0.2	1 Max	APHA 22 <sup>nd</sup> Ed. 2012, 2130-B, 2-13
5	рН		6.9	6.5-8.5	APHA 22 <sup>nd</sup> Ed. 2012, 4500-H+-B, 4-92
6	Free Chlorides (Residual)	mg/l	<0.5	0.2 min	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CI-G, 4-69
7	Total Dissolved Solids	mg/l	292	500 max	IS 3025 (Part 16): 1984, Reaffirmed 2006
8	Monochloramines	mg/l	<0.05		APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
9	Dichioramines	mg/l	<0.05		APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
10	Total hardness (as CaCO3)	mg/l	30.4	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
11	Alkalinirty Total (as CaCO3)	mg/l	31.8	200 max	IS 3025 (Part 237): 1986, Reaffirmed 2009
12	Chloride (as CI)	mg/l	5.6	250 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CI-b, 4-72
13	Sulphate (as SO4)	mg/l	4.4	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-so4-e, 4- 190



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

#### Continuation Sheet MEEPL/FEB/0378/2020-21

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
14	Nitrate (as NO3)	mg/l	1.5	45 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-NO3-E, 4-125
15	Fluoride (as F)	mg/l	0.13	1 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-FB & D, 4-84, 4-87
16	Boron (as B)	mg/l	0.11	0.5 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-BB, 4-25
17	Calcium (as Ca)	mg/l	31	75 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Ca-B, 3-67
18	Magnesium (as Mg)	mg/l	1.5	30 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Mg-B, 3-84
19	Ammonical Nitrogen/Total Ammonia	mg/l	<0.1		APHA 22 <sup>nd</sup> Ed. 2012, 4500-NH3-F, 4-115
20	Iron (as Fe)	mg/l	0.17	0.3 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
21	Manganese (as Mn)	mg/l	N.D	0.1 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
22	Aluminium (as Al)	mg/l	0.01	0.03 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-AI-B, 3-61
23	Cadmium (as Cd)	mg/l	N.D	0.003 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
24	Chromium Total (as Cr)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
25	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
26	Lead (as Pb)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
27	Zinc (as Zn)	mg/l	0.02	5 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
28	Arsenic (as As)	mg/l	<0.01	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
29	Selenium (as Se)	mg/l	N.D	0.001 max	APHA 22 <sup>nd</sup> Ed. 2012, 3112-B, 3-18
30	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
31	Nickel (as Ni)	mg/l	<0.02	0.02 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
32	Mineral Oil	mg/l	N.D	0.5 max	IS 3025 (Part 39): 1991, Reaffirmed 2003: ed. 2.1
33	Cyanide (as CN)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> ED. 2012, 4500-CN.C & 4-39 & 4-44
34	Anionic detergents as MBAS	mg/l	<0.1	0.2 max	APHA 22 <sup>nd</sup> ED. 2012, 5540-C.C & 5- 53
35	Phenolic compounds (as C6H5OH)	mg/l	N.D	0.001 max	APHA 22 <sup>nd</sup> ED. 2012, 5530-B & C 5-4753
36	Polynuclear aromatic hydrocarbons (PAH)	mg/l	N.D	0.0001 max	APHA 22 <sup>nd</sup> ED. 2012, 6440, 6-93
37	Polychlorinated Biphenyls (PCBs)	mg/l	N.D	0.0005 max	USEPA Method 8082
38	Sulphide (as S)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> ED. 2012, 4500-S2-C 4- 175 & F 4-178



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

JANUARY 2021

Continuation Sheet MEEPL/FEB/0378/2020-21

S.No	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method Reference
Micro	biological Analysis	•	•	<u> </u>	
1.	Total Colliforms	MPN/ 100 mL	N.D	<1.1	APHA 22nd Ed. 2012, 9221–B & C, 9-66, 9-69
2.	E-Coli	MPN/ 100 mL	N.D	Absent	APHA 22nd Ed. 2012, 9221– B, C & G, 9-66, 9-69 and 9-76
Pesti	cides Residues	•	•	•	
3.	p,p DDT	μg/L	N.D	1	US EPA 508-1995
4.	o,p DDT	μg/L	N.D	1	US EPA 508-1995
5.	p,p DDE	μg/L	N.D	1	US EPA 508-1995
6.	o,p DDE	μg/L	N.D	1	US EPA 508-1995
7.	p,p DDD	μg/L	N.D	1	US EPA 508-1995
3.	o,p DDD	μg/L	N.D	1	US EPA 508-1995
9.	γ-HCH (Lindane)	μg/L	<0.01	2	US EPA 508-1995
10.	α-HCH	μg/L	<0.01	0.02	US EPA 508-1995
11.	β-НСН	μg/L	N.D	0.03	US EPA 508-1995
12	δ - HCH	μg/L	N.D	0.03	US EPA 508-1995
13.	Butachlor	μg/L	N.D	120	US EPA 508-1995
14.	Alachlor	μg/L	N.D	20	US EPA 508-1995
15.	Atrazine	μg/L	N.D	2.1	US EPA 532-2000
16.	α Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
17.	βEndosulfan	μg/L	N.D	0.4	US EPA 508-1995
18.	Endosulfan Sulphate	μg/L	N.D	0.3	US EPA 508-1995
19.	Ethion	μg/L	N.D	3	US EPA 8141A-1994
20.	Malathion	μg/L	N.D	185	US EPA 8141A -1994
21.	Methyl Parathion	μg/L	N.D	0.4	US EPA 8141A -1994
22.	Monocrotophos	μg/L	N.D	1	US EPA 8141A-1994
23.	Phorate	μg/L	N.D	2	US EPA 8141A -1994
24.	Chlorpyrifos	μg/L	N.D	26	US EPA 8141A -1994
25.	Aldrin	μg/L	N.D	0.03	US EPA 508-1995
26.	Dieldrin	μg/L	N.D	0.03	US EPA 508-1995
Rema	rks: N.D- Not Detected	•	•	•	

**Conclusion:** The Physical & Chemical Analysis report indicates that water is not contaminated.

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@qmail.com /ecoventures@eco-ventures.in

### Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

#### ORSAPAT BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

#### **FEBRUARY 2021**

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

FEBRUARY 2021

#### CONTENT

	LOCATION – ORSAPAT
A.	AMBIENT AIR QUALITY - CORE ZONE
1	Orsa Village – Near Mine Area
2	Orsa Village – Southern Part of Orsa Lease
3	New Mine Office – Near Weigh Bridge
4	Orsa Village – Nothern Part of Orsa Lease
B.	AMBIENT AIR QUALITY - BUFFER ZONE
1.	Amtahi Village – Near Tailoring Centre
2.	Ambakona village



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

FEBRUARY 2021

Date: 25th March, 2021

Report No.: MEEPL/MAR/0416/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

**State:** Jharkhand **Country:** India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Near Mine Area

Sample collected on: 16.02.2021

	LOCATION / IDENTIFICATION: Orsa Village - Near Mine Area					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	65		
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	39		
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	4.2		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.8		
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.5		
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.5		
07.	Carbon Monoxide (CO)	mg/m³	02	0.30		
08.	Lead (Pb)	µg/m³	1.0	0.02		
09.	Nickel (Ni)	ng/m³	20	2.2		
10.	Arsenic (As)	ng/m³	06	2.3		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.5		
12.	Benzo (a) Pyrene	μg/m³	01	0.24		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

FEBRUARY 2021

Date: 25th March, 2021

Report No.: MEEPL/MAR/0417/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Southern Part of Orsa Lease

Sample collected on: 16.02.2021

	LOCATION / IDENTIFICATION: Orsa Village - Southern Part of Orsa Lease					
SI. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	69		
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	41		
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.9		
04.	Nitrogen Dioxide (NO2)	µg/m³	80	4.5		
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	6.3		
06.	Ozone (O <sub>3</sub> )	µg/m³	180	10.5		
07.	Carbon Monoxide (CO)	mg/m³	02	0.27		
08.	Lead (Pb)	µg/m³	1.0	0.02		
09.	Nickel (Ni)	ng/m³	20	2.1		
10.	Arsenic (As)	ng/m³	06	1.4		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.5		
12.	Benzo (a) Pyrene	μg/m³	01	0.20		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

FEBRUARY 2021

Date: 25th March, 2021

Report No.: MEEPL/MAR/0418/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: New Mine Office - Near Weigh Bridge

Sample collected on: 16.02.2021

	LOCATION / IDENTIFICATION: New Mine Office - Near Weigh Bridge					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	66		
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	32		
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	4.1		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	5.5		
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	6.3		
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.5		
07.	Carbon Monoxide (CO)	mg/m³	02	0.37		
08.	Lead (Pb)	µg/m³	1.0	0.02		
09.	Nickel (Ni)	ng/m³	20	2.4		
10.	Arsenic (As)	ng/m³	06	1.8		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.2		
12.	Benzo (a) Pyrene	µg/m³	01	0.22		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

FEBRUARY 2021

**Report No. : MEEPL/MAR/0419/2020-21 Date:** 25th March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

**Client Name:** Hindalco Industries Limited

**Client Address**: Lohardaga **Postal Code**: 835203

**State:** Jharkhand **Country:** India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Northern Part of Orsa Lease

Sample collected on: 16.02.2021

	LOCATION / IDENTIFICATION: Orsa Village - Northern Part of Orsa Lease					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	69		
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	34		
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.9		
04.	Nitrogen Dioxide (NO2)	µg/m³	80	4.5		
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.9		
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.1		
07.	Carbon Monoxide (CO)	mg/m³	02	0.29		
08.	Lead (Pb)	µg/m³	1.0	0.02		
09.	Nickel (Ni)	ng/m³	20	2.0		
10.	Arsenic (As)	ng/m³	06	1.6		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.9		
12.	Benzo (a) Pyrene	μg/m³	01	0.16		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

FEBRUARY 2021

Date: 25th March, 2021

**Report No.: MEEPL/MAR/0420/2020-21** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Amtahi Village - Near Tailoring Centre

Sample collected on: 16.02.2021

	LOCATION / IDENTIFICATION: Amtahi Village - Near Tailoring Centre					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	46		
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	28		
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	2.7		
04.	Nitrogen Dioxide (NO2)	µg/m³	80	2.1		
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.5		
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.1		
07.	Carbon Monoxide (CO)	mg/m³	02	0.05		
08.	Lead (Pb)	µg/m³	1.0	0.03		
09.	Nickel (Ni)	ng/m³	20	0.9		
10.	Arsenic (As)	ng/m³	06	1.5		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.3		
12.	Benzo (a) Pyrene	μg/m³	01	0.18		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

FEBRUARY 2021

Date: 25th March, 2021

Report No.: MEEPL/MAR/0421/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Ambakona Village

Sample collected on: 16.02.2021

	LOCATION / IDENTIFICATION: Ambakona Village										
SI. No.	PARAMETERS	UNIT	Standard Limit	Concentration							
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	53							
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	29							
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.5							
04.	Nitrogen Dioxide (NO2)	µg/m³	80	1.9							
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.6							
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.1							
07.	Carbon Monoxide (CO)	mg/m³	02	0.19							
08.	Lead (Pb)	µg/m³	1.0	0.04							
09.	Nickel (Ni)	ng/m³	20	1.8							
10.	Arsenic (As)	ng/m³	06	0.6							
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	0.9							
12.	Benzo (a) Pyrene	µg/m³	01	0.20							

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

FEBRUARY 2021

**Report No.: MEEPL/MAR/0426/2020-21 Date:** 25<sup>th</sup> March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Kudag Village - Near Hindalco Campus

Sample collected on: 17.02.2021

]	LOCATION / IDENTIFICATION: Near Chiro Kudag Village - Near Hindalco Campus										
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration							
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	49							
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	30							
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.7							
04.	Nitrogen Dioxide (NO2)	µg/m³	80	2.2							
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.5							
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.5							
07.	Carbon Monoxide (CO)	mg/m³	02	0.24							
08.	Lead (Pb)	µg/m³	1.0	0.04							
09.	Nickel (Ni)	ng/m³	20	1.8							
10.	Arsenic (As)	ng/m³	06	1.6							
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	0.7							
12.	Benzo (a) Pyrene	μg/m³	01	0.25							

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Chiro Kukud

**Environmental Monitoring Report** 

FEBRUARY 2021

Date: 25th March, 2021

Report No.: MEEPL/MAR/0427/2020-21

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Jaljali Village - Near Shiv Temple Sabag Road

Sample collected on: 17.02.2021

	LOCATION / IDENTIFICATION: Jaljali Village – Near Shiv Temple Sabag Road											
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration								
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	μg/m³	100	56								
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	35								
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.4								
04.	Nitrogen Dioxide (NO2)	μg/m³	80	2.7								
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.7								
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.5								
07.	Carbon Monoxide (CO)	mg/m³	02	0.25								
08.	Lead (Pb)	μg/m³	1.0	0.03								
09.	Nickel (Ni)	ng/m³	20	1.4								
10.	Arsenic (As)	ng/m³	06	1.8								
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.9								
12.	Benzo (a) Pyrene	µg/m³	01	0.22								

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi -110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: <u>ecoventures.mumbai@qmail.com</u> /<u>ecoventures@eco-ventures.in</u>

### Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

#### ORSAPAT BAUXITE MINE – ENVIRONMENTAL MONITORING REPORT

**MARCH 2021** 

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

**MARCH 2021** 

#### CONTENT

	LOCATION – ORSAPAT
A.	AMBIENT AIR QUALITY - CORE ZONE
1	Orsa Village – Near Mine Area
2	Orsa Village – Southern Part of Orsa Lease
3	New Mine Office – Near Weigh Bridge
4	Orsa Village – Nothern Part of Orsa Lease
B.	AMBIENT AIR QUALITY - BUFFER ZONE
1.	Amtahi Village – Near Tailoring Centre
2.	Ambakona village



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

**MARCH 2021** 

**Report No. : MEEPL/MAR/0411/2020-21 Date:** 30th March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Near Mine Area

Sample collected on: 15.03.2021

	LOCATION / IDENTIFICATION: Orsa Village - Near Mine Area										
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration							
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	60.4							
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	35.1							
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.5							
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	4.3							
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.5							
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.1							
07.	Carbon Monoxide (CO)	mg/m³	02	0.30							
08.	Lead (Pb)	µg/m³	1.0	0.02							
09.	Nickel (Ni)	ng/m³	20	2.2							
10.	Arsenic (As)	ng/m³	06	1.9							
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.5							
12.	Benzo (a) Pyrene	µg/m³	01	0.24							

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

MARCH 2021

**Report No. : MEEPL**/MAR/0412/2020-21 **Date:** 30th March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Southern Part of Orsa Lease

Sample collected on: 15.03.2021

	LOCATION / IDENTIFICATION: Orsa Village - Southern Part of Orsa Lease											
Sl. No.	PARAMETERS	PARAMETERS UNIT										
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	69								
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	37								
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.9								
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.1								
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	5.0								
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.4								
07.	Carbon Monoxide (CO)	mg/m³	02	0.30								
08.	Lead (Pb)	µg/m³	1.0	0.02								
09.	Nickel (Ni)	ng/m³	20	2.1								
10.	Arsenic (As)	ng/m³	06	1.4								
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.5								
12.	Benzo (a) Pyrene	µg/m³	01	0.17								

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

**MARCH 2021** 

**Report No. : MEEPL/MAR/0413/2020-21 Date:** 30th March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: New Mine Office - Near Weigh Bridge

Sample collected on: 15.03.2021

	LOCATION / IDENTIFICATION: New Mine Office - Near Weigh Bridge										
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration							
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	72							
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	μg/m³	60	38							
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	7.5							
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.1							
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	8.5							
06.	Ozone (O <sub>3</sub> )	µg/m³	180	9.2							
07.	Carbon Monoxide (CO)	mg/m³	02	0.35							
08.	Lead (Pb)	µg/m³	1.0	0.02							
09.	Nickel (Ni)	ng/m³	20	2.1							
10.	Arsenic (As)	ng/m³	06	1.8							
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.2							
12.	Benzo (a) Pyrene	μg/m³	01	0.27							

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

**MARCH 2021** 

Report No.: MEEPL/MAR/0414/2020-21

**Date:** 30<sup>th</sup> March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Orsa Village - Northern Part of Orsa Lease

Sample collected on: 15.03.2021

	LOCATION / IDENTIFICATION: Orsa Village - Northern Part of Orsa Lease										
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration							
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	65							
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	33							
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.8							
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	4.5							
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	4.9							
06.	Ozone (O <sub>3</sub> )	µg/m³	180	8.3							
07.	Carbon Monoxide (CO)	mg/m³	02	0.30							
08.	Lead (Pb)	μg/m³	1.0	0.02							
09.	Nickel (Ni)	ng/m³	20	2.0							
10.	Arsenic (As)	ng/m³	06	1.6							
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	1.9							
12.	Benzo (a) Pyrene	μg/m³	01	0.18							

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

MARCH 2021

**Report No. : MEEPL**/MAR/0415/2020-21 **Date:** 30th March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Amtahi Village - Near Tailoring Centre

Sample collected on: 15.03.2021

	LOCATION / IDENTIFICATION: Amtahi Village - Near Tailoring Centre										
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration							
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	49							
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	28							
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	2.6							
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.1							
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.9							
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.5							
07.	Carbon Monoxide (CO)	mg/m³	02	0.05							
08.	Lead (Pb)	µg/m³	1.0	0.03							
09.	Nickel (Ni)	ng/m³	20	0.9							
10.	Arsenic (As)	ng/m³	06	1.5							
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	2.3							
12.	Benzo (a) Pyrene	μg/m³	01	0.20							

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262.

E-mail: mahabalranchi@qmail.com

Hindalco Industries: Orsapat

**Environmental Monitoring Report** 

MARCH 2021

**Report No. : MEEPL/MAR/0416/2020-21 Date:** 30th March, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

**Sample type:** AMBIENT AIR QUALITY MONITORING **Marks on Sample:** Location: **Ambakona Village** 

Sample collected on: 15.03.2021

	LOCATION / IDENTIFICATION: Ambakona Village										
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration							
01.	Particulate Matter (size less than 10 µm) PM <sub>10</sub>	µg/m³	100	57							
02.	Particulate Matter (size less than 2.5 µm) PM <sub>2.5</sub>	µg/m³	60	31							
03.	Sulphur Dioxide (SO <sub>2</sub> )	µg/m³	80	3.4							
04.	Nitrogen Dioxide (NO <sub>2</sub> )	µg/m³	80	2.7							
05.	Ammonia (NH <sub>3</sub> )	µg/m³	400	3.9							
06.	Ozone (O <sub>3</sub> )	µg/m³	180	7.0							
07.	Carbon Monoxide (CO)	mg/m³	02	0.22							
08.	Lead (Pb)	µg/m³	1.0	0.04							
09.	Nickel (Ni)	ng/m³	20	1.8							
10.	Arsenic (As)	ng/m³	06	1.0							
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	µg/m³	05	0.9							
12.	Benzo (a) Pyrene	µg/m³	01	0.22							

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



#### Annexure-2

#### BREAK UP THE COST OF ENVIRONMENTAL MEASURES DURING THE YEAR 2020-21

The composite cost during the year 2020-21 for environmental protection & pollution control by Jharkhand Mines division of M/s Hindalco Industries Ltd & M/s Minerals & Minerals Ltd for implementation of the suggested measures in EC at our all the operating mines in the state of Jharkhand-namely Pakhar (115,13 ha), Pakhar (15.58 ha), Pakhar (109.507 ha), Pakhar (8.09 ha), Pakhar (35.12 ha), Serengdag (140.06 ha), Serengdag (155.81 ha), Jalim & Sanai (12.14 ha), Gurdari (584.19 ha), Amtipani (190.95 ha), Kujam I (80.97 ha) Kujam II (157.38 ha), Bagru (75.41 ha), Hisri New (14.55 ha), Chiro kukud (152.57 ha), Orsa pat (196.36 ha), Bhusar (65.31 ha) and Bimarla Bauxite Mines (134.52 ha).

S No	Description	Budget (in Rupees) FY 2020-21	Actual (in Rupees) FY 2020-21 (From October'20 to March'21					
1	Pollution Control & Environment monitoring	38,21,524.00	26,99,875.07					
2	Reclamation/ Back filing & Rehabilitation**	3,21,50,000.00	2,90,93,388.00					
3	Green belt, Plantation & Water spraying arrangement	49,25,800.00	46,95,346.80					
4	Rural Development	3,20,21,451.00	1,65,48,825.39					

<sup>\*\*</sup>Part of OB removed cost.

(Basudev Gangopadhyay) Head (Geology & Environment)



Annexure 3

Date - 06.07.2020

#### Office Order

Environmental Cell has been re-constituted at Orsa Bauxite Mine (Area 196.36 ha) comprising below mentioned team members. The team will ensure compliance of Environment Act, Regulation & Rule in respect of the said mines of Hindalco Industries Limited.

- 1. Mr. Rajesh Ambastha (Coordinator)
- 2. Mr. Tapas Gachhyat -Geologist
- 3. Mr. Satyendra Sharma Member
- 4. Mr. Abhay Kumar Environment Engineer

The Undersigned is the in charge of above Environment Management Cell constituted for the purpose of ensuring compliances of environmental act rule and regulation for the above mine.

Basudev Gangopadhyay
Senior Executive (Quality & Environment)

	34		_			1			_			1																					
		10			9			o	0		`	1		σ			ر.	'		4			w			2			ь		SNO		
	Mine	Jalim & Sanai Bauxite		Mine	Shrengdag B Bauxite		Mine	onrengdag A Bauxite			Gurdari Bauxite Mine			Amtipani Bauxite Mine			Kujam - Il Bauxite Mine			Kujam - I Bauxite Mine		Mine	Hisri (New) Bauxite			Bhusar Bauxite Mine			Bagru bauxite Mine	7	Name of the Mines		Production, Mined Out, Back Filled and Over Burden removal
		12.14			140.07			155.81			584.19			190.95			157.38			80.87			14.55			65.31			75.41	(ha)	lease area	Mining	ined Out, Ba
		50000			100000			260000			325000			150000			300000			150000			100000			280000			85000	(MT)*	Capacity	Production	ack Filled and
31.03.2030	to	16.10.1974	31.03.2030	<del>o</del>	04.10.1978	31.03.2030	to	16.10.1974	22.03.2035	to	23.03.1985	12.03.2056	to	13.03.2006	23.03.2056	to	24.03.2006	12.03.2056	₽	13.03.2006	31.03.2030	to	19.07.1981	31.03.2030	ð	11.07.1981	31.03.2030	to	22.01.1974		Period*	ease	d Over Burde
		23128			Z			81960			138808			79180			90915			37780			57149			25490			N L	(MI)	Production		
		0.46			Z			1.9			6.52			3.27			3.19			1.52			0.512			0.178			N.F.		area (ha)	Minodon	from October'20 to March'21
		0.44		-	Z			1.2			6.23			8.420			6.18			4.28			0.00		6.10	0.15		i	2	area (ha)	Back filled		0 to March
	1.00033	22658 4		NII	NII			225276.75			208233.55			285021.770			157480.42			50116 10			000		0.00	000		i	Z	(Cu.M)	Over burden		91



	18 Bim			17 Pak			16 Pak				15 Pak			14 Pak			13 Pak		Mine	12 Chi	-		11 Ors
	Bimarla Bauxite Mine			Pakhar (109.507)			Pakhar (15.58)				Pakhar (115.13)			Pakhar (35.12)			Pakhar (8.09)		<b>н</b> е	Chiro Kukud bauxite			Orsapat Bauxite Mine
	134.37			109.507			15.58	Minerals & M			115.13			35.12			8.09			152.57			196.36
	300000			280000			60000	Minerals & Minerals Limited			300000			200000			80000			100000			200000
to 17.07.2059	18.07.2009	25.07.2058	ť	26.07.2008	31.03.2030	to	28.04.1965		31.03.2030	to	19.07.1996	31.03.2030	6	17.04.1975	31.03.2030	to	16.05.1973	28.01.2035	to	29.01.1985	16.07.2036	to	17.07.1986
	62100			108500			3200				111000			NIE.			NIL			NIL			NIL
	2.95			0.46			0.20				0.80			NE.			NE			Z F			NIL
	2.50			0.75			0.10				0.70			NIL			N.E.			NIL			NE
	160141.10			234214.42			31346.54				272905.96			N.			NE.			N			NE.

<sup>\*</sup>Static information about the mines included in the above table

Basudev Gangopadhyay
Head (Geology & Environment)