

Ref No: HIL/LHD/JP (M)/MoEF/944

Date: 25.11.14

To, Joint Director(S) MoEF,GOI, Eastern Regional Office A/3,Chandrashekharpur, Bhubaneshwar- 751023 (Orissa)

Sub: Compliance Report of EC conditions for Hisri New (14.55 ha) Bauxite Mining project of M/s Hindalco Industries Limited located in Lohardaga District of Jharkhand for the period April'14 to Sep'14.

Ref: Environmental Clearance letter no J-11015/531/2007-IA II (M) dated 17th June 2011

Sir,

With reference to the above, we are submitting herewith the Compliance status report of EC conditions for **Hisri New (14.55 ha)** Bauxite Mining project of **M/s Hindalco Industries Limited**, located in Lohardaga District of Jharkhand for the period **April'14 to Sep'14**.

Hope you will find the same in order.

Thanking You

Yours Sincerely
FOR M/s Hindalco Industries Limited,

(Bijesh Kumar Jha) Joint President (Mines)

Enclosure: - As Above

Website www.hindalco.com

Compliance of conditions laid down in Environmental Clearance

HISRI (NEW) BAUXITE MINES(14.55 Ha)

Period :April'14 - Sep'14

Environmental Clearance letter no J-11015/531/2007-IA II (M) dated 17th June 2011

SI No	Conditions	Compliance Status
	Specific Conditions	
1	The project proponent shall obtain Consent to Establish and Consent to Operate from the Jharkhand State Pollution Control Board and effectively implement all the conditions stipulated therein.	Consent to Establish and Consent to Operate has been obtained prior to start of mining. Implementations of stipulated conditions are fulfilled.
2	The environmental clearance is subject to forestry clearance.	Forest clearance obtained.
3	The environmental clearance is subject to approval of the state land use Department, Government of Jharkhand for diversion of agricultural land for non-agricultural use.	Mining Lease is granted/ renewed by the State Govt. after due consideration and Cabinet approval on recommendation of DC who is the competent authority to give permission for using the agricultural land for non-agricultural purpose.
4	The mining operation shall be restricted to above ground water table and it should not intersect the ground water table. In case of working below ground water table, prior approval of the Ministry of Environment & Forests and Central Ground Water Authority shall be obtained, for which a detailed hydro – geological study shall be carried out.	Depth of mining will be 15-20 mtr bgl (maximum). Ground water table level is 40-50 mtr bgl. Thus there is no chance to intersect ground water table during mining operation. Working zone will be restricted to above ground water table.
5	The Project proponent shall ensure that no natural watercourse shall be obstructed due to any mining operations. The first order streams and the seasonal nallahs originating from the mining lease area shall be protected.	It is being ensured. No natural water course has been obstructed.
6	The top soil, if any shall temporarily be stored at earmarked site (s) only and it should not be kept unutilized for long. The topsoil shall be used for land reclamation and plantation.	Sequential backfilling and reclamation of the mined out area are being exercised. Topsoil is being spread on backfilled area for reclamation of the area.
7	The solid waste generated during the mining operation shall be backfilled and there shall be no external overburden dump left at the end of the mine life. The entire excavated area of 12.19 ha. shall be backfilled and reclaimed by plantation. The backfilling should be carried out in such a manner that it is restored to the normal ground level. Monitoring and management of	Overburden and waste rock are being used for back filling. Data pertaining to backfilling is enclosed as Annexure.

	rehabilitated areas should continue until the vegetation becomes self-sustaining. Compliance status should be submitted to the Ministry of Environment & Forest on six month basis.	
8	Catch drains and siltation ponds of appropriate size should be constructed around the working pit, subgrade dump, soil and mineral dumps to arrest flow of silt and sediment directly into the agricultural fields, the Kisco Nadi, the Sukri Nadi, the Chungahat nallah, the Barki nallah and other water bodies. The water so collected should be utilized for watering the mine area, roads, green belt development etc. The drains should be regularly desilted, particularly after monsoon and maintained properly.	No run off is being generated from mining activities. However, to collect and manage rainwater during monsoon drains, Pit sumps are made, part of mined out area is used as settling tank. Settled water is being used for sprinkling of quarry, roads, green belt development, etc.
	Garland drain, settling tanks and check dams of appropriate size, gradient and length shall be constructed for both around the minepit and sub grade dump to prevent run off of water and flow sediments directly into the agricultural fields, the Kisco Nadi, the Sukri Nadi, the Chungahat nallah, the Barki nallah and other water bodies and sump capacity should be designed keeping 50% safety margin over and above peak sudden rainfall (based on 50 years data) and maximum discharge in the area adjoining the mine site. Sump capacity should also provide adequate retention period to allow proper setting of silt material. Sedimentation pits should be constructed at the corners of the garland drains and desilted at regular intervals.	
9	Dimension of the retaining wall at the toe of the sub-grade, dump and OB benches within the mine to check run-off and siltation should be based on the rain fall data.	The dimensions of the retaining wall OB dumps are based on the average rainfall.
10	Plantation shall be raised in an area of 12.7 ha including a 7.5 m. wide green belt in the safety zone around the mining lease by planting the native species around ML area, backfilled and reclaimed area, around water body, roads etc. in consultation with the local DFO / Agriculture Department. At least 1500 trees per year shall be planted with a tree density of 1000 trees per hectare. Greenbelt shall be developed all along the mine lease area in a phased manner and shall be completed within first five years.	Being carried out progressively. During FY 2014-15 —around 150 saplings planted in this mine.

11	Effective safe guard measures, such as regular water sprinkling shall be carried out in critical areas prone to air pollution and having high levels to particulate matter such as around loading and unloading point and all transfer points. Extensive water sprinkling shall be carried out on haul roads. It should be ensured that the Ambient Air Quality parameters conform to the norms prescribed by the Central Pollution Control Board in this regard.	Effective safe guard measures, such as regular water sprinkling are being carried out in critical areas prone to air pollution. Regular Ambient Air Quality monitoring are being carried out.
12	The project authority should implement suitable conservation measures to augment ground water resources in the area in consultation with the	System is already in place.
	Regional Director, Central Ground Water Board.	
13	Regular monitoring of ground water level and quality should be carried out by establishing a network of existing wells and constructing new piezometers during the mining operation. The periodic monitoring [(at least four times in a year – pre-monsoon (April-May), monsoon (August), post-monsoon (November) and winter (January) once in each season)] shall be carried out in consultation with the State Ground Water Board/Central Ground water Authority and the data thus collected may be sent regularly tot eh Ministry of Environment and Forests and its Regional office Bhubneshwar, The Central Ground Water Authority and the Regional Director, Central Ground Water Board. If at any stage, it is observed that the ground water table is getting depleted due to the mining activity, necessary corrective measures shall be carried out.	It is being monitored.
14	Monitoring to the springs shall be carried out for the quality and quantity of water regularly so as to ensure that there is no adverse impact on the same due to the project. Records in this regards shall be maintained.	Monitoring is being done, water quality report enclosed.
15.	It shall be ensured that there is no change in the hydrology of the area due to the project.	Being adhered to.
16.	The project proponent shall obtain necessary prior permission of the competent authorities for drawl of requisite quantity of water (surface water and ground water) required for the project.	Complied. Water cess is being paid to State Pollution Control Board regularly.
17.	Suitable rain water harvesting measures on long term basis shall be planned and implemented in consultation with the Regional Director, Central Ground Water Board.	Suitable rain water harvesting measures on long term basis have been planned and implemented.

18.	Appropriate mitigative measures shall be taken to	Appropriate mitigative measures have
2.5.0	prevent pollution of the Kisco Nadi, the Sukri Nadi	been taken to prevent pollution of the
	and other rivers in the buffer zone of the mine, in	Kisco Nadi, the Sukri Nadi and other
	consultation with the State Pollution Control	rivers in the buffer zone of the mine.
1.0	Board.	
19	Vehicular emissions should be kept under control	Regular maintenance of vehicles are
	and regularly monitored. Measures shall be taken for maintenance of vehicles used in mining	undertaken to minimize vehicular
	operations and transportation of mineral from mine	emission. Care is taken on regular basis to arrest spillage/fugitive dust emission.
	face to the Beneficiation plant The vehicles	At most care is taken to cover bauxite
	should be covered with a tarpaulin and shall not be	loaded trucks with Tarpaulin and
	overloaded.	overloading is avoided.
20	Blasting operation should be carried out only	Blasting operation is being carried out
	during the daytime. Controlled blasting should be	only during the daytime. Controlled
	practiced. The mitigative measures for control of	blasting is in practice. The mitigative
	ground vibration and to arrest fly rocks and	measures for control of ground vibration
	boulders should be implemented.	and to arrest fly rocks and boulders are
21	Drills shall either be operated with dust extractors	being implemented. Wet drilling is done in the drill holes
21	or equipped with water injection system.	intermittently for dust suppression by
	type with water injection by stein.	pumping water.
22	Mineral handling area shall be provided with	We are exploring the possibilities.
	adequate number of high efficiency dust extraction	However, water sprinkling is being
	system. Loading and unloading areas including all	carried out regularly at loading and
	the transfer points should also have efficient dust	unloading areas.
	control arrangements. These should be properly	
23	maintained and operated.	The section 121 1 1 1 1 0 000 100
23	Sewage treatment plant should be installed for the colony. ETP should also be provided for workshop	There is no likely hood of effluent from mine, hence ETP is not required. The
	and wastewater generated from mining operations.	sewage water for working population is
	gg operations.	planned to be collected through Septic
		Tank/Soak Pit and treated in Sewage
		Treatment Plant already existing in
2.4		adjoining Bagru ML.
24	The project authorities should undertake sample	Agreed. Being getting done through
	survey to generate data on pre-project community health status within a radius of 1 Km. from	medical camp.
	proposed mine.	
25	Pre-placement medical examination and periodical	System is already in place
	medical examination of the workers engaged in the	James and the place
	project shall be carried out and records maintained.	
	For the purpose, schedule of health examination of	
	the workers should be drawn and followed	
26	accordingly.	
26.	Provision shall be made for the housing of construction labour within the site with all	System is already in place.
	necessary infrastructure and facilities such as fuel	
	for cooking, mobile toilets, mobile STP, safe	
	moone tonots, moone 511, sale	

	drinking water, medical health care, crèche etc.	
	The housing may be in the form of the temporary	
	structures to be removed after the completion of	
	the project.	
27	The critical parameters such as RSPM (Particulate	Being carried out. Monitoring report
	matter with size less than 10 μm (i.e. PM ₁₀ , PM _{2.5)}	enclosed.
	and NO_x in the ambient air within the impact zone,	
	peak particle velocity at 300 m. distance or within	
	the nearest habitation, whichever is closer shall be	
	monitored periodically. Further, quality of	
	discharge water shall also be monitored [(TDS,	
	DO, PH and Total Suspended Solids (TSS)], The	
	monitored data shall be uploaded on the website of	
	the Company as well as displayed on a display	
	board at the project site at a suitable location near	
	the main gate of the Company in Public domain.	
	The Circular no. J-20012/1/2006-IA.II(M) dated	
	27.05.2009 issued by Ministry of Environment and	
	Forests, which is available on the website of the	
	Ministry www.envfor.nic.in shall also be referred	
	in this regard for its compliance.	
28	A Final Mine Closure plan along with details of	Progressive Mine Closure Plan duly
	Corpus Fund should be submitted to the Ministry	approved by Indian Bureau of Mines is
	of Environment & Forest 5 years in advance of	with us. FMCP is submitted to IBM for
	final mine closure for approval.	approval.

GENERAL CONDITIONS

Sl	Conditions	Compliance Status
No		A second
1	No change in mining technology and scope of working should be made without prior approval of the Ministry of Environment & Forests.	Being adhered to.
2	No change in the calendar plan including excavation, quantum of mineral bauxite and waste should be made.	Mining of ore and OB is being done as per approved calendar plan.
3	Conservation measures for protection of flora and fauna in the core & buffer zone should be drawn up in consultation with the local forest and wildlife department.	Conservation measures for protection of flora and fauna in the core & buffer zone has been drawn up in consultation with the local forest and wildlife department.
4	Four ambient air quality-monitoring station should be established in the core zone as well as in the buffer zone for RSPM (Particulate matter with size less than 10 μ m (i.e. PM_{10}) $PM_{2.5)}$ & NO_X monitoring. Location of the stations should be decided based on the	Being carried out. Enclosed as Annexure.

	metrological data, topographical features and environmentally and ecologically sensitive targets and frequency of monitoring should be undertaken in consultation with the State Pollution Control Board.	
5	Data on ambient air quality RSPM (Particulate matter with size less than 10 μm i.e. PM_{10}) & NO_X should be regularly submitted to the Ministry including its Regional office located at Bhubneshwar and the State Pollution Control Board / Central pollution Control Board once in six months.	Being carried out. Enclosed as Annexure.
6	Fugitive dust emission from all the sources should be controlled regularly. Water spraying arrangements on haul roads, loading and unloading and at transfer points should be provided and properly maintained.	Water spraying arrangements on haul roads, loading and unloading and at transfer points have been provided and properly maintained.
7	Measures should be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operation of HEMM, etc. should be provided with ear plug / muffs.	Measures are being taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operation of HEMM, etc. has been provided with ear plug / muffs.
8	Industrial waste water (workshops and waste water from the mine) Should be properly collected, treated so as to conform to the standards prescribed under GSR 422 (E) dated 19 th May, 1993 and 31 st December, 1993 or as amended from time to time. Oil and grease trap should be installed before discharge of workshop effluents.	Is being done as applicable.
9	Personnel working in dusty areas should wear protective respiratory devices and they should also provided with adequate training and information on safety and health aspects. Occupational health surveillance program of the workers should be undertaken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed.	Complied. Use of Personal Protective Equipment (PPE) by the individuals is being ensured. All the mine workers are being regularly and periodically sent to our own hospital for health checkup for any contraction of diseases due to exposure in dusty and noisy areas.
		Training on safety, health and environmental aspects of mining is being regularly imparted through VT centre and also through various other training programmes conducted by the State Government, recognized agencies, etc

10	A caparata anvironmental management 11	C , F , 114 C ;
10	A separate environmental management cell	Separate Environmental Management Cell
	with suitable qualified personnel should be set-	(EMC) has been constituted and is
	up under the control of a Senior Executive,	functioning effectively. Copy enclosed as
	who will report directly to the Head of the	Annexure.
	Organization.	
11	The funds earmarked for environmental	The fund earmarked for environmental
	protection measures should be kept in separate	protection measures is being kept in
	account and should not be diverted for other	separate account. Year wise expenditure is
	purpose. Year wise expenditure should be	being reported to the Ministry and its
	reported to the Ministry and its Regional	Regional Office located at Bhubneshwar.
	Office located at Bhubneshwar.	regional office located at bilubileshwar.
12	The project authorities should inform to the	Compliat Day CD: 111 1 24st
12		Complied. Date of Financial closure is 31 st
	Regional Office located at Bhubneshwar	March.
	regarding date of financial closures and final	
	approval of the project by the concerned	
	authorities and the date of start of land	
	development work.	
13	The Regional Office of this Ministry located at	Agreed.
	Bhubneshwar shall monitor compliance of the	
	stipulated conditions. The project authorities	
	should extend full cooperation to the officer (s)	
	of the Regional Office by furnishing the	
	requisite data / information / monitoring	
	reports.	
14	*	D.I. I. I. I.
14	The project proponent shall submit six monthly	Duly submitted.
	report on the status of the compliance of the	
	stipulated environmental Clearance conditions	
	including results of monitoring data (both in	
	hard copies as well as by e-mail) to the	
	Ministry of Environment and Forests, its	
	Regional Officer, Bhubaneshwar, the	
	respective Zonal office of Central Pollution	
	Control Board the State Pollution Control	
	Board. The proponent shall upload the status of	
	compliance of the Environmental Clearance	
	conditions, including results of monitored data	
	on their website and shall update the same	
	periodically. It shall simultaneously be sent to	
	the Pagional Office of the Ministry	
	the Regional Office of the Ministry of	
	Environment and Forests, Bhubneshwar, the	
	respective Zonal Office of Central Pollution	
	Control Board and State Pollution Control	
	Board.	
15	A copy of clearance letter shall be sent by the	Duly submitted.
	proponent to concerned Panchyat, Zila Parisad/	
	Municipal Corporation, Urban Local Body and	
	the Local NGO, if any, from whom	
	the Local NGO, if any, from whom suggestions/ representations, if any, were	

	received while processing the proposal. The clearance letter shall also be put on the website of the Company by the proponent.	
16	State Pollution Control Board should display a copy of the clearance letter at the Regional office, District Industry Center and Collector's office / Tehsildar's Office for 30 days.	Displayed.
17	The environmental statement for each financial year ending 31 st March in Form – V as is mandated to be submitted by the project proponent to the concerned Stated pollution Control Board as prescribed under the Environment (Protection) Rules, 1986, as amended subsequently, shall also be put on the website of the company along with the status of the compliance of environmental clearance conditions and shall also be sent to the Regional Office of the Ministry of Environment and Forests, Bhubneshwar by email.	Submitted.
18.	The Company shall submit within 3 month their policy towards Corporate Environment Responsibility which should inter-alia address (i) Standard operating process/ procedure to bring into focus any infringements/ deviation/ violation of environmental or forest norms/ conditions, (ii) Hierarchical system or Administrative order of the Company to deal with environmental issues and ensuring compliance with environmental issues and ensuring compliance with Environment Clearance conditions and (iii) System of reporting of non compliance / violation of environmental norms to the Board of Directors of the Company and / or stakeholders or shareholders.	Already Submitted.
19	The project authorities should advertise at least in two local newspapers widely circulated, one of which locality concerned, within 7days of the issue of the clearance letter informing that the project has been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution Control Board and also at web site of the Ministry of Environment and Forests at http://envfor.nic.in and a copy of the same should be forwarded to the Regional Office of this Ministry located at Bhubneshwar.	Complied and informed.



Date: 10.11.14

OFFICE ORDER

In connection with the earlier office order dated 30.10.2013 the re constituted team of Environment management cell to ensure compliance of various environmental Acts, regulations & rules at Mines Division, Hindalco, Lohardaga as follows:

The Environment Management Cell will consist of:

1. B. K. Mahapatra, AGM (Quality & Environment), Convenor.

Members:

- 2. Ajay Kumar Pandey, Manager (Bagru Mines)
- 3. A Anbarasu, Mines Manager (Serengdag Mines)
- 4. S P Jha, Mines Manager (Pakhar Mines)
- 5. Kiran Sankar Singh, Mines Manager (Gurdari)
- 6. Vidya Sagar Singh, Mines Manager (Kujam)
- 7. Amar Bharati, Mines Manager (Amtipani)
- 8. Rajesh Ambastha, Mines Manager (Chiro Kukud & Orsa)
- 9. Biplab Mukherjee (Asst Manager- Geology)

By order

Bijesh Kumar Jha Joint President (Mines)

Cc to: - All Mines Manager All Department head Notice Board.

Website www.hindalco.com



BREAK UP THE COST OF ENVIRONMENTAL MEASURES DURING THE YEAR 2014-15

The composite cost during the year 2014-15 for environmental protection & pollution control by Jharkhand Mines division of M/s Hindalco Industries Ltd & M/s Minerals & Minerals Ltd for implementation of the suggested measures in EC at our all the operating mines in the state of Jharkhand-namely Pakhar (115,13 Ha), Pakhar (15.58 Ha), Pakhar (109.507 Ha), Pakhar (8.09 Ha), Pakhar (35.12Ha), Serengdag (140.06 Ha), Serengdag (155.81 Ha), Jalim & Sanai (12.14 Ha), Gurdari (584.19 Ha), Amtipani (190.95 Ha), Kujam I (80.97 Ha) Kujam II (157.38 Ha) and Bagru (75.41 Ha), Hisri New (14.55 Ha), Chiro kukud, *Orsa pat(196.36 Ha)*, Bhusar (65.31 Ha)& *Bimarla Bauxite Mines (134.52 Ha*).

SI	Description	Budget (in Lakh Rupees)	Actual (in Lakh Rupees)
No		FY 2014-15	FY 2014-2015
			(from April'14 to Sep'14)
1	Pollution Control & Environment monitoring	5.50	6.00
2	Reclamation/ Back filing & Rehabilitation	42.50	36.00
3	Green belt & Plantation	60.03	54.46
4	Rural Development	85.29	111.37

^{**}Part of OB removed cost.

Convener

Environment Management Cell Hindalco Industries Limited

PRODUCTION, MINED OUT, BACKFILLED, PRODUCTION AND OVERBURDEN REMOVAL FROM APR-14 TO SEP-14

		P		2	-
JS	Name of Mines	(Ha)	(in Acres)	(in Acres)	Production (in MT)
₽	Shrengdag Bauxite Mines	155.81	7.80	4.80	105050
2	2 Gurdari Bauxite Mines	584.19	22.10	11.80	168585
ω	3 Jalim & Sanai	12.14	0.70	0.30	5311
4	Serangdag	140.07	2.00	0.50	31650
5	Pakhar Buxite Mines	115.13	3.69	1.50	137290
6	6 Pakhar Buxite Mines	8.09	0.00	0.00	0.00
7	Pakhar Buxite Mines	38.95	0.00	0.00	0.00
∞	8 Kujam-l	80.87	4.15	3.46	37960
9	9 Kujam-II	157.38	13.84	12.75	104325
10	10 Amtipani	190.95	4.03	3.26	93330
11	11 Chiro-Kukud	152.57	3.95	6.42	17584
12	12 Orsa Bauxite Mines	196.36	0.00	0.00	0.00
13	13 Hisri New	14.55	1.29	0.65	54529
14	14 Bagru	75.41	0.00	0.00	0.00
15	15 Bhusar	65.31	0.94	1.50	82032
	Minerals & Minerals Limited				
16	16 Pakhar Buxite Mines	109.507	4.21	3.51	183605
17	17 Pakhar Buxite Mines	15.58	0.30	0.20	31175
18	18 Bimarla Bauxite Mines	134.526	0.00	0.00	0.00

			3	Monsoon 2014	Post M	Post Monsoon 2014
Location (Mines)	Elevation (Mtr)	Well type	Inside ML	Outside ML	Inside ML	Outside ML
	905	Open Well		21.72		24.15
	910	Open Well		24.30		24.55
D S S S	915	Open Well		29.40		28.44
Cag	903	Open Well		22.85		33.12
	909	Open Well		17.55		28.75
	1000	Open Well		24.90		22.66
Pakhar	1083	Hand Pump	35.35		31.65	
	1027	Open Well		25.85		28.35
	1094	Hand Pump	41.75		39.54	
Sherengdag	1081	Hand Pump	39.65		31.30	
	1055	Hand Pump	33.05		27.55	
	1066	Hand Pump	27.75		26.25	
	1045	Hand Pump	29.30		27.84	
	1061	Hand Pump	28.35		24.90	
Gurdari	1059	Hand Pump	38.15		36.63	
	1075	Hand Pump	28.22		26.88	
	1075	Hand Pump	28.36		29.30	
	1040	Open Well		33.95		21.85
Kiism	1041	Open Well		33.65		24.82
Nujum	1064	Hand Pump	31.58		28.65	
	1052	Hand Pump				21.12
	1148	Hand Pump	33.45		28.40	
Chiro Kukud	1151	Hand Pump	37.60		31.80	
	1084	Hand Pump	34.35		36.86	

Monitored water level

Fig in meter





Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

e ecoventures.mumbai@gmail.com /ecoventures@eco-ventures.in

Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

BAGRU PLATEAU- ENVIRONMENTAL MONITORING REPORT

SEPTEMBER 2014

Vijay Pandey SENIOR EXECUTIVE

For Mahabal Enviro Eng. Pvt. Ltd.

Authorised Signatory

Canco Engo P



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

Report no: SEPT001/2014-15

Date: 1st October, 2014

SAMPLE DRAWN BY MAHABAL ENVIRO ENGINEERS PVT LTD

Sample described as: FLUE GAS

Name of the Industry: M/s HINDALCO INDUSTRIES LIMITED

Address: Mines Division, Lohardaga, Jharkhand, Pin-835 302

Date & time of Sampling: 18.09.2014 (11.00-11.30 Hrs)

Sampling Site: Bagru Mines Office-Bagru Plateau

A. General Information about Stack

- Stack connected to: DG-Set (250 KVA)
- Emission due to: Burning of H.S.D
- Material of construction: M.S
- Shape of Stack: Circular
- Whether stack is provided with permanent platform & ladder: Yes
- Capacity: 250 KVA
- Running Load: 90 KVA

B. Physical characteristics of stack

- Height of the stack (a) from ground level: 7.0
- Diameter of the Stack at sampling point: 0.2030
- Height of the sampling point from GL: 6.25

C. Analysis/Characteristic of Stack

- Fuel used: H.S.D
- Fuel Consumption: 30 lt/hr

S.No	PARAMETERS	PROTOCOL	RESULTS	Limits as per MoEF G.S.R.448(E)
	Temperature of Emission (°C)	IS 11255 Part:3 1985 (Realf 2008)	300	
1.	Barometric pressure (mm of Hg)	IS 11255 Part:3 1985 (Realf 2008)	650	
2.	Velocity of Gas (m/sec)	IS 11255 Part:3 1985 (Realf 2008)	10.2	••
3.	Quantity of Gas flow (Nm³/hr)	IS 11255 Part:3 1985 (Realf 2008)	490	
4.	Concentration of CO ₂ (% v/v)	IS 11255 Part:3 1985 (Realf 2008)	6.0	5.0
5.		IS 11255 Part:3 1985 (Realf 2008)	0.30	
6.	Concentration of CO (gm/kw-h)	USEPA-6C	49	
7.	Concentration of SO ₂ (mg/Nm³)	USEPA-7E	0.60	9.2
8.	Concentration of NO ₂ (gm/kw-h)		20000	0.0
9.	Concentration of Particulate Matters (gm/kw-h)	IS 11255 Part 3: 1985 (Realf 2003)	0.10	0.3
E. Poll Det	ution Control Device ails of pollution control devices attache	ed with the stack: Nil		

Vijay Pandey SENIOR EXECUTIVE For Mahabal Enviro Eng. Pvt. Ltd.

Authorised Signatory

110 E

Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room, Near J B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring report

Date: 1st October,2014

Report no: SEPT001/2014-15

Sample described by customer: EFFLUENT

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India Sample Type: Effluent

Received:18.09.2014 Registered: 18.09.2014

Marks on Sample: Location: STP Outlet (Bagru Mines)

Sample collected on: 18.09.2014

Quantity: 4 litres

Test Start/End Date: 18.09.2014/19.09.2014

S.No	collected by: Mahabal EnviroEng Analysis	Method	Result	Unit	Limits
1.	рН	APHA 22nd Ed. 2012, 4500-H+-B, 4-92	8.0		5.5-9.0
2.	Total Suspended Solids	APHA 22nd EDN:2012- 2540	18.0	mg/l	100
3.	BOD @ 27°C	IS 3025 (Part 44): 1993, RA2003, Amd.1	12.5	mg/l	30
4.	Oil & Grease	IS 3025(Part 39): 1991, RA 2003, Ed.2.1	< 5.0	mg/l	10
5.	Total Dissolved Solids	APHA 22 nd EDN 2012- 2540	20.2	mg/l	2100
6.	Aluminum(as Al)	APHA 22 nd EDN 2012- 3120B	1.5	mg/l	3
7.	Calcium (as Ca)	APHA 22 nd EDN 2012- 3120B	5.0	mg/l	75
8.	Iron (as Fe)	APHA 22 nd EDN 2012- 3120B	1.2	mg/l	3
9.	Temperature		15	°C	shall not exceed 5°C above the receiving water temperature

Vijay Pandey SENIOR EXECUTIVE For Mahabai Enviro Eng. P 41 td.

Authorised Signatory



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room, Near J B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October,2014

Report no: SEPT001/2014-15

Sample described by customer: SOIL

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: SOIL Received:17.09.2014 Registered: 17.09.2014

Marks on Sample: Location: Bagru Mines Sample collected on: 17.09.2014

Quantity: 2 kgs

Test Start/End Date: 17.09.2014/18.09.2014

S.No Analysis			Method	Result	Unit
1.	Colour	***		Gray	
2.	Texture		F.A.U.N (2007)	Loamy Sand	-
3.	Bulk Density		By Bulk density Apparatus	1.00	gm/cm3
1.	Water Holding Capacity		F.A.U.N (2007)	28.5	0/0
5.	pH		F.A.U.N (2007)	6.58	
5.	Electrical Conductivity	••	F.A.U.N (2007)	200.0	μs/cm
7.	Organic Carbon	**		0.55	%
8.	Organic Matter		Black & White Wet Digestion Method	0.79	%
9.	Available Nitrogen		Soil & Water Book by P.K Gupta	111.5	mg/kg
10.	Available Phosphorus	•••	Soil & Water Book by P.K Gupta	16.5	mg/kg
11.	Available Potassium	*	Soil & Water Book by P.K Gupta	381	mg/kg
12.	Exchangeable Calcium	Ca	Soil & Water Book by P.K Gupta	25.80	meq/100gm
13.	Exchangeable Magnesium	Mg	Soil & Water Book by P.K Gupta	1.38	meq/100gm
14	Exchangeable Sodium	Na	Soil & Water Book by P.K Gupta	2.20	meq/100gm
15.	Exchangeable Potassium	K	Soil & Water Book by P.K Gupta	1.40	meq/100gm
16	Total Exchangeable Bases		Soil & Water Book by P.K Gupta	31.50	meq/100gm
17	Manganese	Mn	USEPA 3052	0.40	mg/kg
18	Arsenic	As	USEPA 3052	2.0	mg/kg
19	Silica	SiO ₂	USEPA 3052	57.5	%
20.	Aluminum	Al ₂ O ₃	USEPA 3052	6.5	%
21.	Iron	Fe ₂ O ₃	USEPA 3052	5.00	%
22.	Calcium	CaO	USEPA 3052	8.90	%
23.	Magnesium	MgO	USEPA 3052	1.83	%
24.	Sodium	Na ₂ O	. USEPA 3052	0.270	%
25.	Potassium	K ₂ O	USEPA 3052	0.230	%
26.	Sulphate	504	USEPA 3052	0.69	%

Vijay Pandey

SENIOR EXECUTIVE

For Mahabal Ehring Eng. Politid.

Authorised Signator



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near J B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October,2014

Report no: SEPT001/2014-15

Sample described by customer: DRINKING WATER

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: DRINKING WATER

Received:19.09.2014 Registered: 19.09.2014

Marks on Sample: Location: Tap Water-Bagru Plateau near office.

Sample collected on: 18.09.2014 Quantity: 5 L X 2 No. PVC Can

Test Start/End Date: 19.09.2014/22.09.2014

Sample collected by: Mahabal EnviroEngineers Pvt Limited

S.No	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method Reference
1.	Colour	Hazen	< 1: 'h	5 Max	APHA 22nd Ed. 2012, 2120-B, 2-6
2.	Odour	-	Agreeable	Agreeable	IS 3025 (Part 5):1983, Reaffirmed 2006
3.	Taste		Agreeable	Agreeable	IS 3025 (Part 7):1984, Reaffirmed 2006
4.	Turbidity	NTU	0.5	1 Max	APHA 22nd Ed. 2012, 2130-B, 2-13
5.	рН		7.1	6.5-8.5	APHA 22nd Ed. 2012, 4500- H+-B, 4-92
6.	Free Chlorides(Residual)	mg/l	<0.05	0.2 min	APHA 22nd Ed. 2012, 4500-Cl G, 4-69
7	Total Dissolved Solids	mg/l	93	500 Max	IS 3025 (Part 16):1984 Reaffirmed 2006
8.	Monochloramines	mg/l	<0.05	•	APHA 22nd Ed. 2012, 4500-CIG, 4-69
9.	Dichloramines	mg/l	<0.05		APHA 22nd Ed. 2012, 4500-ClG, 4-69
10.	Total Hardness (as CaCO ₃)	mg/l	60	200 Max	APHA 22nd Ed. 2012, 2340-C, 2-44,45
11.	Alkalinity Total (as CaCO ₃)	mg/t	64	200 Max	IS 3025 (Part 23):1986 Reaffirmed 2009
12.	Chloride (as Cl)	mg/l	8.0	250 Max	APHA 22nd Ed. 2012, 4500- CI-B, 4-72
13.	Sulphate (as SO ₄)	mg/l	4.8	200 Max	APHA 22nd Ed. 2012, 4500- SO4-E, 4-190





Branch Office: At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

S.No	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method Reference
4.	Nitrate (as NO3)	mg/l	1.13	45 Max	APHA 22nd Ed. 2012, 4500- NO ₃ -E, 4-125
5.	Fluoride (as F)	mg/l	0.23	1 Max	APHA 22nd Ed. 2012, 4500-FB& D, 4- 84, 4-87
.6.	Boron (as B)	mg/l	0.18	0.5 Max	APHA 22nd Ed. 2012, 4500-BB, 4-25
7.	Calcium(as Ca)	mg/l	18.4	75 Max	APHA 22nd Ed. 2012, 3500- Ca-B, 3-67
18.	Magnesium (as Mg)	mg/l	3.4	30 Max	APHA 22nd Ed. 2012, 3500- Mg- B, 3- 84
19.	Ammonical Nitrogen/ Total Ammonia	mg/l	<0.1		APHA 22nd Ed. 2012, 4500 NH3-F, 4- 115
20.	Iron (as Fe)	mg/l	0.18	0.3 Max	APHA 22nd Ed. 2012, 3111-B,3-18
21.	Manganese (as Mn)	mg/l	N.D	0.1 Max	APHA 22nd Ed. 2012, 3111-B, 318
22.	Aluminium (as Al)	mg/l	0.09	0.03 Max	APHA 22nd Ed. 2012, 3500- Al-B, 3-6
200	Cadmium (as Cd)	mg/l	N.D	0.003 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
23.	Chromium Total (as Cr)	mg/l	N.D	0.05 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
24.	Copper (as Cu)	mg/l	N.D	0.05 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
25.	Lead (as Pb)	mg/l	N.D	0.01 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
27.	Zinc (as Zn)	mg/l	0.03	5 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
28.	Arsenic (as As)	mg/l	<0.01	0.01 Max.	APHA 22nd Ed. 2012, 3114-C,3-38
29.	Mercury (as Hg)	mg/l	N.D.	0.001 Max.	APHA 22nd Ed. 2012, 3112-B,3-23
30.	Selenium (as Se)	mg/l	N.D.	0.01 Max.	APHA 22nd Ed. 2012, 3114-C, 3-38
31.	Nickel (as Ni)	mg/l	< 0.06	0.02 Max.	APHA 22nd Ed. 2012, 3111 B,3-18
32.	Mineral Oil	mg/l	N.D.	0.5 Max.	IS 3025 (Part 39): 1991, Reaffirmed 2003, Ed. 2.1
33.	Cyanide (as CN)	mg/l	N.D.	0.05 Max.	APHA 22nd Ed. 2012, 4500- CN, C & E, 4-39 & 4-44
34.	Anionic detergents as	mg/l	<0.1	0.2 Max.	APHA 22nd Ed. 2012, 5540-C, 5-53
35.	Phenolic compounds (as CoHsOH)	mg/l	N.D	0.001 Max.	APHA 22nd Ed. 2012, 5530- B & C, 5
36.	Polynuclear aromatic hydrocarbons (PAH)	μg/L	N.D	0.0001 mg/L Max.	APHA 22nd Ed. 2012, 6440, 6-93
37.	Polychlorinated Biphenyls (PCBs)	μg/L	N.D	0.0005 mg/l Max.	USEPA Method 8082
38.	Sulphide (as S)	mg/l	N.D	÷	APHA 22nd Ed. 2012, 4500- S2-C 4 175 & F 4-178



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room, Near J B Sawant Bus Stop)
Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

S.No	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method Reference
ti arabi	ological Analysis				APHA 22nd Ed. 2012, 9221-B
	Total Colliforms	MPN/	<1.1	N.D	& C, 9-66, 9-69
	Total Comforms	100 mL			APHA 22nd Ed. 2012, 9221-
	E-Coli	MPN/	Absent	N.D	B, C & G, 9-66, 9-69 and 9-76
2.	E-Con	100 mL			B, C & G, 7 GG, 7 G S and
Postició	les Residues	1			US EPA 508-1995
3.	p,p DDT	μg/L	N.D	1	US EPA 508-1995
4.	o,p DDT	µg/L	N.D	1	US EPA 508-1995
5.	p,p DDE	μg/L	N.D	1	US EPA 508-1995
6.	o,p DDE	μg/L	N.D	1	US EPA 508-1995
7.	p,p DDD	μg/L	N.D	1	US EPA 508-1995
8.	o,p DDD	μg/L	N.D	1	US EPA 508-1995
9	y-HCH (Lindane)	μg/L	<0.01	2	US EPA 508-1995
10.	α-НСН	μg/L	<0.01	0.01	US EPA 508-1995
11.	в-нсн	µg/L	N.D	0.04	US EPA 508-1995
12	δ-HCH	μg/L	N.D	0.04	US EPA 508-1995
13.	Butachlor	μg/L	N.D	125	US EPA 508-1995
14.	Alachlor	µg/L	N.D	20	US EPA 532-2000
15.	Atrazine	μg/L	N.D	2	US EPA 508-1995
16.	α Endosulfan	μg/.L	N.D	0.4	US EPA 508-1995
17.	ß Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
18.	Endosulfan Sulphate	µg/L	N.D	3	US EPA 8141A-1994
19.	Ethion	μg/L	N.D	190	US EPA 8141A -1994
20.	Malathion	μg/L	N.D	0.3	US EPA 8141A -1994
21.	Methyl Parathion	µg/L	N.D		US EPA 8141A-1994
22.	Monocrotophos	µg/L	N.D	1	US EPA 8141A -1994
23.	Phorate	μg/L	N.D	2	US EPA 8141A -1994
24.	Chlorpyrifos	μg/L	N.D	30	US EPA 508-1995
25.	Aldrin	μg/L	N.D	0.03	US EPA 508-1995
26.	Dieldrin	µg/L	N.D	0.03	03 1171 003 1770

Conclusion: The Physical & Chemical Analysis report indicates that water is not contaminated.

Vijay Pandey

SENIOR EXECUTIVE

Authorised Signatory

Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near | B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

Date: 1st October,2014

Report no: SEPT001/2014-15

Sample described by customer: SURFACE WATER

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: SURFACE WATER Received:19.09.2014

Registered: 19.09.2014 Marks on Sample: Location: Bagru Colony

Sample collected on: 18.09.2014 Quantity: 5 L X 2 No. PVC Can

Test Start/End Date: 19.09.2014/22.09.2014

Sample collected by: Mahabal EnviroEngineers Pvt Limited

S.No	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method Reference
1.	Colour	Hazen	< 1	5 Max	APHA 22nd Ed. 2012, 2120-B, 2-6
2.	Odour		Agreeable	Agreeable	IS 3025 (Part 5):1983, Reaffirmed 2006
3.	Taste		Agreeable	Agreeable	IS 3025 (Part 7):1984. Reaffirmed 2006
4.	Turbidity	NTU	0.3	1 Max	APHA 22nd Ed. 2012, 2130-B, 2-13
5.	pH		6.9	6.5-8.5	APHA 22nd Ed. 2012, 4500- H+-B, 4-92
6.	Free Chlorides(Residual)	mg/l	<0.05	0.2 min	APHA 22nd Ed. 2012, 4500-Cl G, 4-69
7	Total Dissolved Solids	mg/l	100	500 Max	IS 3025 (Part 16):1984 Reaffirmed 2006
650	Monochloramines	mg/l	<0.05		APHA 22nd Ed. 2012, 4500-ClG, 4-69
8.	Dichloramines	mg/l	<0.05.		APHA 22nd Ed. 2012, 4500-ClG, 4-69
9.	Total Hardness (as CaCO ₃)	mg/l	52	200 Max	APHA 22nd Ed. 2012, 2340-C, 2-44,4
11.	Alkalinity Total (as CaCO ₃)	mg/l	59	200 Max	IS 3025 (Part 23):1986 Reaffirmed 2009
12.	Chloride (as Cl)	mg/l	7.8	250 Max	APHA 22nd Ed. 2012, 4500- Cl-B, 4-72
13.	Sulphate (as SO ₄)	mg/l	4.0	200 Max	APHA 22nd Ed. 2012, 4500- SO4-E, 4-190



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near J B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

September 2014

S.No	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method Reference
14.	Nitrate (as NO3)	mg/l	1.10	45 Max	APHA 22nd Ed. 2012, 4500- NO ₁ -E, 4-125
15.	Fluoride (as F)	mg/l	0.19	1 Max	APHA 22nd Ed. 2012, 4500-FB& D, 4-84, 4-87
16.	Boron (as B)	mg/l	0.15	0.5 Max	APHA 22nd Ed. 2012, 4500-BB, 4- 25
17.	Calcium(as Ca)	mg/l	16.5	75 Max	APHA 22nd Ed. 2012, 3500- Ca-B, 3-67
18.	Magnesium (as Mg)	mg/l	3.3	30 Max	APHA 22nd Ed. 2012, 3500- Mg- B, 3-84
19.	Ammonical Nitrogen/ Total Ammonia	mg/l	<0.1	•	APHA 22nd Ed. 2012, 4500 NH3-F, 4-115
20.	Iron (as Fe)	mg/l	0.11	0.3 Max	APHA 22nd Ed. 2012, 3111-B,3-18
21.	Manganese (as Mn)	mg/l	N.D	0.1 Max	APHA 22nd Ed. 2012, 3111-B, 318
22.	Aluminium (as Al)	mg/l	0.06	0.03 Max	APHA 22nd Ed. 2012, 3500- Al-B, 3- 61
0.0	Cadmium (as Cd)	mg/l	N.D	0.003 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
23.	Chromium Total (as Cr)	mg/i	N.D	0.05 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
24.	Copper (as Cu)	mg/l	N.D	0.05 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
25.	Lead (as Pb)	mg/l	N.D	0.01 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
26.	Zinc (as Zn)	mg/l	0.08	5 Max.	APHA 22nd Ed. 2012, 3111-B,3-18
1	Arsenic (as As)	mg/l	< 0.01	0.01 Max.	APHA 22nd Ed. 2012, 3114-C,3-38
28.	Mercury (as Hg)	mg/l	N.D.	0.001 Max.	APHA 22nd Ed. 2012, 3112-B,3-23
30.	Selenium (as Se)	mg/l	N.D.	0.01 Max.	APHA 22nd Ed. 2012, 3114-C, 3-38
31.	Nickel (as Ni)	mg/l	< 0.06	0.02 Max.	APHA 22nd Ed. 2012, 3111 B,3-18
32.	Mineral Oil	mg/l	N.D.	0.5 Max.	IS 3025 (Part 39): 1991, Reaffirmer 2003, Ed. 2.1
33.	Cyanide (as CN)	mg/l	N.D.	0.05 Max.	APHA 22nd Ed. 2012, 4500- CN, C & E, 4-39 & 4-44
34.	Anionic detergents as MBAS	mg/l	<0.1	0.2 Max.	APHA 22nd Ed. 2012, 5540-C, 5-53
35.	Phenolic compounds (as	mg/l	N.D	0.001 Max.	APHA 22nd Ed. 2012, 5530- B & C 5-47
36.	Polynuclear aromatic hydrocarbons (PAH)	μg/L	N.D	0.0001 mg/L Max.	APHA 22nd Ed. 2012, 6440, 6-93
37.	Polychlorinated Biphenyls (PCBs)	μg/L	N.D	0.0005 mg/l Max.	USEPA Method 8082 APHA 22nd Ed. 2012, 4500 – S2-C
38.	Sulphide (as S)	mg/l	N.D	-	175 & F 4-178



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near J B Sawant Bus Stop)
Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring report

September 2014

S.No	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method Reference
Microl	piological Analysis				
1.	Total Colliforms	MPN/ 100 mL	<1.1	N.D	APHA 22nd Ed 2012, 9221-B & C. 9-66, 9-69
2.	E-Coli	MPN/ 100 mL	Absent	N.D	APHA 22nd Ed. 2012, 9221- B, C & G, 9-66, 9-69 and 9-76
Pestic	ides Residues		,		1/C PD 4 500 1005
3.	p,p DDT	μg/L	N.D	1	US EPA 508-1995
4.	o,p DDT	µg/L	N.D	1	US EPA 508-1995
5.	p,p DDE	μg/L	N.D	1	US EPA 508-1995
6.	o,p DDE	μg/L	N.D	1	US EPA 508-1995
7.	p,p DDD	μg/L	N.D	1	US EPA 508-1995
8.	o,p DDD	μg/L	N.D	1	US EPA 508-1995
9.	y-HCH (Lindane)	μg/L	< 0.01	2	US EPA 508-1995
10.	α-НСН	μg/L	< 0.61	0.01	US EPA 508-1995
11.	в-нсн	μg/L	N.D	0.04	US EPA 508-1995
12	δ-HCH	μg/L	N.D	0.04	US EPA 508-1995
13.	Butachlor	μg/L	N.D	125	US EPA 508-1995
14.	Alachlor	μg/l.	N.D	20	US EPA 508-1995
15.	Atrazine	μg/L	N.D	2	US EPA 532-2000
16.	α Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
17.	ß Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
18.	Endosulfan Sulphate	µg/L	N.D	0.4	US EPA 508-1995
19.	Ethion	μg/L	N.D	3	US EPA 8141A-1994
20.	Malathion	µg/L	N.D	190	US EPA 8141A -1994
21.	Methyl Parathion	μg/L	N.D	0.3	US EPA 8141A -1994
22.	Monocrotophos	µg/L	N.D	1	US EPA 8141A-1994
23.	Phorate	μg/L	N.D	2	US EPA 8141A -1994
24.	Chlorpyrifos	μg/L	N.D	30	US EPA 8141A -1994
25.	Aldrin	μg/L	N.D	0.03	US EPA 508-1995
26.	Dieldrin	μg/L	N.D	0.03	US EPA 508-1995

Conclusion: The Physical & Chemical Analysis report indicates that water is not contaminated.

Vijay Pandey

SENIOR EXECUTIVE

For Mahabal Enviro Eng. Pvf. Ltd.

Authorised Signatory

Ranchi Lia



Branch Office:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring report

Date: 1st October,2014

Report no: SEPT001/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Received:19.09.2014 Registered: 19.09.2014

Marks on Sample: Location: Bagru Plateau-Bagru Colony near Office

Sample collected on: 17.09.2014

Test Start/End Date: 19.09.2014/21.09.2014

			T		
PARAMETERS		UNIT	LIMIT	METHOD	21/09/2014
Sulphur Dioxide	SO ₂	μg/m³	80	IS:5182 (Part-2):2001 (Reaff:2006)	11.50
Nitrogen Dioxide	NO ₂	μg/m³	80	IS:5182(Part-6):1975 (Reaff:2004)	15.20
Particulate Matter (size less than 10 μm)	PM ₁₀	μg/m³	100	IS:5182 (Part 23)	70.5
Particulate Matter (size less than 2.5 µm)	PM ₂ s	μg/m³	60	USEPA CFR(40) Appendix-L	40.2
Carbon Monoxide	СО	mg/m³	2	EPA 600/P-99/001F	0.15

Vijay Pandey SENIOR EXECUTIVE For Maha

Authorised Signatory



Branch Office:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

Date: 1st October, 2014

Report no: SEPT001/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Received: 19.09.2014 Registered: 19.09.2014

Marks on Sample: Location: Bagru Plateau- Hisri Pit Bagru Plateau

Sample collected on: 17.09.2014

Test Start/End Date: 19.09.2014/21.09.2014

LOCATION / IDENTIFICATION: Bagru Plateau- Hisri Pit Bagru Plateau

PARAMETERS		UNIT	LIMIT	METHOD	21/09/2014
Sulphur Dioxide	SO ₂	μg/m³	80	IS:5182 (Part-2):2001 (Reaff:2006)	10.2
Nitrogen Dioxide	NO _{2 z} -	μg/m³	80	IS:5182(Part-6):1975 (Reaff:2004)	8.0
Particulate Matter (size less than 10 μm)	PM ₁₀	μg/m³	100	IS:5182 (Part 23)	80.0
Particulate Matter (size less than 2.5 µm)	PM _{2.5}	μg/m³	60	USEPA CFR(40) Appendix-L	51.5
Carbon Monoxide	СО	mg/m³	2	EPA 600/P-99/001F	0.13

Vijay Pandey SENIOR EXECUTIVE For Mahabal Enviro Eng. Pvt. Ltd.

Authorised Signatory





Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

Date: 1st October,2014

0.5

Report no: SEPT001/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India Sample type: AMBIENT AIR QUALITY MONITORING

Received: 20.09.2014 Registered: 20.09.2014

Carbon Monoxide

Marks on Sample: Location: Bagru Plateau- Bhusar Mine Pit Bagru Plateau

Sample collected on: 18.09.2014

Test Start/End Date: 20.09.2014/22.09.2014

PARAMETERS		UNIT	LIMIT	метнор	22/09/2014
Sulphur Dioxide	SO ₂	μg/m³	80	IS:5182 (Part-2):2001 (Reaff:2006)	6.2
Nitrogen Dioxide	NO ₂	μg/m³	80	IS:5182(Part-6):1975 (Reaff:2004)	5.8
Particulate Matter (size less than 10 μm)	PM ₁₀	μg/m³	100	IS:5182 (Part 23)	70.1
Particulate Matter (size less than 2.5 μm)	PM ₂₅	μg/m³	60	USEPA CFR(40) Appendix-L	45.0

mg/m³

Vijay Pandey SENIOR EXECUTIVE For Mahabai Enviro Ling, Pvt, Ltd.

CO

Authorised Signatory



EPA 600/P-99/001F

Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near J B Sawant Bus Stop)
Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office: At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October, 2014

Report no: SEPT001/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India Sample type: AMBIENT AIR QUALITY MONITORING

Received: 21.09.2014 Registered: 21.09.2014

Marks on Sample: Location: Bagru Plateau- Kekrang Village Bagru Plateau

Sample collected on: 19.09.2014

Test Start/End Date: 21.09.2014/23.09.2014

LOCATION / IDENTIFICATION: Bagru Plateau- Kekrang Village Bagru Plateau

PARAMETERS		UNIT	LIMIT	METHOD	21/09/2014
Sulphur Dioxide	SO ₂	μg/m³	80	IS:5182 (Part-2):2001 (Reaff:2006)	6.8
Nitrogen Dioxide	NOz	μg/m³	80	IS:5182(Part-6):1975 (Reaff:2004)	9.0
Particulate Matter (size less than 10 μm)	PM10	μg/m³	100	IS:5182 (Part 23)	89.1
Particulate Matter (size less than 2.5 μm)	PM _{2.5}	μg/m³	60	USEPA CFR(40) Appendix-L	50.2
Carbon Monoxide	СО	mg/m³	2	EPA 600/P-99/001F	0.40

Vijay Pandey SENIOR EXECUTIVE

Authorised Signatory

OVITO F



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October,2014

Report no: SEPT001/2014-15

Sample Description: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise Level.
Sampling Method: Instrumental, Using Sound level Meter

Sampling Done by: Mahabal Enviro.

Test Start: 17.09.2014 End Date: 18.09.2014

Location / Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Month		-	Average of 24 continuous hours in Sep- 14		Average of 24 continuous hours in Sep- 14	
Bagru Plateau Bagru Colony	dB(A) L _{eq}	75	70.0	70	61.9	17/09/2014

Vijay Pandey SENIOR EXECUTIVE

For Mahabal Enviro Eng. Pvt. Ltd.

Authorised Signatory





Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

Date: 1st October,2014

Report no: SEPT001/2014-15

Sample described by customer: EFFLUENT

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India Sample Type: Effluent

Received:18.09.2014 Registered: 18.09.2014

Marks on Sample: Location: Maintenance Garage Bagru Mines

Sample collected on: 18.09.2014

Quantity: 4 litres

Test Start/End Date: 18.09.2014/19.09.2014

Samula collected by Mahahal Engiro Engineers But Limited

S.No	Analysis	Method	Result	Unit	Limits
1.	рН	APHA 22nd Ed. 2012, 4500-H+-B, 4-92	7.2		5.5-9.0
2.	Total Suspended Solids	APHA 22 nd EDN:2012- 2540	16.8	mg/l	100
3.	BOD @ 27°C	IS 3025 (Part 44): 1993, RA2003, Amd.1	13.5	mg/l	30
4.	Oil & Grease	IS 3025(Part 39): 1991, RA 2003, Ed.2.1	< 5.0	mg/l	10
5.	Total Dissolved Solids	APHA 22nd EDN 2012- 2540	19.8	mg/l	2100
6.	Aluminum(as AI)	APHA 22 nd EDN 2012- 3120B	1.3	mg/l	3
7.	Calcium (as Ca)	APHA 22 nd EDN 2012- 3120B	5.2	mg/l	75
8.	Iron (as Fe)	APHA 22 nd EDN 2012- 3120B - ···	1.1	mg/l	3
9.	Temperature		20	οС	shall not exceed 5°C above the receiving water temperature

For Mahabat Linving Eng. Pvt. Ltd.

Authorised Signatory



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near | B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com