

Registered Post

The Additional PCCF,
Ministry of Environment, Forests & Climate Change
Regional office (West Central Zone),
Ground Floor, East Wing,
"New Secretary Building"
Civil lines, Nagpur - 440001

26/05/2018

Subject:

Revised Compliance Status of Environment Clearance conditions

Dear Sir.

We have been granted Environment Clearance to our **Kasarsada Bauxite Mines** on 1st March 2007 vide clearance No J-11015/247/2005-IA-II (M).

The compliance for the 6 months duration (October 2017 to March 2018) against the conditions laid down in the Environment Clearance is attached herewith. In this regard, please be informed that, since 2nd October 2011, the mining activities of our above mine have been stopped for want of forest clearance.

Please be informed that, we have already submitted the above compliance status of Environment Clearance vide our letter dated 14th May 2018 which is please be ignored and consider this corrected compliance.

Hope, you will please find the above in order.

Thanking you,

Yours very truly,

Mainak Chakraborty Vice President-Mines

Encl. A/a
Copy to:

The Chief Conservator of Forests (Central)
 Ministry of Environment & Forests
 Regional office, <u>BHOPAL</u>

The Member Secretary,
 Central Pollution Control Board,
 Parivesh Bhavan, East Arjun Nagar,
 DELHI - 110032

The Regional Officer
 Maharashtra Pollution Control Board
 Udyog Bhawan, KOLHAPUR – 416 003

पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय Ministry of Environment Fores & Chimele Change क्षेत्रीय कार्यालय (१८) है जिस्स क्ष्म स्ट्रिक्टिक Office (१८) व्याव Zones मून्या सचिवस्थ १६०० वर्ष Secretage (१८००) रिप्तित लाईपर्य असी Lines समपुर (Naggintage 001

Hindalco Industries Limited

Durgmanwadi Mines: PO Radhanagari - 416 212, Dist. Kolhapur, Maharashtra, T: +91 02321 202072, 202178, 133, Kolhapur Office: T:+91 0231 2661458, 2666621, 2021461, 2021462

COMPLIANCE TO ENVIRONMENT CLEARANACE CONDITIONS (Kasarsada Bauxite Mines Environment clearance No J-11015/247/2005-IA-II (M) Dt. 01/03/2007)

S.NO	CONDITIONS:	PRESENT COMPLIANCE STATUS
	A. SPECIFIC CONDITIONS	
1	Top soil shall be stacked properly with proper slope and with adequate safeguards and shall be backfilled for reclamation and rehabilitation of mined out area.	The top soil stacked during mine development is rehandled and used for mine restoration. There is no top soil on the mine plateau. The Mine is not in operation since Oct 2011 post expiry of forest clearance
2	Overburden shall be stacked at earmarked dump site(s) only and shall not be active for long period. The maximum height of dump shall not exceed 30m; each stage shall preferably be 10m and over all slope of the dump shall not exceed 28 degree. The mine pit area shall be reclaimed by back filling by back filling O.B in a phased manner. The O.B dump shall be scientifically vegetated with suitable native species to prevent erosion and surface run off.	Overburden generated during development stage has been back filled into the mind out pits for reclamation. The Mine is not in operation since Oct 2011 post expiry of forest clearance.
3	Garland drains shall be constructed to arrest silt and sediment flows from soil, and mineral dumps. The water so collected shall be utilized for watering the mine area, roads, green belt development etc. The drains shall be regularly desilted particularly after monsoon and maintained properly. Garland drain (size, gradient and length) shall be constructed for both mine pit and for waste dump.	The drains have been developed to channelise the run-off water to silt check dams. The Mine is not in operation since Oct 2011 post expiry of forest clearance.
4	Drilling and blasting shall be using extractors/wet drilling.	The Mine is not in operation since Oct 2011 post expiry of forest clearance.
5	Plantation shall be raised in an area of 92.6 ha including green belt of adequate width by planting the native species around the ML area, roads, OB dump sites etc. in consultation with local DFO/Agriculture Department. The density of the trees shall be around 2000 plants per ha.	Scientific plantation activities have been carried out with the help of reputed forestry experts & local forest department on the mined out areas. The Mine is not in operation since Oct 2011 post expiry of forest clearance

6	The project authority shall implement suitable conservation measures to augment ground water resources in the area in consultation with the Regional Director, central Ground Water Board.	Water harvesting ponds are developed in the mined out areas. The Mine is not in operation since Oct 2011 post expiry of forest clearance
7	Regular monitoring of ground water level and quality shall be carried out by establishing a network of existing wells and constructing new piezomometers during the mining operation.	The ground water quality was monitored on quarterly basis during the mining operations. The mining carried out to a depth of 7 to 10 mts from the surface. There is no interaction with the ground water and hence there is no disturbance to the ground water table. The Mine is not in operation since Oct 2011 post expiry of forest clearance
8	Prior permission from the competent authority shall be obtained for drawal of ground water, if any.	The Mine is not in operation since Oct 2011 post expiry of forest clearance
9	Vehicular emission shall be kept under control and regularly monitored; Measures shall be taken for maintenance of vehicle used in mining operations and in transportation of minerals. The vehicle shall be covered with tarpaulin and shall not be overloaded	The Mine is not in operation since Oct 2011 post expiry of forest clearance.
10	A Final Mine Closure plan, along with the details of the Corpus fund, shall be submitted to the ministry of Environment and Forests 5 years in advance of final mine closure in advance.	The progressive mine closure plan is approved by IBM .The final closure plan will be submitted as per the prescribed time.
11	The Company shall limit production to 0.25 million TPA of bauxite and shall not operate with 0.45 million TPA till the IBM has granted approval.	Noted and agreed. The Mine is not in operation since Oct 2011 post expiry of forest clearance
	B. GENERAL CONDITIONS	
1	No change in mining technology and scope of working shall be made without prior approval of the Ministry of Environment & Forests.	_
2	No change in the calendar plan including excavation, quantum of minerals bauxite and waste shall be made.	
3	Conservation measure for protection of flora and fauna in the core & buffer zone shall be drawn up in consultation with the local forest and wildlife department.	plantation was carried out scientifically. The

4	Four ambient air quality-monitoring stations shall be established in the core zone as well as in the buffer zone for RPM,SPM,SO2,Nox,	Ambient air quality monitoring station was established in the core zone as well as buffer zone as per requirement. The Mine is not in operation since Oct 2011 post expiry of forest clearance
5	Data on the ambient air quality (RPM, SPM, SO2, and Nox) should be regularly submitted to the Ministry including its Regional offices located at Bangalore and State Pollution Control Board / Central Pollution Control Board once in six months.	The air quality monitoring was carried out periodically while the mining activity was ongoing. The Mine is not in operation since Oct 2011 post expiry of forest clearance
6	Fugitive dust emission from all the sources shall be controlled regularly water spraying arrangement on haul roads, loading and unloading and at transfer points shall be provided and properly maintained.	Noted and agreed. The Mine is not in operation since Oct 2011 post expiry of forest clearance
7	Measures shall be taken for control of noise level below 85 dBA in the work environment. Workers engaged in operations of HEMM etc shall be provided with ear plugs/muffs.	The Mine is not in operation since Oct 2011 post expiry of forest clearance
8	Industrial waste water (workshop and waste water from the mine) should be properly collected treated so as to conform to the standards prescribed under GSR 422 (E) dated 19th May 1993 and 31st December, 1993 or as amended from time to time.	The Mine is not in operation since Oct 2011 post expiry of forest clearance
9	Personnel working in dusty areas shall wear protective respiratory devices and they shall also be provided with adequate training and information on safety and health aspects.	The Mine is not in operation since Oct 2011 post expiry of forest clearance
10	Occupational health surveillance program of the workers shall be undertaken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed	
11	A separate environmental management cell with suitable qualified personnel shall be setup under the control of a Senior Executive, who will report directly to the Head of the organization.	The Mine is not in operation since Oct 2011 post expiry of forest clearance.
12	The funds earmarked for Environment protection shall be kept in separate account and should not be diverted for any other purpose.	- · · · · · · · · · · · · · · · · · · ·
13	The funds earmarked for environmental protection measures shall be kept in separate account and should be diverted for other purposes.	•

14	The project authority shall inform to the regional office located at Bhopal regarding date of financial closures and final approval of the project by the concerned authorities and the date of start of land development.	The Mine is not in operation since Oct 2011 post expiry of forest clearance Provision related to financial closure not applicable.
15	The project authorities should extend full cooperation to the officer(s) of the Regional office by furnishing the requisite data/information / monitoring reports.	
16	A copy of clearance letter will be marked to concern Panchayat.	Complied
17	The project authority should advertise at least in two local news papers within 7 days of the issue of the clearance letter.	Complied