

Ref No: HIL/LHD/GM (Geo)/MoEF/+5/ Date: 28.11.2017

To,
The Additional Principal Chief Conservator of Forest (C)
Ministry of Environment, Forests and Climate Changes
Regional Office (ECZ), Ranchi-834002.

Sub: Compliance Report of EC conditions for Pakhar Bauxite Mining (115.13 Ha) project of M/s Hindalco Industries Limited located in Dist- Lohardaga, Jharkhand for the period Apr'17 to Sept'17.

Ref: Environmental Clearance letter no J-11015/406/2007 -IA II (M) dated 27th Nov 2012

Sir.

With reference to the above, we are submitting herewith the Compliance status report of EC conditions for Pakhar Bauxite Mining (115.13 Ha) project of M/s Hindalco located in Lohardaga, Jharkhand for the period **Apr'17 to Sept'17**.

Hope you will find the same in order.

Thanking You

Yours Sincerely FOR HINDALCO INDUSTRIES LIMITED

> Basudev Gangopadhyay GM(Geology)

Enclosure: - As Above

Copy to: Member Secretary, JSPCB, Ranchi

RO, JSPCB, Ranchi

CPCB, Zonal Office, Kolkata

<mef@ori.nic.in>, <mef@nic.in>, <mef.or@nic.in>, mef.or@nic.in

Compliance of conditions laid down in Environmental Clearance

PAKHAR BAUXITE MINES

Period; Apr'17- Sept'17

<u>Area (115.13 Ha)</u>
MoEF Environment Clearance ref: No. J-11015/406/2007-IA.II (M) dated 27th Nov. 2012

Sl No	Specific Conditions	Compliance Status		
i)	The project proponent shall obtain Consent to Operate from the Jharkhand State Pollution Control Board and effectively implement all the conditions stipulated therein.	Consent to operate is in place and conditions are being complied. The Consent operate is valid upto 30 June 2020.		
(ii)	All the conditions stipulated by the Jharkhand State Pollution Control Board in their NOC shall be effectively implemented.	submitted at MoEF, Delhi on due date: (i) Standard operating process/procedure to bring interprocess/procedure to bring interprocess any infringements/ deviation violation of environmental or forest norms/conditions, (ii) Hierarchical system or Administrative order of the company to deal with environmental issues and ensuring compliance EC conditions and (iii)		
(iii)	Corporate Environment Policy and hierarchical system for ensuring adherence to the policy and compliance with environmental regulation in accordance with the office memorandum dated 26.4.2011 issued by MoEF should be put in place.			
(iv)	The Company shall submit within 3 month their policy towards Corporate Environment Responsibility which should inter-alia address (i) Standard operating process/procedure to bring Into focus any infringements/ deviation/ violation of environmental or forest norms/conditions. (ii) Hierarchical system or Administrative order of the company to deal with environmental issues and ensuring compliance EC conditions and (iii) System of reporting of non compliance/violation environmental norms to the Board of Directors of the Company and/or stakeholders or shareholders.			
(v)	The environmental clearance is subject to approval of the State Land use Department Government of Jharkhand for diversion of	, State Gove area as		

	agricultural land for nonagricultural use	approval on recommendation of District Collector who is the competent authority to give permission for using the agricultural land for non- agricultural purpose.
(vi)	The critical habitat in the area including dens of python, fox and hear should be protected by adopting appropriate wildlife conservation measures.	Appropriate wildlife conservation measures are being taken to protect critical habitat in the area. The measures includes: 1. Permanent pillars are established within the mine lease area at 7.5m from the forest boundary. 2. Maintenance of the forest road 3. Ensured necessary air and noise pollution control measures. 4. Daily water sprinkling is being carried out on the forest road 5. Transportation is done only in day time.
(vii)	The mining operations shall be restricted to above ground water table and it should not intersect the groundwater table. In case of working below the ground water table, prior approval of the Ministry of Environment and Forests and the Central Ground Water Authority shall be obtained, for which a detailed hydro-geological study shall be carried out.	Shallow depth mining is being done in the Pakhar Bauxite Mines & the ground water table is much below the working depth. Hence, ground water will not be intersected due to mining activities.
(viii)	The project proponent shall ensure that no natural watercourse and/or water resources shall be obstructed due to any mining operations. Adequate measures shall be taken for conservation and protection of the 1st and 2 nd order streams, if any emanating or passing through the mine lease during the course of mining operation.	It is being ensured. No natural water course—is obstructed due to mining activities.
(ix)	The top soil shall temporarily be stored at earmarked site(s) only and it should not be kept unutilized for long. The topsoil shall be used for land reclamation and plantation.	Sequential backfilling and reclamation of the mined out area are being implemented during mining operation. Top soil which is temporarily stored separately

spread over the back fitted area in the process of reclamation (data of back filling is enclosed Annexure 4)

This will be done progressively with the progress of mining activity.

(x)

The over burden (OB) generated during the mining operation shall be temporarily stacked at earmarked dump site(s) only for the Backfilling shall purpose of backfilling. commence from the third year onwards and thereafter the waste generated shall be concurrently backfilled in the mined out area. There shall be no external OB dump. An area of 16.39ha of the worked out pit shall be backfilled and reclaimed by plantation during the plan period. Monitoring and management of rehabilitated areas shall continue until the self-sustaining. becomes vegetation Compliance status should be submitted to the Ministry of Environment & Forests and its Regional Office, Bhubneshwar on six monthly basis.

The over burden (OB) generated during the mining operation temporarily stacked at earmarked dump site(s) only for the purpose of backfilling. Backfilled area will be reclaimed by plantation. Monitoring and management of rehabilitated areas will continue until the vegetation becomes self-sustaining. Compliance status is being submitted to the Ministry of Environment & Forests regularly on six monthly basis.

(xi)

Catch drains and siltation ponds of appropriate size shall be constructed for the working pit, temporary soil. OB and mineral dumps to arrest flow of silt and sediment directly into the agricultural fields, the Chaupat Nadi, the Kisko Nadi, the Shankh Nadi, Kisko Nallah, the Narachiya Nal lah and other water bodies, The water so collected should be utilized for watering the mine area, roads, green belt development etc. The drains should be regularly desilted particularly after the monsoon and maintained properly.

Garland drains, settling tanks and check dams of appropriate size, gradient and length shall be constructed both around the mine pit and temporary over burden dumps to prevent run off of water and flow of sediments directly into the agricultural fields, the Chaupat Nadi, the Kisko Nadi, the Shankh Nadi, Kisko Nallah, the Narachiya Nallah and other water bodies and sump capacity should be designed

No run-off is generated from mining activities. However to collect & manage rain water during monsoon, part of mined out area is used as settling tank for the runoff. Rain water stored is being used for watering the mine area, roads, green belt development and sprinkling as necessary.

Catch drains, Garland drains, settling tanks and check dams of appropriate size have been constructed both around the mine pit and temporary over burden dumps to prevent run off of water and flow of sediments directly into the agricultural field and rivers.

	keeping 50% safety margin over and above peak sudden rainfall (based on 50 years data) and maximum discharge in the area adjoining the mine site. Sump capacity should also provide adequate retention period to allow proper settling of silt material. Sedimentation pits should be constanted at the corners of the garland drains and desilted at regular intervals:	
xii)	Dimension of the retaining wall at the toe of the temporary OB dumps and the OB benches within the mine to check run-off and siltation should be based on the rain fall data.	The dimensions of the retaining wall of OB dumps are based on the average rainfull.
(xiii)	The void left untilled in an area of 4.5ha shall be converted into water body. The higher benches of excayated void/mining pit shall be terraced and plantation done to stabilize the slopes. The slope of higher benches shall be made gentler for easy accessibility by local people to use the water body. Peripheral fencing shall be carried out all along the excavated area.	
(xiv)	Plantation shall be raised in an area of 24.09ha including a 7.5m wide green belt in the safety zone around the mining lease by planting the native species around reclaimed area, mine benches, around water body, along the roads etc. in consultation with the local DFO/Agriculture Department. The density of the trees should be around 1500 plants per hectare. Greenbelt shall be developed a along the mine lease area in a phased manner and shall be completed within first five years.	consultation with forest department is being carried out within the safety zone and mined out/reclaimed pits. Total 5400 nos of saplings have been planted during 2017-18 within this mine. Green belt development programme is in progress with
(xv)	Effective safeguard measures such as regular water sprinkling shall be carried out in critic areas prone to air pollution and having his levels of particulate matter such as around crushing and screening plant, loading at unloading point and transfer points. Extensi water sprinkling shall be carried out on ha roads. It should be ensured that the Ambie Air Quality parameters conform to the normal prescribed by the Central Pollution Contact Board in this regard.	Mobile water tankers have been provided for sprinkling of water or haul roads and are generally being engaged at the places where active mining is in progress to contain fugitive dust. AAQ parameters are monitored from time to time.

(xvi)	contoble conservation measures to augment	Rain water harvesting pond is constructed within Mine and water is being harvested in mined out pit.
(xvii)	Regular monitoring of ground water level and quality shall be carried out in and around the mine lease by establishing a network of existing wells and installing new piezometers during the operation. The periodic monitoring [(at least four times in a year- pre-monsoon (April-May). monsoon (August), post-monsoon (November) and winter (January); once in each season)] shall be carried out in consultation with the State Ground Water Board/Central Ground Water Authority and the data thus collected may be sent regularly to the Ministry of Environment and Forests and its Regional Office Bhubneswar, the Central Ground Water Authority and the Regional Director, Central Ground Water Board. If at any stage, it is observed that the groundwater table is getting depleted due to the mining activity, necessary corrective measures shall be carried out.	It is being done. Report enclosed.
(xviii)	Appropriate mitigative measures should be taken to prevent pollution of the Chaupat Nadi, the Kisko Nadi and the Shankh Nadi in consultation with the State Pollution Control Board.	discharge of mine water that any drainage network. Monitoring is
(xix)	The project proponent shall obtain necessary prior permission of the competent authorities for drawl of requisite quantity of ground water required for the project.	Mining lease deed, we have the
(xx)	The project proponent shall practice suitable rainwater harvesting measures on long term	Rain water is being harvested in mined out pit.

	basis and work out a detailed scheme for rainwater harvesting in consultation with the Central Groundwater Authority and submit a copy of the same to the Ministry of Environment and Ferests and its Regional Office, Bhubneswan	
(XXI)	Vehicular emissions shall be kept under control and regularly monitored. Measures shall be taken for maintenance of vehicles used in mining operations and in transportation of mineral. The mineral transportation shall be carried out through the covered trucks only and the vehicles carrying the mineral shall not be overloaded.	Regular maintenance of vehicles are undertaken to minimize vehicular emission. All the transporters have been instructed to obtain PUC for their vehicles from the competent authority and submit to the concerned officer for verification. Bauxite are transported through tarpaulin cover trucks.
(xxii)	Drills shall either be operated with the dust extractors or equipped with water injection system.	Wet drilling is done in the drill holes intermittently for dust suppression by pumping water
(xiii)	Blasting operation should be carried out only during the daytime. Controlled blasting should be practiced. The mitigative measures for control of ground vibrations and to arrest fly rocks and boulders should be implemented.	Blasting time is fixed during Lunch Time i.e. 12.00 Noon -1.00 PM. Controlled blasting method is in practice. Ground vibration study has been conducted by IIT, Kharagpur. All efforts are being taken to mitigate impact of blasting.
(xxiv)	Mineral handling area shall be provided with adequate number of high efficiency dust extraction system. Loading and unloading areas including all the transfer points should also have efficient dust control arrangements. These should be properly maintained and operated.	unloading and mineral handling areas as well as at all the transfer points by water sprinkler/ mobile
(XXV)	Sewage treatment plant shall be installed for the colony. ETP shall also be provided for the workshop and wastewater generated during the mining operation.	from nime, nence bit is

		Tank Soak Pit and treated in Sewage Freatment Plant
(XXVI)	Pre-planation medical examination and periodical medical examination of the workers engaged in the project shall be carried out and records maintained For the purpose, schedule of health examination of the workers should be drawn and followed accordingly.	System is already in place
(xxvii)	It shall be ensured that the fluoride level in the drinking water to be used by the workers in the project as well as to be provided to the public, if any, should meet the prescribed norms in this regard.	There is no issue found in respect of fluoride in and around the mines. Water monitoring report is annexed as annexure-1 with this report.
(xxviii)	The project proponent shall take all precautionary measures during mining operation for conservation and protection of endangered fauna namely python, leaf monkey (Presbyits phayrei) etc. spotted in the study area. The critical habitats in the area including dens of python, fox and bear should be protected by adopting appropriate wildlife conservation measures and the conservation plan prepared specific to this project in consultation with the state Forest and Wildlife Department should effectively address the same. All the safeguard measures brought out in the Wildlife Conservation Plan prepared specific to this project site shall be effectively implemented in consultation with the State Forest and Wildlife Department A copy of approved wildlife conservation plan shall be submitted to the Ministry and its Regional. Office, Bhubaneswar within 3 months.	All precautionary measures during mining operation for conservation and protection of endangered fauna are being taken care in consultation with forest Dept. viz. 1. Permanent pillars are established within the mine lease area at 7.5m from the forest boundary. 2. Maintenance of the forest road. 3. Ensured necessary air and noise pollution control measures. 4. Daily water sprinkling is being carried out on the forest road. 5. Transportation is being done only in day time.
(xxix)	Provision shall he made for the housing of construction labour within the site with all necessary infrastructure and facilities such as fuel for cooking, mobile toilets, mobile sTp,	Necessary infrastructure and

	safe drinking water, medical "casta care," ereche etc. The housing may be in the form of temporary structures to be removed after the completion of the project.	
(888)	Particulate matter with size less than 10 micron he PM10) and NOx in the ambient air within the impact zone, peak particle velocity at 300m distance or within the nearest habitation, whichever is element shall be monitored periodically. Further, quality of discharged water shall also be monitored [(TDS, DO, PH and Total Suspended Solids (TSS)]. The monitored data shall be uploaded on the website of the company as well as displayed on a display board at the project site at a suitable location near the main gate of the Company in public domain. The Circular No. J-20012/1/2005-IA II(M) dated 27.05.2009 issued by Ministry of Environment and Forests, which is available on the website of the Ministry www.envfor.nic.in shall also be referred in this regard for its compliance.	Complied Monitoring Reports is enclosed as Annexure-1. Presently, there is no discharge of water from the mines.
(xxxi)	A Final Mine Closure Plan along with details of Corpus Fund shall be submitted to the Ministry of Environment & Forests 5 years in advance of final mine closure for approval.	has been duly approved of

No	General Conditions	ompliance Status
ri)	No change in mining technology and scope of working should be made without of approval of the Ministry of Environment & Forests.	Being adhered to
(1)	No change in the calendar plan inclusions excavation, quantum of mineral ! axite = 1 waste should be made	Excavation of Over Burden and Bauxite is being done as per the approved calendar plan. Details of excavation, quantum of mineral, OB, etc. have been furnished for the financial year 2017-18 as Annexure-4.
(iii)	At least four ambient air quality monitoring stations should be established in the core zone as well as in the buffer zone for RSPM (Particulate matter with size less than 10micron i.e., P1410) and NOx monitoring. Location of the stations should be decided based on the meteorological data, topographical features and environmentally and ecologically sensitive targets and frequency of monitoring should be undertaken in consultation with the State Pollution Control Board.	Complied
(iv)	Data on ambient air quality RSPM(Particulate matter with size less than 10micron i.e., PM10) and N0x) should be regularly submitted to the Ministry including its Regional office located at Bhubaneswar and the State Pollution Control Board / Central Pollution Control Board once in six months.	Complied
(v)	Fugitive dust emissions from all the sources should be controlled regularly. Water spraying arrangement on haul roads, loading and unloading and at transfer points should be provided and properly maintained.	haul roads and are generally being
(yi)	Measures should be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operations of HEMM, etc. should be provided with ea- plugs / muffs.	the work zone area Worker

viii	Industrial waste water (workshop and water from the nune) should be properly collected, treated so as to conform to the standards prescribed under GSR 122 (1) dated 19th May, 1993 and 31st Decemb 1993 or as amended from time to time. On and grease trap should be installed befor discharge of workshop effluents.	There is no effluent discharge from stine. Workshop has an Oil Catchment Pit to trap oil and grease it is being ensured to make it operational and effective as and when required.
4 + + + + + +	Personnel working in dusty areas should wear protective respiratory devices. I they should also be provided with Lightate training and information on safety and habit aspects. Occupational health surveillance program of the workers should be unaccooken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed	Protective Equipment (PPE) by the individuals is being ensured. All the mine workers are being regularly and periodically sent to our own hospital for health checkup for any contraction of diseases due to exposure in dusty and noisy areas. Training on safety, health and environmental aspects of mining is being regularly imparted through VT centre and also through various other training programmes conducted by the State Government, recognized agencies, etc.
(ix)	A separate environmental management cell with suitable qualified personnel should be set-up under the control of a Senior Executive, who will report directly to the Head of the Organization.	Separate Environmental Management Cell (EMC) has been constituted and is functioning effectively. Copy enclosed as Annexure-3.
(x)	The funds carmarked for environmental protection measures should be kept in separate account and should not be diverted for other purpose. Year wise expenditure should be reported to the Ministry and its Regional Office located at Bhubaneswar.	Statement of budgetary provision and actual expenses for environmental protection measure is enclosed as Annexure-2. It is once again reiterated that the funds so ear marked shall not be diverted for any other purposes other than it is committed at the beginning of the financial year.
(xi)	The project authorities should inform to the Regional Office located at Bhubaneswar regarding date of financial closures and final approval of the project by the concerned	The provision related to financia closure is not applicable as this is an operating mine.

	authorities and the date of start of land development work	
5.8157	The Regional Office of this Ministry located at Bhuhaneswar shall monitor compliance of the stipulated conditions. The project authorities should extend full cooperation to the officer (s) of the Regional Office by furnishing the requisite data: information is monitoring reports.	Agreed
{Xinx	The project proponent shall submit six monthly reports on the status of compliance of the stipulated environmental clear conditions including results of monocus data (both in hard copies as well as by mail) to the Ministry of Environment and Forests, its Regional Office Bhubneswar the respective Zonal Office of Central Pollution Control Board and the State Pollution Control Board. The proponent shall upload the status of compliance of environmental clearance conditional including results of monitored data or website and shall update the same periodically. It shall simultaneously be sent to the Regional Office of the Ministry of Environment and Forests, Bhubneswar, the respective Zonal Officer of Central Pollution Control Board and the State Pollution Control Board.	i.eg complied
(xiv)	A copy of the clearance letter shall be sent by the proponent to concerned Panchayat, Zila Parisad/ Municipal Corporation, Urban Local Body and the Local NGO, if any, from whom suggestions/ representations, if any, were received while processing the proposal. The clearance letter shall also be put on the website of the Company by the proponent.	Duly submitted.
(xv)	The State Pollution Control Board should display a copy of the clearance letter at the Regional office, District Industry Centre and the Collector's office/ Tehsildar's Office for 30 days.	Displayed.
(xvi)	The environmental statement for each financial year ending 31st March in Form-V as is mandated to be submitted by the project proponent to the concerned State Pollution	Duly submitted.

Control Board as prescribed under the Environment (Protection) Rules, 1986, as amended subsequently, shall also be put on the website of the company along with the datus of compliance of environmental learance conditions and shall also be seat a me respective Regional Office of the Ministry of Environment and Forests combineswar by e-mail.

ii) the project authorities should advertise seast in two local newspapers of the District

State in which the project is located and widely circulated, one of which shall be ... the vernacular language of the locative concerned, within 7 days of the issue of the clearance letter informing that the projechas been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution Control Board and also at web site of the Ministry Environment and Forests at littp://envfonnic.in and a copy of the same should be forwarded to the Regional Office of this Ministry located at Bhubaneswar.

Computed in due time.

-Hornexuri - I



Eco Ventures Pvt. Ltd.

Regd Office 2/37 Sarvapriya Vihar Near IIT Gate, New Celbi 110016.

Corporate Office, 7/6 Bhaveshwar Bhaven, Opp Porthugese Church, Near Diridayar Upadhyay Garden Gokhale Road (North), Dadar (West), Mumbai 400 028, 191, 491 072 2437/1520 15612.

E. ecoventures mumbai@gmail.com /ecoventures@eco-ventures.i/

Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

PAKHAR PLATEAU- ENVIRONMENTAL MONITORING REPORT

JULY TO SEPTEMBER 2017

For Mahabal Enviro Engineers Pvt. Ltd. For Mahabal Enviro Eng. Pvt. Ltd.

Vijay PanAuthorised Signatory

SENIOR EXECUTIVE

Sherica Paris Property Propert



Branch Office: At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009 Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail mahabalranchi@smail.com

Hindalco Industries:

Environmental Monitoring Report

CONTENT

	LOCATION	
	AMBIENT AIR QUALITY	
1	Pakhar Plateau-Near Weigh Bridge	
2	Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4	
3	Pakhar Plateau- Near Office	
4	Pakhar Plateau- Pakhar Quarry (109 507 ha Near Shed)	
5	Pakhar Plateau Pakhar Mines(109.507 ha. Yatri Shed)	
6	Pakhar Plateau - Pakhar Loading Area (109.507 ha.)	
	SURFACE WATER	
1	Pakhar Plateau	





Branch Office:

At Booty, Near PHED Colony, Behind Pump House Fill - RMCC, District - Ranchi 834005, Mobile No. +91 9431.102.102 / +91 9955.358.262 E-mail muhabalranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report | July - SEPTEMBER 2017

Report no: MEEPL/OCT0129/2017-18

Date: 24: October 2012

Sample described by customer: AMBIENT AIR QUALITY MONITORING Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: Iharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau-Near Weigh Bridge

Sample collected on: 18.09.2017

SI. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM10	μg/m³	100	63.9
02;	Particulate Matter (size less than 2.5 µm) PM25	µg/m³	60	30.7
03.	Sulphur Dioxide (SO ₂)	μg/m ³	80	4.7
04.	Nitrogen Dioxide (NO ₂)	µg/m³	80	8.4
05	Ammonia (NH ₃)	μg/m ³	400	14.3
06.	Ozone (O ₃)	μg/m³	180	13.9
07.	Carbon Monoxide (CO)	mg/m³	02	0.40
08.	Lead (Pb)	μg/m ³	1.0	
09.	Nickel (Ni)	ng/m ³	20	0.03
10.	Arsenic (As)	The second secon		3.5
11.	Benzene (C ₆ H ₆)	ng/m³	06	2.42
12.	Benzo (a) Pyrene	μg/m³	05	2.10
	Same 1st Chance	µg/m³	01	0.40

For Mahabal Enviro Engineers Pvt. Ltd.

For Mahabal Enviro Eng. Pvt. Ltd.

Villay PandAuthorised Signatory





Branch Office

At Booty, Near PHED Colony, Behind Pump House, F. -- RMCC, District - Ranchi 834009, Mobile No: +91 9431,102.102 / +91 9955.358 262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries:

... Environmental Monitoring Report

Report no: MEEPL/OCT0130/2017-18

Date: 24th October, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address. Lohardaga Postal Code: 835203 State: Thankhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- Pakhar (115.12 ha.) Quarry No. 4

Sample collected on: 18.09 2017


SI. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	µg/m³	100	68.6
02.	Particulate Matter (size less than 2.5 µm) PM25	μg/m³	60	35.1
03.	Sulphur Dioxide (SO ₂)	μg/m³	80	5,3
04	Nitrogen Dioxide (NO ₂)	µg/m³	80	8.0
05.	Ammonia (NH ₃)	μg/m ³	400	12.6
06.	Ozone (O ₃)	μg/m³	180	13.0
07.	Carbon Monoxide (CO)	mg/m³	02	0.38
08.	Lead (Pb)	μg/m [*]	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	3.1
10.	Arsenic (As)	ng/m³	06	2.3
11.	Benzene (C ₆ H ₆)	μg/m ³	05	2.1
12.	Benzo (a) Pyrene	μg/m³	01	0.47

For Mahabal Enviro Engineers Pvt. Ltd.

For Mahabal Enviro Eng. Pvt. Ltd.

Vitas ParAuthorised Signatory





Branch Office

At Booty, Near PHED Colony, Behind Pump House, P.J. – RMCC, District – Ranch, 834009, Mobile No: +91 9431,102,102 / +91 9955 358 262 E-mail:mahabalranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

Report no: MEEPL/OCT0131/2017-12

Date: 24th October, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address Lohardaga Postal Code: B35203

State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau-Near Office

Sample collected on: 18.09.2017

CONTRACTOR OF	LOCATION / IDENTIFICATION: Pakhar	r rateau-ry	ear Oince	
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 µm) PM ₁₀	μg/m ³	100	61.5
02.	Particulate Matter (size less than 2.5 µm) PM25	μg/m³	60	30.2
03.	Sulphur Dioxide (SO ₂)	µg/m³	80	4.9
04.	Nitrogen Dioxide (NO ₂)	µg/m³	80	8.3
05.	Ammonia (NH ₃)	μg/m ³	400	770777
06.	Ozone (O3)	μg/m ³		12.4
07.	Carbon Monoxide (CO)	mg/m ³	180	13.8
08.	Lead (Pb)	Production of the second	02	0.40
09.	Nickel (Ni)	μg/m³	1.0	0.02
10.	Arsenic (As)	ng/m³	20	3.2
11	Benzene (C ₆ H ₆)	ng/m³	06	2.2
12.		μg/m³	05	2.1
12.	Benzo (a) Pyrene	μg/m³	01	0.32

For Mahabal Enviro Engineers Pvt. Ltd.

Authorised Signatory Vitas Pandes



At Booty, Near PHED Colony, Behind Pump Hours, PC - RMCC, District - Ranchi 834009, Mobile No: +91 9431 102.102 / +91 9955 358 262 E-mail mahabairanchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

Report no: MEEPL/OCT0132/2017-18

Date: 24% October, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalon Industries Limited

Client Address: Lohardaga Postal Code: 835203 state: |harkhand Country: India

sample type: AMBIENT AIR QUALITY MONITORING

Fig. ks on Sample: Location: Pakhar Plateau- Pakhar Quarry 105 507 ha. (Near Shed) Sample collected on: 19.09.2017

SI. No.	LOCATION / IDENTIFICATION: Pakhar Plateau- Pak	T		410.000.00
	PARAMETERS	UNIT	Standard	Concentration
01	Particulate Matter (size less than 10 µm) PM10		Limit	concentration
02.	Particulate Malter (size less than 2.5 µm) PM ₂₅	µg/m³	100	66.0
03.	Sulphur Dioxide (SO ₂)	μg/m³	60	30.7
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	5.1
05,	Ammonia (NH ₃)	μg/m [±]	80	8.9
06,	Ozone (O ₃)	µg/m³	400	12.7
07,	Carbon Monoxide (CO)	μg/m ⁴	100	14.3
)8.	Lead (Pb)	mg/m³	02	0.40
9.	Nickel (Ni)	μg/m³	1.0	0.03
10.	Arsenic (As)	ng/m/	20	3.2
11.	Benzene (CoHo)	ng/m ⁺	06	2.2
2.	Benzo (a) Pyrene	μg/m³	0.5	2.10
	(-) Trene	µg/m³	01	0.40

For Mahabal Enviro Engineers Pvt. Ltd.

For Mahabal Enviro Eng. Pvt. Ltd.

May Panu Authorised Signatory



At Booty, Near PHED Colony, Behind Pump House, Fine RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358 262 E-mail:mahabalranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

Date: 24" October, 2017

Report no: MEEPL/OCT0133/2017-18

Sil..., ... described by customer: AMBIENT AIR QUALITY MONITON

Citent Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

olarks on sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 https://www.shed. Sample collected on: 19 09 2017

SI. No.	LOCATION / IDENTIFICATION: Pakhar Plateau- Pal	,,	103.507 na. [(atri Shed)
	PARAMETERS	UNIT	Standard	
01.	Particulate Matter (size less than 10 µm) PM ₁₀	The second second	Limit	Concentration
02,	Particulate Matter (size less than 2.5 μm) PM ₂₅	μg/m³	100	52.5
03.	Sulphur Dioxide (SO ₂)	µg/m²	60	27.0
04.	Nitrogen Dioxide (NO ₂)	µg/m³	80	4.6
05,	Ammonia (NH ₃)	4g/m³	80	8.2
06.	Ozone (O ₃)	µg/m³	400	12.9
07.	Carbon Monoxide (CO)	μg/m³	180	14.0
08	Lead (Pb)	mg/m³	02	0.37
09,	Nickel (Ni)	μg/m3	1.0	0.03
10.	Arsenic (As)	ng/m³	20	3.0
	Benzene (C ₆ H ₆)	ng/m³	06	2.2
	Benzo (a) Pyrene	μg/m¹	05	2.7
	The state of the s	µg/m³	01	0.45

For Mahabal Enviro Engineers Pvt. Ltd.

For Mahabal Enwire Eng. Pvt. Ltd.

Villa PaniAnthonised Signatory

SENIOR EXECUTIVE

VIO En



At Booty, Near PHED Colony, Behind Pump House PC - RMCC, District - Ranchi 834009. E-mail mahabairanchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JULY - SEPTEMBER 2017

Report no: MEEPL/OCT0134/2017-18

Date: 24% ()ctober, 2017

Sample described by customer: AMBIENT AIR QUALITY MONIT

Chent Name: Hindalco Industries Limited

Client Address Lohardaga Postal Code: 835203 State: !harkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- 109.507 ha. Londing Are...

Sample collected on: 19 09.2017

SI. No.	LOCATION / IDENTIFICATION: Pakhar Plate:	iu- 109.507	ha. Loading Ar	ea.
31. 140.	PARAMETERS	UNIT	Standard	#(P000000000000000000000000000000000000
01.	Particulate Matter (size less than 10 µm) PM ₁₀		Limit	Concentration
02.	Particulate Matter (size less than 10 µm) PM10	HZ/m³	100	57.2
03.	Particulate Matter (size less than 2.5 µm) PM ₁₈ Sulphur Dioxide (SO ₂)	μg/m [†]	60	26.8
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	4.4
05.	Ammonia (NH ₃)	µg/m ⁺	80	7.1
06.	Ozone (O ₃)	μg/m³	400	10.6
07.	Carbon Monoxide (CO)	μg/m ³	180	13,5
08.	Lead (Pb)	mg/m ³	02	0.41
09_	Nickel (Ni)	μg/m*	1.0	0.03
10.	Arsenic (As)	ng/m ³	20	3.0
11.	Benzene (C ₆ H ₆)	ng/m³	06	2,5
2.	Benzo (a) Pyrene	μg/m³	05	2.12
-50		μg/m³	01	0.50

For Mahabal Enviro Engineers Pvt. Ltd.

For Mahabal Enviro Eng. Pvt. Ltd.

Vilay Pand Authorised Signatory





At Booty, Near PHED Colony, Behind Pump House, PC - THOC. District - Ranch: 834009 Mobile No: +91 9431.102.102 / +91 9955.358.762 E-mail: mahabal/anchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

Date: 24% October, 2017

Report no: MEEPL/OCT0135/2017-18

Samme described by customer: SURFACE-WATER

Client Name: Hindalso Industries Limited

Client Address: Lohardaga Postal Code: 835203


State: Jharkhand Country: India

Sample Type: SURFACE WATER

Marks on Sample: Location: Pakhar Plateau

Quantity: 5 L X Z No. PVC Can Sample collected on:18 09:2017

51. No.	Parameters Colour	Unit	Result	Acceptanie Limit (la 103-0:2012)	Method Reference
9.	The state of the s	Hazen	<2	5 (*10)	= 2 440 APP CANADASA
	Odour	125	Agreeable		APHA 22*4 Ed. 2012, 2120-B, 2-6 IS 3025 (Part 7): 1983, Reaffirmed
3	Taste		Agreeable	Agrerable	2006 IS 3025 (Part 7): 1983, Reaffirmed
4	Turbidity	NTU	0.31	1 **ax	2006
5	рH		7.5		APHA 22 ^{cut} Ed 2012, 2130-8, 2-13
6	Eron Citi	1	7.5	6.5-8.5	APHA 22nd Ed. 2012, 4500-H+-B, 4-92
	Free Chlorides (Residual)	mg/I	<0.5	0.2 min	APHA 22 ^{eu} Ed. 2012, 4500-Cl-G, 4
7	Total Dissolved Solids	mg/I	482	500 max	69 IS 3025 (Part 16) 1984.
. /	Total hardness (as CaCO3)	200		max	Reaffirmed 2006
	Alkalinirty Total (as	mg/I	49	200 max	APHA 22 nd Ed. 2012, 4500-CIG, 4-
	Caco3)	mg/l	43	200 max	IS 3025 (Part 237), 1986.
0	Chloride (as CI)	mg/l	1	W-1	Reaffirmed 2009
		ring/1	47	250 ma-	APHA 22nd Ed. 2012, 4500-CI-b, 4-72
-	Sulphate (as SO4)	mg/l	32.9	200 max	APHA 22nd Ed. 2012, 4500-so4-e
1	Boron (as B)	THE SEARCH OF THE	Parties and the second		4-190
	or research Will Made	mg/l	0.20	0.5 max	APHA 22ml Ed. 2012, 4500-BB, 4- 25
	(agnesium (as Mg)	mg/l	6.1		ADUA 22 July
			Ma	30 max	APHA 22*d Ed. 2012, 3500-Mg-E, 3-84





Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PF - FMCC District - Ranchi 834909, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail.mahabalranchi@gmail.com

Hindalco Industries:

Environmental Monitoring Report

JULY - SEPTEMBER 2017

Continuation Sheet MEEPL/OCT0135/2017-18

St. No	Parameters			T	Date: 24th October, 201
14	11 - CAMBINE (177)	Unit	Result	Acceptable Limit (IS 10500:2012)	Method Reference
	Fluoride (*s F)	ing/[0.12	1 max	APHA 22m Ed 2012, 4500 FH & D a
15	Calcium (as Ca)	mg/I	21.3	76	84, 4-87
14	fron (as Fe)	mg/l		75 max	APHA 22 m Ed. 2012; 3500-Ca-F; 3-67
7	Cadmium (as Cd)	mg/l	0.08	0.3 max	APRIA 22m Ed. 2012, 31(1 h + 18
B.	Chromium Total (as Cr)	100000	ND	0.003 max	APHA 22™ Ed. 2012 3111 B. 3-18
9	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22nd Ed. 2012, 3111 B. 3-18
0	Lead (as Pb)	mg/l	N.D	0.05 ma.,	APHA 22-4 Ed. 2012, 3111-B, 3-18
	Zinc (as Zn)	mg/l	N.D	0.01 max	APHA 22m F.4. 2012, 3111-H, 3-1H
	Arsenic (as As)	mg/l	0.03	5 max	APHA 22mi Ed. 2012, 3111-B, 3-16
		mg/l	< 0.01	0.01 max	APHA 22 nd Ed. 2012, 3111 B, 3-18
- +	Selenium (as Se)	mg/l	N.D	0.004	APHA 22nd Ed. 2012, 3114-B, 3-38
- 4	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22m Ed. 2012, 3112-B, 3-23
	Cyanide (as CN)	mg/l	N.O.		r PHA 22*4 Ed. 2012; 3114-8; 3-39
-+	Manganese (as Mn)		N.D	0.05 may	APHA 22 ^{ml} ED 2012, 4500 €N € & 4 39 & 4-44
		rng/l	N.D	0.1	The state of the s
	Dissolved Oxygen	mg/l	7.5	2.0	APHA 22 nd Ed. 2012; 3111-B. 3-18 APHA 20 nd ED. Method 4500 o.g.

For Mahabal Enviro Engineers Pvt. Ltd.

no. kiahabal Envijo Eng. Pvi. Lid.

Vijay nai Authorised Signatory

SENIOR EXECUTIVE

Ranchi Ci

Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Shew Room Near) B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com

BREAK UP THE COST OF ENVIRONMENTAL MEASURES DURING THE YEAR 2016-17

The composite cost during the year 2017-18 for environmental protection & pollution control by Jharkhand Mines division of M/s Hindalco Industries Ltd & M/s Minerals & Minerals Ltd for implementation of the suggested measures in EC at our all the operating mines in the state of Jharkhand-namely Pakhar (115.13 Ha), Pakhar (15.58 Ha), Pakhar (109.507 Ha), Pakhar (8.09 Ha), Pakhar (35.12Ha), Serengdag (140.06 Ha), Serengdag (155.81 Ha), Jalim & Sanai (12.14 Ha), Gurdari (584.19 Ha), Amtipani (190.95 Ha), Kujam I (80.87 Ha) Kujam II (157.38 Ha) and Bagru (75.41 Ha), Hisri New (14.55 Ha), Chiro kukud(152.57 Ha), Orsa pat(196.36 Ha), Bhusar (65.31 Ha)& Bimaria Bauxite Mines (134.52 Ha).

SI No	Description	Budget (in Rupees) FY 2017-18	Actual (in Rupees) FY 2017-18 (from April'17 to Sep'2017)
1	Pollution Control & Environment monitoring	1316000.00	651832.00
2	Reclamation/ Back filing & Rehabilitation**	30000000.00	131262375.00
3	Green belt, Plantation & Water spraying arrangement	3400000.00	3373300,00
	Rural Development	4000000.00	18500000,00

^{**}Part of OB removed cost.

(Basudev Gangopadhayay)
Convenor (Quality & Environment)

1-2111 -



Date: 03.04.17

Office Order

Environmental Cell has been re-constituted at Pakhar Bauxite Mines (Area 115.13 Ha) comprising below mentioned team members. The team will ensure compliance of Environment Act, Regulation & Rule in respect of the said mines of Hindalco Industries Limited.

- 1. Mr. Narayan Pramanik (Geologist) Coordinator
- 2. Mr. S.P.Jha (Mines Manager) Member
- 3. Mr. Gaurang Agarwal (Mining Engineer) Member
- 4. Mr. Sunil Kumar Pandey (Fore man) Member
- 5. Mr. Amlendu Kumar Singh (Foreman) Member

Basudev Gangopadhyay Convenor (Quality & Environment)

ANNEXURE-4 PRODUCTION, MINED OUT, BACKFILLED, PRODUCTION AND OVERBURDEN REMOVAL FROM APR-17 to Sep-17

STATE OF THE WITNES IN	MINING LEASE AREA (IN HA)	MINED OUT AREA (HA)	BACK FILLED ADEA GOAL		
Shrengdag Bauxite	155.81		TOWN TILLED ANEA (HA)	PRODUCTION (In MT)	OVERBURDEN (In C., M.)
Gurdari Bauxite Mines	\$82.10	2.57	2.00	148330.00	
Jalim & Sanai	12.14	8.10	4.70	175860 00	141538.00
Serangdag	140.06	1.25	0.50	25137.00	391/07.00
Pakhar Buxite Mines	115.13	0000	0.00	0.00	16365.00
Pakhar Buxite Mines	60'8	1.32	1.89	137420.00	0.00
Kujam-1	80.87	0.00	0.00	0.00	0.0505.00
Kujam-II	157.38	1.87	1.95	67925.00	0.00
Amtipani	190.95	3.32	3.70	132480 00	108182.00
Chiro-Kukud	152.57	4.70	3.17	102545.00	209216:00
Orsa Bauxite Mines	196.36	1./3	1.28	41460 00	138980.00
Hisri New	14.55	0,00	0,00	0.00	64089.00
Bhusar	65.31	1.05	0.91	35561.00	0.00
Bagru		0.16	1.80	63239.00	44239.00
Minerals & Minerals Limited		0.00	0.00	0.00	68532.00
Pakhar Buxite Mines	109.51	A 7-			0.00
Pakhar Buxite Mines	15.58	0.30	1.70	136490.00	16,0016,00
Bimarla Bauxite Mines	134.52	0.20	0.00	0.00	1716.00



164820.00

(Basudev Gangopadhayay) Convenor (Quality & Environment)