MINERALS & MINERALS LIMITED

Regd. Office P.O. & Dist. – Lohardaga (Jharkhand) PIN – 835302 Phone: 06526-224016, 224112, FAX: 06526-224118

Ref No: M&M/LHD/JP (M)/MoEF/ 109

Date: 23.05.2017

To,

The Additional Principal Chief Conservator of Forest (C) Ministry of Environment, Forests and Climate Changes Regional Office (ECZ), Ranchi-834002.

Sub: Compliance Report of EC conditions for Pakhar (15.58 ha) Bauxite Mining project of M/s Minerals & Minerals Limited located in Lohardaga, Jharkhand for the period Oct'16 to March'17.

Ref: Environmental Clearance letter no J-11015/123/2006-IA II (M) dated 24th January 2007

Sir,

With reference to the above, we are submitting herewith the Compliance status report of EC conditions for **Pakhar (15.58 ha)** Bauxite Mining project of M/s Minerals & Minerals Limited, located in Lohardaga, Jharkhand for the period **Oct'16 to March'17**.

Hope you will find the same in order.

Thanking You

Yours Sincerely FOR Minerals & Minerals Limited

> (Bijesh Kumar Jha) Agent of Mines

Enclosure: - As Above

Copy to: Member Secretary, JSPCB, Ranchi RO, JSPCB, Ranchi

CPCB, Zonal Office, Kolkata

er eb, zonar office, kolkata

<mef@ori.nic.in>, <mef@nic.in>, <mef.or@nic.in>, mef.or@nic.in

Compliance of conditions laid down in Environmental Clearence PAKHAR BAUXITE MINES(15.58 Ha) MINERALS & MINERALS LTD.

Period: Period: Oct'16-March17 J-11015/123/2006-IA.II(M) Dated 24.01.2007

SI No	Conditions	Compliance Status
	Specific Conditions	
1	All the conditions stipulated by SPCB in their NOC shall be effectively implemented.	Implementations of the stipulated condition are fulfilled. Mines is discontinued since Sep'14 due to second renewal case as per directive by DMO.
2	The environmental clearance is subject to approval of the state land use Department, Government of Jharkhand for diversion of agricultural land for non-agricultural use.	Mining Lease is granted by the State
3	Mining shall not intersect groundwater. The mine working shall be restricted to ground water table. Prior approval of the Ministry of Environment & Forests and Central Ground Water Authority shall be obtained for mining below water table.	Shallow depth mining was carried out so mining not intersected ground water. Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO.
4	The project proponent shall ensure that no natural watercourse shall be obstructed due to any mining operation.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. The provision set herewith will be complied with the progress of mining activity as complied in past post resumption of mining activity.
5	Top soil shall be stacked properly with proper slope with adequate measures and should be used for reclamation and rehabilitation of mined out areas.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. The provision set herewith will be complied with the progress of mining activity as complied in past post resumption of mining activity.
6	The waste generated shall be concurrently backfilled in the mined out area. There shall be no external OB dump. Monitoring and management of rehabilitated areas should continue until the vegetation becomes self-sustaining. Compliance status should be submitted to the Ministry of Environment & Forest on six monthly basis.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. The provision set herewith will be complied with the progress of mining activity as complied in past post resumption of mining activity.

	1	
7	Catch drains and siltation ponds of appropriate size should be constructed to arrest silt and sediment flows from mine working. The water so collected should be utilized for watering the mine area, roads, green belt development etc. The drains should be regularly desilted particularly after monsoon and maintained properly. Garland drain (size, gradient and length) shall be constructed for mine pit and sump capacity should be designed keeping 50% safety margin over and above peak sudden rainfall (based on 50 years data) and maximum discharge in the area adjoining the mine site. Sump capacity should also provide adequate retention period to allow proper setting of silt material. Sedimentation pits should be constructed at the corners of the garland drains and desilted at regular intervals.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. The provision set herewith will be complied with the progress of mining activity as complied in past post resumption of mining activity.
8	Plantation shall be raised in an area of 6.98ha including a green belt of adequate width by planting the native species around the ML area, roads, reclaimed area etc. in consultation with the local DFO / Agriculture Department. The density of the trees should be around 1500 plants per ha.	This will be complied with the progress of mining activity as complied in past.
9	The project proponent shall ensure that there shall be no discharge from the mine.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. The provision set herewith will be complied with the progress of mining activity as complied in past.
10	The Project proponent shall carry out regular monitoring of spring discharge and its quality near Pakhar village on long term basis.	There is no spring in and around this lease.
11	The project authority should implement suitable conservation measures to augment ground water resources in the area in consultation with the Regional Director, Central Ground Water Board.	Will be implemented after resume of mining activity.
12	Regular monitoring of ground water level and quality should be carried out by establishing a network of existing wells and constructing new piezometers during the mining operation. The monitoring should be carried out four times in a year — pre-monsoon (April-May), monsoon (August), post-monsoon (November) and winter (January) and the data thus collected may be sent regularly to MOEF, Central Ground water Authority and Regional Director Central Ground	It is being monitored. Report enclosed.

	Water Board.	
13	Prior permission from the competent authority should be obtained for drawl of water from the surface water bodies.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. We will not use natural water/ground water for mining
14	Vehicular emissions should be kept under control and regularly monitored. Measures shall be taken for maintenance of vehicles used in mining operations and transportation of mineral. The vehicles should be covered with a tarpaulin and shall not be overloaded.	purpose. Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. This will be complied with the progress of mining activity as complied in past.
15	Drills should either be operated with dust extractors or should be equipped with water injection system.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. This will be complied with the progress of mining activity as complied in past.
16	Blasting operation should be carried out only during the daytime. Controlled blasting should be practiced. The mitigative measures for control of ground vibration and to arrest fly rocks and boulders should be implemented.	Mines is discontinued since Sep'2014 due to second renewal case as per
17	Consent to operate should be obtained from SPCB prior to start of enhanced production from the mine.	Mines is discontinued since Sep'14 due to second renewal case as per directive by DMO. All procedure for getting the lease extension is being done & very shortly mine will be operative.
18	Sewage treatment plant should be installed for the colony. ETP should also be provided for workshop and wastewater generated from mining operations.	There is no effluent from mine; hence ETP has not been installed.
19	The project proponent should take all precautionary measures during mining operation for conservation and protection of endangered fauna such as Indian Python etc. Spotted in the study area. Action plan for conservation of flora and fauna shall be prepared and implemented in consultation with the State Forest and Wildlife Department. Necessary allocation of funds for implementation of the conservation plan shall be made and the funds so allocated shall be included in the project cost. Copy of action plan may be submitted to the Ministry and its Regional Office within 3 months.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. The copy of Action plan for conservation of flora and fauna (Pakhar Plateau) is attached herewith and implementation for Pakhar Plateau under implementation.

of Environment & Forest 5 years in advance of M	dully approved by Indian Bureau of Mines. FMCP related provision will be compiled as per statue.
---	--

GENERAL CONDITIONS

SI No	Conditions	Compliance Status
1	No change in mining technology and scope of working should be made without prior approval of the Ministry of Environment & Forest	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. This will be complied in future post resumption of mining activity as complied in past.
2	No change in the calendar plan including excavation, quantum of mineral bauxite and waste should be made.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. This conditions will be complied in future post resumption of mining activity as complied in past.
3	Four ambient air quality-monitoring station should be established in the core zone as well as in the buffer zone for RPM, SPM, SO ₂ , NO _X monitoring. Location of the stations should be decided based on the metrological data, topographical features and environmentally and ecologically sensitive targets and frequency of monitoring should be undertaken in consultation with the State Pollution Control Board.	Complied. Monitoring Reports is enclosed as Annexure-1.
4	Data on ambient air quality (RPM, SPM, SO ₂ , NOx) should be regularly submitted to the Ministry including its Regional office located at Bhubneshwar and the State Pollution Control Board / Central pollution Control Board once in six months.	Complied. Monitoring Reports is enclosed as Annexure-1.
5	Fugitive dust emission from all the sources should be controlled regularly. Water spraying arrangements on haul roads, loading and unloading and at transfer points should be provided and properly maintained.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. This will be complied in future post resumption of mining activity as complied in past.
6	Measures should be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operation of HEMM, etc. should be provided with ear plug / muffs.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. This will be complied in future post resumption of mining activity as complied in past.

7	Industrial waste water (workshops and waste water from the mine) Should be properly collected, treated so as to conform to the standards prescribed under GSR 422 (E) dated 19 th May, 1993 and 31 st December, 1993 or as amended from time to time. Oil and grease trap should be installed before discharge of workshop effluents.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO.
8	Personnel working in dusty areas should wear protective respiratory devices and they should also provided with adequate training and information on safety and health aspects. Occupational health surveillance program	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. This will be complied in future post
	of the workers should be undertaken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed.	resumption of mining activity as complied in past.
9	A separate environmental management cell with suitable qualified personnel should be set-up under the control of a Senior Executive, who will report directly to the Head of the Organization.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO.
		A separate environment management cell
10	The project authorities should inform to the Regional Office located at Bhubneshwar regarding date of financial closures and final approval of the project by the concerned authorities and the date of start of land development work.	will be formed with the start of Mining. This falls the category of operational mine and not project, therefore provision related to financial closure is not applicable.
11	The funds earmarked for environmental protection measures should be kept in separate account and should not be diverted for other purpose. Year wise expenditure should be reported to the Ministry and its Regional Office located at Bhubneshwar.	Mines is discontinued since Sep'2014 due to second renewal case as per directive by DMO. The funds are ear-marked for environmental protection.
12	The Regional Office of this Ministry located at Bhubneshwar shall monitor compliance of the stipulated conditions. The project authorities should extend full cooperation to the officer (s) of the Regional Office by furnishing the requisite data / information / monitoring reports.	Agreed.
13	A copy of clearance letter will be marked to concerned Panchayat / local NGO, if any, from whom suggestion / representation has been received while processing the proposal.	Complied.
14	State Pollution Control Board should display a copy of the clearance letter at the Regional office, District Industry Center and Collector's office / Tehsildar's Office for 30 days.	Displayed.

The project authorities should advertise at least in two local newspapers widely circulated, one of which locality concerned, within 7days of the issue of the clearance letter informing that the project has been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution Control Board and also at web site of the Ministry of Environment and Forests at http://envfor.nic.in and a copy of the same should be forwarded to the Regional Office of this Ministry located Bhubneshwar.

Complied. Copies of the advertisement made in the local newspapers, have already been submitted to the Regional Office.



Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden, Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

ecoventures.mumbai@gmail.com /ecoventures@eco-ventures.in

Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

PAKHAR PLATEAU- ENVIRONMENTAL MONITORING REPORT

JANUARY TO MARCH 2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@qmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

CONTENT

	LOCATION
	AMBIENT AIR QUALITY
1	Pakhar Plateau-Near Weigh Bridge
2	Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4
3	Pakhar Plateau- Near Office
4	Pakhar Plateau- Pakhar Quarry (109.507 ha. Near Shed)
5	Pakhar Plateau Pakhar Mines(109.507 ha. Yatri Shed)
6	Pakhar Plateau- Pakhar Loading Area (109.507 ha.)
	NOISE LEVEL
1	Pakhar Near Office.
2	Pakhar Mine (115.13 ha.) Pakhar Plateau
3	Pakhar Mine (109.507 ha. Loading Area) Pakhar Plateau
4	Pakhar Mine (109.507 Ha Yatri Shed) Pakhar Plateau
5	Pakhar Quary (Near Shed)
	SPOT NOISE LEVEL
1	Near Poclain at Pakhar Mine (115.13 ha.)
2	Loading point near Dumper at Pakhar Mines (109.507 ha. Minerals & Minerals)
	DRINKING WATER
1	Pakhar Mine-Near Canteen





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0140/2016-17

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau-Near Weigh Bridge

Sample collected on: 26.03.2017

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μ m) PM ₁₀	μg/m³	100	63.5
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	39.5
03.	Sulphur Dioxide (SO ₂)	μg/m³	80	32.5
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	41.2
05.	Ammonia (NH ₃)	μg/m³	400	12.1
06.	Ozone (O ₃)	μg/m³	180	17.2
07.	Carbon Monoxide (CO)	mg/m³	02	0.60
08.	Lead (Pb)	μg/m³	1.0	0.05
09.	Nickel (Ni)	ng/m³	20	8.9
10.	Arsenic (As)	ng/m³	06	2.95
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.18
12.	Benzo (a) Pyrene	μg/m³	01	0.45

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0141/2016-17

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4

Sample collected on: 26.03.2017

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM ₁₀	μg/m³	100	66.4
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	35.1
03.	Sulphur Dioxide (SO ₂)	μg/m³	80	9.8
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	19.2
05.	Ammonia (NH ₃)	μg/m³	400	12.9
06.	Ozone (O ₃)	μg/m³	180	14.3
07.	Carbon Monoxide (CO)	mg/m³	02	0.50
08.	Lead (Pb)	μg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	3.9
10.	Arsenic (As)	ng/m³	06	2.4
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.10
12.	Benzo (a) Pyrene	μg/m³	01	0.52

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0142/2016-17

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Pakhar Plateau-Near Office

Sample collected on: 26.03.2017

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM ₁₀	μg/m³	100	60.4
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	29.9
03.	Sulphur Dioxide (SO ₂)	μg/m³	80	10.1
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	18.5
05.	Ammonia (NH ₃)	μg/m³	400	17.2
06.	Ozone (O ₃)	μg/m³	180	14.6
07.	Carbon Monoxide (CO)	mg/m³	02	0.4
08.	Lead (Pb)	μg/m³	1.0	0.02
09.	Nickel (Ni)	ng/m³	20	3.8
10.	Arsenic (As)	ng/m³	06	2.5
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.1
12.	Benzo (a) Pyrene	μg/m³	01	0.34

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE





At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Report no: MEEPL/APRIL0143/2016-17

Date: 20th April, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Near Shed)

Sample collected on: 26.03.2017

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μ m) PM ₁₀	μg/m³	100	64.1
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	31.7
03.	Sulphur Dioxide (SO ₂)	μg/m³	80	9.4
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	18.6
05.	Ammonia (NH ₃)	μg/m³	400	12.5
06.	Ozone (O ₃)	μg/m³	180	15.5
07.	Carbon Monoxide (CO)	mg/m³	02	0.49
08.	Lead (Pb)	μg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	3.8
10.	Arsenic (As)	ng/m³	06	2.3
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.10
12.	Benzo (a) Pyrene	μg/m³	01	0.42

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Report no: MEEPL/APRIL0144/2016-17

Date: 20th April, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Yatri Shed)

Sample collected on: 27.03.2017

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μ m) PM ₁₀	μg/m³	100	43.5
02.	Particulate Matter (size less than 2.5 μ m) PM _{2.5}	μg/m³	60	27.8
03.	Sulphur Dioxide (SO ₂)	μg/m³	80	9.9
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	20.1
05.	Ammonia (NH ₃)	μg/m³	400	12.7
06.	Ozone (O ₃)	μg/m³	180	16.1
07.	Carbon Monoxide (CO)	mg/m³	02	0.49
08.	Lead (Pb)	μg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	3.8
10.	Arsenic (As)	ng/m³	06	2.3
11.	Benzene (C ₆ H ₆)	μg/m³	05	3.1
12.	Benzo (a) Pyrene	μg/m³	01	0.52

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Report no: MEEPL/APRIL0145/2016-17

Date: 20th April, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- 109.507 ha. Loading Area.

Sample collected on: 27.03.2017

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM_{10}	μg/m³	100	64.5
02.	Particulate Matter (size less than 2.5 μ m) PM _{2.5}	μg/m³	60	37.4
03.	Sulphur Dioxide (SO ₂)	μg/m³	80	9.9
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	19.5
05.	Ammonia (NH ₃)	μg/m³	400	11.2
06.	Ozone (O ₃)	μg/m³	180	15.8
07.	Carbon Monoxide (CO)	mg/m³	02	0.52
08.	Lead (Pb)	μg/m³	1.0	0.03
09.	Nickel (Ni)	ng/m³	20	3.6
10.	Arsenic (As)	ng/m³	06	2.7
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.13
12.	Benzo (a) Pyrene	μg/m³	01	0.50

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0146/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 27.03.2017

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Near Office	dB (A) L _{eq}	75	55.1	70	49.9	27.03.2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

Edenor Phi

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0147/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 27.03.2017

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Mines (115.13 ha.)	dB (A) L _{eq}	75	59.5	70	49.2	27.03.2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

Partin Co. Phil



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0148/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 2703.2017

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Mines (109.507 ha. Loading Area)	dB (A) L _{eq}	75	60.3	70	38.6	27.03.2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

REACHI OF THE REACHING PAIN

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0149/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 27.03.2017

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Mines (109.507 ha. of Yatri Shed)	dB (A) L _{eq}	75	57.9	70	44.6	27.03.2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

POR REACH IN CO.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0150/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 27.03.2017

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Quary (Near Shed)	dB (A) L _{eq}	75	52.9	70	47.1	27.03.2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

regeneration Pvi.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Report no: MEEPL/APRIL0151/2016-17

Date: 20th April, 2017

Sample described by customer: Measurement of Spot Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: **Measurement of Spot Noise** Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 27.03.2017

Location/Identification	Unit	Limit (day)	Result	Dates
Near Poklen at Pakhar Mines (115.13 ha.)	dB (A) Leq	75	61.9	27.03.2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

Republication of the second of

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Date: 20th April, 2017

Report no: MEEPL/APRIL0152/2016-17

Sample described by customer: Measurement of Spot Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Spot Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 27.03.2017

Location/Identification	Unit	Limit (day)	Result	Dates
Pakhar Mines (109.507 ha. of Minerals & Minerals) Loading point near Dumper	dB (A) L _{eq}	75	67.3	27.03.2017

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Report no: MEEPL/APRIL0153/2016-17

Date: 20th April, 2017

Sample described by customer: DRINKING WATER-POTABILITY

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: DRINKING WATER-POTABILITY Marks on Sample: Location: Near Canteen

Quantity: 5 L X 2 No. PVC Can **Sample collected on:**27.03.2017

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method reference
1	Colour	Hazen	<1	5 Max	APHA 22 nd Ed. 2012, 2120- B, 2-6
2	Odour		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
3	Taste	**	Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
4	Turbidity	NTU	0.20	1 Max	APHA 22 nd Ed. 2012, 2130- B, 2-13
5	рН		7.1	6.5-8.5	APHA 22 nd Ed. 2012, 4500- H+-B, 4-92
6	Free Chlorides (Residual)	mg/l	<0.5	1 max	APHA 22 nd Ed. 2012, 4500- CI-G, 4-69
7	Total Dissolved Solids	mg/l	83	500 max	IS 3025 (Part 16): 1984, Reaffirmed 2006
8	Monochloramines	mg/l	<0.05	**	APHA 22 nd Ed. 2012, 4500- CIG, 4-69
9	Dichioramines	mg/l	<0.05		APHA 22 nd Ed. 2012, 4500- CIG, 4-69
10	Total hardness (as CaCO3)	mg/l	61	200 max	APHA 22 nd Ed. 2012, 4500- CIG, 4-69
11	Alkalinirty Total (as CaCO3)	mg/l	67	200 max	IS 3025 (Part 237): 1986, Reaffirmed 2009
12	Chloride (as CI)	mg/l	8.1	250 max	APHA 22 nd Ed. 2012, 4500- CI-b, 4-72
13	Sulphate (as SO4)	mg/l	3.9	200 max	APHA 22 nd Ed. 2012, 4500- so4-e, 4-190





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Continuation Sheet MEEPL/APRIL0153/2016-17

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
14	Nitrate (as NO3)	mg/l	1.01	45 max	APHA 22 nd Ed. 2012, 4500-NO3-E, 4- 125
15	Fluoride (as F)	mg/l	0.26	1 max	APHA 22 nd Ed. 2012, 4500-FB & D, 4-84, 4-87
16	Boron (as B)	mg/l	0.02	0.5 max	APHA 22nd Ed. 2012, 4500-BB, 4-25
17	Calcium (as Ca)	mg/l	20.4	75 max	APHA 22 nd Ed. 2012, 3500-Ca-B, 3-67
18	Magnesium (as Mg)	mg/l	2.7	30 max	APHA 22nd Ed. 2012, 3500-Mg-B, 3-84
19	Ammonical Nitrogen/Total Ammonia	mg/l	<0.1	924	APHA 22 nd Ed. 2012, 4500-NH3-F, 4- 115
20	Iron (as Fe)	mg/l	0.10	0.3 max	APHA 22nd Ed. 2012, 3111-B, 3-18
21	Manganese (as Mn)	mg/l	N.D	0.1 max	APHA 22 nd Ed. 2012, 3111-B, 3-18
22	Aluminium (as Al)	mg/l	0.01	0.03 max	APHA 22nd Ed. 2012, 3500-Al-B, 3-61
23	Cadmium (as Cd)	mg/l	N.D	0.003 max	APHA 22nd Ed. 2012, 3111-B, 3-18
24	Chromium Total (as Cr)	mg/l	N.D	0.05 max	APHA 22nd Ed. 2012, 3111-B, 3-18
25	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22nd Ed. 2012, 3111-B, 3-18
26	Lead (as Pb)	mg/l	N.D	0.01 max	APHA 22nd Ed. 2012, 3111-B, 3-18
27	Zinc (as Zn)	mg/l	0.10	5 max	APHA 22nd Ed. 2012, 3111-B, 3-18
28	Arsenic (as As)	mg/l	0.006	0.01 max	APHA 22nd Ed. 2012, 3114-B, 3-38
29	Selenium (as Se)	mg/l	N.D	0.001 max	APHA 22nd Ed. 2012, 3112-B, 3-23
30	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22nd Ed. 2012, 3114-B, 3-38
31	Nickel (as Ni)	mg/l	<0.008	0.02 max	APHA 22nd Ed. 2012, 3111-B, 3-18
32	Mineral Oil	mg/l	N.D	0.5 max	IS 3025 (Part 39): 1991, Reaffirmed 2003: ed. 2.1
33	Cyanide (as CN)	mg/l	N.D	0.05 max	APHA 22 nd ED. 2012, 4500-CN.C & 4- 39 & 4-44
34	Anionic detergents as MBAS	mg/l	<0.1	0.2 max	APHA 22nd ED. 2012, 5540-C.C & 5-53
35	Phenolic compounds (as C6H5OH)	mg/l	N.D	0.001 max	APHA 22nd ED. 2012, 5530-B & C 5- 4753
36	Polynuclear aromatic hydrocarbons (PAH)	mg/l	N.D	0.0001 max	APHA 22nd ED. 2012, 6440, 6-93
37	Polychlorinated Biphenyls (PCBs)	mg/l	N.D	0.0005 max	USEPA Method 8082
38	Sulphide (as S)	mg/l	N,D	0.05 max	APHA 22nd ED. 2012, 4500-S2-C 4- 175 & F 4-178





Mahabal Enviro Engineers Pvt. Ltd.

Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

JAN. - MAR. 2017

Continuation Sheet MEEPL/JAN0153/2016-17

	no: MEEPL/APRIL015				Pate: 20 th April, 201
Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method Reference
Microbio	logical Analysis				
1	Total Colliforms	MPN/100mL	N.D	<1.1	APHA 22nd Ed. 2012, 9221-B & C, 9-66, 9-69 and 9-67
2	E-Coli MPN/100ml		N.D	Absent	APHA 22nd Ed. 2012, 9221-B & C, 9-66, 9-69 and 9-76
Pesticide	s Residues				1 2002 100 100 100 100 100 100 100 100 1
3	p.p DDT	μg/L	N.D	1	US EPA 508-1995
4	o.p DDT	μg/L	N.D	1	US EPA 508-1995
5	p.p DDE	μg/L	N.D	1	US EPA 508-1995
6	o.p DDE	μg/L	N.D	1	US EPA 508-1995
7	p.p DDD	μg/L	N.D	1	US EPA 508-1995
8	o.p DDD	μg/L	N.D	1	US EPA 508-1995
9	γ-HCH (Lindance)	μg/L	< 0.01	2	US EPA 508-1995
10	α –НСН	μg/L	< 0.01	0.01	US EPA 508-1995
11	β-НСН	μg/L	N.D.	0.04	US EPA 508-1995
12	Б- НСН	μg/L	N.D	0.04	US EPA 508-1995
13	Butachlor	μg/L	N.D	125	US EPA 508-1995
14	Alachlor	μg/L	N.D	20	US EPA 508-1995
15	Atrazine	μg/L	N.D	2	US EPA 508-1995
16	α Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
17	β Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
18	Endosulfan Sulphate	μg/L	N.D	0.4	US EPA 508-1995
19	Ethion	μg/L	N.D	3	US EPA 8141A-1994
20	Malathion	μg/L	N.D	190	US EPA 8141A-1994
21	Methoyl Parathion	μg/L	N.D	0.3	US EPA 8141A-1994
22	Monocrotophos	μg/L	N.D	1	US EPA 8141A-1994
23	Phorate	μg/L	N.D	2	US EPA 8141A-1994
24	Chlorpyrifos	μg/L	N.D	30	US EPA 8141A-1994
25	Aldrin	μg/L	N.D	0.03	US EPA 508-1995
26	Dieldrin N.D- Not Detected	μg/L	N.D	0.03	US EPA 508-1995

Conclusion : The Physical & Chemical Analysis report indicates that the water is not contaminated and potable.

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

POR REACH IN THE PROPERTY OF T



Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com /ecoventures@eco-ventures.in

Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

PAKHAR PLATEAU- ENVIRONMENTAL MONITORING REPORT

OCTOBER TO DECEMBER 2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





Branch Office:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

CONTENT

	LOCATION
	AMBIENT AIR QUALITY
1	Pakhar Plateau- Near Office
2	Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4
3	Pakhar Plateau- Pakhar Quarry (109.507 ha. Near Shed)
4	Pakhar Plateau Pakhar Mines(109.507 ha. Yatri Shed)
5	Pakhar Plateau- Pakhar Loading Area (109.507 ha.)
6	Pakhar Plateau-Near Weigh Bridge
	NOISE LEVEL
1	Pakhar Near Office.
2	Pakhar Mine (115.13 ha.) Pakhar Plateau
3	Pakhar Mine (109.507 ha. Loading Area) Pakhar Plateau
4	Pakhar Mine (109.507 Ha Yatri Shed) Pakhar Plateau
5	Pakhar Quary (Near Shed)
	SPOT NOISE LEVEL
1	Near Poclain at Pakhar Mine (115.13 ha.)
2	Loading point near Dumper at Pakhar Mines (109.507 ha. Minerals & Minerals)
	DRINKING WATER
1	Pakhar Mine-Near Canteen
	SURFACE WATER
1	Pakhar Mine-115.13 Quarry





At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Report no: : MEEPL/ JAN0167/2016-17

Date: 30th January, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: [harkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Pakhar Plateau-Near Office

Sample collected on: 29.12.2016

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration 65.2	
01.	Particulate Matter (size less than 10 μm) PM ₁₀	μg/m³	100		
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	32.2	
03.	03. Sulphur Dioxide (SO ₂)		80	26.2	
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	38.5	
05.	Ammonia (NH ₃)	μg/m³	400	18.9	
06.	Ozone (O ₃)	μg/m³	180	19.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.43	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	5.3	
10.	Arsenic (As)	ng/m³	06	2.72	
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.1	
12.	Benzo (a) Pyrene	μg/m³	01	0.34	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Report no: : MEEPL/ JAN0168/2016-17

Date: 30th January, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- Pakhar (115.13 ha.) Quarry No. 4

Sample collected on: 29.12.2016

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration 61.2	
01.	Particulate Matter (size less than 10 μm) PM ₁₀	μg/m³	100		
02.	Particulate Matter (size less than 2.5 µm) PM _{2.5}	μg/m³	60	45.2	
03.	3. Sulphur Dioxide (SO ₂)		80	20.1	
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	31.2	
05.	Ammonia (NH ₃)	μg/m³	400	12.5	
06.	Ozone (O ₃)	μg/m³	180	14.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.52	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	6.3	
10.	Arsenic (As)	ng/m³	06	2.71	
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.10	
12.	Benzo (a) Pyrene	μg/m³	01	0.52	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Report no: : MEEPL/ JAN0169/2016-17

Date: 30th January, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Near Shed)

Sample collected on: 29.12.2016

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μ m) PM ₁₀	less than 10 μm) PM ₁₀ μg/m ³		62.2	
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	33.5	
03.	Sulphur Dioxide (SO ₂)		80	20.4	
04.	Nitrogen Dioxide (NO ₂)		80	41.2	
05.	Ammonia (NH ₃)	μg/m³	400	12.5	
06.	Ozone (O ₃)	μg/m³	180	18.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.52	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	6.5	
10.	Arsenic (As)	ng/m³	06	2.89	
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.10	
12.	Benzo (a) Pyrene	μg/m³	01	0.42	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Report no: : MEEPL/ JAN0170/2016-17

Date: 30th January, 2017

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- Pakhar Quarry 109.507 ha. (Yatri Shed)

Sample collected on: 29.12.2016

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μ m) PM ₁₀	μg/m³	100	43.5	
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	27.8	
03.	. Sulphur Dioxide (SO ₂)		80	23.5	
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	36.8	
05.	Ammonia (NH ₃)	μg/m³	400	12.5	
06.	Ozone (O ₃)	μg/m³	180	19.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.62	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	7.3	
10.	Arsenic (As)	ng/m³	06	2.89	
11.	Benzene (C ₆ H ₆)	μg/m³	05	3.3	
12.	Benzo (a) Pyrene	μg/m³	01	0.52	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Report no: : MEEPL/ JAN0171/2016-17

Date: 30th January, 2017 Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau- 109.507 ha. Loading Area.

Sample collected on: 29.12.2016

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration 64.5	
01.	Particulate Matter (size less than 10 μ m) PM ₁₀	μg/m³	100		
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	41.5	
03.	. Sulphur Dioxide (SO ₂)		80	26.8	
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	41.2	
05.	Ammonia (NH ₃)	μg/m³	400	10.2	
06.	Ozone (O ₃)	μg/m³	180	15.9	
07.	Carbon Monoxide (CO)	mg/m ³	02	0.52	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	8.4	
10.	Arsenic (As)	ng/m³	06	3.00	
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.15	
12.	Benzo (a) Pyrene	μg/m³	01	0.50	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0172/2016-17

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Pakhar Plateau-Near Weigh Bridge

Sample collected on: 29.12.2016

Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration 63.5	
01.	Particulate Matter (size less than 10 μ m) PM_{10}	μg/m³	100		
02.	Particulate Matter (size less than 2.5 μm) PM _{2.5}	μg/m³	60	39.5	
03.	Sulphur Dioxide (SO ₂)		80	32.5	
04.	Nitrogen Dioxide (NO ₂)	μg/m³	80	41.2	
05.	Ammonia (NH ₃)	μg/m³	400	12.1	
06.	Ozone (O ₃)	μg/m³	180	17.2	
07.	Carbon Monoxide (CO)	mg/m³	02	0.60	
08.	Lead (Pb)	μg/m³	1.0	0.05	
09.	Nickel (Ni)	ng/m³	20	8.9	
10.	Arsenic (As)	ng/m³	06	2.95	
11.	Benzene (C ₆ H ₆)	μg/m³	05	2.18	
12.	Benzo (a) Pyrene	μg/m³	01	0.45	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0173/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 29.12.2016

Analyse Date: 30.12.2016

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Near Office	dB (A) L _{eq}	75	53.5	70	47.8	29.12.2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Report no: : MEEPL/ JAN0174/2016-17

Date: 30th January, 2017

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 29.12.2016 Analyse Date: 30.12.2016

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Mines (115.13 ha.)	dB (A) L _{eq}	75	59.8	70	49.1	29.12.2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

LEUNIO F30 PM



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0175/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 29.12.2016 Analyse Date: 30.12.2016

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Mines (109.507 ha. Loading Area)	dB (A) L _{eq}	75	61.8	70	36.2	29.12.2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0176/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 29.12.2016

Analyse Date: 30.12.2016

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Mines (109.507 ha. of Yatri Shed)	dB (A) L _{eq}	75	53.5	70	43.5	29.12.2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0177/2016-17

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 29.12.2016 Analyse Date: 30.12.2016

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result	Dates
Pakhar Quary (Near Shed)	dB (A) L _{eq}	75	52.5	70	44.5	29.12.2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0178/2016-17

Sample described by customer: Measurement of Spot Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: **Measurement of Spot Noise**Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 29.12.2016 Analyse Date: 30.12.2016

Location/Identification	Unit	Limit (day)	Result	Dates
Near Poklen at Pakhar Mines (115.13 ha.)	dB (A) L _{eq}	75	61.5	29.12.2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

Page Ray Chi



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0179/2016-17

Sample described by customer: Measurement of Spot Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: **Measurement of Spot Noise** Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 29.12.2016 Analyse Date: 30.12.2016

Location/Identification	Unit	Limit (day)	Result	Dates
Pakhar Mines (109.507 ha. of Minerals & Minerals) Loading point near Dumper	dB (A) L _{eq}	75	64.5	29.12.2016

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Date: 30th January, 2017

Report no: : MEEPL/ JAN0180/2016-17

Sample described by customer: DRINKING WATER-POTABILITY

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: DRINKING WATER-POTABILITY Marks on Sample: Location: Near Canteen

Quantity: 5 L X 2 No. PVC Can **Sample collected on:**29.12.2016

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method reference
1	Colour	Hazen	<1	5 Max	APHA 22 nd Ed. 2012, 2120- B, 2-6
2	Odour	**	Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
3	Taste	22	Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
4	Turbidity	NTU	0.20	1 Max	APHA 22 nd Ed. 2012, 2130- B, 2-13
5	pH	(44)	7.0	6.5-8.5	APHA 22 nd Ed. 2012, 4500- H+-B, 4-92
6	Free Chlorides (Residual)	mg/l	<0.5	0.2 min	APHA 22 nd Ed. 2012, 4500- CI-G, 4-69
7	Total Dissolved Solids	mg/l	80	500 max	IS 3025 (Part 16): 1984, Reaffirmed 2006
8	Monochloramines	mg/l	<0.05	1441	APHA 22 nd Ed. 2012, 4500- CIG, 4-69
9	Dichioramines	mg/l	<0.05		APHA 22 nd Ed. 2012, 4500- CIG, 4-69
10	Total hardness (as CaCO3)	mg/l	65	200 max	APHA 22 nd Ed. 2012, 4500- CIG, 4-69
11	Alkalinirty Total (as CaCO3)	mg/l	70	200 max	IS 3025 (Part 237): 1986, Reaffirmed 2009
12	Chloride (as CI)	mg/l	10.5	250 max	APHA 22 nd Ed. 2012, 4500- CI-b, 4-72
13	Sulphate (as SO4)	mg/l	4.0	200 max	APHA 22 nd Ed. 2012, 4500- so4-e, 4-190





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Continuation Sheet MEEPL/JAN0180/2016-17

	no: : MEEPL/ JAN0180/2				Date: 30th January, 2017
Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
14	Nitrate (as NO3)	mg/l	1.05	45 max	APHA 22 nd Ed. 2012, 4500-N03-E, 4- 125
15	Fluoride (as F)	mg/l	0.35	1 max	APHA 22 nd Ed. 2012, 4500-FB & D, 4-84, 4-87
16	Boron (as B)	mg/l	0.08	0.5 max	APHA 22nd Ed. 2012, 4500-BB, 4-25
17	Calcium (as Ca)	mg/l	25.6	75 max	APHA 22nd Ed. 2012, 3500-Ca-B, 3-67
18	Magnesium (as Mg)	mg/l	5.0	30 max	APHA 22 nd Ed. 2012, 3500-Mg-B, 3-84
19	Ammonical Nitrogen/Total Ammonia	mg/l	<0.1	-	APHA 22 nd Ed. 2012, 4500-NH3-F, 4- 115
20	Iron (as Fe)	mg/l	0.15	0.3 max	APHA 22nd Ed. 2012, 3111-B, 3-18
21	Manganese (as Mn)	mg/l	N.D	0.1 max	APHA 22nd Ed. 2012, 3111-B, 3-18
22	Aluminium (as Al)	mg/l	0.01	0.03 max	APHA 22nd Ed. 2012, 3500-Al-B, 3-61
23	Cadmium (as Cd)	mg/l	N.D	0.003 max	APHA 22nd Ed. 2012, 3111-B, 3-18
24	Chromium Total (as Cr)	mg/l	N.D	0.05 max	APHA 22nd Ed. 2012, 3111-B, 3-18
25	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22nd Ed. 2012, 3111-B, 3-18
26	Lead (as Pb)	mg/l	N.D	0.01 max	APHA 22nd Ed. 2012, 3111-B, 3-18
27	Zinc (as Zn)	mg/l	0.16	5 max	APHA 22 nd Ed. 2012, 3111-B, 3-18
28	Arsenic (as As)	mg/l	0.007	0.01 max	APHA 22nd Ed. 2012, 3114-B, 3-38
29	Selenium (as Se)	mg/l	N.D	0.001 max	APHA 22nd Ed. 2012, 3112-B, 3-23
30	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22nd Ed. 2012, 3114-B, 3-38
31	Nickel (as Ni)	mg/l	<0.008	0.02 max	APHA 22nd Ed. 2012, 3111-B, 3-18
32	Mineral Oil	mg/l	N.D	0.5 max	IS 3025 (Part 39): 1991, Reaffirmed 2003: ed. 2.1
33	Cyanide (as CN)	mg/l	N.D	0.05 max	APHA 22 nd ED. 2012, 4500-CN.C & 4-39 & 4-44
34	Anionic detergents as MBAS	mg/l	<0.1	0.2 max	APHA 22nd ED. 2012, 5540-C.C & 5-53
35	Phenolic compounds (as C6H5OH)	mg/l	N.D	0.001 max	APHA 22 nd ED. 2012, 5530-B & C 5-4753
36	Polynuclear aromatic hydrocarbons (PAH)	mg/l	N.D	0.0001 max	APHA 22nd ED. 2012, 6440, 6-93
37	Polychlorinated Biphenyls (PCBs)	mg/l	N.D	0.0005 max	USEPA Method 8082
38	Sulphide (as S)	mg/l	N.D	0.05 max	APHA 22 nd ED. 2012, 4500-S2-C 4- 175 & F 4-178





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Continuation Sheet MEEPL/JAN0180/2016-17

	no: : MEEPL/ JAN0180/2	016-1/		D	ate: 30 th January , 201
Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method Reference
Microbio	logical Analysis		-Av		
1	Total Colliforms	MPN/100mL	N.D	<1.1	APHA 22nd Ed. 2012, 9221-B & C, 9-66, 9-69 and 9-67
2	E-Coli	MPN/100mL	N.D	Absent	APHA 22nd Ed. 2012, 9221-B & C, 9-66, 9-69 and 9-76
	es Residues				
3	p.p DDT	μg/L	N.D	1	US EPA 508-1995
4	o.p DDT	μg/L	N.D	1	US EPA 508-1995
5	p.p DDE	μg/L	N.D	1	US EPA 508-1995
6	o.p DDE	μg/L	N.D	1	US EPA 508-1995
7	p.p DDD	μg/L	N.D	1	US EPA 508-1995
8	o.p DDD	μg/L	N.D	1	US EPA 508-1995
9	γ-HCH (Lindance)	μg/L	< 0.01	2	US EPA 508-1995
10	α –HCH	μg/L	< 0.01	0.01	US EPA 508-1995
11	β-нсн	μg/L	N.D	0.04	US EPA 508-1995
12	Б- НСН	μg/L	N.D	0.04	US EPA 508-1995
13	Butachlor	μg/L	N.D	125	US EPA 508-1995
14	Alachlor	μg/L	N.D	20	US EPA 508-1995
15	Atrazine	μg/L	N.D	2	US EPA 508-1995
16	α Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
17	β Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
18	Endosulfan Sulphate	μg/L	N.D	0.4	US EPA 508-1995
19	Ethion	μg/L	N.D	3	US EPA 8141A-1994
20	Malathion	μg/L	N.D	190	US EPA 8141A-1994
21	Methoyl Parathion	μg/L	N.D	0.3	US EPA 8141A-1994
22	Monocrotophos	μg/L	N.D	_ 1	US EPA 8141A-1994
23	Phorate	μg/L	N.D	2	US EPA 8141A-1994
24	Chlorpyrifos	μg/L	N.D	30	US EPA 8141A-1994
25	Aldrin	μg/L	N.D	0.03	US EPA 508-1995
26	Dieldrin N.D- Not Detected	μg/L	N.D	0.03	US EPA 508-1995

Conclusion : The Physical & Chemical Analysis report indicates that the water is not contaminated and potable.

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

Partie Policy Po



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Report no: : MEEPL/ JAN0181/2016-17 **Date: 30th** January , 2017

Sample described by customer: SURFACE WATER - POTABILITY

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: SURFACE WATER

Marks on Sample: Location: 115.13 Quarry

Quantity: 5 L X 2 No. PVC Can **Sample collected on:**29.12.2016

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS 10500:2012)	Method reference
1	Colour	Hazen	<1	5 Max	APHA 22 nd Ed. 2012, 2120- B, 2-6
2	Odour		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
3	Taste	-	Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
4	Turbidity	NTU	0.30	1 Max	APHA 22 nd Ed. 2012, 2130- B, 2-13
5	рН	-22	6.8	6.5-8.5	APHA 22 nd Ed. 2012, 4500- H+-B, 4-92
6	Free Chlorides (Residual)	mg/l	<0.5	0.2 min	APHA 22 nd Ed. 2012, 4500- CI-G, 4-69
7	Total Dissolved Solids	mg/l	124	500 max	IS 3025 (Part 16): 1984, Reaffirmed 2006
8	Monochloramines	mg/l	<0.05	997	APHA 22 nd Ed. 2012, 4500- CIG, 4-69
9	Dichioramines	mg/l	<0.05	57	APHA 22 nd Ed. 2012, 4500- CIG, 4-69
10	Total hardness (as CaCO3)	mg/l	70	200 max	APHA 22 nd Ed. 2012, 4500- CIG, 4-69
11	Alkalinirty Total (as CaCO3)	mg/l	82	200 max	IS 3025 (Part 237): 1986, Reaffirmed 2009
12	Chloride (as CI)	mg/l	8.2	250 max	APHA 22 nd Ed. 2012, 4500- CI-b, 4-72
13	Sulphate (as SO4)	mg/l	7.0	200 max	APHA 22 nd Ed. 2012, 4500- so4-e, 4-190





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262. E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Continuation Sheet MEEPL/JAN0181/2016-17

	no: : MEEPL/ JAN0181/2				Date: 30th January, 2017
Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
14	Nitrate (as NO3)	mg/l	1.20	45 max	APHA 22 nd Ed. 2012, 4500-NO3-E, 4- 125
15	Fluoride (as F)	mg/l	0.3	1 max	APHA 22 nd Ed. 2012, 4500-FB & D, 4-84, 4-87
16	Boron (as B)	mg/l	0.23	0.5 max	APHA 22nd Ed. 2012, 4500-BB, 4-25
17	Calcium (as Ca)	mg/l	18.9	75 max	APHA 22 nd Ed. 2012, 3500-Ca-B, 3-67
18	Magnesium (as Mg)	mg/l	5.2	30 max	APHA 22nd Ed. 2012, 3500-Mg-B, 3-84
19	Ammonical Nitrogen/Total Ammonia	mg/l	<0.1	**	APHA 22nd Ed. 2012, 4500-NH3-F, 4- 115
20	Iron (as Fe)	mg/l	0.10	0.3 max	APHA 22nd Ed. 2012, 3111-B, 3-18
21	Manganese (as Mn)	mg/l	N.D	0.1 max	APHA 22nd Ed. 2012, 3111-B, 3-18
22	Aluminium (as Al)	mg/l	0.01	0.03 max	APHA 22nd Ed. 2012, 3500-Al-B, 3-61
23	Cadmium (as Cd)	mg/l	N.D	0.003 max	APHA 22nd Ed. 2012, 3111-B, 3-18
24	Chromium Total (as Cr)	mg/l	N.D	0.05 max	APHA 22 nd Ed. 2012, 3111-B, 3-18
25	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22 nd Ed. 2012, 3111-B, 3-18
26	Lead (as Pb)	mg/l	N.D	0.01 max	APHA 22nd Ed. 2012, 3111-B, 3-18
27	Zinc (as Zn)	mg/l	0.15	5 max	APHA 22nd Ed. 2012, 3111-B, 3-18
28	Arsenic (as As)	mg/l	< 0.01	0.01 max	APHA 22nd Ed. 2012, 3114-B, 3-38
29	Selenium (as Se)	mg/l	N.D	0.001 max	APHA 22nd Ed. 2012, 3112-B, 3-23
30	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22nd Ed. 2012, 3114-B, 3-38
31	Nickel (as Ni)	mg/l	<0.008	0.02 max	APHA 22nd Ed. 2012, 3111-B, 3-18
32	Mineral Oil	mg/l	N.D	0.5 max	IS 3025 (Part 39): 1991, Reaffirmed 2003: ed. 2.1
33	Cyanide (as CN)	mg/l	N.D	0.05 max	APHA 22 nd ED. 2012, 4500-CN.C & 4-39 & 4-44
34	Anionic detergents as MBAS	mg/l	<0.1	0.2 max	APHA 22 nd ED. 2012, 5540-C.C & 5-53
35	Phenolic compounds (as C6H5OH)	mg/l	N.D	0.001 max	APHA 22 nd ED. 2012, 5530-B & C 5-4753
36	Polynuclear aromatic hydrocarbons (PAH)	mg/l	N.D	0.0001 max	APHA 22nd ED. 2012, 6440, 6-93
37	Polychlorinated Biphenyls (PCBs)	mg/l	N.D	0.0005 max	USEPA Method 8082
38	Sulphide (as S)	mg/l	N.D	0.05 max	APHA 22 nd ED. 2012, 4500-S2-C 4- 175 & F 4-178





At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries: Environmental Monitoring Report

OCT-DEC 2016

Continuation Sheet MEEPL/JAN0181/2016-17

Sl. No.	Parameters	Unit	Result	Acceptable Limit	Method Reference
) XXXXXXXX		(IS 10500:2012)	The thio and the left chee
Microbio	logical Analysis				
1	Total Colliforms	MPN/100mL	N.D	<1.1	APHA 22nd Ed. 2012, 9221-B & C, 9-66, 9-69 and 9-67
2	E-Coli	MPN/100mL	N.D	Absent	APHA 22nd Ed. 2012, 9221-B & C, 9-66, 9-69 and 9-76
Pesticide	s Residues				
3	p.p DDT	μg/L	N.D	1	US EPA 508-1995
4	o.p DDT	μg/L	N.D	1	US EPA 508-1995
5	p.p DDE	μg/L	N.D	1	US EPA 508-1995
6	o.p DDE	μg/L	N.D	1	US EPA 508-1995
7	p.p DDD	μg/L	N.D	1	US EPA 508-1995
8	o.p DDD	μg/L	N.D	1	US EPA 508-1995
9	γ-HCH (Lindance)	μg/L	< 0.01	2	US EPA 508-1995
10	α –HCH	μg/L	< 0.01	0.01	US EPA 508-1995
11	β-НСН	μg/L	N.D	0.04	US EPA 508-1995
12	Б- НСН	μg/L	N.D	0.04	US EPA 508-1995
13	Butachlor	μg/L	N.D	125	US EPA 508-1995
14	Alachlor	μg/L	N.D	20	US EPA 508-1995
15	Atrazine	μg/L	N.D	2	US EPA 508-1995
16	α Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
17	β Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
18	Endosulfan Sulphate	μg/L	N.D	0.4	US EPA 508-1995
19	Ethion	μg/L	N.D	3	US EPA 8141A-1994
20	Malathion	μg/L	N.D	190	US EPA 8141A-1994
21	Methoyl Parathion	μg/L	N.D	0,3	US EPA 8141A-1994
22	Monocrotophos	μg/L	N.D	1	US EPA 8141A-1994
23	Phorate	μg/L	N.D	2	US EPA 8141A-1994
24	Chlorpyrifos	μg/L	N.D	30	US EPA 8141A-1994
25	Aldrin	μg/L	N.D	0.03	US EPA 508-1995
26	Dieldrin	μg/L	N.D	0.03	US EPA 508-1995

Conclusion: The Physical & Chemical Analysis report indicates that the water is not contaminated and potable.

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

SENIOR EXECUTIVE

READ PUL

BREAK UP THE COST OF ENVIRONMENTAL MEASURES DURING THE YEAR 2016-17

The composite cost during the year 2016-17 for environmental protection & pollution control by Jharkhand Mines division of M/s Hindalco Industries Ltd & M/s Minerals & Minerals Ltd for implementation of the suggested measures in EC at our all the operating mines in the state of Jharkhand-namely Pakhar (115,13 Ha), Pakhar (15.58 Ha), Pakhar (109.507 Ha), Pakhar (8.09 Ha), Pakhar (35.12Ha), Serengdag (140.06 Ha), Serengdag (155.81 Ha), Jalim & Sanai (12.14 Ha), Gurdari (584.19 Ha), Amtipani (190.95 Ha), Kujam I (80.97 Ha) Kujam II (157.38 Ha) and Bagru (75.41 Ha), Hisri New (14.55 Ha), Chiro kukud, Orsa pat(196.36 Ha), Bhusar (65.31 Ha)& Bimarla Bauxite Mines (134.52 Ha).

SI No	Description	Budget (in Rupees) FY 2016-17	Actual (in Rupees) FY 2016-17 (from April'16 to Sep'2016)	Actual (in Rupees) FY 2016-17 (from April'16 to March'2017)
1	Pollution Control & Environment monitoring	1540000.00	574975.50	1674221.50
2	Reclamation/ Back filing & Rehabilitation**	4000000.00	33837173.00	74355537.00
3	Green belt, Plantation & Water spraying arrangement	2100000.00	2051751.00	6821323.50
4	Rural Development	2000000.00	10244807.32	21404308.19

^{**}Part of OB removed cost.

(B.K. Mahapatra)

Convenor (Quality & Environment)

Date: 05.09.16

Office Order

Environmental Cell has been re-constituted at Pakhar Bauxite Mines (Area 15.58 Ha) comprising below mentioned team members. The team will ensure compliance of Environment Act, Regulation & Rule in respect of the said mines of Hindalco Industries Limited.

- 1. Mr. Pradeep Kumar Bhaleker- Manager (Coordinator)
- 2. Mr. Akhilesh Singh (Mine Surveyor)-Member
- 3. Mr. Ramnath Bhagat (Mining Mate)-Member

(B.K. Mahapatra)

Convenor (Quality & Environment)

PRODUCTION, MINED OUT, BACKFILLED, PRODUCTION AND OVERBURDEN REMOVAL FROM APR-16 to March-17

Shrengdag Bauxite 155.81 Gurdari Bauxite Mines 584.19 Jalim & Sanai 12.14 Serangdag 140.06 Pakhar Buxite Mines 8.09 Kujam-I 80.87 Kujam-II 157.38 Amtipani 190.95 Chiro-Kukud 152.57 Orsa Bauxite Mines 196.36 Hisri New 14.55 Bhusar 65.31 Bagru 75.41	5.87 12.94 1.04 0.00 3.90 0.00	5.10		
ri Bauxite Mines & Sanai & Sanai sidag r Buxite Mines -I -II -II Kukud auxite Mines ew	12.94 1.04 0.00 3.90 0.00	10.63	258487.00	413395.00
sk Sanai sdag r Buxite Mines r Buxite Mines -I -II Ani Kukud auxite Mines	1.04 0.00 3.90 0.00	., 0	324200.00	428811.00
r Buxite Mines r Buxite Mines -I -II Aukud auxite Mines ew	3.90	0.45	44624.00	36500.00
r Buxite Mines r Buxite Mines -I -II -II Ani Aukud auxite Mines ew	3.90	0.00	0.00	0.00
r Buxite Mines -I -II Ani Auxite Mines ew	0.00	3.40	282190.00	370111.00
-I -II Aukud auxite Mines ew		0.00	0.00	0.00
ani Kukud auxite Mines ew	4.52	4.05	148770.00	272334.00
Kukud auxite Mines ew	8.30	7.85	294830.00	572328.00
Kukud auxite Mines ew	6.61	5.91	149450.00	282375.00
auxite Mines	3.09	2.03	87570.00	154928.20
ew	0.00	00:00	00.00	0.00
	1.77	1.27	00.80986	09206
	0.68	1.38	171961.00	51545.00
	0:00	0.00	0.00	0.00
Minerals & Minerals Limited				
Pakhar Buxite Mines 109.51	3.78	3.28	277220.00	414676.00
Pakhar Buxite Mines 15.58	0.00	0.00	0.00	0.00
Bimarla Bauxite Mines 134.53	5.47	2.61	112730.00	135260.64

(8) prodale.

(B.K. Mahapatra) Convenor (Quality & Environment)

Monitored water level (FY 2016-17)

			Monsoor	Monsoon (July-Sep)	Post Monse	Post Monsoon (November)	Winter	Winter (January)	Pre Mons	Pre Monsoon (April-May)
Location (Mines)	Elevation (Mtr)	Well type	Inside ML	Outside ML	Inside ML	Outside ML	Inside ML	Outside ML	Inside ML	Outside ML
	905	Open Well		21.32		22.70		27.30		29.10
	910	Open Well		24.38		24.56		26.50		27.40
isri new,	915	Open Well		29.00		28.43		29.90		31.35
Bagru & Bhusar)	903	Open Well		22.81		33.15		35.15		35.70
	606	Open Well		20.15		28.72		30.15		30.25
	1000	Open Well		24.93		22.65		25.15		25.85
Pakhar Gr. Of Mines										
(115.13,109.507,15.58,8.	1083	Hand Pump	35.35		31.60		34.2		35.45	
Charanadaa Distanii	1027	Open Well		25.80		28.40		30.15		31.35
9	1094	Hand Pump	41.74		39.55		42.60		42.85	
Sherangdag 140 OK Ha	1081	Hand Pump	39.60		31.30		41.10		42.10	
	1055	Hand Pump	33.00		27.50		35.50		35.65	
	1066	Hand Pump	27.75		26.25		29.10		30.10	
	1045	Hand Pump	29.30		27.70		29.90		30.50	
	1061	Hand Pump	28.30		24.90		25.20		25.90	
Gurdari	1059	Hand Pump	38.10		36.15		35.15		36.25	
	1075	Hand Pump	27.90		26.75		28.40		29.65	
	1075	Hand Pump	28.30		29.30		30.20		30.15	
	1040	Open Well		33.90		21.85		35.15		36.65
Kujam I, Kujam II &	1041	Open Well		33.65		24.80		36.25		39.35
Amtipani Mines	1064	Hand Pump	31.50		28.60		36.10		42.00	
	1052	Hand Pump	22.35			21.05		24.60		23.50
	1148	Hand Pump	33.40		28.30		34.20		37.45	
Chiro Kukud	1151	Hand Pump	37.60		31.80		36.20		36.00	
	1084	Hand Pump	34.20		33.15		35.60		39.50	
								(

(B.K. Mahapatra)
Convenor (Quality & Environment)