

Ref No: HIL/LHD/JP (M)/MoEF/ 946

Date: 25.11.14

To, Joint Director(S) MoEF,GOI, Eastern Regional Office A/3,Chandrashekharpur, Bhubaneshwar- 751023 (Orissa)

Sub: Compliance Report of EC conditions for Pakhar Bauxite Mining (115.13 Ha) project of M/s Hindalco Industries Limited located in Dist- Lohardaga, Jharkhand for the period April'14 to Sep'14.

Ref: Environmental Clearance letter no J-11015/406/2007 -IA II (M) dated 27th Nov 2012

Sir,

With reference to the above, we are submitting herewith the Compliance status report of EC conditions for **Pakhar** Bauxite Mining (115.13 Ha) project of M/s Hindalco located in Lohardaga, Jharkhand for the period **April'14 to Sep'14**.

Hope you will find the same in order.

Thanking You

Yours Sincerely FOR HINDALCO INDUSTRIES LIMITED

(Bijesh Kumar Jha) Joint President (Mines)

Enclosure: - As Above

## ompliance of conditions laid down in Environmental Clearance

## PAKHAR BAUXITE MINES

#### <u>Period</u>: April'14 – Sep'14 <u>Area</u> (115.13 Ha)

## MoEF Environment Clearance ref: No. J-11015/406/2007-IA.II(M) dated 27<sup>th</sup> Nov, 2012

| Sl No Specific Conditions |   | Compliance Status  |  |
|---------------------------|---|--|--|
| (i)                       | The project proponent shall obtain Consent to Operate from the Jharkhand State Pollution Control Board and effectively implement all the conditions stipulated therein.   | implemented.   |  |
| (ii)                      | All the conditions stipulated by the Jharkhand State Pollution Control Board in their NOC shall be effectively implemented.   | Implementations of the stipulated condition are fulfilled.   |  |
| (iii)                     | Corporate Environment Policy and hierarchical system for ensuring adherence to the policy and compliance with environmental regulation in accordance with the office memorandum dated 26.4.2011 issued by MoEF should be put in place.  | Corporate Environment Policy and hierarchical system is in place.  |  |
| (iv)                      | The Company shall submit within 3 month their policy towards Corporate Environment Responsibility which should inter-alia address (i) Standard operating process/procedure to bring Into focus any infringements/ deviation/ violation of environmental or forest norms/conditions, (ii) Hierarchical system or Administrative order of the company to deal with environmental issues and ensuring compliance EC conditions and (iii) System of reporting of non compliance/violation environmental norms to the Board of Directors of the Company and/or stakeholders or shareholders. | Environment responsibility have been submitted at MoEF, Delhi on due date:  (i) Standard operating process/procedure to bring into focus any infringements/ deviation/ violation of environmental or forest norms/conditions, (ii) Hierarchical system or Administrative order of the company to deal with environmental issues and ensuring compliance EC conditions at 1000 cms. |  |

| ( )    |   |  |  |
|--------|---|--|--|
| (vi)   | The environmental clearance is subject to approval of the State Land use Department, Government of Jharkhand for diversion of agricultural land for nonagricultural use.  | by the State Govt after due  |  |
| (VI)   | The critical habitat in the area including dens of python, fox and bear should be protected by adopting appropriate wildlife conservation measures.   | Appropriate wildlife conservation measures are being taken to protect critical habitat in the area.  |  |
| (vii)  | The mining operations shall be restricted to above ground water table and it should not intersect the groundwater table. In case of working below the ground water table, prior approval of the Ministry of Environment and Forests and the Central Ground Water Authority shall be obtained, for which a detailed hydro-geological study shall be carried out. | & the ground water table is much<br>below the working depth. Hence,<br>ground water will not be<br>intersected due to mining   |  |
| (viii) | The project proponent shall ensure that no natural watercourse and/or water resources shall be obstructed due to any mining operations. Adequate measures shall be taken for conservation and protection of the 1st and 2 <sup>nd</sup> order streams, if any emanating or passing through the mine lease during the course of mining operation.                | It is being ensured .No natural water course is obstructed due to mining activities.   |  |
| (ix)   | The top soil shall temporarily be stored at earmarked site(s) only and it should not be kept unutilized for long. The topsoil shall be used for land reclamation and plantation.  | Sequential backfilling and reclamation of the mined out area are being implemented during mining operation. Top soil which is temporarily stored separately spread over the back filled area in the process of reclamation. (enclosed Annexure). |  |

(x)

The over burden (OB) generated during the mining operation shall be temporarily stacked at earmarked dump site(s) only for the purpose of backfilling. Backfilling shall commence from the third year onwards and thereafter the waste generated shall be concurrently backfilled in the mined out area. There shall be no external OB dump. An area of 16.39ha of the worked out pit shall be backfilled and reclaimed by plantation during the plan period. Monitoring and management of rehabilitated areas shall continue until the vegetation becomes self-sustaining. Compliance status should be submitted to the Ministry of Environment & Forests and its Regional Office, Bhubneshwar on six monthly basis.

The over burden (OB) generated during the mining operation temporarily stacked at earmarked dump site(s) only for the purpose of backfilling. Backfilled area will be reclaimed by plantation. Monitoring and management of rehabilitated areas will continue until the vegetation becomes self-sustaining. Compliance status is being submitted to the Ministry of Environment & Forests regularly on six monthly basis.

(xi)

Catch drains and siltation ponds of appropriate size shall be constructed for the working pit, temporary soil, OB and mineral dumps to arrest flow of silt and sediment directly into the agricultural fields, the Chaupat Nadi, the Kisko Nadi, the Shankh Nadi, Kisko Nallah, the Narachiya Nal lah and other water bodies, The water so collected should be utilized for watering the mine area, roads, green belt development etc. The drains should be regularly desilted particularly after the monsoon and maintained properly.

Garland drains, settling tanks and check dams of appropriate size, gradient and length shall be constructed both around the mine pit and temporary over burden dumps to prevent run off of water and flow of sediments directly into the agricultural fields, the Chaupat Nadi, the Kisko Nadi, the Shankh Nadi, Kisko Nallah, the Narachiya Nallah and other water bodies and sump capacity should be designed keeping 50% safety margin over and above peak sudden rainfall (based on 50 years data) and maximum discharge in the area adjoining the mine site. Sump capacity should also provide adequate retention

No run-off is generated from mining activities. However to collect & manage rain water during monsoon, part of mined out area is used as settling tank for the runoff. Rain water stored is being used for watering the mine area, roads, green belt development and sprinkling as necessary.

Garland drains, settling tanks and check dams of appropriate size have been constructed both around the mine pit and temporary over burden dumps to prevent run off of water and flow of sediments directly into the agricultural field and rivers.

|        | period to allow proper settling of silt material. Sedimentation pits should be constructed at the corners of the garland drains and desilted at regular intervals.   |  |  |
|--------|--|--|--|
| (xii)  | Dimension of the retaining wall at the toe of the temporary OB dumps and the OB benches within the mine to check run-off and siltation should be based on the rain fall data.  The dimensions of the of OB dumps are be average rainfall.  |  |  |
| (xiii) | The void left unfilled in an area of 4.5ha shall be converted into water body. The higher benches of excavated void/mining pit shall be terraced and plantation done to stabilize the slopes. The slope of higher benches shall be made gentler for easy accessibility by local people to use the water body. Peripheral fencing shall be carried out all along the excavated area.  |  |  |
| (xiv)  | Plantation shall be raised in an area of 24.09ha including a 7.5m wide green belt in the safety zone around the mining lease by planting the native species around reclaimed area, mine benches, around water body, along the roads etc. in consultation with the local DFO/Agriculture Department. The density of the trees should be around 1500 plants per hectare. Greenbelt shall be developed all along the mine lease area in a phased manner and shall be completed within first five years. | It is already in practice. Phase wise plantation of native species in consultation with forest department is being carried out within the safety zone and mined out/reclaimed pits.      |  |
| (xv)   | Effective safeguard measures such as regular water sprinkling shall be carried out in critical areas prone to air pollution and having high levels of particulate matter such as around crushing and screening plant, loading and unloading point and transfer points. Extensive water sprinkling  | Mobile water tankers have been provided for sprinkling of water on haul roads and are generally being engaged at the places where active mining is in progress to contain fugitive dust. |  |

|         | shall be carried out on haul roads. It should<br>be ensured that the Ambient Air Quality<br>parameters conform to the norms<br>prescribed by the Central Pollution Control<br>Board in this regard.   | AAO parameters are monitored from  |  |
|---------|---|--|--|
| (xvi)   | The project authority should implement suitable conservation measures to augment ground water resources in the area in consultation with the Regional Director, Central Ground Water Board.   | A plan will be drawn on the basis of discussions with Scientists of State unit office of Central Ground Water Board, Ranchi to implement suitable conservation measures to augment ground water resources in the area. |  |
| (xvii)  | Regular monitoring of ground water level and quality shall be carried out in and around the mine lease by establishing a network of existing wells and installing new piezometers during the operation. The periodic monitoring [(at least four times in a year- pre-monsoon (April-May), monsoon (August), post-monsoon (November) and winter (January); once in each season)] shall be carried out in consultation with the State Ground Water Board/Central Ground Water Authority and the data thus collected may be sent regularly to the Ministry of Environment and Forests and its Regional Office Bhubneswar, the Central Ground Water Authority and the Regional Director, Central Ground Water Board. If at any stage, it is observed that the groundwater table is getting depleted due to the mining activity, necessary corrective measures shall be carried out. | augment ground water resources in the area.  This is being done by engaging recognized agency.   |  |
| (xviii) | Appropriate mitigative measures should be taken to prevent pollution of the Chaupat Nadi, the Kisko Nadi and the Shankh Nadi in consultation with the State Pollution Control Board.  | Being complied, There is no discharge of mine water into any drainage network. Monitoring is being done.   |  |
| (xix)   | The project proponent shall obtain necessary prior permission of the competent authorities  | Will be complied, However water cess is being paid regularly to  |  |

|        | for drawl of requisite quantity of ground water, required for the project.  | Jharkhand State Pollution Control Board, Ranchi.  |  |
|--------|---|---|--|
| (xx)   | The project proponent shall practice suitable rainwater harvesting measures on long term basis and work out a detailed scheme for rainwater harvesting in consultation with the Central Groundwater Authority and submit a copy of the same to the Ministry of Environment and Forests and its Regional Office, Bhubneswar.             | A suitable scheme for rainwater harvesting is under preparation.  |  |
| (xxi)  | Vehicular emissions shall be kept under control and regularly monitored. Measures shall be taken for maintenance of vehicles used in mining operations and in transportation of mineral. The mineral transportation shall be carried out through the covered trucks only and the vehicles carrying the mineral shall not be overloaded. | Regular maintenance of vehicles are undertaken to minimize vehicular emission. All the transporters have been instructed to obtain PUC for their vehicles from the competent authority and submit to the concerned officer for verification. Bauxite are transported through tarpaulin cover trucks only. |  |
| (xxii) | Drills shall either be operated with the dust extractors or equipped with water injection system.   | Wet drilling is done in the drill holes intermittently for dust suppression by pumping water.   |  |
| (xiii) | Blasting operation should be carried out only during the daytime. Controlled blasting should be practiced. The mitigative measures for control of ground vibrations and to arrest fly rocks and boulders should be implemented.   | Blasting at Mines is done at fixed blasting period i.e. 12.00 Noon to 1.00 PM on working days. Mobile mining activities are not being practiced during blasting. All the precautionary and mitigative measures to control ground vibration and to arrest fly rocks are being implemented.                 |  |
| (xxiv) | Mineral handling area shall be provided with adequate number of high efficiency dust extraction system. Loading and unloading areas including all the transfer points should also have efficient dust control arrangements. These should be properly maintained and operated.   | We are exploring the possibilities. However, water sprinkling is being carried out regularly at loading and unloading areas as well as at all the transfer points by water sprinkler/ mobile water tanker.  |  |

| (xxv)    | Sewage treatment plant shall be installed for the colony. ETP shall also be provided for the workshop and wastewater generated during the mining operation.   | from mine hence FTP is not  |  |
|----------|---|---|--|
| (xxvi)   | Pre-placement medical examination and periodical medical examination of the workers engaged in the project shall be carried out and records maintained. For the purpose, schedule of health examination of the workers should be drawn and followed accordingly.  | System is already in place.   |  |
| (xxvii)  | It shall be ensured that the fluoride level in<br>the drinking water to be used by the<br>workers in the project as well as to be<br>provided to the public, if any, should meet<br>the prescribed norms in this regard.  | There is no issue found in respect of fluoride in and around the mines. Water monitoring report is annexed with this report.  |  |
| (xxviii) | The project proponent shall take all precautionary measures during mining operation for conservation and protection of endangered fauna namely python, leaf monkey (Presbyits phayrei) etc. spotted in the study area. The critical habitats in the area including dens of python, fox and bear should be protected by adopting appropriate wildlife conservation measures and the conservation plan prepared specific to this project in consultation with the State Forest and Wildlife Department should effectively address the same. All the safeguard measures brought out in the Wildlife Conservation Plan prepared specific to this project site shall be effectively implemented in consultation with the State Forest and Wildlife Department A copy of approved wildlife conservation plan shall be submitted to the Ministry and its Regional Office, Bhubaneswar within 3 months. | onent shall take all sures during mining rvation and protection a namely python, leaf chayrei) etc. spotted in critical habitats in the of python, fox and bear ected by adopting conservation measures plan prepared specific consultation with the Wildlife Department address the same. All res brought out in the tion Plan prepared roject site shall be ented in consultation Gorest and Wildlife of approved wildlife all be submitted to the Regional Office. |  |


| (xxix) | Provision shall he made for the housing of construction labour within the site with all necessary infrastructure and facilities such as fuel for cooking, mobile toilets, mobile sTp, safe drinking water, medical health care, crèche etc. The housing may be in the form of temporary structures to be removed after the completion of the project.   | Necessary infrastructure and facilities are already in place.   |
|--------|---|---|
| (xxx)  | The critical parameters such as RSPM (Particulate matter with size less than 10 micron i.e PM10) and NOx in the ambient air within the impact zone, peak particle velocity at 300m distance or within the nearest habitation, whichever is closer shall be monitored periodically. Further, quality of discharged water shall also be monitored [(TDS, DO, PH and Total Suspended Solids (TSS)]. The monitored data shall be uploaded on the website of the company as well as displayed on a display board at the project site at a suitable location near the main gate of the Company in public domain. The Circular No. J-20012/1/2005-IA.II(M) dated 27.05.2009 issued by Ministry of Environment and Forests, which is available on the website of the Ministry www.envfor.nic.in shall also be referred in this regard for its compliance. | Complied Monitoring Reports is enclosed as <b>Annexure</b> .  Presently, there is no discharge of water from the mines.               |
| (xxxi) | A Final Mine Closure Plan along with details of Corpus Fund shall be submitted to the Ministry of Environment & Forests 5 years in advance of final mine closure for approval.  | Progressive Mine Closure Plan has been duly approved by Indian Bureau of Mine. FMCP related provision will be compiled as per statue. |

| Sl No | <b>General Conditions</b>   | Compliance Status   |  |
|-------|---|---|--|
| (i)   | No change in mining technology and scope of working should be made without prior approval of the Ministry of Environment & Forests.   | Being adhered to.   |  |
| (ii)  | No change in the calendar plan including excavation, quantum of mineral bauxite and waste should be made.   | Excavation of Over Burden and Bauxite is being done as per the approved calendar plan. Details of excavation, quantum of mineral, OB etc have been furnished for the financial year 2014-15 as Annexure |  |
| (iii) | At least four ambient air quality-monitoring stations should be established in the core zone as well as in the buffer zone for RSPM (Particulate matter with size less than 10micron i.e., P1410) and NOx monitoring. Location of the stations should be decided based on the meteorological data, topographical features and environmentally and ecologically sensitive targets and frequency of monitoring should be undertaken in consultation with the State Pollution Control Board. | Complied Monitoring Reports is enclosed as Annexure   |  |
| (iv)  |   |   |  |
|       | Pollution Control Board once in six months.   |   |  |
| (v)   | Fugitive dust emissions from all the sources should be controlled regularly. Water spraying arrangement on haul roads, loading and unloading and at transfer points should be provided and properly maintained.   | Mobile water tankers have been provided for sprinkling of water on haul roads and are generally being engaged at the places where active mining is in progress to arrest fugitive dust emission.        |  |

| (vi)   | Measures should be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operations of HEMM, etc. should be provided with ear plugs / muffs.  | regularly at various locations of the work zone area Workers  |  |
|--------|--|---|--|
| (vii)  | Industrial waste water (workshop and waste water from the mine) should be properly collected, treated so as to conform to the standards prescribed under GSR 422 (E) dated 19th May, 1993 and 31st December, 1993 or as amended from time to time. Oil and grease trap should be installed before discharge of workshop effluents.                                       | There is no effluent discharge from Mine. Workshop has an Oil Catchment Pit to trap oil and grease. It is being ensured to make it operational and effective as and when required.  |  |
| (viii) | Personnel working in dusty areas should wear protective respiratory devices and they should also be provided with adequate training and information on safety and health aspects.  Occupational health surveillance program of the workers should be undertaken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed | Complied. Use of Personal Protective Equipment (PPE) by the individuals is being ensured. All the mine workers are being regularly and periodically sent to our own hospital for health checkup for any contraction of diseases due to exposure in dusty and noisy areas. |  |
|        |  | Training on safety, health and environmental aspects of mining is being regularly imparted through VT centre and also through various other training programmes conducted by the State Government, recognized agencies, etc   |  |
| (ix)   | A separate environmental management cell with suitable qualified personnel should be set-up under the control of a Senior Executive, who will report directly to the Head of the Organization.   | Separate Environmental Management<br>Cell (EMC) has been constituted and<br>is functioning effectively. Copy<br>enclosed as Annexure.   |  |
| (x)    | The funds earmarked for environmental protection measures should be kept in separate account and should not be diverted for other purpose. Year wise expenditure should be reported to the Ministry and its Regional Office located at Bhubaneswar.  | Statement of budgetary provision and actual expenses for environmental protection measure is enclosed as Annexure  It is once again reiterated that the funds so ear marked shall not be  |  |

|        |   | diverted for any other purposes other than it is committed at the beginning of the financial year. |  |
|--------|---|--|--|
| (xi)   | The project authorities should inform to the Regional Office located at Bhubaneswar regarding date of financial closures and final approval of the project by the concerned authorities and the date of start of land development work  | Complied. Yearly date of financial closure is 31 <sup>st</sup> March.                              |  |
| (xii)  | The Regional Office of this Ministry located at Bhubaneswar shall monitor compliance of the stipulated conditions. The project authorities should extend full cooperation to the officer (s) of the Regional Office by furnishing the requisite data / information / monitoring reports.  |  |  |
| (xiii) | The project proponent shall submit six monthly reports on the status of compliance of the stipulated environmental clearance conditions including results of monitored data (both in hard copies as well as by email) to the Ministry of Environment and Forests, its Regional Office Bhubneswar, the respective Zonal Office of Central Pollution Control Board and the State Pollution Control Board. The proponent shall upload the status of compliance of the environmental clearance conditions, including results of monitored data on their website and shall update the same periodically. It shall simultaneously be sent to the Regional Office of the Ministry of Environment and Forests, Bhubneswar, the respective Zonal Officer of Central Pollution Control Board and the State Pollution Control Board. | Being complied   |  |
| (xiv)  | A copy of the clearance letter shall be sent by the proponent to concerned Panchayat, Zila Parisad/ Municipal Corporation, Urban Local Body and the Local NGO, if any, from whom suggestions/ representations, if any, were received while processing the proposal. The clearance letter shall also be put on the website of the Company by the proponent.  | Duly submitted.  |  |

| (xv)   | The State Pollution Control Board should display a copy of the clearance letter at the Regional office, District Industry Centre and the Collector's office/ Tehsildar's Office for 30 days.  | Displayed.            |  |
|--------|---|-----------------------|--|
| (xvi)  | The environmental statement for each financial year ending 31st March in Form-V as is mandated to be submitted by the project proponent to the concerned State Pollution Control Board as prescribed under the Environment (Protection) Rules, 1986, as amended subsequently, shall also be put on the website of the company along with the status of compliance of environmental clearance conditions and shall also be sent to the respective Regional Office of the Ministry of Environment and Forests, Bhubneswar by e-mail.  | Duly submitted.       |  |
| (xvii) | The project authorities should advertise at least in two local newspapers of the District or State in which the project is located and widely circulated, one of which shall be in the vernacular language of the locality concerned, within 7 days of the issue of the clearance letter informing that the project has been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution Control Board and also at web site of the Ministry of Environment and Forests at littp://envfonnic.in and a copy of the same should be forwarded to the Regional Office of this Ministry located at Bhubaneswar. | Complied in due time. |  |



Date: 10.11.14

#### **OFFICE ORDER**

In connection with the earlier office order dated 30.10.2013 the re constituted team of Environment management cell to ensure compliance of various environmental Acts, regulations & rules at Mines Division, Hindalco, Lohardaga as follows:

The Environment Management Cell will consist of:

1. B. K. Mahapatra, AGM (Quality & Environment), Convenor.

#### Members:

- 2. Ajay Kumar Pandey, Manager (Bagru Mines)
- 3. A Anbarasu, Mines Manager (Serengdag Mines)
- 4. S P Jha, Mines Manager (Pakhar Mines)
- 5. Kiran Sankar Singh, Mines Manager (Gurdari)
- 6. Vidya Sagar Singh, Mines Manager (Kujam)
- 7. Amar Bharati, Mines Manager (Amtipani)
- 8. Rajesh Ambastha, Mines Manager (Chiro Kukud & Orsa)
- 9. Biplab Mukherjee (Asst Manager- Geology)

By order

Bijesh Kumar Jha
Joint President (Mines)

Cc to: - All Mines Manager All Department head Notice Board.



#### BREAK UP THE COST OF ENVIRONMENTAL MEASURES DURING THE YEAR 2014-15

The composite cost during the year 2014-15 for environmental protection & pollution control by Jharkhand Mines division of M/s Hindalco Industries Ltd & M/s Minerals & Minerals Ltd for implementation of the suggested measures in EC at our all the operating mines in the state of Jharkhand-namely Pakhar (115,13 Ha), Pakhar (15.58 Ha), Pakhar (109.507 Ha), Pakhar (8.09 Ha), Pakhar (35.12Ha), Serengdag (140.06 Ha), Serengdag (155.81 Ha), Jalim & Sanai (12.14 Ha), Gurdari (584.19 Ha), Amtipani (190.95 Ha), Kujam I (80.97 Ha) Kujam II (157.38 Ha) and Bagru (75.41 Ha), Hisri New (14.55 Ha), Chiro kukud, *Orsa pat(196.36 Ha)*, Bhusar (65.31 Ha)& *Bimarla Bauxite Mines (134.52 Ha*).

| SI | Description                                | Budget (in Lakh Rupees) | Actual (in Lakh Rupees)   |
|----|--|-------------------------|---------------------------|
| No |  | FY 2014-15              | FY 2014-2015              |
|    |  |                         | (from April'14 to Sep'14) |
|    |  |                         |                           |
| 1  | Pollution Control & Environment monitoring | 5.50                    | 6.00                      |
| 2  | Reclamation/ Back filing & Rehabilitation  | 42.50                   | 36.00                     |
| 3  | Green belt & Plantation                    | 60.03                   | 54.46                     |
| 4  | Rural Development                          | 85.29                   | 111.37                    |

<sup>\*\*</sup>Part of OB removed cost.

Convener

Environment Management Cell Hindalco Industries Limited

# PRODUCTION, MINED OUT, BACKFILLED, PRODUCTION AND OVERBURDEN REMOVAL FROM APR-14 TO SEP-14

| JS | Name of Mines               | Mining lease area | Mined Out area | Backfilled area | Production |
|----|-----------------------------|-------------------|----------------|-----------------|------------|
| C  |                             | (на)              | (in Acres)     | (in Acres)      |            |
| 1  | Shrengdag Bauxite Mines     | 155.81            | 7.80           | 4.80            |            |
| 2  | 2 Gurdari Bauxite Mines     | 584.19            | 22.10          | 11.80           |            |
| ω  | 3 Jalim & Sanai             | 12.14             | 0.70           | 0.30            |            |
| 4  | 4 Serangdag                 | 140.07            | 2.00           | 0.50            |            |
| 5  | Pakhar Buxite Mines         | 115.13            | 3.69           | 1.50            |            |
| 6  | 6 Pakhar Buxite Mines       | 8.09              | 0.00           | 0.00            |            |
| 7  | Pakhar Buxite Mines         | 38.95             | 0.00           | 0.00            |            |
| ∞  | 8 Kujam-l                   | 80.87             | 4.15           | 3.46            |            |
| 9  | 9 Kujam-II                  | 157.38            | 13.84          | 12.75           |            |
| 10 | 10 Amtipani                 | 190.95            | 4.03           | 3.26            |            |
| 11 | 11 Chiro-Kukud              | 152.57            | 3.95           | 6.42            |            |
| 12 | 12 Orsa Bauxite Mines       | 196.36            | 0.00           | 0.00            |            |
| 13 | 13 Hisri New                | 14.55             | 1.29           | 0.65            |            |
| 14 | 14 Bagru                    | 75.41             | 0.00           | 0.00            |            |
| 15 | 15 Bhusar                   | 65.31             | 0.94           | 1.50            |            |
|    | Minerals & Minerals Limited |                   |                |                 |            |
| 16 | 16 Pakhar Buxite Mines      | 109.507           | 4.21           | 3.51            |            |
| 17 | Pakhar Buxite Mines         | 15.58             | 0.30           | 0.20            |            |
| 18 | 18 Bimarla Bauxite Mines    | 134.526           | 0.00           | 0.00            |            |

| Location (Mines)         Elevation (Mir by Elevation (Mines)         Well type Post Nonsoon 2014         Monsoon 2014 (Outside MIL Post Monsoon 2014         Post Monsoon 2014 (Outside MIL Post Monsoon 2014         Post Monsoon 2014 (Outside MIL Post Monsoon 2014         Outside MIL Post Monsoon 2014         All State Mile Mile Mile Mile Mile Mile Mile Mil  |                  |                 |           |           |             |           | Fig in meter |
|--|------------------|-----------------|-----------|-----------|-------------|-----------|--------------|
| tion (Mines)         Elevation (Mtr)         Well type         Inside ML         Outside ML         Inside ML           905         Open Well         21.72         21.72         21.72         21.72           910         Open Well         22.330         22.330         22.330         22.330           909         Open Well         22.85         22.85         31.65           1000         Open Well         22.85         31.65           1007         Open Well         25.85         39.54           1003         Hand Pump         35.35         25.85         39.54           1004         Hand Pump         39.65         25.85         39.54           10081         Hand Pump         39.55         25.85         39.54           10081         Hand Pump         33.05         25.85         39.54           1005         Hand Pump         23.05         25.85         39.54           1005         Hand Pump         23.05         25.85         27.55           1005         Hand Pump         28.35         26.25         27.84           1005         Hand Pump         28.35         24.90         26.88           1004         Open Well <td< th=""><th></th><th></th><th></th><th>3</th><th>onsoon 2014</th><th>Post Mi</th><th>onsoon 2014</th></td<>  |                  |                 |           | 3         | onsoon 2014 | Post Mi   | onsoon 2014  |
| 905   Open Well   21.72   910   911   910   915   915   Open Well   29.40   29.40   915   903   Open Well   22.85   909   Open Well   22.85   909   Open Well   24.90   31.65   909   909   Well   24.90   31.65   909   9 | Location (Mines) | Elevation (Mtr) | Well type | Inside ML | Outside ML  | Inside ML | Outside ML   |
| 910   Open Well   24.30   915   915   Open Well   29.40   29.40   903   Open Well   22.85   29.40   909   Open Well   17.55   17.55   31.65   31.30   31.65   31.65    |                  | 905             | Open Well |           | 21.72       |           | 24.15        |
| 915 Open Well 29.40   29.40   903   Open Well 22.85   17.55   1000   Open Well 22.85   17.55   1000   Open Well 24.90   24.90   31.65   1000   Open Well 25.85   24.90   31.65 |                  | 910             | Open Well |           | 24.30       |           | 24.55        |
| 903   Open Well   17.55   17.55   1000   Open Well   17.55   17.55   1000   Open Well   17.55   17.55   1000   Open Well   17.55   1000   Open Well   17.55   1000   31.65   1000 | Barri            | 915             | Open Well |           | 29.40       |           | 28.44        |
| 909   Open Well   17.55   17.60   17.6 | cagic            | 903             | Open Well |           | 22.85       |           | 33.12        |
| r     1000     Open Well     24.90     3.65       r     1083     Hand Pump     35.35     25.85     31.65       1027     Open Well     25.85     39.54     39.54       1094     Hand Pump     41.75     25.85     39.54       1081     Hand Pump     39.65     31.30     27.55       1066     Hand Pump     27.75     26.25       1061     Hand Pump     29.30     27.84       1075     Hand Pump     28.35     24.90       1075     Hand Pump     28.22     26.88       1075     Hand Pump     28.36     29.30       1040     Open Well     33.95     29.30       1064     Hand Pump     28.36     33.95       1064     Hand Pump     31.58     29.30       1052     Hand Pump     31.80     33.65       1084     Hand Pump     33.45     28.65       1084     Hand Pump     33.45     28.65   |                  | 909             | Open Well |           | 17.55       |           | 28.75        |
| r     1083     Hand Pump     35.35     31.65       1027     Open Well     25.85     39.54       1094     Hand Pump     41.75     25.85     39.54       1081     Hand Pump     39.65     31.30     31.30       1055     Hand Pump     27.75     27.55     27.84       1064     Hand Pump     28.35     27.84       1075     Hand Pump     28.22     26.88       1075     Hand Pump     28.36     29.30       1040     Open Well     28.36     33.95       1064     Hand Pump     31.58     33.65       1052     Hand Pump     31.58     28.65       1084     Hand Pump     37.60     31.80       34.80     34.35     36.86  |                  | 1000            | Open Well |           | 24.90       |           | 22.66        |
| 1027 Open Well 25.85 39.54 1094 Hand Pump 41.75 39.54 1081 Hand Pump 39.65 31.30 1055 Hand Pump 27.75 26.25 1066 Hand Pump 29.30 27.84 1061 Hand Pump 28.35 24.90 1075 Hand Pump 28.22 26.88 1075 Hand Pump 28.22 26.88 1075 Hand Pump 28.36 29.30 1040 Open Well 33.65 29.30 1064 Hand Pump 31.58 33.65 1064 Hand Pump 31.58 33.65 1052 Hand Pump 31.58 33.65 1064 Hand Pump 31.58 33.65 33.80 33.80  | Pakhar           | 1083            | Hand Pump | 35.35     |             | 31.65     |              |
| 1094     Hand Pump     41.75     39.54       1081     Hand Pump     39.65     31.30       1085     Hand Pump     33.05     27.55       1066     Hand Pump     29.30     26.25       1061     Hand Pump     29.30     27.84       1059     Hand Pump     28.35     24.90       1075     Hand Pump     28.22     26.28       1075     Hand Pump     28.36     29.30       1040     Open Well     33.95     29.30       1064     Hand Pump     31.58     33.65       1052     Hand Pump     31.58     28.65       1052     Hand Pump     31.58     28.65       1044     Open Well     33.45     28.40       1052     Hand Pump     31.80     31.80       1044     Hand Pump     33.45     28.40   |                  | 1027            | Open Well |           | 25.85       |           | 28.35        |
| ngdag     1081     Hand Pump     39.65     31.30       1055     Hand Pump     33.05     27.55       1066     Hand Pump     27.75     26.25       1045     Hand Pump     29.30     27.84       1061     Hand Pump     28.35     24.90       1075     Hand Pump     28.22     26.88       1075     Hand Pump     28.36     29.30       1040     Open Well     33.95     29.30       1041     Open Well     33.65     28.65       1052     Hand Pump     31.58     28.65       1048     Hand Pump     33.45     28.40       1084     Hand Pump     34.35     36.86  |                  | 1094            | Hand Pump | 41.75     |             | 39.54     |              |
| 1055     Hand Pump     33.05     27.55       1066     Hand Pump     27.75     26.25       1045     Hand Pump     29.30     27.84       1061     Hand Pump     28.35     24.90       1059     Hand Pump     28.22     26.88       1075     Hand Pump     28.36     29.30       1040     Open Well     33.95     29.30       1041     Open Well     33.95     29.30       1052     Hand Pump     31.58     33.65     28.65       1052     Hand Pump     33.45     28.40       (ukud     1151     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86  | Sherengdag       | 1081            | Hand Pump | 39.65     |             | 31.30     |              |
| 1066     Hand Pump     27.75     26.25       1045     Hand Pump     29.30     27.84       1061     Hand Pump     28.35     24.90       1059     Hand Pump     38.15     36.63       1075     Hand Pump     28.22     26.88       1040     Open Well     33.95     29.30       1041     Open Well     33.95     29.30       1052     Hand Pump     31.58     33.65     28.65       1052     Hand Pump     33.45     28.40       (ukud     1151     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86   |                  | 1055            | Hand Pump | 33.05     |             | 27.55     |              |
| 1045     Hand Pump     29.30     27.84       1061     Hand Pump     28.35     24.90       1059     Hand Pump     38.15     36.63       1075     Hand Pump     28.22     26.88       1040     Open Well     33.95     29.30       1041     Open Well     33.95     29.30       1052     Hand Pump     31.58     33.65       1052     Hand Pump     33.45     28.40       1151     Hand Pump     34.35     36.86   |                  | 1066            | Hand Pump | 27.75     |             | 26.25     |              |
| 1061     Hand Pump     28.35     24.90       1059     Hand Pump     38.15     36.63       1075     Hand Pump     28.22     26.88       1040     Open Well     33.95     29.30       1041     Open Well     33.65     29.30       1052     Hand Pump     31.58     28.65       1148     Hand Pump     33.45     28.40       1084     Hand Pump     34.35     36.86  |                  | 1045            | Hand Pump | 29.30     |             | 27.84     |              |
| ri     1059     Hand Pump     38.15     36.63       1075     Hand Pump     28.22     26.88       1075     Hand Pump     28.36     29.30       1040     Open Well     33.95     29.30       1041     Open Well     33.95     29.30       1064     Hand Pump     31.58     28.65       1052     Hand Pump     33.45     28.65       1148     Hand Pump     33.45     28.40       1084     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86   |                  | 1061            | Hand Pump | 28.35     |             | 24.90     |              |
| 1075     Hand Pump     28.22     26.88       1075     Hand Pump     28.36     29.30       1040     Open Well     33.95     29.30       1041     Open Well     33.65     29.30       1064     Hand Pump     31.58     28.65       1052     Hand Pump     31.58     28.65       1148     Hand Pump     33.45     28.40       1151     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86   |                  | 1059            | Hand Pump | 38.15     |             | 36.63     |              |
| 1075     Hand Pump     28.36     29.30       1040     Open Well     33.95     29.30       1041     Open Well     33.65     28.65       1064     Hand Pump     31.58     28.65       1052     Hand Pump     33.45     28.40       1148     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86   |                  | 1075            | Hand Pump | 28.22     |             | 26.88     |              |
| 1040     Open Well     33.95       1041     Open Well     33.65       1064     Hand Pump     31.58     28.65       1052     Hand Pump     3.45     28.65       1148     Hand Pump     33.45     28.40       1151     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86  |                  | 1075            | Hand Pump | 28.36     |             | 29.30     |              |
| 1041     Open Well     33.65       1064     Hand Pump     31.58     28.65       1052     Hand Pump     33.45     28.40       1148     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86   |                  | 1040            | Open Well |           | 33.95       |           | 21.85        |
| 1064     Hand Pump     31.58     28.65       1052     Hand Pump     33.45       1148     Hand Pump     33.45     28.40       1151     Hand Pump     37.60     31.80       1084     Hand Pump     34.35     36.86   |                  | 1041            | Open Well |           | 33.65       |           | 24.82        |
| 1052       Hand Pump       33.45       28.40         1148       Hand Pump       37.60       31.80         1084       Hand Pump       34.35       36.86   |                  | 1064            | Hand Pump | 31.58     |             | 28.65     |              |
| 1148       Hand Pump       33.45         1151       Hand Pump       37.60         1084       Hand Pump       34.35   |                  | 1052            | Hand Pump |           |             |           | 21.12        |
| 1151 Hand Pump 37.60 1084 Hand Pump 34.35  |                  | 1148            | Hand Pump | 33.45     |             | 28.40     |              |
| Hand Pump 34.35  |                  | 1151            | Hand Pump | 37.60     |             | 31.80     |              |
|  |                  | 1084            | Hand Pump | 34.35     |             | 36.86     |              |

Monitored water level





## Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016

Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028, Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com /ecoventures@eco-ventures.in

## Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009

#### PAKHAR PLATEAU- ENVIRONMENTAL MONITORING REPORT

SEPTEMBER 2014

The sail

Vijay Pandey
SENIOR EXECUTIVE

For Mahaba

Authorised Signatory

Bush Shirt S



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

**Hindalco Industries: Environmental Monitoring report** 

Date: 1st October,2014

VILO E

Rainchi

Report no: SEPT004/2014-15

Sample described by customer: SOIL

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India Sample type: SOIL

Received:26.09.2014 Registered: 26.09.2014

Marks on Sample: Location: Pakhar Mines

Sample collected on: 26.09.2014

Quantity: 2 kgs

Test Start/End Date: 26.09.2014/27.09.2014

| S.No | Analysis                    |                                | Method                                | Result     | Unit      |
|------|-----------------------------|--------------------------------|---------------------------------------|------------|-----------|
| 1.   | Colour                      |                                |                                       | Gray       | -         |
| 2.   | Texture                     | ••                             | F.A.U.N (2007)                        | Loamy Sand | -         |
| 3.   | Bulk Density                |                                | By Bulk density Apparatus             | 1.0        | gm/cm3    |
| 4.   | Water Holding Capacity      |                                | F.A.U.N (2007)                        | 23.5       | %         |
| 5.   | pH                          |                                | F.A.U.N (2007)                        | 6.9        |           |
| 6.   | Electrical Conductivity     |                                | F.A.U.N (2007)                        | 20.5       | μs/cm     |
| 7.   | Organic Carbon              |                                |                                       | 0.52       | %         |
| 8.   | Organic Matter              |                                | Black & White Wet Digestion<br>Method | 0.68       | %         |
| 9.   | Available Nitrogen          | **                             | Soil & Water Book by P.K<br>Gupta     | 112.0      | mg/kg     |
| 10.  | Available Phosphorus        | F                              | Soil & Water Book by P.K<br>Gupta     | 14.9       | mg/kg     |
| 11.  | Available Potassium         |                                | Soil & Water Book by P.K<br>Gupta     | 380        | mg/kg     |
| 12.  | Exchangeable Calcium        | Ca                             | Soil & Water Book by P.K<br>Gupta     | 22.5       | meq/100gm |
| 13.  | Exchangeable<br>Magnesium   | Mg                             | Soil & Water Book by P.K<br>Gupta     | 1.89       | meq/100gm |
| 14   | Exchangeable Sodium         | Na                             | Soil & Water Book by P.K<br>Gupta     | 2.23       | meq/100gm |
| 15.  | Exchangeable<br>Potassium   | К                              | Soil & Water Book by P.K<br>Gupta     | 1.48       | meq/100gm |
| 16   | Total Exchangeable<br>Bases |                                | Soil & Water Book by P.K<br>Gupta     | 30.5       | meq/100gm |
| 17   | Manganese                   | Mn                             | USEPA 3052                            | 0.50       | mg/kg     |
| 18   | Arsenic                     | As                             | USEPA 3052                            | 2.30       | mg/kg     |
| 19   | Silica                      | SiO <sub>2</sub>               | USEPA 3052                            | 60.0       | %         |
| 20.  | Aluminum                    | Al <sub>2</sub> O <sub>3</sub> | USEPA 3052                            | 6.9        | %         |
| 21.  | Iron                        | Fe <sub>2</sub> O <sub>3</sub> | USEPA 3052                            | 5.0        | %         |
| 22.  | Calcium                     | CaO                            | USEPA 3052                            | 8.98       | %         |
| 23.  | Magnesium                   | MgO                            | USEPA 3052                            | 1.90       | %         |
| 24.  | Sodium                      | Na <sub>2</sub> O              | USEPA 3052                            | 0.38       | %         |
| 25.  | Potassium                   | K <sub>2</sub> O               | USEPA 3052                            | 0.22       | %         |
| 26.  | Sulphate                    | SO <sub>4</sub>                | USEPA 3052                            | 0.84       | %         |

Vijay Pandey SENIOR EXECUTIVE For Maha'. . .

Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near J B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

#### Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October, 2014

Report no: SEPT004/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Received:28.09.2014 Registered: 28.09.2014

Marks on Sample: Location: Pakhar Plateau- Pakhar Hindalco Colony

Sample collected on: 26.09.2014

Test Start/End Date: 28.09.2014/30.09.2014

| LOCATION / IDI                             | ENTIFICATION: P   | akilar i late |       | ,                                     |            |
|--|-------------------|---------------|-------|---------------------------------------|------------|
| PARAMETERS                                 |                   | UNIT          | LIMIT | метнор                                | 30/09/2014 |
| Sulphur Dioxide                            | SO <sub>2</sub>   | μg/m³         | 80    | IS:5182 (Part-2):2001<br>(Reaff:2006) | 22.1       |
| Nitrogen Dioxide                           | NO2               | μg/m³         | 80    | IS:5182(Part-6):1975<br>(Reaff:2004)  | 25.1       |
| Particulate Matter (size less than 10 μm)  | PM10              | μg/m³         | 100   | IS:5182 (Part 23)                     | 50.5       |
| Particulate Matter (size less than 2.5 μm) | PM <sub>2.5</sub> | μg/m³         | 60    | USEPA CFR(40)<br>Appendix-L           | 29.5       |
| Carbon Monoxide                            | СО                | mg/m³         | 2     | EPA 600/P-99/001F                     | 0.1        |

Vijay Pandey SENIOR EXECUTIVE For Mahalad Transp Eng. Pvt. Ltd.

Authorised Signatory





Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009,

Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

#### Hindalco Industries:Environmental Monitoring report

Date: 1st October, 2014

Report no: SEPT004/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Iharkhand

Country: India Sample type: AMBIENT AIR QUALITY MONITORING

Received:27.09.2014 Registered: 27.09.2014

Marks on Sample: Location: Pakhar Plateau- Pakhar 115.13 Pit

Sample collected on: 26.09.2014

Test Start/End Date: 27.09.2014/29.09.2014

| PARAMETERS                                 |                   | UNIT  | LIMIT | METHOD                                | 29/09/2014 |
|--|-------------------|-------|-------|---------------------------------------|------------|
| Sulphur Dioxide                            | SOz               | μg/m³ | 80    | IS:5182 (Part-2):2001<br>(Reaff:2006) | 65.8       |
| Nitrogen Dioxide                           | NO <sub>2</sub>   | μg/m³ | 80    | IS:5182(Part-6):1975<br>(Reaff:2004)  | 71.2       |
| Particulate Matter (size less than 10 µm)  | PM10              | μg/m³ | 100   | IS:5182 (Part 23)                     | 60.1       |
| Particulate Matter (size less than 2.5 μm) | PM <sub>2.5</sub> | μg/m³ | 60    | USEPA CFR(40)<br>Appendix-L           | 35.2       |
| Carbon Monoxide                            | СО                | mg/m³ | 2     | EPA 600/P-99/001F                     | 0.5        |

Vijay Pandey SENIOR EXECUTIVE For Mai

Frig. Pvt. Ltd.

Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room, Near J B Sawant Bus Stop)
Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

Date: 1st October,2014

Report no: SEPT004/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Received: 27.09.2014 Registered: 27.09.2014

Marks on Sample: Location: Pakhar Plateau- Pakhar 109.507 Dumarpat Village

Sample collected on: 26.09.2014

Test Start/End Date: 27.09.2014/29.09.2014

|  |                   | UNIT  | LIMIT  | METHOD                                | 29/09/2014 |
|--|-------------------|-------|--------|---------------------------------------|------------|
| PARAMETERS                                 |                   | UNII  | Livili | METHOD                                | 27/07/2011 |
| Sulphur Dioxide                            | SO <sub>2</sub>   | μg/m³ | 80     | IS:5182 (Part-2):2001<br>(Reaff:2006) | 23.5       |
| Nitrogen Dioxide                           | NO2:              | μg/m³ | 80     | IS:5182(Part-6):1975<br>(Reaff:2004)  | 52.5       |
| Particulate Matter (size less than 10 μm)  | PM10              | μg/m³ | 100    | IS:5182 (Part 23)                     | 80.2       |
| Particulate Matter (size less than 2.5 μm) | PM <sub>2.5</sub> | μg/m³ | 60     | USEPA CFR(40)<br>Appendix-L           | 45.2       |
| Carbon Monoxide                            | CO                | mg/m³ | 2      | EPA 600/P-99/001F                     | 0.7        |

Vijay Pandey

SENIOR EXECUTIVE

For Mahabal Enviro Eng. Pvt. Ltd.

Authorised Signatory





**Branch Office:** 

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

#### Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October, 2014

Report no: SEPT004/2014-15

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Received: 27.09.2014 Registered: 27.09.2014

Marks on Sample: Location: Pakhar Plateau- Pakhar 84.38 Pokhrapat

Sample collected on:26.09.2014

Test Start/End Date: 27.09.2014/29.09.2014

|  |                  |       |       |                                       | 00 100 1004 |
|--|------------------|-------|-------|---------------------------------------|-------------|
| PARAMETERS                                 |                  | UNIT  | LIMIT | METHOD                                | 29/09/2014  |
| Sulphur Dioxide                            | SO <sub>2</sub>  | μg/m³ | 80    | IS:5182 (Part-2):2001<br>(Reaff:2006) | 50.0        |
| Nitrogen Dioxide                           | NO <sub>2</sub>  | μg/m³ | 80    | IS:5182(Part-6):1975<br>(Reaff:2004)  | 55.1        |
| Particulate Matter (size less than 10 μm)  | PM10             | μg/m³ | 100   | IS:5182 (Part 23)                     | 50.5        |
| Particulate Matter (size less than 2.5 μm) | PM <sub>25</sub> | μg/m³ | 60    | USEPA CFR(40)<br>Appendix-L           | 40.0        |
| Carbon Monoxide                            | CO               | mg/m³ | 2     | EPA 600/P-99/001F                     | 0.5         |

Vijay Pandey SENIOR EXECUTIVE For Managasi Enviso Eng. Pvt. Ltd.

Authorised Signators

Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near | B Sawant Bus Stop)
Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

#### Hindalco Industries:Environmental Monitoring report

Date: 1st October, 2014

Report no: SEPT004/2014-15

Sample Description: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Iharkhand

Country: India Sample Description: Measurement of Noise Level. Sampling Method: Instrumental, Using Sound level Meter

Sampling Done by: Mahabal Enviro.

Test Start: 25.09.2014 End Date: 26.09.2014

| Location / Identification | Unit                  | Limit (day) | Result  | Limit (night) | Result                                    | Dates      |
|---------------------------|-----------------------|-------------|---|---------------|---|------------|
| Month                     |                       |             | Average of 24<br>continuous hours<br>in Sep- 14 |               | Average of 24 continuous hours in Sep- 14 |            |
| Pakhar Mining Area        | dB(A) L <sub>eq</sub> | 75          | 55  | 70            | 49  | 26/09/2014 |

Vijay Pandey SENIOR EXECUTIVE For Mahabal Enviro Eng. Pvt. Ltd.

Authorised Signat

1100



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail:mahabalranchi@gmail.com

#### Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October,2014

Report no: SEPT004/2014-15

Sample described by customer: DRINKING WATER

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India Sample type: DRINKING WATER

Received:21.09.2014 Registered: 21.09.2014

Marks on Sample: Location: Pakhar Plateau - Tap water, Near Colony

Sample collected on: 21.09.2014 Quantity: 5 L X 2 No. PVC Can

Test Start/End Date: 21.09.2014/22.09.2014

Sample collected by: Mahabal EnviroEngineers Pvt Limited

| S.No  | Parameters                               | Unit  | Result    | Acceptable<br>Limit<br>(IS10500:2012) | Method Reference                          |
|-------|--|-------|-----------|---------------------------------------|---|
| 1.    | Colour                                   | Hazen | < 1       | 5 Max                                 | APHA 22nd Ed. 2012, 2120-B,<br>2-6        |
| 2.    | Odour                                    |       | Agreeable | Agreeable                             | IS 3025 (Part 5):1983,<br>Reaffirmed 2006 |
| 3.    | Taste                                    |       | Agreeable | Agreeable                             | IS 3025 (Part 7):1984,<br>Reaffirmed 2006 |
| 4.    | Turbidity                                | NTU   | 0.7       | 1 Max                                 | APHA 22nd Ed. 2012, 2130-B,<br>2-13       |
| 5.    | pH                                       |       | 6.9       | 6.5-8.5                               | APHA 22nd Ed. 2012, 4500-<br>H+-B, 4-92   |
| 6.    | Free Chlorides( Residual)                | mg/l  | <0.05     | 0.2 min                               | APHA 22nd Ed. 2012, 4500-Cl<br>G, 4-69    |
| 7     | Total Dissolved Solids                   | mg/l  | 89        | 500 Max                               | IS 3025 (Part 16):1984<br>Reaffirmed 2006 |
| 8.    | Monochloramines                          | mg/l  | <0.05     | 4                                     | APHA 22nd Ed. 2012, 4500-ClG, 4-69        |
| 9.    | Dichloramines                            | mg/l  | <0.05     |                                       | APHA 22nd Ed. 2012, 4500-ClG, 4-69        |
|       | Total Hardness (as CaCO <sub>3</sub> )   | mg/l  | 59        | 200 Max                               | APHA 22nd Ed. 2012, 2340-C, 2-44,45       |
| 10.   | Alkalinity Total (as CaCO <sub>3</sub> ) | mg/l  | 65        | 200 Max                               | IS 3025 (Part 23):1986<br>Reaffirmed 2009 |
| . 12. | Chloride (as Cl)                         | mg/l  | 7.6       | 250 Max                               | APHA 22nd Ed. 2012, 4500-<br>Cl-B, 4-72   |
| 13.   | Sulphate (as SO <sub>4</sub> )           | mg/l  | 4.3       | 200 Max                               | APHA 22nd Ed. 2012, 4500-<br>SO4-E, 4-190 |



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near J B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

Hindalco Industries:Environmental Monitoring report

September 2014

| S.No | Parameters                                 | Unit | Result | Acceptable<br>Limit (IS<br>10500:2012) | Method Reference                                       |
|------|--|------|--------|--|--|
| 14.  | Nitrate (as NO3)                           | mg/l | 1.14   | 45 Max                                 | APHA 22nd Ed. 2012, 4500-<br>NO <sub>3</sub> -E, 4-125 |
| 15.  | Fluoride (as F)                            | mg/l | 0.20   | 1 Max                                  | APHA 22nd Ed. 2012, 4500-FB& D, 4-<br>84, 4-87         |
| .6.  | Boron (as B)                               | mg/l | 0.19   | 0.5 Max                                | APHA 22nd Ed. 2012, 4500-BB, 4-25                      |
| 17.  | Calcium(as Ca)                             | mg/l | 18.1   | 75 Max                                 | APHA 22nd Ed. 2012, 3500-<br>Ca-B, 3-67                |
| 18.  | Magnesium (as Mg)                          | mg/l | 3.2    | 30 Max                                 | APHA 22nd Ed. 2012, 3500- Mg- B, 3-<br>84              |
| 19.  | Ammonical Nitrogen/<br>Total Ammonia       | mg/l | <0.1   | -                                      | APHA 22nd Ed. 2012, 4500 NH3-F, 4-<br>115              |
| 20.  | Iron (as Fe)                               | mg/l | 0.18   | 0.3 Max                                | APHA 22nd Ed. 2012, 3111-B,3-18                        |
|      | Manganese (as Mn)                          | mg/l | N.D    | 0.1 Max                                | APHA 22nd Ed. 2012, 3111-B, 318                        |
| 21.  | Aluminium (as Al)                          | mg/l | 0.09   | 0.03 Max                               | APHA 22nd Ed. 2012, 3500- Al-B, 3-6.                   |
| 22.  | Cadmium (as Cd)                            | mg/l | N.D    | 0.003 Max.                             | APHA 22nd Ed. 2012, 3111-B,3-18                        |
| 23.  | Chromium (as Cd)  Chromium Total (as Cr)   | mg/l | N.D    | 0.05 Max.                              | APHA 22nd Ed. 2012, 3111-B,3-18                        |
| 24.  | Copper (as Cu)                             | mg/l | N.D    | 0.05 Max.                              | APHA 22nd Ed. 2012, 3111-B,3-18                        |
| 25.  | Lead (as Pb)                               | mg/l | N.D    | 0.01 Max.                              | APHA 22nd Ed. 2012, 3111-B,3-18                        |
| 26.  | Zinc (as Zn)                               | mg/l | 0.03   | 5 Max.                                 | APHA 22nd Ed. 2012, 3111-B,3-18                        |
| 27.  | Arsenic (as As)                            | mg/l | < 0.01 | 0.01 Max.                              | APHA 22nd Ed. 2012, 3114-C,3-38                        |
| 28.  | Mercury (as Hg)                            | mg/l | N.D.   | 0.001 Max.                             | APHA 22nd Ed. 2012, 3112-B,3-23                        |
| 29.  | Selenium (as Se)                           | mg/l | N.D.   | 0.01 Max.                              | APHA 22nd Ed. 2012, 3114-C, 3-38                       |
| 30.  | Nickel (as Ni)                             | mg/l | < 0.06 | 0.02 Max.                              | APHA 22nd Ed. 2012, 3111 B,3-18                        |
| 31.  | Mineral Oil                                | mg/l | N.D.   | 0.5 Max.                               | IS 3025 (Part 39): 1991, Reaffirmed<br>2003, Ed. 2.1   |
| 33.  | Cyanide (as CN)                            | mg/l | N.D.   | 0.05 Max.                              | APHA 22nd Ed. 2012, 4500-<br>CN, C & E, 4-39 & 4-44    |
| 34.  | Anionic detergents as                      | mg/l | <0.1   | 0.2 Max.                               | APHA 22nd Ed. 2012, 5540-C, 5-53                       |
| 35.  | Phenolic compounds (as                     | mg/l | N.D    | 0.001 Max.                             | APHA 22nd Ed. 2012, 5530- B & C, 5                     |
| 36.  | Polynuclear aromatic<br>hydrocarbons (PAH) | µg/L | N.D    | 0.0001 mg/L Max.                       | APHA 22nd Ed. 2012, 6440,<br>6-93                      |
| 37.  | Polychlorinated<br>Biphenyls (PCBs)        | μg/L | N.D    | 0.0005 mg/l Max.                       | USEPA Method 8082  APHA 22nd Ed. 2012, 4500 – S2-C 4   |
| 38.  | Sulphide (as S)                            | mg/l | N.D    |  | 175 & F 4-178  |





<u>Branch Office</u>:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail: mahabalranchi@gmail.com

### Hindalco Industries:Environmental Monitoring report

September 2014

| S.No       | Parameters                         | Unit           | Result | Acceptable<br>Limit (IS<br>10500:2012) | Method Reference   |
|------------|------------------------------------|----------------|--------|--|--|
| Mi arabia  | ological Analysis                  |                | 121    |  | 121 2012 0221 B  |
| 1.         | Total Colliforms                   | MPN/<br>100 mL | <1.1   | N.D                                    | APHA 22nd Ed. 2012, 9221-B<br>& C, 9-66, 9-69              |
| 2.         | E-Coli                             | MPN/<br>100 mL | Absent | N.D                                    | APHA 22nd Ed. 2012, 9221-<br>B, C & G, 9-66, 9-69 and 9-76 |
| Pesticid   | les Residues                       |                |        |  | US EPA 508-1995  |
| 3.         | p,p DDT                            | μg/L           | N.D    | 1                                      | US EPA 508-1995  |
| 4.         | o,p DDT                            | μg/L           | N.D    | 1                                      | US EPA 508-1995  |
| 5.         | p,p DDE                            | μg/L           | N.D    | 1                                      | US EPA 508-1995  |
| 6.         | o,p DDE                            | μg/L           | N.D    | 1                                      | US EPA 508-1995  |
| 7.         | p,p DDD                            | μg/L           | N.D    | 1                                      | US EPA 508-1995  |
| 8.         | o,p DDD                            | μg/L           | N.D    | 1                                      | US EPA 508-1995  |
| 9.         | y-HCH (Lindane)                    | μg/L           | < 0.01 | 2                                      | US EPA 508-1995  |
| 10.        | α-НСН                              | µg/L           | < 0.01 | 0.01                                   | US EPA 508-1995  |
| 11.        | в-нсн                              | μg/L           | N.D    | 0.04                                   | US EPA 508-1995  |
| 12         | δ·HCH                              | µg/L           | N.D    | 0.04                                   |  |
| 13.        | Butachlor                          | μg/L           | N.D    | 125                                    | US EPA 508-1995  |
| 14.        | Alachlor                           | μg/L           | N.D    | 20                                     | US EPA 508-1995  |
| 15 (27.17) | Atrazine                           | μg/L           | N.D    | 2                                      | US EPA 532-2000  |
| 15.        | α Endosulfan                       | µg/L           | N.D    | 0.4                                    | US EPA 508-1995  |
| 16.        | β Endosulfan                       | µg/L           | N.D.   | 0.4                                    | US EPA 508-1995  |
| 17.        | Endosulfan Sulphate                | μg/L           | N.D    | 0.4                                    | US EPA 508-1995  |
| 18.        |                                    | µg/L           | N.D    | 3                                      | US EPA 8141A-1994  |
| 19.        | Ethion                             | µg/L           | N.D    | 190                                    | US EPA 8141A -1994   |
| 20.        | Malathion                          | µg/L           | . N.D  | 0.3                                    | US EPA 8141A -1994   |
| 21.        | Methyl Parathion                   | μg/L           | N.D    | 1                                      | US EPA 8141A-1994  |
| 22.        | Monocrotophos                      | μg/L<br>μg/L   | N.D    | 2                                      | US EPA 8141A -1994   |
| 23.        | Phorate                            | μg/L           | N.D    | 30                                     | US EPA 8141A -1994   |
| 24.        | Chlorpyrifos                       |                | N.D    | 0.03                                   | US EPA 508-1995  |
| 25.        | Aldrin                             | µg/L           | N.D    | 0.03                                   | US EPA 508-1995  |
| 26.        | Dieldrin<br>rks: N.D- Not Detected | μg/L           | II.D   |  |  |

Vijay Pandey SENIOR EXECUTIVE For Mahabal Enviro Eng. Pvt. Ltd.

Authorised Signatory





Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

#### Hindalco Industries: Environmental Monitoring report

September 2014

Date: 1st October, 2014

Report no: SEPT004/2014-15

Sample described by customer: SURFACE WATER

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: SURFACE WATER

Received:21.09.2014 Registered: 21.09.2014

Marks on Sample: Location: Water Harvesting Pond (Pakhar Mines)

Sample collected on: 21.09.2014 Quantity: 5 L X 2 No. PVC Can

Test Start/End Date: 21.09.2014/22.09.2014

Sample collected by: Mahabal EnviroEngineers Pvt Limited

| S.No | Parameters                               | Unit  | Result    | Acceptable<br>Limit<br>(IS10500:2012) | Method Reference                          |
|------|--|-------|-----------|---------------------------------------|---|
| 1.   | Colour                                   | Hazen | < 1       | 5 Max                                 | APHA 22nd Ed. 2012, 2120-B,<br>2-6        |
| 2.   | Odour                                    | -     | Agreeable | Agreeable                             | IS 3025 (Part 5):1983,<br>Reaffirmed 2006 |
| 3.   | Taste                                    |       | Agreeable | Agreeable                             | IS 3025 (Part 7):1984,<br>Reaffirmed 2006 |
| 4.   | Turbidity                                | NTU   | 0.3       | 1 Max                                 | APHA 22nd Ed. 2012, 2130-B,<br>2-13       |
| 5.   | рН                                       | :•:   | 6.9       | 6.5-8.5                               | APHA 22nd Ed. 2012, 4500-<br>H+-B, 4-92   |
| 6.   | Free Chlorides( Residual)                | mg/l  | <0.05     | 0.2 min                               | APHA 22nd Ed. 2012, 4500-Cl<br>G, 4-69    |
| 7    | Total Dissolved Solids                   | mg/l  | 98        | 500 Max                               | IS 3025 (Part 16):1984<br>Reaffirmed 2006 |
| 8.   | Monochloramines                          | mg/l  | <0.05     |                                       | APHA 22nd Ed. 2012, 4500-ClG, 4-69        |
| 9.   | Dichloramines                            | mg/l  | <0.05     |                                       | APHA 22nd Ed. 2012, 4500-ClG, 4-69        |
| 10.  | Total Hardness (as CaCO <sub>3</sub> )   | mg/l  | 45        | 200 Max                               | APHA 22nd Ed. 2012, 2340-C, 2-44,45       |
| 11.  | Alkalinity Total (as CaCO <sub>3</sub> ) | mg/l  | 61        | 200 Max                               | 1S 3025 (Part 23):1986<br>Reaffirmed 2009 |
| 12,  | Chloride (as Cl)                         | mg/l  | 7.0       | 250 Max                               | APHA 22nd Ed. 2012, 4500-<br>CI-B, 4-72   |
| 13.  | Sulphate (as SO <sub>4</sub> )           | mg/l  | 3.9       | 200 Max                               | APHA 22nd Ed. 2012, 4500-<br>SO4-E, 4-190 |



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near | B Sawant Bus Stop) Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

#### Hindalco Industries:Environmental Monitoring report

September 2014

| S.No | Parameters   | Unit | Result  | Acceptable<br>Limit (IS<br>10500:2012) | Method Reference                                       |  |
|------|--|------|---------|--|--|--|
| 14.  | Nitrate (as NO3)   | mg/l | 1.1     | 45 Max                                 | APHA 22nd Ed. 2012, 4500-<br>NO <sub>3</sub> -E, 4-125 |  |
| 15.  | Fluoride (as F)  | mg/l | 0.21    | 1 Max                                  | APHA 22nd Ed. 2012, 4500-FB& D, 4-<br>84, 4-87         |  |
| 16   | Boron (as B)   | mg/l | 0.19, : | 0.5 Max                                | APHA 22nd Ed. 2012, 4500-BB, 4-25                      |  |
| 17.  | Calcium(as Ca)   | mg/l | 15.2    | 75 Max                                 | APHA 22nd Ed. 2012, 3500-<br>Ca-B, 3-67                |  |
| 18.  | Magnesium (as Mg)  | mg/l | 3.9     | 30 Max                                 | APHA 22nd Ed. 2012, 3500- Mg- B, 3-<br>84              |  |
| 19.  | Ammonical Nitrogen/<br>Total Ammonia                     | mg/l | <0.1    | -                                      | APHA 22nd Ed. 2012, 4500 NH3-F, 4-<br>115              |  |
| 20.  | Iron (as Fe)   | mg/l | 0.09    | 0.3 Max                                | APHA 22nd Ed. 2012, 3111-B,3-18                        |  |
| 21.  | Manganese (as Mn)  | mg/l | N.D     | 0.1 Max                                | APHA 22nd Ed. 2012, 3111-B, 318                        |  |
| 22.  | Aluminium (as Al)  | mg/l | 0.06    | 0.03 Max                               | APHA 22nd Ed. 2012, 3500- Al-B, 3-61                   |  |
| 23.  | Cadmium (as Cd)  | mg/l | N.D     | 0.003 Max.                             | APHA 22nd Ed. 2012, 3111-B,3-18                        |  |
| 24.  | Chromium Total (as Cr)                                   | mg/l | N.D     | 0.05 Max.                              | APHA 22nd Ed. 2012, 3111-B.3-18                        |  |
| 25.  | Copper (as Cu)   | mg/l | N.D     | 0.05 Max.                              | APHA 22nd Ed. 2012, 3111-B,3-18                        |  |
| 26.  | Lead (as Pb)   | mg/l | N.D     | 0.01 Max.                              | APHA 22nd Ed. 2012, 3111-B,3-18                        |  |
| 27.  | Zinc (as Zn)   | mg/l | 0.10    | 5 Max.                                 | APHA 22nd Ed. 2012, 3111-B,3-18                        |  |
| 28.  | Arsenic (as As)  | mg/l | < 0.01  | 0.01 Max.                              | APHA 22nd Ed. 2012, 3114-C,3-38                        |  |
| 29.  | Mercury (as Hg)  | mg/l | N.D.    | 0.001 Max.                             | APHA 22nd Ed. 2012, 3112-B,3-23                        |  |
| 30.  | Selenium (as Se)   | mg/l | N.D.    | 0.01 Max.                              | APHA 22nd Ed. 2012, 3114-C, 3-38                       |  |
| 31.  | Nickel (as Ni)   | mg/l | < 0.06  | 0.02 Max.                              | APHA 22nd Ed. 2012, 3111 B,3-18                        |  |
| 32.  | Mineral Oil  | mg/l | N.D.,   | 0.5 Max.                               | IS 3025 (Part 39): 1991, Reaffirmed 2003, Ed. 2.1      |  |
| 33.  | Cyanide (as CN)  | mg/l | N.D.    | 0.05 Max.                              | APHA 22nd Ed. 2012, 4500-<br>CN, C & E, 4-39 & 4-44    |  |
| 34.  | Anionic detergents as<br>MBAS                            | mg/l | <0.1    | 0.2 Max.                               | APHA 22nd Ed. 2012, 5540-C, 5-53                       |  |
| 35.  | Phenolic compounds (as C <sub>6</sub> H <sub>5</sub> OH) | mg/l | N.D     | 0.001 Max.                             | APHA 22nd Ed. 2012, 5530- B & C, 5<br>47               |  |
| 36.  | Polynuclear aromatic<br>hydrocarbons (PAH)               | μg/L | N.D     | 0.0001 mg/L Max.                       | APHA 22nd Ed. 2012, 6440,<br>6-93                      |  |
| 37.  | Polychlorinated<br>Biphenyls (PCBs)                      | μg/L | N.D     | 0.0005 mg/l Max.                       | USEPA Method 8082                                      |  |
| 38.  | Sulphide (as S)  | mg/l | N.D     | *                                      | APHA 22nd Ed. 2012, 4500- S2-C 4-<br>175 & F 4-178     |  |



Head Office: Plot No. F-7, Road No. 21, Wagle Estate, Thane West - 400604, Maharashtra, India (600 m from Hotel Rukhmini Palace Turn Opp Toyota Show Room. Near ] B Sawant Bus Stop)
Phone: 2582 0658/3139/1663/3154 Fax: 91-22-25823543 thane@mahabal.com



Branch Office:

At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

#### Hindalco Industries: Environmental Monitoring report

September 2014

| S.No     | Parameters          | Unit           | Result | Acceptable<br>Limit (IS<br>10500:2012) | Method Reference   |  |
|----------|---------------------|----------------|--------|--|--|--|
| Microbi  | ological Analysis   |                |        |  | The Assets   |  |
| 1.       | Total Colliforms    | MPN/<br>100 mL | <1.1   | N.D                                    | APHA 22nd Ed. 2012, 9221-B<br>& C, 9-66, 9-69              |  |
| 2.       | E-Coli              | MPN/<br>100 mL | Absent | N.D                                    | APHA 22nd Ed. 2012, 9221–<br>B, C & G, 9-66, 9-69 and 9-76 |  |
| Pesticid | es Residues         |                |        |  |  |  |
| 3.       | p,p DDT             | µg/L           | N.D    | 1                                      | US EPA 508-1995  |  |
| 4.       | o.p DDT             | µg/L           | N.D    | 1                                      | US EPA 508-1995  |  |
| 5.       | p.p DDE             | µg/L           | N.D    | 1                                      | US EPA 508-1995  |  |
| 6.       | o,p DDE             | μg/L           | N.D    | 1                                      | US EPA 508-1995  |  |
| 7.       | p,p DDD             | μg/L           | N.D    | 1                                      | US EPA 508-1995  |  |
| 8.       | o,p DDD             | μg/L           | N.D    | 1                                      | US EPA 508-1995  |  |
| 9.       | y-HCH (Lindane)     | µg/L           | < 0.01 | 2                                      | US EPA 508-1995  |  |
| 10.      | α-НСН               | µg/L           | < 0.01 | 0.01                                   | US EPA 508-1995  |  |
| 11.      | β-НСН               | μg/L           | N.D    | 0.04                                   | US EPA 508-1995  |  |
| 12       | δ - НСН             | μg/L           | N.D    | 0.04                                   | US EPA 508-1995  |  |
| 13.      | Butachlor           | μg/L           | N.D    | 125                                    | US EPA 508-1995  |  |
| 14.      | Alachlor            | μg/L           | N.D    | 20                                     | US EPA 508-1995  |  |
| 15.      | Atrazine            | µg/L           | N.D    | 2                                      | US EPA 532-2000  |  |
| 16.      | α Endosulfan        | μg/L           | N.D    | 0.4                                    | US EPA 508-1995  |  |
| 17.      | β Endosulfan        | μg/L           | N.D    | 0.4                                    | US EPA 508-1995  |  |
| 18.      | Endosulfan Sulphate | μg/L           | N.D    | 0.4                                    | US EPA 508-1995  |  |
| 19.      | Ethion              | μg/L           | N.D    | 3                                      | US EPA 8141A-1994  |  |
| 20.      | Malathion           | μg/L           | N.D    | 190                                    | US EPA 8141A -1994   |  |
| 21.      | Methyl Parathion    | μg/L           | N.D    | 0.3                                    | US EPA 8141A -1994   |  |
| 22.      | Monocrotophos       | μg/L           | N.D    | 1                                      | US EPA 8141A-1994  |  |
| 23.      | Phorate             | μg/L           | N.D    | 2                                      | US EPA 8141A -1994   |  |
| 24.      | Chlorpyrifos        | μg/L           | N.D    | 30                                     | US EPA 8141A -1994   |  |
| 25.      | Aldrin              | μg/L           | N.D    | 0.03                                   | US EPA 508-1995  |  |
| 26.      | Dieldrin            | µg/L           | N.D    | 0.03                                   | US EPA 508-1995  |  |

Conclusion: The Physical & Chemical Analysis report indicates that water is not contaminated.

Vijay Pandey
SENIOR EXECUTIVE

For Mahabal Enviro Eng. Pvt. Ltd

Authorised Signatory





Branch Office:
At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262, E-mail:mahabalranchi@gmail.com

#### Hindalco Industries:Environmental Monitoring report

September 2014

Date: 1st October, 2014

Report no: SEPT004/2014-15

Sample Description: Measurement of Noise: Spot Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise Level.
Sampling Method: Instrumental, Using Sound level Meter

Sampling Done by: Mahabal Enviro.

Test Start: 25.09.2014 End Date: 25.09.2014

| Location / Identification         | Unit      | Limit (day) | Result   | Dates      |
|-----------------------------------|-----------|-------------|----------|------------|
| POCKLAN (TATA HITACHI EX 2001 LC) | dB(A) Leq | 75          | 66<br>72 | 25/09/2014 |
| COMPRESSOR (ATLAS XAHS-186)       | dB(A) Leq | 75          |          |            |
| WAGAN DRILL (ROC – 203)           | dB(A) Leq | 75          | 71.4     | 25/09/2014 |
| COMPRESSOR (ATLAS XAHS-186)       | dB(A) Leq | 75          | 69       | 25/09/2014 |

Note: (i) The value is the Leq of twenty readings taken in location (Day time)

Č

Vijay Pandey
SENIOR EXECUTIVE

For Mahas

Manager Signatory

