

HDD-272, PHASE III- NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPUR, C.G. -99 PH - 0771-2972364 / EMAIL-ultimatenviro@gmail.com




Name A Address Of The Customer TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA – IV/4, COAL MINE, VILLAGE – BANKHETA, POST - MILUPARA, DISTT RAIGARH (C.G.) 496 107		REPORT NO LAB REF NO DATE OF REPORT DATE OF SAMPLING	UES/TR/II/18-19/0027 UES/18-19/N/027 18/04/2018 11/04/2018 to 12/04/2018
	SAMI	PLE DETAILS	
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. 6 DATE	M/PO/SRV/1718/0115, dtd. 02.08.2017
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE	COAL MINE (AS DESCRIBE	ED BELOW)
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY	LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION		
SAMPLE QUANTITY/PACKING	NOT APPLICABLE		

	TES	T REPO	RT		
	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
LOCATION		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, BANJIKHOL	dB(A)	68	63	10	
INCLINE AREA, BANJIKHOL	dB(A)	58	44	75	70
BUNKER AREA, BANJIKHOL	dB(A)	72	61		
DG SET AREA, BANJIKHOL	dB(A)	65	56		
WEIGHBRIGE AREA, BANJIKHOL	dB(A)	62	58		
TRUCK PARKING AREA, BANJIKHOL	dB(A)	73	68		
OFFICE AREA, BANKHETA	dB(A)	58	52		
WEIGHBRIGE AREA, BANKHETA	dB(A)	74	60		
		RES	ULT	LIMIT (RESIDENTIAL ZONE	
LOCATION	UNIT	DAY	NIGHT TIME	DAY TIME	NIGHT TIME
Outside Plant					
BANJIKHOL VILLAGE	dB(A)	48	42	55	45
BELJOR VILLAGE	dB(A)	46	39		

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- > The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- > Test sample value retained for 07 days after issue of test report unless otherwise agreed with customer.



--End of the test report......



HDD-272, PHASE III- NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPER, C.G. -99 PH - 0771-2972364 J EMAIL-ultimatenviro@gmail.com




Name & Address Of The Customer TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA – IV/4, COAL MINE, VILLAGE – BANKHETA, POST - MILUPARA, DISTT RAIGARH (C.G.) 496107		REPORT NO UES/TR/II/18-19/0	
	SAM	PLE DETAILS	
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. 6 DATE	N/PO/SRV/1718/0115, dtd. 02.08.2017
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE	COAL MINE (AS DESCRIBE	D BELOW)
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY	LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION		
SAMPLE QUANTITY/PACKING	NOT APPLICABLE		

	TES	T REPO	RT		
	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
LOCATION		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, BANJIKHOL	dB(A)	61	56	10	
INCLINE AREA, BANJIKHOL	dB(A)	69	65	75	70
BUNKER AREA, BANJIKHOL	dB(A)	72	68		
DG SET AREA, BANJIKHOL	dB(A)	59	64		
WEIGHBRIGE AREA, BANJIKHOL	dB(A)	62	59		
TRUCK PARKING AREA, BANJIKHOL	dB(A)	68	57		
OFFICE AREA, BANKHETA	dB(A)	56	54		
WEIGHBRIGE AREA, BANKHETA	dB(A)	70	64		
		RES	ULT	LIMIT (RESID	ENTIAL ZONE)
LOCATION	UNIT	DAY	NIGHT TIME	DAY TIME	NIGHT TIME
Outside Plant					
BANJIKHOL VILLAGE	dB(A)	53	40	55	45
BELJOR VILLAGE	dB(A)	52	38		

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- > Test sample retained for 07 days after issue of test report unless otherwise agreed with customer.





HDD-272, PHASE III- NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPUR, C.G. -99 PH - 0771-2972364 J EMAIL-ultimatenviro@gmail.com



TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA – IV/4, COAL MINE, VILLAGE – BANKHETA, POST - MILUPARA, DISTT RAIGARH (C.G.) 496107		REPORT NO	UES/TR/II/18-19/0541	
		LAB REF NO	UES/18-19/N/541	
		DATE OF REPORT	30/06/2018	
		DATE OF SAMPLING	25/06/2018 to 26/06/201	
	SAM	PLE DETAILS	~	
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. 6 DATE	N/FO/SRV/1718/0115, dtd. 02.08.2017	
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE	COAL MINE (AS DESCRIE	RED BELOW)	
SAMPLE COLLECTED BY	LABORATORY CHEMIST			
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION			

	TES	T REPO	RT		
		RESULT		LIMIT (INDUSTRIAL ZONE)	
LOCATION	UNIT	DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, BANJIKHOL	dB(A)	54	51		
INCLINE AREA, BANJIKROL	dB(A)	68	67	75	70
BUNKER AREA, BANJIKHOL	dB(A)	71	68		
DG SET AREA, BANJIKHOL	dB(A)	62	59		
WEIGHBRIGE AREA, BANJIKHOL	dB(A)	58	56		
TRUCK PARKING AREA, BANJIKHOL	dB(A)	64	60		
OFFICE AREA, BANKHETA	dB(A)	52	51		
MEIGHBRIGE AREA, BANKHETA	dB(A)	69	66		
		RES	ULT	LIMIT (RESIDENTIAL ZON	
LOCATION	UNIT	DAY	NIGHT	DAY TIME	NIGHT TIME
Outside Plant					
BANJIKHOL VILLAGE	dB(A)	49	42	55	45
BELJOR VILLAGE	dB(A)	51	44		0000

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- Test sample will temptained for 07 days after issue of test report unless otherwise agreed with customer.

For ULTIMATE ENVIROLYTICAL SOLUTIONS

AUTHORIZED SIGNATORY

-----End of the test report.....



HDD-272, PHASE III- NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPER, C.G. -99 PH - 0771-2972364 J EMAIL-ultimatenviro@gmail.com



Name & Address Of The Customer TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA – IV/4, COAL MINE,VILLAGE – BANKHETA, POST -MILUPARA, DISTT RAIGARH (C.G.) 496107		REPORT NO LAB REF NO DATE OF REPORT DATE OF SAMPLING	UES/TR/II/18-19/0768 UES/18-19/N/768 26/07/2018 11/07/2018 to 12/07/2018		
	and the same of th	PLE DETAILS	- 		
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. 6 DATE	M/F0/SRV/1718/0115, dtd. 02.08.2017		
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE	COAL MINE (AS DESCRIE	RED BELOW)		
SAMPLE COLLECTED BY	LABORATORY CHEMIST				
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION				

	TES	T REPO	RT		
		RES	ULT	LIMIT (INDUSTRIAL ZONE)	
LOCATION	UNIT	DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, BANJIKHOL	dB(A)	54	49		
INCLINE AREA, BANJIKROL	dB(A)	65	64	75	70
BUNKER AREA, BANJIKHOL	dB(A)	68	64		
DG SET AREA, BANJIKHOL	dB(A)	61	56		
WEIGHBRIGE AREA, BANJIKHOL	dB(A)	52	53		
TRUCK PARKING AREA, BANJIKHOL	dB(A)	58	54		
OFFICE AREA, BANKHETA	dB(A)	51	50		
MEIGHBRIGE AREA, BANKHETA	dB(A)	58	61		
		RES	ULT	LIMIT (RESIDENTIAL ZO	
LOCATION	UNIT	DAY	NIGHT	DAY TIME	NIGHT TIME
Outside Plant					
BANJIKHOL VILLAGE	dB(A)	49	40	55	45
BELJOR VILLAGE	dB(A)	52	43		

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- Test sample will to retained for 07 days after issue of test report unless otherwise agreed with customer.

For ULTIMATE ENVIROLYTICAL SOLUTIONS

AUTHORIZED SIGNATORY

-----End of the test report.....



HDD-272, PHASE III- NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPER, C.G. -99 PH - 0771-2972364 J EMAIL-ultimatenviro@gmail.com



TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA – IV/4, COAL MINE, VILLAGE – BANKHETA, POST - MILUPARA, DISTT RAIGARH (C.G.) 496107		REPORT NO	UES/TR/18-19/01086	
		LAB REF NO	UES/18-19/N/1086	
		DATE OF REPORT	30/08/2018	
		DATE OF SAMPLING	18/08/2018 to 19/08/201	
	SAM	PLE DETAILS	~	
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. 6 DATE	M/PO/SRV/1819/0085, DTD. 07.08.2018	
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE	COAL MINE (AS DESCRIE	BED BELOW)	
SAMPLE COLLECTED BY	LABORATORY CHEMIST			
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION			

	TES	T REPO	RT		
	UNIT	RES	BULT	LIMIT (INDUSTRIAL ZONE)	
LOCATION		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, BANJIKHOL	dB(A)	55	52		
INCLINE AREA, BANJIKHOL	dB(A)	66	62		70
BUNKER AREA, BANJIKHOL	dB(A)	68	64		
DG SET AREA, BANJIKHOL	dB(A)	62	58		
WEIGHBRIGE AREA, BANJIKHOL	dB(A)	56	58	75	
TRUCK PARKING AREA, BANJIKHOL	dB(A)	59	57		
OFFICE AREA, BANKHETA	dB(A)	51	49		
MEIGHBRIGE AREA, BANKHETA	dB(A)	59	55		
		RES	ULT	LIMIT (RESIDENTIAL ZO	
LOCATION	UNIT	DAY	NIGHT TIME	DAY TIME	NIGHT TIME
Outside Plant					
BANJIKHOL VILLAGE	dB(A)	50	42	55	45
BELJOR VILLAGE	dB(A)	52	44		985

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- Test sample will be retained for 07 days after issue of test report unless otherwise agreed with customer.
- This is for information as the party has asked for above test(s) only.



-----End of the test report.....



HDD-272, PHASE III- NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPER, C.G. -99 PH - 0771-2972364 | EMAIL-ultimatenviro@gmail.com



TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA – IV/4, COAL MINE,VILLAGE – BANKHETA, POST -MILUPARA, DISTT RAIGARH (C.G.) 496107		REPORT NO LAB REF NO DATE OF REPORT DATE OF SAMPLING	UES/TR/II/18-19/01445 UES/18-19/N/1445 02/10/2018 27/09/2018 to 28/09/2018		
	SAM	PLE DETAILS	10 10 N N N		
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. 6 DATE	M/PO/SRV/1819/0085, DTD: 07.08.2018		
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE	COAL MINE (AS DESCRIE	BED BELOW)		
SAMPLE COLLECTED BY	LABORATORY CHEMIST				
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION				

	TES	T REPO	RT		
	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
LOCATION		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, BANJIKHOL	dB(A)	54	51		
INCLINE AREA, BANJIKHOL	dB(A)	64	61		70
BUNKER AREA, BANJIKHOL	dB(A)	66	60		
DG SET AREA, BANJIKHOL	dB(A)	63	55		
WEIGHBRIGE AREA, BANJIKHOL	dB(A)	56	52	75	
TRUCK PARKING AREA, BAMJIKHOL	dB(A)	59	55		
OFFICE AREA, BANKHETA	dB(A)	51	48		
MEIGHBRIGE AREA, BANKHETA	dB(A)	60	56	1	
100000000000000000000000000000000000000	4000000	RES	ULT	LIMIT (RESIDENTIAL ZONE	
LOCATION	UNIT	DAY	NIGHT TIME	DAY TIME	NIGHT TIME
Outside Plant					
BANJIKHOL VILLAGE	dB(A)	52	41	55	45
BELJOR VILLAGE	dB(A)	49	40		

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- > Test sample will be retained for 07 days after issue of test report unless otherwise agreed with customer.
- > This is for information as the party has asked for above test(s) only.



------End of the test report.....