

Format No.: UES/FORM/09

 <b>Ultimate</b> ENVIROLYTICAL SOLUTIONS HAS ACCREDITED & CHECK APPROVED LABORATORY	HODD-272, PHASE III - NEAR JP CHOWK, KING ROAD NO -2, KAHIR NAGAR, RAIPUR, C.G. -99 PH - 0771-2972364   EMAIL-ultimatenviro@gmail.com	

Name & Address Of The Customer <b>TO,          HINDALCO INDUSTRIES LIMITED,          GARE PALMA - IV/5, COAL MINE,          VILLAGE - BANKHETA, POST -          MILUPARA, DISTT. - RAIGARH (C.G.)          496 107.</b>		REPORT NO UES/TR/II/18-19/0042	
		LAB REF NO UES/18-19/N/042	
		DATE OF REPORT 18/04/2018	
		DATE OF SAMPLING 11/04/2018 to 12/04/2018	
<b>SAMPLE DETAILS</b>			
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. & DATE	N/PO/SRV/1718/0115, DTD. 02.08.2017
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE COAL MINE (AS DESCRIBED BELOW)		
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY	LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION		
SAMPLE QUANTITY/PACKING	NOT APPLICABLE		

<b>TEST REPORT</b>					
LOCATION	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, MILUPARA	DB (A)	62	59	75	70
INCLINE AREA, MILUPARA	DB (A)	72	63		
BUNKER AREA, MILUPARA	DB (A)	62	58		
DG SET AREA, KONDKEL	DB (A)	69	61		
WEIGHERIGE AREA, MILUPARA	DB (A)	56	48		
OFFICE AREA, KONDKEL	DB (A)	68	60		
BUNKER AREA, KONDKEL	DB (A)	70	65		
LOCATION	UNIT	RESULT		LIMIT (RESIDENTIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
<b>Outside Plant</b>					
SIDARPARA VILLAGE	DB (A)	48	40	55	45
HILL COLONY, KONDKEL	DB (A)	42	38		
HILL STAFF QUARTER, MILUPARA	DB (A)	44	36		

**REMARKS: RESULTS ARE AS ABOVE****Terms & conditions**

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- Test samples will be retained for 07 days after issue of test report unless otherwise agreed with customer.

	For <b>ULTIMATE ENVIROLYTICAL SOLUTIONS</b>  <b>AUTHORIZED SIGNATORY</b>
---	--

-----End of the test report.....

Format No.: UES/FORM/09

 <b>Ultimate</b> ENVIROLYTICAL SOLUTIONS <small>NAB ACCREDITED &amp; CMA APPROVED LABORATORY</small>	HDD-272, PHASE III- NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPUR, C.G. -99 PH - 0771-2972364   EMAIL-ultimatenviro@gmail.com	

Name & Address Of The Customer <b>TO,          HINDALCO INDUSTRIES LIMITED,          GARE PALMA - IV/5, COAL MINE,          VILLAGE - BANKHETA, POST -          MILUPARA, DISTT. - RAIGARH (C.G.)          496107</b>		REPORT NO UES/TR/II/18-19/0256	
		LAB REF NO UES/18-19/N/256	
		DATE OF REPORT 16/05/2018	
		DATE OF SAMPLING 10/05/2018 to 11/05/2018	
<b>SAMPLE DETAILS</b>			
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. & DATE	N/PO/SRV/1718/0115, DTD. 02.08.2017
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE COAL MINE (AS DESCRIBED BELOW)		
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY	LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION		
SAMPLE QUANTITY/PACKING	NOT APPLICABLE		

<b>TEST REPORT</b>					
LOCATION	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, MILUPARA	DB (A)	66	61	75	70
INCLINE AREA, MILUPARA	DB (A)	73	70		
BUNKER AREA, MILUPARA	DB (A)	64	60		
DG SET AREA, KONKEL	DB (A)	67	63		
WEIGHBRIDGE AREA, MILUPARA	DB (A)	60	54		
OFFICE AREA, KONKEL	DB (A)	65	57		
BUNKER AREA, KONKEL	DB (A)	71	61		
LOCATION	UNIT	RESULT		LIMIT (RESIDENTIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
<b>Outside Plant</b>					
SIDARPARA VILLAGE	DB (A)	49	39	55	45
HIL COLONY, KONKEL	DB (A)	52	41		
HIL STAFF QUARTER, MILUPARA	DB (A)	45	37		

**REMARKS: RESULTS ARE AS ABOVE****Terms & conditions**

- > The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- > Test sample will be retained for 07 days after issue of test report unless otherwise agreed with customer.

	For <b>ULTIMATE ENVIROLYTICAL SOLUTIONS</b>  <b>AUTHORIZED SIGNATORY</b>
---	---

-----End of the test report-----

Format No.: UES/FORM/09



HDD-272, PHASE III - NEAR JP CHOWK,  
RING ROAD NO -2, KABIR NAGAR, RAIPUR, C.G. -99  
PH - 0771-2972364 | EMAIL-ultimatenviro@gmail.com



<b>Name &amp; Address Of The Customer</b>		REPORT NO	UES/TR/II/18-19/0555
<b>TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA - IV/5, COAL MINE, VILLAGE - BANKHETA, POST -MILUPARA, DISTT. - RAIGARH (C.G.) 496 107</b>		LAB REF NO	UES/18-19/N/555
		DATE OF REPORT	30/06/2018
		DATE OF SAMPLING	25/06/2018 to 26/06/2018
<b>SAMPLE DETAILS</b>			
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. & DATE	M/PO/SRV/1718/0115, DTD. 02.08.2017
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE COAL MINE (AS DESCRIBED BELOW)		
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY	LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION		
SAMPLE QUANTITY/PACKING	NOT APPLICABLE		

### TEST REPORT

LOCATION	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, MILUPARA	DB (A)	56	52	75	70
INCLINE AREA, MILUPARA	DB (A)	65	66		
BUNKER AREA, MILUPARA	DB (A)	68	60		
DG SET AREA, KONDKEL	DB (A)	64	58		
WEIGHERIE AREA, MILUPARA	DB (A)	58	53		
OFFICE AREA, KONDKEL	DB (A)	57	52		
BUNKER AREA, KONDKEL	DB (A)	70	65		
LOCATION	UNIT	RESULT		LIMIT (RESIDENTIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
<b>Outside Plant</b>					
SIDARPADA VILLAGE	DB (A)	49	40	55	45
HIL COLONY, KONDKEL	DB (A)	52	42		
HIL STAFF QUARTER, MILUPARA	DB (A)	46	38		

**REMARKS: RESULTS ARE AS ABOVE**

**Terms & conditions**

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- Test sample will be retained for 07 days after issue of test report unless otherwise agreed with customer.

	For <b>ULTIMATE ENVIROLYTICAL SOLUTIONS</b>   <b>AUTHORIZED SIGNATORY</b>
--	--

-----End of the test report-----

Format No.: UES/FORM/09



HDD-272, PHASE III - NEAR JP CHOWK,  
RING ROAD NO -2, KASBI NAGAR, RAIPUR, C.G. -99  
PH - 0771-2972364 / EMAIL-ultimatenviro@gmail.com



<b>Name &amp; Address Of The Customer</b>		REPORT NO	UES/TR/II/18-19/0787
<b>TO, HINDALCO INDUSTRIES LIMITED, GARE PALMA - IV/5, COAL MINE, VILLAGE - BANKHETA, POST - MILUPARA, DISTT. - RAIGARH (C.G.) 496 107</b>		LAB REF NO	UES/18-19/N/787
		DATE OF REPORT	26/07/2018
		DATE OF SAMPLING	11/07/2018 to 12/07/2018
<b>SAMPLE DETAILS</b>			
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. & DATE	M/PO/SRV/1718/0115, DTD. 02.08.2017
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE COAL MINE (AS DESCRIBED BELOW)		
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY	LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION		
SAMPLE QUANTITY/PACKING	NOT APPLICABLE		

<b>TEST REPORT</b>					
LOCATION	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, MILUPARA	dB(A)	58	54	75	70
INCLINE AREA, MILUPARA	dB(A)	67	62		
BUNKER AREA, MILUPARA	dB(A)	59	65		
DG SET AREA, KONDKEL	dB(A)	65	52		
WEIGHBRIDGE AREA, MILUPARA	dB(A)	62	55		
OFFICE AREA, KONDKEL	dB(A)	58	53		
BUNKER AREA, KONDKEL	dB(A)	71	65		
LOCATION	UNIT	RESULT		LIMIT (RESIDENTIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
<b>Outside Plant</b>					
SIDARPARA VILLAGE	dB(A)	48	39	55	45
HIL COLONY, KONDKEL	dB(A)	51	41		
HIL STAFF QUARTER, MILUPARA	dB(A)	42	38		

**REMARKS: RESULTS ARE AS ABOVE****Terms & conditions**

- > The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- > Test sample will be retained for 07 days after issue of test report unless otherwise agreed with customer.

	For <b>ULTIMATE ENVIROLYTICAL SOLUTIONS</b>   <b>AUTHORIZED SIGNATORY</b>
--	--

-----End of the test report-----

Format No.: UES/FORM/09

 <b>Ultimate</b> ENVIROLYTICAL SOLUTIONS NAB ACCREDITED & CHECK APPROVED LABORATORY	HODD-272, PHASE III - NEAR JP CHOWK, KING ROAD NO -2, KAHIR NAGAR, RAIPUR, C.G. -99 PH - 0771-2972364   EMAIL-ultimatenviro@gmail.com	

Name & Address Of The Customer		REPORT NO	UES/TR/II/18-19/01098
<b>TO,          HINDALCO INDUSTRIES LIMITED, GARE          PALMA - IV/5, COAL MINE, VILLAGE -          BANKHETA, POST - MILUPARA, DISTT. -          RAIGARH (C.G.) 496 107</b>		LAB REF NO	UES/18-19/N/1098
		DATE OF REPORT	30/08/2018
		DATE OF SAMPLING	18/08/2018 to 19/08/2018
<b>SAMPLE DETAILS</b>			
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. & DATE	M/PO/SRV/1819/0084, DTD. 07.08.2018
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE COAL MINE (AS DESCRIBED BELOW)		
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY	LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION		
SAMPLE QUANTITY/PACKING	NOT APPLICABLE		

<b>TEST REPORT</b>					
LOCATION	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, MILUPARA	DB (A)	54	51	75	70
INCLINE AREA, MILUPARA	DB (A)	66	62		
BUNKER AREA, MILUPARA	DB (A)	67	63		
DG SET AREA, KONDKEL	DB (A)	64	60		
WEIGHERIE AREA, MILUPARA	DB (A)	62	58		
OFFICE AREA, KONDKEL	DB (A)	58	54		
BUNKER AREA, KONDKEL	DB (A)	60	55		
LOCATION	UNIT	RESULT		LIMIT (RESIDENTIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
<b>Outside Plant</b>					
SIDARPARA VILLAGE	DB (A)	48	38	55	45
HIL COLONY, KONDKEL	DB (A)	52	42		
HIL STAFF QUARTER, MILUPARA	DB (A)	50	37		

**REMARKS: RESULTS ARE AS ABOVE****Terms & conditions**

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- Test sample will be retained for 07 days after issue of test report unless otherwise agreed with customer.

	For <b>ULTIMATE ENVIROLYTICAL SOLUTIONS</b>    <b>AUTHORIZED SIGNATORY</b>
---	--

-----End of the test report-----

Format No.: UES/FORM/09

 <b>Ultimate</b> ENVIROLYTICAL SOLUTIONS HAS ACCREDITED & CHECK APPROVED LABORATORY	HDD-272, PHASE III - NEAR JP CHOWK, RING ROAD NO -2, KABIR NAGAR, RAIPUR, C.G. -99. PH - 0771-2972364   EMAIL-ultimatenviro@gmail.com	

Name & Address Of The Customer <b>TO,          HINDALCO INDUSTRIES LIMITED, GARE          PALMA - IV/5, COAL MINE,          VILLAGE - BANKHETA,          POST -MILUPARA,          DISTT. - RAIGARH (C.G.) 496 107</b>		REPORT NO UES/TR/II/18-19/01457
		LAB REF NO UES/18-19/N/1457
		DATE OF REPORT 02/10/2018
		DATE OF SAMPLING 27/09/2018 to 28/09/2018
<b>SAMPLE DETAILS</b>		
MONITORING FOR	NOISE LEVEL MONITORING	CUSTOMER REF. NO. & DATE M/PO/SRV/1819/0084, DTD. 07.08.2018
SAMPLING LOCATION	INSIDE COAL MINE & OUTSIDE COAL MINE (AS DESCRIBED BELOW)	
SAMPLE RECEIVED ON	MONITORING AT	SAMPLE COLLECTED BY LABORATORY CHEMIST
SAMPLING PROCEDURE	MANUFACTURER'S INSTRUCTION	
SAMPLE QUANTITY/PACKING	NOT APPLICABLE	

<b>TEST REPORT</b>					
LOCATION	UNIT	RESULT		LIMIT (INDUSTRIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
OFFICE AREA, MILUPARA	DB (A)	56	52	75	70
INCLINE AREA, MILUPARA	DB (A)	64	60		
BUNKER AREA, MILUPARA	DB (A)	62	59		
DG SET AREA, KONDKEL	DB (A)	69	64		
WEIGHERIDGE AREA, MILUPARA	DB (A)	61	58		
OFFICE AREA, KONDKEL	DB (A)	57	52		
BUNKER AREA, KONDKEL	DB (A)	67	61		
LOCATION	UNIT	RESULT		LIMIT (RESIDENTIAL ZONE)	
		DAY TIME	NIGHT TIME	DAY TIME	NIGHT TIME
<b>Outside Plant</b>					
SIDARPARA VILLAGE	DB (A)	49	41	55	45
HIL COLONY, KONDKEL	DB (A)	52	43		
HIL STAFF QUARTER, MILUPARA	DB (A)	46	39		

**REMARKS: RESULTS ARE AS ABOVE****Terms & conditions**

- The above analysis report refers to the particular sample received at our end and the use of the report for publication, arbitration or as legal dispute is forbidden.
- Test sample will be retained for 07 days after issue of test report unless otherwise agreed with customer.

	For <b>ULTIMATE ENVIROLYTICAL SOLUTIONS</b>   <b>AUTHORIZED SIGNATORY</b>
---	--

-----End of the test report-----