

Recognized by Ministry of Environment Forest and Climate Change under EP act 1986

to Name & Address Of The Customer To, HINDALCO INDUSTRIES LIMITED, KATHAUTIA OPEN CAST COAL MINES, POST – NAUDIHA, P.S. PANDWA, DALTONGANJ, DISTT PALAMU (JH)		Report No Lab Ref No	-	UES/TR/21-22/09764 UES/21-22/W/15694 27/01/2022 27/01/2022 31/01/2022		
		Date Of Sampling	27			
		Date Of Receipt	27			
		Date Of Report	31			
		Date Of Analysis	St	art:27/01/2022	End: 31/01/2022	
	SA	MPLE DETAILS				
Sampling Location	1. SECURITY BAIRCK 2. SIKKS VILLAGE 3. BATSARA VILLAGE	Customer Ref. No. & Date		K/PO/SRV/2122/0058, DATE:30-SEP-2021		
Monitoring For	Piezometer Ground Water Sample Condition At Receipt		0k			
Sample Collected By	Laboratory Chemist				2	

TEST REPORT							
SR. NO.	LOCATION LATITUDE LONGITUDE		UNIT	RESULT (DEPTH/BELOW GROUND WATER LEVEL)			
1	NEAR SECURITY BARRAK	24°01′10.28″N	84°05′18.88″E	METER	2.43		
2	NEAR SIKKA VILLAGE	24°06′54.88″N	84°05′34.33″E	METER	3.28		
3	NEAR BATSARA VILLAGE	24°06′52.49″N	84°05′41.49″E	METER	7.14		

Note: BGWL-Below Ground Water Level.

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- > The report for publication, arbitration or as legal dispute is forbidden.
- > Test sample will be retained for 15 days after issue of test report unless otherwise agreed with customer.

> This is for information as the party has asked for above test(s) only.

REVIEWED BY

For ULTIMATE ENVIROLYTICAL SOLUTIONS

AUTHORIZED SIGNATORY

End of the test report-



Recognized by Ministry of Environment Forest and Climate Change under EP act 1986

To, HINDALCO INDUSTRIES LIMITED, KATHAUTIA OPEN CAST COAL MINES, POST – NAUDIHA, P.S. PANDWA,		Report No	UE:	UES/TR/21-22/09829		
		Lab Ref No	UE	UES/21-22/W/15759		
		Date Of Sampling	11,	11/02/2022 11/02/2022 18/02/2022		
		Date Of Receipt	11,			
DALTONGANJ, DISTT PALAMU (JH)	Date Of Report	18,				
DALIGNOANS, DISTI PALAWIO (JH)		Date Of Analysis	Sta	Start:11/02/2022 End:18/02/2		
	SA	MPLE DETAILS				
1. SECURITY BAIRCK Sampling Location 2. SIKKS VILLAGE 3. BATSARA VILLAGE		Customer Ref. No. & Date		K/PO/SRV/2122/0058, DATE:30-SEP-2021		
Monitoring For Piezometer Ground Water Depth		Sample Condition At Receipt Ok				
Sample Collected By Laboratory Chemist						

	TEST REPORT							
SR. NO.	LOCATION	LATITUDE	LONGITUDE	UNIT	RESULT (DEPTH/BELOW GROUND WATER LEVEL)			
1	NEAR SECURITY BARRAK	24°01′10.28″N	84°05′18.88″E	METER	4.82			
2	NEAR SIKKA VILLAGE	24°06′54.88″N	84°05′34.33″E	METER	6.42			
3	NEAR BATSARA VILLAGE	24°06′52.49″N	84°05′41.49″E	METER	8.26			

Note: BGWL -Below Ground Water Level.

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- > The report for publication, arbitration or as legal dispute is forbidden.
- Test sample will be retained for 15 days after issue of test report unless otherwise agreed with customer.

This is for information as the party has asked for above test(s) only.

REVIEWED BY

For ULTIMATE ENVIROLYTICAL SOLUTIONS

AUTHORIZED SIGNATORY

End of the test report-



Recognized by Ministry of Environment Forest and Climate Change under EP act 1986

to Name & Address Of The Customer To, HINDALCO INDUSTRIES LIMITED, KATHAUTIA OPEN CAST COAL MINES, POST – NAUDIHA, P.S. PANDWA, DALTONGANJ, DISTT PALAMU (JH)		Report No	UE	UES/TR/21-22/09899		
		Lab Ref No U		UES/21-22/W/15829		
		Date Of Sampling	14	14/03/2022 14/03/2022 21/03/2022		
		Date Of Receipt	14			
		Date Of Report	21,			
		Date Of Analysis	St	Start:14/03/2022 End:21/0.		
	SA	MPLE DETAILS				
Sampling Location 1. SECURITY BAIRCK 2. SIKKS VILLAGE 3. BATSARA VILLAGE Monitoring For Piezometer Ground Water Depth		Customer Ref. No. & Date		K/PO/SRV/2122/0058, DATE:30-SEP-2021		
		Sample Condition At Receipt		Ok		
Sample Collected By	Laboratory Chemist	•				

	TEST REPORT							
SR. NO.	LOCATION	LATITUDE	LONGITUDE	UNIT	RESULT (DEPTH/BELOW GROUND WATER LEVEL)			
1	NEAR SECURITY BARRAK	24°01′10.28″N	84°05′18.88″E	METER	5.38			
2	NEAR SIKKA VILLAGE	24°06′54.88″N	84°05′34.33″E	METER	8.21			
3	NEAR BATSARA VILLAGE	24°06′52.49″N	84°05′41.49″E	METER	11.24			

Note: BGWL -Below Ground Water Level.

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- > The report for publication, arbitration or as legal dispute is forbidden.
- > Test sample will be retained for 15 days after issue of test report unless otherwise agreed with customer.

This is for information as the party has asked for above test(s) only.

REVIEWED BY

ForULTIMATE ENVIROLYTICAL SOLUTIONS

AUTHORIZED SIGNATORY

AN ISO: 9001:2015 / ISO: 14001:2015 / ISO 45001:2018 CERTIFIED LABORATORY

-End of the test report-



Recognized by Ministry of Environment Forest and Climate Change under EP act 1986

to Name & Address Of The Customer To, HINDALCO INDUSTRIES LIMITED, KATHAUTIA OPEN CAST COAL MINES, POST – NAUDIHA, P.S. PANDWA,		Report No		UES/TR/21-22/09704		
		Lab Ref No	UE	UES/21-22/W/15634		
		Date Of Sampling	27	27/12/2021		
		Date Of Receipt	27	27/12/2021 31/12/2021		
DALTONGANJ, DISTT PALAMU (JH)	Date Of Report	31,				
DALIGNOANS, DISTT. PALAMO (3H)		Date Of Analysis	St	art:27/12/2021	End:31/12/2021	
	SA	MPLE DETAILS				
1. SECURITY BAIRCK Sampling Location 2. SIKKS VILLAGE 3. BATSARA VILLAGE		Customer Ref. No. & Date	K/PO/SRV/2122/0058, DATE:30-SEP-2021			
Monitoring For Piezometer Ground Water Depth		Sample Condition At Receipt		Ok		
Sample Collected By	Laboratory Chemist					

TEST REPORT							
SR. NO.	LOCATION	LATITUDE	LONGITUDE	UNIT	RESULT (DEPTH/BELOW GROUND WATER LEVEL)		
1	NEAR SECURITY BARRAK	24°01′10.28″N	84°05′18.88″E	METER	1.78		
2	NEAR SIKKA VILLAGE	24°06′54.88″N	84°05′34.33″E	METER	3.14		
3	NEAR BATSARA VILLAGE	24°06′52.49″N	84°05′41.49″E	METER	6.28		

Note: BGWL -Below Ground Water Level.

REMARKS: RESULTS ARE AS ABOVE

Terms & conditions

- > The report for publication, arbitration or as legal dispute is forbidden.
- > Test sample will be retained for 15 days after issue of test report unless otherwise agreed with customer.

This is for information as the party has asked for above test(s) only.

REVIEWED BY

SOUTH TOWN TOWN WEST AND THE STATE OF THE ST

End of the test report-

For ULTIMATE ENVIROLYTICAL SOLUTIONS

AUTHORIZED SIGNATORY

AN ISO: 9001:2015 / ISO: 14001:2015 / ISO 45001:2018 CERTIFIED LABORATORY