

HIL/LHD/ENV/MOEF/ 384

Date: 19.11.2021

To,
The Additional Principal Chief Conservator of Forest (C)
Ministry of Environment, Forests and Climate Changes
Regional Office (ECZ), Ranchi-834002.

Sub: Compliance Report of EC conditions for Bhusar (65.31 ha) Bauxite Mining project of M/s Hindalco Industries Limited located in Lohardaga, Jharkhand for the period April'21 to September'21.

Ref: Environmental Clearance No-J-11015/184/2011-IA.II (M) dated 17th June 2013.

Sir,

With reference to the above, we are submitting herewith the Compliance status report of EC conditions for **Bhusar (65.31 ha) Bauxite** Mining project of **M/s Hindalco Industries Limited** located in Lohardaga, Jharkhand for the period April'21 to September'21. The lease detail is as below.

Lease area (ha)	Production Capacity (MT)	Lease Period
65.31	280000	11.07.1981 to 31.03.2030

Hope you will find the same in order.

Thanking You

Yours Sincerely

FOR HINDALCO INDUSTRIES LIMITED

(Basudev Gangopadhyay) Sr GM (Geology & Environment)

Enclosure: - As Above

CC: ro.ranchi-mef@gov.in, mef@ori.nic.in, mef@nic.in, mef.or@nic.in, mscb.cpcb@nic.in, zokolkatta.cpcb@nic.in, ranchijspcb@gmail.com, roranchi47@gmail.com

Name of the Project

: Bhusar Bauxite Mine (65.31 ha) M/s Hindalco Industries Ltd

Environment Clearance No & date

: J-11015/184/2011-IA.II (M), dated 17.06.2013

Period of compliance Report

: From 1st April 2021 to 30th September 2021

S No	Specific Condition	Compliance
(i)	All the conditions stipulated by State Pollution Control Board in their NOC shall be effectively implemented.	Implementations of stipulated conditions in NOC are fulfilled post which consent to operate has been obtained from time to time. Existing consent to operate is valid up to 30.09.2021. We have applied online renewal of CTO for further validity in JSPCB portal.
(ii)	Environmental clearance is subject to obtaining clearance under the wildlife (Protection) Act, 1972 from the competent authority, as may be applicable to this project.	We understand, this is not applicable. Mine is located far away from nearest Eco sensative zone.
(iii)	The mining operations shall be restricted to above ground water table and it should not intersect groundwater table. Prior approval of the Ministry of Environment & Forests and Central Ground Water Authority shall be obtained for mining below water table.	Shallow depth mining is being done and not intersected ground water.  In future also, working zone will be restricted to above ground water table.  We undertake that no mining is/was carried out below groundwater table and the same status will be maintained in future also.
(iv)	The project proponent shall ensure that no natural watercourse shall be obstructed due to any mining operations.	Agreed. No natural water course is being and will be obstructed due to mining activities.
(v)	Topsoil should be stacked with proper slope at earmarked site(s) only with adequate measures and should be used for reclamation and rehabilitation of mined out areas.	Topsoil is being temporary stored with proper slope as applicable and is being spread over back filled area in process of reclamation. Entire topsoil generated earlier has been used for reclamation and plantation purpose.
(vi)	The entire waste generated shall be backfilled and there shall be no external over burden dump left at the end of the mine life. The entire backfilled area shall be reclaimed by plantation. The back filling should be carried out in such a manner that it is restored to the normal ground level. Monitoring and management of rehabilitated areas should continue until the vegetation becomes self-sustaining. Compliance status should be	Over burden generated during mining operation temporarily stacked at earmarked dump site (s) only for purpose of backfilling. Backfilling is in progress. The entire area is being reclaimed by suitable plantation which is under progressive stage as of now. Monitoring and management of rehabilitated area is continuous until vegetation becomes self-sustaining. There shall be no external dump left at the end of mine life as applicable. However existing dump is stabilized.

	submitted to the Ministry of Environment as Forests and its Regional Office, Bhubaneswar on six monthly basis.	Compliance status is being submitted to MoEF on six monthly basis.		
(vii)	Catch drains and siltation ponds of appropriate size should be constructed for the working pit, temporary OB dumps, if any and mineral dumps to arrest flow of silt and sediment. The water so collected should be utilized for watering the mine area, roads, green belt development etc. The drains should be regularly desilted, particularly after monsoon, and maintained properly.  Garland drain of appropriate size, gradient and length shall be constructed for both mine pit and temporary dumps and sump capacity should be designed keeping 50% safety margin over and above peak sudden rainfall (based on 50 years data) and maximum discharge in the area adjoining the mine site. Sump capacity should also provide adequate retention period to allow proper settling of silt material. Sedimentation pits should be constructed at the corners of the	However, to collect & manage rain water during monsoon, part of mined out area is used as settling tank for the runoff. Rain water stored is being used for watering the mine area, roads, green belt development and sprinkling as necessary.  Catch drains, Garland drains of appropriate size are being constructed in both around the mine pit to prevent runoff of water and flow of sediments directly into the agricultural field and water bodies, if applicable.  Sump of adequate capacity is being provided and maintained as required.  No active external dump exists and old dumps are stabilized.		
(viii)	garland drains and desilted at regular intervals.  Dimension of the retaining wall at the toe of temporary dumps and OB benches within the mine to check run-off and siltation should be based on the rain fall data.	Dimensions of the retaining wall of OB dumps are maintained based on average rain fall.		
(ix)	Plantation shall be raised in an area of 52.50 ha including a 7.5m wide green belt in the safety zone around the mining lease by planting the native species around ML area, backfilled and reclaimed area, around water body, roads etc. in consultation with the local DFO/Agriculture Department at the end of life of mine. The density of the trees should be around 2500 plants per ha.	It is already in practice. Phase wise plantation of native species in consultation with forest department has been carried out within safety zone and mined out/reclaimed pits.  As on date approx. 45.91 Ha area is covered with plantation. Total 2970 saplings have been planted during April'21 to September'21 period within the Bhusar mine lease area.  In addition to this agricultural activity is going on reclaimed land.  Green belt development programme is in progress with progress of mining activities.		
(x)	Regular water sprinkling should be carried out in critical areas prone to air pollution and having high levels of SPM and RSPM such as haul road, loading and unloading point and transfer points. It should be ensured that the Ambient Air Quality parameters conform to	progress with progress of mining activities.  Mobile water tankers have been provided for sprinkling of water in critical areas to suppress dust. AAQ parameters in mine monitored on regular basis is attached as Annexure-1.		

	the norms prescribed by the Central Pollution Control Board in this regard.	
(xi)	The project authority should implement suitable conservation measures to augment ground water resources in the area in consultation with the Regional Director, Central Ground Water Board.	suitable conservation measures to augment ground water resources in area (Ragnu
		The water reservoir, drainage system, sequential backfilling in mining lease area is so designed that all the rainwater within lease will be collected in pond only. Required slope is being maintained for this purpose. No water is allowed to flow out of lease. Near the portion of the slopes, bund is created by boulder and morrum to arrest outflow.
		Plantation is done at susceptible portions to prevent soil erosion. The same practice will continue in future.
(xii)		It may be noted that as mentioned earlier there is no chance of intersection of ground water table during mining operation at present and in future also.
(XII)	Regular monitoring of ground water level and quality should be carried out in and around the mine lease by establishing a network of existing wells and constructing new piezometers during the mining operation. The monitoring should be carried out four times in a year i.e. January, April-	We are not using ground water for any mining purpose. There is no chance of intersection ground water table during mining operation at present and in future also as the total mining depth is being and will be restricted above water table.
	May, August, November and the data thus collected may be sent regularly to Ministry of Environment and Forests, its Regional Office, Bhubaneswar; Central Ground Water Authority and Central Ground Water Board.	Piezometer has been installed for monitoring of ground water level. Water quality and level report are attached herewith as <b>Annexure 1</b> .
(xiii)	The project authorities should obtain prior approval of the competent authority for drawl of groundwater if any, required	Now Regional office is at Ranchi.  Suitable arrangement for collection of water in rainwater harvesting pond is in practice.
	for the project.	Water is drawn from rainwater harvesting pond being used for sprinkling on haul roads and for raising plantation.
		We are not using any ground water for mining purposes.  No Objection Certificate (NOC) for ground water abstraction for Bhusar mines has been obtained for drinking purpose only.

(xiv)	Vehicular emissions should be kept under control and regularly monitored. Measures shall be taken for maintenance of vehicles used in mining operations and in transportation of mineral. The vehicles should be covered with a tarpaulin and shall not be overloaded.	measures are being undertaken to minimize vehicular emission.  Bauxite is transported through ropeway from
(xv)	Blasting operation should be carried out only during the daytime. Controlled blasting should be practiced. The mitigative measures for control of ground vibrations and to arrest fly rocks and boulders should be implemented	mine to Lohardaga siding.  Blasting time is fixed during lunch time i.e. 1.00 PM -2.00 PM.  Controlled blasting method is in practice. Ground vibration study has been conducted by IIT, Kharagpur.
(xvi)	Drills shall either be operated with dust extractors or equipped with water injection	All efforts are being taken to mitigate impact of blasting  Wet drilling is in practice.
(xvii)	system.  Consent to operate should be obtained from SPCB before starting/ enhanced production from the mine.	Consent to operate has been obtained. Current CTO is valid up to Sept'2021. We have applied online renewal of CTO for further validity in JSPCB portal.
(xviii)	A Final Mine Closure Plan along with details of Corpus Fund should be submitted to the Ministry of Environment & Forests 5 years in advance of final mine closure for approval.	Progressive mine closure plan along with mining scheme has been approved by IBM. Final mine closure plan will be prepared in due time. Based on present resource estimate, and peak rated production capacity mentioned
S No	General Condition	in EC, Mining operation is being carried out.  Compliance
(i)	No change in mining technology and scope of working should be made without prior approval of the Ministry of Environment and Forests.	Noted.
(ii)	No change in the calendar plan including excavation, quantum of mineral bauxite and waste should be made.	Calendar plan including excavation, quantum of mineral bauxite and waste is being done as per IBM approved mining scheme. Report is attached as Annexure-4.
(iii)	Four ambient air quality-monitoring stations should be established in the core zone as well as in the buffer zone for PM10, SO2 as NOx monitoring. Location of the stations should be decided based on the meteorological data, topographical features and environmentally and ecologically sensitive targets and frequency of monitoring should be undertaken in consultation with the State Pollution Control	We have already established four ambient air quality monitoring stations in core zone as well as buffer zone. Monitoring is being carried out and reported to concern authorities. Report is attached as <b>Annexure 1</b> .

	Board.	
(iv)	Fugitive dust emissions from all the sources should be controlled regularly. Water spraying arrangement on haul roads, loading and unloading and at transfer points should be provided and properly maintained.	Suitable water spraying system is already available. To arrest fugitive dust proper water sprinkling is being carried out on haul roads, loading and unloading and at transfer points.
(v)	Measures should be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in operations of HEMM, etc. should be provided with ear plugs / muffs.	Noise monitoring is being done regularly. Workers engaged in operation of HEMMs, etc. has also been provided with PPEs such as ear plugs and ear muffs. Monitoring of noise level is being conducted at various locations of the work zone area.
(vi)	Industrial wastewater (workshop and waste water from the mine) should be properly collected, treated so as to conform to the standards prescribed under GSR 422(E) dated 19th May 1993 and 31st December 03 or as amended from time to time. Oil and grease trap should be installed before discharge of effluents from workshop.	There is no industrial waste water generation from workshop within mine lease area. We are not discharging any waste water outside mine lease area. Effluent treatment mechanism (Oil and grease trap) has been installed at suitable site in Bagru Plateau.
(vii)	Personnel working in dusty areas should wear protective respiratory devices and they should also be provided with adequate training and information on safety and health aspects.	Workers engaged in operation of HEMMs, etc. has been provided with PPEs such as ear plugs and ear muffs.  Monitoring of noise level is being conducted at various locations of work zone area.  Training is being provided through group vocational training Centre on safety and health
(viii)	Occupational health surveillance programme of the workers should be undertaken periodically to observe any contractions due to exposure to dust and take corrective measures, if needed.	aspects.  Being carried out.
(ix)	A separate environmental management cell with suitable qualified personnel should be set up under the control of a senior Executive, who will report directly to the Head of the organization.	Separate Environmental Management Cell (EMC) has been constituted and is functioning effectively. Copy is enclosed as Annexure-3.
(x)	The funds earmarked for environmental protection measures should be kept in separate account and should not be diverted for other purposes. Year-wise expenditure should be reported to the Ministry and its Regional Office located at Bhubaneswar	Year wise expenditure is being reported to the Ministry and its Regional Office located at Ranchi. Copy is enclosed as Annexure-2.

(xi)	The Regional Office of this Ministry located at Bhubaneswar shall monitor compliance of the stipulated conditions. The Project authorities should extend full cooperation to the officer(s) of the Regional Office by furnishing requisite data/information/monitoring reports.	Agreed. Now Regional office is at Ranchi.
(xii)	The project proponent shall submit six monthly report on the status of the implementation of the stipulated environmental safeguards to the Ministry of Environment and Forests, its Regional Office, Bhubaneswar, Central Pollution Control Board and State Pollution Control Board.	Six monthly reports on status of compliance of stipulated environmental clearance conditions including results of monitored data (by e mail) are being submitted to the Ministry of Environment and Forests, its Regional office Ranchi, the respective Zonal office of Central Pollution Control Board, the State Pollution Control Board and uploaded in company's website.  Now Regional office is at Ranchi.
(xiii)	A copy of the clearance letter will be marked to the concerned Panchayat/local NGO, if any, from whom suggestions/representation has been received while processing the proposal.	A copy of clearance letter has been sent to concerned Panchayat, Zila Parisad / Municipal corporation, urban local body and the local NGO.
(xiv)	The project authorities should inform to the Regional Office located at Bhubaneswar regarding date of financial closures and final approval of the project by the concerned authorities and the date of start of land development work.	It is an operational mine. Hence provisional related to financial closure is not applicable.
(xv)	State Pollution Control Board should display a copy of the clearance letter at the Regional Office, District Industry Centre and Colleator's/Tehsildar's Office for 30 days.	Displayed.
(xvi)	The project authorities should advertise at least in two local newspapers widely circulated, one of which shall be in the vernacular language of the locality concerned, within 7 days of the issue of the Clearance letter informing that the project has been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution Control Board and also at web site of the Ministry of Environment and Forests at http://envfor.nic.in and a copy of the same should be forwarded to the Regional Office	Complied. Copies of relevant paper cutting are submitted earlier.
	of this Ministry located at Bhubaneswar.	

Signature

## Photographs of Bhusar Bauxite Mine – Hindalco Industries Ltd



(Plantation at Bhusar Bauxite mine)





(Plantation at Bhusar Bauxite mine)



(Stylohameta, Sindwar & Lantana For Slope Stability)



(Rainwater Harvesting Pond at Bhusar mine)



(Oil & Grease Trap)



(Water Sprinkling)



(Ropeway transportation- eco-friendly)



# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

## Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009

#### BHUSAR BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

APRIL 2021

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

 $\pmb{\text{E-mail:}} \underline{\textbf{mahabalranchi@gmail.com}}$ 

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

#### CONTENT

	LOCATION - BHUSAR BAUXITE MINE		
	AMBIENT AIR QUALITY – CORE ZONE		
1	Near View Point 1 (Bhusar Mine Pit I)		
2	Near View Point 2 (Bhusar Mine Pit II)		
3	Near Rest Shelter		
4	Near GTS Point		
	AMBIENT NOISE		
	SPOT NOISE		
	DRINKING WATER ANALYSIS		



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

Date: 10th May, 2021

Report No: MEEPL/MAY/0136/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample Location: Near View Point 1 (Bhusar Mine Pit I)

Sample collected on: 06.04.2021

	LOCATION / IDENTIFICATION: Near View Point 1 (Bhusar Mine Pit I)			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	66
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	38
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.5
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.8
05.	Ammonia (NH₃)	μg/m³	400	7.4
06.	Ozone (O₃)	μg/m³	180	12.1
07.	Carbon Monoxide (CO)	mg/m³	02	0.36
08.	Lead (Pb)	μg/m³	1.0	0.05
09.	Nickel (Ni)	ng/m³	20	2.7
10.	Arsenic (As)	ng/m³	06	2.5
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.4
12.	Benzo (a) Pyrene	μg/m³	01	0.35

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

Date: 10th May, 2021

**Report No: MEEPL/MAY/0137/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near View Point 2 (Bhusar Mine Pit II)

Sample collected on: 07.04.2021

	LOCATION / IDENTIFICATION: Near View point 2 (Bhusar Mine Pit II)			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	68.1
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	36.9
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.6
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.3
05.	Ammonia (NH₃)	μg/m³	400	7.8
06.	Ozone (O <sub>3</sub> )	μg/m³	180	12.1
07.	Carbon Monoxide (CO)	mg/m³	02	0.37
08.	Lead (Pb)	μg/m³	1.0	0.05
09.	Nickel (Ni)	ng/m³	20	2.7
10.	Arsenic (As)	ng/m³	06	3.2
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.6
12.	Benzo (a) Pyrene	μg/m³	01	0.41

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Near Rest Shelter

Sample collected on: 07.04.2021

	LOCATION / IDENTIFICATION: Near Rest Shelter			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	62
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	34
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.6
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.8
05.	Ammonia (NH3)	μg/m³	400	5.9
06.	Ozone (O <sub>3</sub> )	μg/m³	180	11.3
07.	Carbon Monoxide (CO)	mg/m³	02	0.37
08.	Lead (Pb)	μg/m³	1.0	0.08
09.	Nickel (Ni)	ng/m³	20	2.9
10.	Arsenic (As)	ng/m³	06	3.9
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.6
12.	Benzo (a) Pyrene	μg/m³	01	0.34

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

Date: 10th May, 2021

Report No: MEEPL/MAY/0139/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near GTS Point

Sample collected on: 06.04.2021

	LOCATION / IDENTIFICATION: Near GTS Point			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	67
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	43
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.5
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	6.5
05.	Ammonia (NH₃)	μg/m³	400	5.9
06.	Ozone (O₃)	μg/m³	180	10.6
07.	Carbon Monoxide (CO)	mg/m³	02	0.24
08.	Lead (Pb)	μg/m³	1.0	0.06
09.	Nickel (Ni)	ng/m³	20	3.7
10.	Arsenic (As)	ng/m³	06	2.8
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.2
12.	Benzo (a) Pyrene	μg/m³	01	0.41

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

April 2021

Date: 10th May, 2021

Report No: MEEPL/MAY/0126/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: **Lohardaga**Postal Code: **835203**State: **Jharkhand**Country: **India** 

Sample Type: **AMBIENT AIR QUALITY MONITORING**Marks on Sample Location: **Near Daldaliya Village** 

Sample collected on: 05.04.2021

	LOCATION / IDENTIFICATION: Near Daldaliya Village						
Sl. No.	PARAMETERS		Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	54.5			
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	22.9			
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.8			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	6.2			
05.	Ammonia (NH₃)	μg/m³	400	7.6			
06.	Ozone (O <sub>3</sub> )	μg/m³	180	11.8			
07.	Carbon Monoxide (CO)	mg/m³	02	0.31			
08.	Lead (Pb)	μg/m³	1.0	0.04			
09.	Nickel (Ni)	ng/m³	20	4.2			
10.	Arsenic (As)	ng/m³	06	2.9			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.8			
12.	Benzo (a) Pyrene	μg/m³	01	0.48			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

April 2021

**Report No: MEEPL/MAY/0127/2021-22 Date: 10th May, 2021** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Aditya School Gangupara

Sample collected on: 05.04.2021

	LOCATION / IDENTIFICATION: Aditya School Gangupara						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	54			
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	29			
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.9			
04.	Nitrogen Dioxide (NO2)	μg/m³	80	5.6			
05.	Ammonia (NH₃)	μg/m³	400	4.8			
06.	Ozone (O <sub>3</sub> )	μg/m³	180	9.1			
07.	Carbon Monoxide (CO)	mg/m³	02	0.11			
08.	Lead (Pb)	μg/m³	1.0	0.03			
09.	Nickel (Ni)	ng/m³	20	2.2			
10.	Arsenic (As)	ng/m³	06	2.4			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.9			
12.	Benzo (a) Pyrene	μg/m³	01	0.7			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

April 2021

Date: 10th May, 2021

**Report No: MEEPL/MAY/0128/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Ropeway Unloading Station

Sample collected on: 05.04.2021

	LOCATION / IDENTIFICATION: Ropeway Unloading Station						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	59			
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	29			
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.8			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.7			
05.	Ammonia (NH₃)	μg/m³	400	5.2			
06.	Ozone (O₃)	μg/m³	180	11.6			
07.	Carbon Monoxide (CO)	mg/m³	02	0.29			
08.	Lead (Pb)	μg/m³	1.0	0.05			
09.	Nickel (Ni)	ng/m³	20	3.2			
10.	Arsenic (As)	ng/m³	06	2.5			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.9			
12.	Benzo (a) Pyrene	μg/m³	01	0.35			

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

April 2021

Date: 10th May, 2021

Report No: MEEPL/MAY/0129/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: **AMBIENT AIR QUALITY MONITORING** Marks on Sample: Location: **Ropeway Angle Station** 

Sample collected on: 05.04.2021

	LOCATION / IDENTIFICATION: Ropeway Angle Station						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	53			
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	37			
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	5.3			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	7.8			
05.	Ammonia (NH3)	μg/m³	400	5.3			
06.	Ozone (O₃)	μg/m³	180	10.9			
07.	Carbon Monoxide (CO)	mg/m³	02	0.21			
08.	Lead (Pb)	μg/m³	1.0	0.05			
09.	Nickel (Ni)	ng/m³	20	2.4			
10.	Arsenic (As)	ng/m³	06	3.3			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.5			
12.	Benzo (a) Pyrene	μg/m³	01	0.31			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

**Report No: MEEPL/MAY/0140/2021-22 Date: 10th May, 2021** 

Sample described by customer: Measurement of Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Noise

Sampling Method: Instrumental, using Sound level Meter

Data Collection Date: 06.04.2021

Location/Identification	Unit	Limit (day)	Result	Limit (night)	Result
Bhusar Mines Pit 1	dB (A) L <sub>eq</sub>	75	64.2	70	53.5

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

**Report No: MEEPL/MAY/0141/2021-22 Date: 10<sup>th</sup> May, 2021** 

Sample described by customer: Measurement of Spot Noise

Client Name: Hindalco Industries Limited

Client Address: Lohardaga

Postal Code: 835203 State: Jharkhand Country: India

Sample Description: Measurement of Spot Noise

Sampling Method: Instrumental, using Sound level Metter

Data Collection Date: 06.04.2021

Location/Identification	Unit	Limit (day)	Result
Bhusar Mines Pit - II	dB (A) L <sub>eq</sub>	<b>7</b> 5	72.0

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

Report No.: MEEPL/MAY/0142/2021-22 Date: 10th May, 2021

Sample described by customer: DRINKING WATER-POTABILITY

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: DRINKING WATER-POTABILITY

Marks on Sample: Location: Tap Water - Near Rest Shelter.

Sample collected on:06.04.2021

SL No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
1	Colour	Hazen	<1	5 Max	APHA 22 <sup>nd</sup> Ed. 2012, 2120-B, 2-6
2	Odour		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
3	Taste		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
4	Turbidity	NTU	0.4	1 Max	APHA 22 <sup>nd</sup> Ed. 2012, 2130-B, 2-13
5	рН		7.1	6.5-8.5	APHA 22md Ed. 2012, 4500-H+-B, 4-92
6	Free Chlorides (Residual)	mg/l	<0.5	0.2 min	APHA 22md Ed. 2012, 4500-CI-G, 4-69
7	Total Dissolved Solids	mg/l	147	500 max	IS 3025 (Part 16): 1984, Reaffirmed 2006
8	Monochloramines	mg/l	<0.05		APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
9	Dichioramines	mg/l	<0.05		APHA 22md Ed. 2012, 4500-CIG, 4-69
10	Total hardness (as CaCO3)	mg/l	36.8	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
11	Alkalinirty Total (as CaCO3)	mg/l	32.3	200 max	IS 3025 (Part 237): 1986, Reaffirmed 2009
12	Chloride (as CI)	mg/l	6.9	250 max	APHA 22nd Ed. 2012, 4500-CI-b, 4-72
13	Sulphate (as SO4)	mg/l	5.2	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-so4-e, 4- 190



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

April 2021

#### Continuation Sheet MEEPL/MAY/0142/2021-22

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
14	Nitrate (as NO3)	mg/l	1.9	45 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-N03-E, 4-125
15	Fluoride (as F)	mg/l	0.19	1 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-FB & D, 4-84, 4-87
16	Boron (as B)	mg/l	0.12	0.5 max	APHA 22nd Ed. 2012, 4500-BB, 4-25
17	Calcium (as Ca)	mg/l	28	75 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Ca-B, 3- 67
18	Magnesium (as Mg)	mg/l	1.8	30 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Mg-B, 3- 84
19	Ammonical Nitrogen/Total Ammonia	mg/l	<0.1		APHA 22 <sup>nd</sup> Ed. 2012, 4500-NH3-F, 4-115
20	Iron (as Fe)	mg/l	0.18	0.3 max	APHA 22nd Ed. 2012, 3111-B, 3-18
21	Manganese (as Mn)	mg/l	N.D	0.1 max	APHA 22nd Ed. 2012, 3111-B, 3-18
22	Aluminium (as Al)	mg/l	0.01	0.03 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Al-B, 3- 61
23	Cadmium (as Cd)	mg/l	N.D	0.003 max	APHA 22nd Ed. 2012, 3111-B, 3-18
24	Chromium Total (as Cr)	mg/l	N.D	0.05 max	APHA 22nd Ed. 2012, 3111-B, 3-18
25	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22md Ed. 2012, 3111-B, 3-18
26	Lead (as Pb)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
27	Zinc (as Zn)	mg/l	0.07	5 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
28	Arsenic (as As)	mg/l	< 0.01	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
29	Selenium (as Se)	mg/l	N.D	0.001 max	APHA 22 <sup>nd</sup> Ed. 2012, 3112-B, 3-18
30	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
31	Nickel (as Ni)	mg/l	< 0.02	0.02 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
32	Mineral Oil	mg/l	N.D	0.5 max	IS 3025 (Part 39): 1991, Reaffirmed 2003: ed. 2.1
33	Cyanide (as CN)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> ED. 2012, 4500-CN.C & 4-39 & 4-44
34	Anionic detergents as MBAS	mg/l	<0.1	0.2 max	APHA 22 <sup>nd</sup> ED. 2012, 5540-C.C & 5- 53
35	Phenolic compounds (as C6H5OH)	mg/l	N.D	0.001 max	APHA 22 <sup>nd</sup> ED. 2012, 5530-B & C5- 4753
36	Polynuclear aromatic hydrocarbons (PAH)	mg/l	N.D	0.0001 max	APHA 22 <sup>nd</sup> ED. 2012, 6440, 6-93
37	Polychlorinated Biphenyls (PCBs)	mg/l	N.D	0.0005 max	USEPA Method 8082
38	Sulphide (as S)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> ED. 2012, 4500-S2-C 4- 175 & F 4-178



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

April 2021

Continuation Sheet MEEPL/MAY/0142/2021-22

S.No	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method Reference
Micro	biological Analysis				
1.	Total Colliforms	MPN/ 100 mL	N.D	<1.1	APHA 22nd Ed. 2012, 9221–B & C, 9-66, 9-69
2.	E-Coli	MPN/ 100 mL	N.D	Absent	APHA 22nd Ed. 2012, 9221– B, C & G, 9-66, 9-69 and 9-76
Pesti	cides Residues		· L		
3.	p,p DDT	μg/L	N.D	1	US EPA 508-1995
4.	o,p DDT	μg/L	N.D	1	US EPA 508-1995
5.	p,p DDE	μg/L	N.D	1	US EPA 508-1995
6.	o,p DDE	μg/L	N.D	1	US EPA 508-1995
7.	p,p DDD	μg/L	N.D	1	US EPA 508-1995
8.	o,p DDD	μg/L	N.D	1	US EPA 508-1995
9.	γ-HCH (Lindane)	μg/L	< 0.01	2	US EPA 508-1995
10.	α-HCH	μg/L	< 0.01	0.04	US EPA 508-1995
11.	β-нсн	μg/L	N.D	0.03	US EPA 508-1995
12	δ-HCH	μg/L	N.D	0.03	US EPA 508-1995
13.	Butachlor	μg/L	N.D	126	US EPA 508-1995
14.	Alachlor	μg/L	N.D	22	US EPA 508-1995
15.	Atrazine	μg/L	N.D	2.9	US EPA 532-2000
16.	α Endosulfan	μg/L	N.D	0.5	US EPA 508-1995
17.	β Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
18.	Endosulfan Sulphate	μg/L	N.D	0.3	US EPA 508-1995
19.	Ethion	μg/L	N.D	3	US EPA 8141A-1994
20.	Malathion	μg/L	N.D	181	US EPA 8141A -1994
21.	Methyl Parathion	μg/L	N.D	0.4	US EPA 8141A -1994
22.	Monocrotophos	μg/L	N.D	1	US EPA 8141A-1994
23.	Phorate	μg/L	N.D	2	US EPA 8141A -1994
24.	Chlorpyrifos	μg/L	N.D	22	US EPA 8141A -1994
25.	Aldrin	μg/L	N.D	0.04	US EPA 508-1995
26.	Dieldrin	μg/L	N.D	0.03	US EPA 508-1995
Rema	rks: N.D- Not Detected		*		

**Conclusion:** The Physical & Chemical Analysis report indicates that water is not contaminated.

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

## Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009

#### BHUSAR BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

MAY 2021

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

MAY 2021

### CONTENT

	LOCATION - BHUSAR BAUXITE MINE			
	AMBIENT AIR QUALITY - CORE ZONE			
1	Near View Point 1 (Bhusar Mine Pit I)			
2	Near View Point 2 (Bhusar Mine Pit II)			
3	Near Rest Shelter			
4	Near GTS Point			



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

MAY 2021

Report no: MEEPL/JUNE/0018/2021-22

Date: 7th June, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: **[harkhand** Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample Location: Near View Point 1 (Bhusar Mine Pit I)

Sample collected on: 05.05.2021

	LOCATION / IDENTIFICATION: Near View Point 1 (Bhusar Mine Pit I)						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	60			
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	35			
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.4			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	52			
05.	Ammonia (NH3)	μg/m³	400	6.3			
06.	Ozone (O <sub>3</sub> )	μg/m³	180	10.5			
07.	Carbon Monoxide (CO)	mg/m³	02	0.35			
08.	Lead (Pb)	μg/m³	1.0	0.05			
09.	Nickel (Ni)	ng/m³	20	2.6			
10.	Arsenic (As)	ng/m³	06	2.1			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.9			
12.	Benzo (a) Pyrene	μg/m³	01	0.27			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

MAY 2021

Report no: MEEPL/JUNE/0019/2021-22 Date: 7th June, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near View Point 2 (Bhusar Mine Pit II)

Sample collected on: 05.05.2021

	LOCATION / IDENTIFICATION: Near View point 2 (Bhusar Mine Pit II)						
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration			
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	69			
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	35.9			
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.7			
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.9			
05.	Ammonia (NH3)	μg/m³	400	7.8			
06.	Ozone (O <sub>3</sub> )	μg/m³	180	11.1			
07.	Carbon Monoxide (CO)	mg/m³	02	0.39			
08.	Lead (Pb)	μg/m³	1.0	0.05			
09.	Nickel (Ni)	ng/m³	20	2.9			
10.	Arsenic (As)	ng/m³	06	3.5			
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.7			
12.	Benzo (a) Pyrene	μg/m³	01	0.4			

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

MAY 2021

Date: 7th June, 2021

**Report no: MEEPL/JUNE/0020/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Near Rest Shelter

Sample collected on: 05.05.2021

	LOCATION / IDENTIFICATION: Near Rest Shelter			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	61
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	33
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.2
04.	Nitrogen Dioxide (NO2)	μg/m³	80	5.7
05.	Ammonia (NH₃)	μg/m³	400	4.8
06.	Ozone (O <sub>3</sub> )	μg/m³	180	10.2
07.	Carbon Monoxide (CO)	mg/m³	02	0.35
08.	Lead (Pb)	μg/m³	1.0	0.04
09.	Nickel (Ni)	ng/m³	20	2.8
10.	Arsenic (As)	ng/m³	06	3.2
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.9
12.	Benzo (a) Pyrene	μg/m³	01	0.5

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

MAY 2021

Date: 7th June, 2021

Report no: MEEPL/JUNE/0021/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: [harkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near GTS Point

Sample collected on: 05.05.2021

	LOCATION / IDENTIFICATION: Near GTS Point			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	70
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	37.2
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.8
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.5
05.	Ammonia (NH₃)	μg/m³	400	5.6
06.	Ozone (O₃)	μg/m³	180	10.4
07.	Carbon Monoxide (CO)	mg/m³	02	0.26
08.	Lead (Pb)	μg/m³	1.0	0.05
09.	Nickel (Ni)	ng/m³	20	3.5
10.	Arsenic (As)	ng/m³	06	2.8
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.5
12.	Benzo (a) Pyrene	μg/m³	01	0.29

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

MAY 2021

Date: 7th June, 2021

**Report no: MEEPL/JUNE/0014/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: **Lohardaga**Postal Code: **835203**State: **Jharkhand**Country: **India** 

Sample Type: **AMBIENT AIR QUALITY MONITORING**Marks on Sample Location: **Near Daldaliya Village** 

Sample collected on: 04.05.2021

	LOCATION / IDENTIFICATION: Near Daldaliya Village			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	56.4
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	24.3
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.1
04.	Nitrogen Dioxide (NO2)	μg/m³	80	4.6
05.	Ammonia (NH₃)	μg/m³	400	3.5
06.	Ozone (O <sub>3</sub> )	μg/m³	180	8.6
07.	Carbon Monoxide (CO)	mg/m³	02	0.21
08.	Lead (Pb)	μg/m³	1.0	0.05
09.	Nickel (Ni)	ng/m³	20	2.7
10.	Arsenic (As)	ng/m³	06	2.5
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.6
12.	Benzo (a) Pyrene	μg/m³	01	0.24

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

MAY 2021

Date: 7th June, 2021

Report no: MEEPL/JUNE/0015/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Aditya School Gangupara

Sample collected on: 04.05.2021

	LOCATION / IDENTIFICATION: Aditya School Gangupara			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	53.5
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	22.8
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.9
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.2
05.	Ammonia (NH3)	μg/m³	400	4.6
06.	Ozone (O <sub>3</sub> )	μg/m³	180	8.5
07.	Carbon Monoxide (CO)	mg/m³	02	0.24
08.	Lead (Pb)	μg/m³	1.0	0.04
09.	Nickel (Ni)	ng/m³	20	2.4
10.	Arsenic (As)	ng/m³	06	2.3
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.4
12.	Benzo (a) Pyrene	μg/m³	01	0.3

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

MAY 2021

**Report no: MEEPL/JUNE/0016/2021-22 Date: 7th June, 2021** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Ropeway Unloading Station

Sample collected on: 04.05.2021

	LOCATION / IDENTIFICATION: Ropeway Unloading Station			
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	60.1
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	27.1
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.3
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.2
05.	Ammonia (NH₃)	μg/m³	400	5.4
06.	Ozone (O₃)	μg/m³	180	10.7
07.	Carbon Monoxide (CO)	mg/m³	02	0.28
08.	Lead (Pb)	μg/m³	1.0	0.07
09.	Nickel (Ni)	ng/m³	20	3.6
10.	Arsenic (As)	ng/m³	06	3.2
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	3.5
12.	Benzo (a) Pyrene	μg/m³	01	0.25

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

MAY 2021

Date: 7th June, 2021

Report no: MEEPL/JUNE/0017/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: **AMBIENT AIR QUALITY MONITORING** Marks on Sample: Location: **Ropeway Angle Station** 

Sample collected on: 04.05.2021

	LOCATION / IDENTIFICATION: Ropeway Angle Station				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	52.5	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	30.1	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.3	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.6	
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	3.9	
06.	Ozone (O₃)	μg/m³	180	9.9	
07.	Carbon Monoxide (CO)	mg/m³	02	0.35	
08.	Lead (Pb)	μg/m³	1.0	0.05	
09.	Nickel (Ni)	ng/m³	20	2.8	
10.	Arsenic (As)	ng/m³	06	2.7	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.1	
12.	Benzo (a) Pyrene	μg/m³	01	0.31	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/87, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

## Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009

#### BHUSAR BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

JUNE 2021

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JUNE 2021

### CONTENT

	LOCATION - BHUSAR BAUXITE MINE		
	AMBIENT AIR QUALITY - CORE ZONE		
1	Near View Point 1 (Bhusar Mine Pit I)		
2	Near View Point 2 (Bhusar Mine Pit II)		
3	Near Rest Shelter		
4	Near GTS Point		



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JUNE 2021

Date: 12th July, 2021

**Report no: MEEPL/JULY/0018/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: **Lohardaga**Postal Code: **835203**State: **Jharkhand**Country: **India** 

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample Location: Near View Point 1 (Bhusar Mine Pit I)

Sample collected on: 04.06.2021

	LOCATION / IDENTIFICATION: Near View Point 1 (Bhusar Mine Pit I)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	57.6	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	32.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.4	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.9	
05.	Ammonia (NH₃)	μg/m³	400	6.7	
06.	Ozone (O₃)	μg/m³	180	9.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.32	
08.	Lead (Pb)	μg/m³	1.0	0.02	
09.	Nickel (Ni)	ng/m³	20	2.7	
10.	Arsenic (As)	ng/m³	06	1.7	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.8	
12.	Benzo (a) Pyrene	μg/m³	01	0.32	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JUNE 2021

Date: 12th July, 2021

**Report no: MEEPL/JULY/0019/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near View Point 2 (Bhusar Mine Pit II)

Sample collected on: 04.06.2021

	LOCATION / IDENTIFICATION: Near View point 2 (Bhusar Mine Pit II)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	62.5	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	30.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.8	
04.	Nitrogen Dioxide (NO2)	μg/m³	80	5.7	
05.	Ammonia (NH₃)	μg/m³	400	6.9	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	10.7	
07.	Carbon Monoxide (CO)	mg/m³	02	0.35	
08.	Lead (Pb)	μg/m³	1.0	0.05	
09.	Nickel (Ni)	ng/m³	20	2.9	
10.	Arsenic (As)	ng/m³	06	1.6	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.7	
12.	Benzo (a) Pyrene	μg/m³	01	0.41	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

JUNE 2021

**Report no: MEEPL/JULY/0020/2021-22 Date: 12th July, 2021** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Near Rest Shelter

Sample collected on: 04.06.2021

	LOCATION / IDENTIFICATION: Near Rest Shelter				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	68.7	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	31.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.7	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.7	
05.	Ammonia (NH₃)	μg/m³	400	5.8	
06.	Ozone (O₃)	μg/m³	180	10.4	
07.	Carbon Monoxide (CO)	mg/m³	02	0.31	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	2.7	
10.	Arsenic (As)	ng/m³	06	1.8	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.5	
12.	Benzo (a) Pyrene	μg/m³	01	0.27	

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JUNE 2021

Date: 12th July, 2021

Report no: MEEPL/JULY/0021/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near GTS Point

Sample collected on: 04.06.2021

	LOCATION / IDENTIFICATION: Near GTS Point				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	72.7	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	33.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.9	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.8	
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	5.9	
06.	Ozone (O₃)	μg/m³	180	10.4	
07.	Carbon Monoxide (CO)	mg/m³	02	0.27	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	2.8	
10.	Arsenic (As)	ng/m³	06	1.7	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.9	
12.	Benzo (a) Pyrene	μg/m³	01	0.35	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JUNE 2021

**Report no: MEEPL/JULY/0014/2021-22 Date: 12th July, 2021** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: **Lohardaga**Postal Code: **835203**State: **Jharkhand**Country: **India** 

Sample Type: **AMBIENT AIR QUALITY MONITORING**Marks on Sample Location: **Near Daldaliya Village** 

Sample collected on: 03.06.2021

	LOCATION / IDENTIFICATION: Near Daldaliya Village				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	59.3	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	23.7	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.9	
04.	Nitrogen Dioxide (NO2)	μg/m³	80	4.9	
05.	Ammonia (NH₃)	μg/m³	400	3.8	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	9.3	
07.	Carbon Monoxide (CO)	mg/m³	02	0.27	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	1.7	
10.	Arsenic (As)	ng/m³	06	2.8	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.9	
12.	Benzo (a) Pyrene	μg/m³	01	0.27	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JUNE 2021

**Report no: MEEPL/JULY/0015/2021-22 Date: 12th July, 2021** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

**Client Name:** Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Aditya School Gangupara

Sample collected on: 03.06.2021

	LOCATION / IDENTIFICATION: Aditya School Gangupara				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 $\mu$ m) $PM_{10}$	μg/m³	100	55.2	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	23.2	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.4	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.8	
05.	Ammonia (NH₃)	μg/m³	400	2.9	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	8.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.27	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	1.9	
10.	Arsenic (As)	ng/m³	06	2.4	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	0.8	
12.	Benzo (a) Pyrene	μg/m³	01	0.31	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JUNE 2021

**Report no: MEEPL/JULY/0016/2021-22 Date: 12th July, 2021** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Ropeway Unloading Station

Sample collected on: 03.06.2021

	LOCATION / IDENTIFICATION: Ropeway Unloading Station				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	55.7	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	24.7	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.9	
04.	Nitrogen Dioxide (NO2)	μg/m³	80	4.1	
05.	Ammonia (NH₃)	μg/m³	400	4.6	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	9.9	
07.	Carbon Monoxide (CO)	mg/m³	02	0.27	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	2.1	
10.	Arsenic (As)	ng/m³	06	1.6	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.2	
12.	Benzo (a) Pyrene	μg/m³	01	0.25	

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JUNE 2021

**Report no: MEEPL/**JULY/0017/2021-22

Date: 12th July, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: **AMBIENT AIR QUALITY MONITORING** Marks on Sample: Location: **Ropeway Angle Station** 

Sample collected on: 03.06.2021

	LOCATION / IDENTIFICATION: Ropeway Angle Station				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	51.4	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	32.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.9	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.8	
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	3.6	
06.	Ozone (O₃)	μg/m³	180	8.9	
07.	Carbon Monoxide (CO)	mg/m³	02	0.28	
08.	Lead (Pb)	μg/m³	1.0	0.05	
09.	Nickel (Ni)	ng/m³	20	2.4	
10.	Arsenic (As)	ng/m³	06	2.7	
11.	Benzene (C6H6)	μg/m³	05	2.3	
12.	Benzo (a) Pyrene	μg/m³	01	0.36	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

## Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009

#### BHUSAR BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

JULY 2021

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

### CONTENT

	LOCATION - BHUSAR BAUXITE MINE		
	AMBIENT AIR QUALITY – CORE ZONE		
1	Near View Point 1 (Bhusar Mine Pit I)		
2	Near View Point 2 (Bhusar Mine Pit II)		
3	Near Rest Shelter		
4	Near GTS Point		
	RUNOFF WATER		
	DRINKING WATER ANALYSIS		



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

Date: 10th August, 2021

**Report No.: MEEPL/AUG/0024/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample Location: Near View Point 1 (Bhusar Mine Pit I)

Sample collected on: 06.07.2021

	LOCATION / IDENTIFICATION: Near View Point 1 (Bhusar Mine Pit I)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	51.8	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	26.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.8	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.5	
05.	Ammonia (NH₃)	μg/m³	400	6.8	
06.	Ozone (O₃)	μg/m³	180	5.3	
07.	Carbon Monoxide (CO)	mg/m³	02	0.27	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	1.7	
10.	Arsenic (As)	ng/m³	06	2.6	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.8	
12.	Benzo (a) Pyrene	μg/m³	01	0.33	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

Date: 10th August, 2021

**Report No.: MEEPL/AUG/0025/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near View Point 2 (Bhusar Mine Pit II)

Sample collected on: 06.07.2021

	LOCATION / IDENTIFICATION: Near View point 2 (Bhusar Mine Pit II)					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	55.4		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	22.9		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.5		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	5.8		
05.	Ammonia (NH3)	μg/m³	400	6.3		
06.	Ozone (O <sub>3</sub> )	μg/m³	180	6.7		
07.	Carbon Monoxide (CO)	mg/m³	02	0.33		
08.	Lead (Pb)	μg/m³	1.0	0.05		
09.	Nickel (Ni)	ng/m³	20	1.5		
10.	Arsenic (As)	ng/m³	06	1.8		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.7		
12.	Benzo (a) Pyrene	μg/m³	01	0.34		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

**Report No.: MEEPL/AUG/0026/2021-22** 

Date: 10th August, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203

State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Near Rest Shelter

Sample collected on: 06.07.2021

	LOCATION / IDENTIFICATION: Near Rest Shelter					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	54.5		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	25.7		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.8		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.6		
05.	Ammonia (NH₃)	μg/m³	400	5.4		
06.	Ozone (O₃)	μg/m³	180	5.6		
07.	Carbon Monoxide (CO)	mg/m³	02	0.25		
08.	Lead (Pb)	μg/m³	1.0	0.05		
09.	Nickel (Ni)	ng/m³	20	1.7		
10.	Arsenic (As)	ng/m³	06	1.5		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.8		
12.	Benzo (a) Pyrene	μg/m³	01	0.28		

 $For \, \mathbf{Mahabal} \, \mathbf{Enviro} \, \mathbf{Engineers} \, \mathbf{Pvt.} \, \, \mathbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

Date: 10th August, 2021

**Report No.: MEEPL/AUG/0027/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near GTS Point

Sample collected on: 06.07.2021

	LOCATION / IDENTIFICATION: Near GTS Point				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	64.1	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	31.2	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	4.7	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.4	
05.	Ammonia (NH₃)	μg/m <sup>3</sup> 400 5			
06.	Ozone (O₃)	μg/m³	180	6.2	
07.	Carbon Monoxide (CO)	mg/m³	02	0.26	
08.	Lead (Pb)	μg/m³	1.0	0.05	
09.	Nickel (Ni)	ng/m³	20	2.7	
10.	Arsenic (As)	ng/m³	06	1.9	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.7	
12.	Benzo (a) Pyrene	μg/m³	01	0.36	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JULY 2021

Date: 10th August, 2021

Report No.: MEEPL/AUG/0017/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: **Lohardaga**Postal Code: **835203**State: **Jharkhand**Country: **India** 

Sample Type: **AMBIENT AIR QUALITY MONITORING**Marks on Sample Location: **Near Daldaliya Village** 

Sample collected on: 05.07.2021

LOCATION / IDENTIFICATION: Near Daldaliya Village				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	37.9
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	18.5
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.6
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.4
05.	Ammonia (NH3)	μg/m³	400	2.5
06.	Ozone (O <sub>3</sub> )	μg/m³	180	5.8
07.	Carbon Monoxide (CO)	mg/m³	02	0.26
08.	Lead (Pb)	μg/m³	1.0	0.04
09.	Nickel (Ni)	ng/m³	20	2.3
10.	Arsenic (As)	ng/m³	06	1.8
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.5
12.	Benzo (a) Pyrene	μg/m³	01	0.24

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JULY 2021

Date: 10th August, 2021

Report No.: MEEPL/AUG/0018/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Aditya School Gangupara

Sample collected on: 05.07.2021

	LOCATION / IDENTIFICATION: Aditya School Gangupara				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	41.8	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	21.9	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.7	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.5	
05.	Ammonia (NH3)	μg/m³	400	2.7	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	5.6	
07.	Carbon Monoxide (CO)	mg/m³	02	0.24	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	1.8	
10.	Arsenic (As)	ng/m³	06	1.28	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	0.8	
12.	Benzo (a) Pyrene	μg/m³	01	0.33	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JULY 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Ropeway Unloading Station

Sample collected on: 05.07.2021

	LOCATION / IDENTIFICATION: Ropeway Unloading Station				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	45.1	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	20.7	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.9	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	4.5	
05.	Ammonia (NH3)	μg/m³	400	4.7	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	6.6	
07.	Carbon Monoxide (CO)	mg/m³	02	0.29	
08.	Lead (Pb)	μg/m³	1.0	0.06	
09.	Nickel (Ni)	ng/m³	20	1.9	
10.	Arsenic (As)	ng/m³	06	1.7	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.3	
12.	Benzo (a) Pyrene	μg/m³	01	0.29	

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

JULY 2021

Date: 10th August, 2021

**Report No.: MEEPL/AUG/0020/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: **AMBIENT AIR QUALITY MONITORING** Marks on Sample: Location: **Ropeway Angle Station** 

Sample collected on: 05.07.2021

	LOCATION / IDENTIFICATION: Ropeway Angle Station					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	40.5		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	19.9		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.2		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.9		
05.	Ammonia (NH <sub>3</sub> )	μg/m³	400	4.3		
06.	Ozone (O₃)	μg/m³	180	6.8		
07.	Carbon Monoxide (CO)	mg/m³	02	0.24		
08.	Lead (Pb)	μg/m³	1.0	0.05		
09.	Nickel (Ni)	ng/m³	20	1.9		
10.	Arsenic (As)	ng/m³	06	2.7		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.5		
12.	Benzo (a) Pyrene	μg/m³	01	0.21		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

Date: 10th August, 2021

**Report No.: MEEPL/AUG/0028/2021-22** 

Sample described by customer: Runoff Water

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: Runoff Water - Surface Water

Marks on Sample: Location: Runoff Water - Bhusar Bauxite Mines

Quantity: 4 liters.

Sample collected on: 06.07.2021

SL No.	Analysis	Method	Result	Unit	Limits
1.	рН	APHA 22 <sup>nd</sup> Ed. 2012, 4500-H+-B,4-92	7.8	mg/l	5.5-9.0
2.	Total Suspended Solids	APHA 22md EDN: 2012-2540	79	mg/l	100
3.	BOD @ 27℃	IS 3025 (Part 44): 1993, RA2003, Amd.1			30
4.	COD	IS 3025 (Part 58): 1993, RA2006, Amd.1	32	mg/l	250
5.	Oil & Grease	IS 3025 (PART 39): 1991 RA 2003,Ed 2.1	<5.0	mg/l	10
6.	Total Dissolved Solids	APHA 22ND EDN 2012-2540	1729	mg/l	2100
7.	Aluminium (as Al)	APHA 22md EDN 2012-3120B	1.3	mg/l	3
8.	Calcium (as Ca)	APHA 22md EDN 2012-3120B	8.4	mg/l	75
9.	Iron (as Fe)	APHA 22md EDN 2012-3120B	1.1	mg/l	3
10.	Temperature		14.3	۰C	Shall not exceed 5°C above the receiving water temperature

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

**Report No.: MEEPL/**AUG/0029/2021-22 **Date:** 10<sup>th</sup> August, 2021

Sample described by customer: DRINKING WATER

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: DRINKING WATER

Marks on Sample: Location: Bhusar Mines - Drinking Water

Sample collected on:06.07.2021

SL No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
1	Colour	Hazen	<1	5 Мах	APHA 22 <sup>nd</sup> Ed. 2012, 2120-B, 2-6
2	Odour		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
3	Taste		Agreeable	Agreeable	IS 3025 (Part 7): 1983, Reaffirmed 2006
4	Turbidity	NTU	0.3	1 Max	APHA 22 <sup>nd</sup> Ed. 2012, 2130-B, 2-13
5	рН		6.6	6.5-8.5	APHA 22md Ed. 2012, 4500-H+-B, 4-92
6	Free Chlorides (Residual)	mg/l	<0.5	0.2 min	APHA 22md Ed. 2012, 4500-CI-G, 4-69
7	Total Dissolved Solids	mg/l	139	500 max	IS 3025 (Part 16): 1984, Reaffirmed 2006
8	Monochloramines	mg/l	<0.05		APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
9	Dichioramines	mg/l	<0.05		APHA 22md Ed. 2012, 4500-CIG, 4-69
10	Total hardness (as CaCO3)	mg/l	37.5	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CIG, 4-69
11	Alkalinirty Total (as CaCO3)	mg/l	32.4	200 max	IS 3025 (Part 237): 1986, Reaffirmed 2009
12	Chloride (as CI)	mg/l	6.7	250 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-CI-b, 4-72
13	Sulphate (as SO4)	mg/l	4.9	200 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-so4-e, 4- 190



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

JULY 2021

#### Continuation Sheet MEEPL/AUG/0029/2021-22

Sl. No.	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method reference
14	Nitrate (as NO3)	mg/l	1.9	45 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-N03-E, 4-125
15	Fluoride (as F)	mg/l	0.16	1 max	APHA 22 <sup>nd</sup> Ed. 2012, 4500-FB & D, 4-84, 4-87
16	Boron (as B)	mg/l	0.11	0.5 max	APHA 22nd Ed. 2012, 4500-BB, 4-25
17	Calcium (as Ca)	mg/l	32	75 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Ca-B, 3- 67
18	Magnesium (as Mg)	mg/l	1.8	30 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Mg-B, 3- 84
19	Ammonical Nitrogen/Total Ammonia	mg/l	<0.1		APHA 22 <sup>nd</sup> Ed. 2012, 4500-NH3-F, 4-115
20	Iron (as Fe)	mg/l	0.17	0.3 max	APHA 22nd Ed. 2012, 3111-B, 3-18
21	Manganese (as Mn)	mg/l	N.D	0.1 max	APHA 22nd Ed. 2012, 3111-B, 3-18
22	Aluminium (as Al)	mg/l	0.01	0.03 max	APHA 22 <sup>nd</sup> Ed. 2012, 3500-Al-B, 3- 61
23	Cadmium (as Cd)	mg/l	N.D	0.003 max	APHA 22nd Ed. 2012, 3111-B, 3-18
24	Chromium Total (as Cr)	mg/l	N.D	0.05 max	APHA 22nd Ed. 2012, 3111-B, 3-18
25	Copper (as Cu)	mg/l	N.D	0.05 max	APHA 22md Ed. 2012, 3111-B, 3-18
26	Lead (as Pb)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
27	Zinc (as Zn)	mg/l	0.02	5 max	APHA 22nd Ed. 2012, 3111-B, 3-18
28	Arsenic (as As)	mg/l	< 0.01	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
29	Selenium (as Se)	mg/l	N.D	0.001 max	APHA 22md Ed. 2012, 3112-B, 3-18
30	Mercury (as hg)	mg/l	N.D	0.01 max	APHA 22 <sup>nd</sup> Ed. 2012, 3114-B, 3-18
31	Nickel (as Ni)	mg/l	< 0.02	0.02 max	APHA 22 <sup>nd</sup> Ed. 2012, 3111-B, 3-18
32	Mineral Oil	mg/l	N.D	0.5 max	IS 3025 (Part 39): 1991, Reaffirmed 2003: ed. 2.1
33	Cyanide (as CN)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> ED. 2012, 4500-CN.C & 4-39 & 4-44
34	Anionic detergents as MBAS	mg/l	<0.1	0.2 max	APHA 22 <sup>nd</sup> ED. 2012, 5540-C.C & 5- 53
35	Phenolic compounds (as C6H5OH)	mg/l	N.D	0.001 max	APHA 22 <sup>nd</sup> ED. 2012, 5530-B & C5- 4753
36	Polynuclear aromatic hydrocarbons (PAH)	mg/l	N.D	0.0001 max	APHA 22 <sup>nd</sup> ED. 2012, 6440, 6-93
37	Polychlorinated Biphenyls (PCBs)	mg/l	N.D	0.0005 max	USEPA Method 8082
38	Sulphide (as S)	mg/l	N.D	0.05 max	APHA 22 <sup>nd</sup> ED. 2012, 4500-S2-C 4- 175 & F 4-178



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

JULY 2021

Continuation Sheet MEEPL/AUG/0029/2021-22

S.No	Parameters	Unit	Result	Acceptable Limit (IS10500:2012)	Method Reference
Micro	biological Analysis				
1.	Total Colliforms	MPN/ 100 mL	N.D	<1.1	APHA 22nd Ed. 2012, 9221–B & C, 9-66, 9-69
2.	E-Coli	MPN/ 100 mL	N.D	Absent	APHA 22nd Ed. 2012, 9221- B, C & G, 9-66, 9-69 and 9-76
Pesti	cides Residues	•	L		
3.	p,p DDT	μg/L	N.D	1	US EPA 508-1995
4.	o,p DDT	μg/L	N.D	1	US EPA 508-1995
5.	p,p DDE	μg/L	N.D	1	US EPA 508-1995
6.	o,p DDE	μg/L	N.D	1	US EPA 508-1995
7.	p,p DDD	μg/L	N.D	1	US EPA 508-1995
8.	o,p DDD	μg/L	N.D	1	US EPA 508-1995
9.	γ-HCH (Lindane)	μg/L	< 0.01	2	US EPA 508-1995
10.	α-HCH	μg/L	< 0.01	0.02	US EPA 508-1995
11.	β-нсн	μg/L	N.D	0.03	US EPA 508-1995
12	δ-HCH	μg/L	N.D	0.03	US EPA 508-1995
13.	Butachlor	μg/L	N.D	120	US EPA 508-1995
14.	Alachlor	μg/L	N.D	20	US EPA 508-1995
15.	Atrazine	μg/L	N.D	2.1	US EPA 532-2000
16.	α Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
17.	β Endosulfan	μg/L	N.D	0.4	US EPA 508-1995
18.	Endosulfan Sulphate	μg/L	N.D	0.3	US EPA 508-1995
19.	Ethion	μg/L	N.D	3	US EPA 8141A-1994
20.	Malathion	μg/L	N.D	185	US EPA 8141A -1994
21.	Methyl Parathion	μg/L	N.D	0.4	US EPA 8141A -1994
22.	Monocrotophos	μg/L	N.D	1	US EPA 8141A-1994
23.	Phorate	μg/L	N.D	2	US EPA 8141A -1994
24.	Chlorpyrifos	μg/L	N.D	26	US EPA 8141A -1994
25.	Aldrin	μg/L	N.D	0.03	US EPA 508-1995
26.	Dieldrin	μg/L	N.D	0.03	US EPA 508-1995
Rema	rks: N.D- Not Detected				

**Conclusion:** The Physical & Chemical Analysis report indicates that water is not contaminated.

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

## Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009

#### BHUSAR BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

AUGUST 2021

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

AUGUST 2021

### CONTENT

	LOCATION - BHUSAR BAUXITE MINE		
	AMBIENT AIR QUALITY - CORE ZONE		
1	Near View Point 1 (Bhusar Mine Pit I)		
2	Near View Point 2 (Bhusar Mine Pit II)		
3	Near Rest Shelter		
4	Near GTS Point		



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

AUGUST 2021

Report no: MEEPL/SEP/0018/2021-22

Date: 10<sup>th</sup> September, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample Location: Near View Point 1 (Bhusar Mine Pit I)

Sample collected on: 05.08.2021

	LOCATION / IDENTIFICATION: Near View Point 1 (Bhusar Mine Pit I)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	16.4	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	10.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	1.8	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.6	
05.	Ammonia (NH₃)	μg/m³	400	1.5	
06.	Ozone (O₃)	μg/m³	180	4.7	
07.	Carbon Monoxide (CO)	mg/m³	02	0.05	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	1.6	
10.	Arsenic (As)	ng/m³	06	1.4	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	0.8	
12.	Benzo (a) Pyrene	μg/m³	01	0.12	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

AUGUST 2021

**Report no: MEEPL/SEP/0019/2021-22** 

Date: 10th September, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near View Point 2 (Bhusar Mine Pit II)

Sample collected on: 05.08.2021

	LOCATION / IDENTIFICATION: Near View point 2 (Bhusar Mine Pit II)				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	39.2	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	11.9	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.8	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.5	
05.	Ammonia (NH₃)	μg/m³	400	1.9	
06.	Ozone (O₃)	μg/m³	180	6.8	
07.	Carbon Monoxide (CO)	mg/m³	02	0.16	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	1.7	
10.	Arsenic (As)	ng/m³	06	1.4	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.6	
12.	Benzo (a) Pyrene	μg/m³	01	0.19	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

AUGUST 2021

**Report no: MEEPL/SEP/0020/2021-22** 

Date: 10th September, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Near Rest Shelter

Sample collected on: 05.08.2021

	LOCATION / IDENTIFICATION: Near Rest Shelter				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	30.2	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	14.7	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	1.8	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	1.6	
05.	Ammonia (NH₃)	μg/m³	400	2.6	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	8.9	
07.	Carbon Monoxide (CO)	mg/m³	02	0.08	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	1.5	
10.	Arsenic (As)	ng/m³	06	1.7	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.5	
12.	Benzo (a) Pyrene	μg/m³	01	0.18	

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

**Environmental Monitoring Report** 

AUGUST 2021

Date: 10th September, 2021

**Report no: MEEPL/SEP/0021/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near GTS Point

Sample collected on: 05.08.2021

	LOCATION / IDENTIFICATION: Near GTS Point				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	27.6	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	12.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.8	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	1.6	
05.	Ammonia (NH₃)	μg/m³	400	2.9	
06.	Ozone (O₃)	μg/m³	180	7.4	
07.	Carbon Monoxide (CO)	mg/m³	02	0.16	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	2.8	
10.	Arsenic (As)	ng/m³	06	1.9	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.4	
12.	Benzo (a) Pyrene	μg/m³	01	0.21	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

AUGUST 2021

**Report no: MEEPL/SEP/0014/2021-22** 

EP/0014/2021-22 **Date:** 10<sup>th</sup> September, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

 ${\bf Client\,Name:}\, \textbf{Hindalco\,Industries\,Limited}$ 

Client Address: **Lohardaga**Postal Code: **835203**State: **Jharkhand**Country: **India** 

Sample Type: **AMBIENT AIR QUALITY MONITORING**Marks on Sample Location: **Near Daldaliya Village** 

Sample collected on: 04.08.2021

	LOCATION / IDENTIFICATION: Near Daldaliya Village				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	19.5	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	9.4	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	1.5	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	1.9	
05.	Ammonia (NH₃)	μg/m³	400	1.6	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	6.5	
07.	Carbon Monoxide (CO)	mg/m³	02	0.05	
08.	Lead (Pb)	μg/m³	1.0	0.03	
09.	Nickel (Ni)	ng/m³	20	1.5	
10.	Arsenic (As)	ng/m³	06	1.8	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.1	
12.	Benzo (a) Pyrene	μg/m³	01	0.05	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

AUGUST 2021

**Report no: MEEPL/SEP/0015/2021-22** 

2021-22 **Date:** 10<sup>th</sup> September, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Aditya School Gangupara

Sample collected on: 04.08.2021

	LOCATION / IDENTIFICATION: Aditya School Gangupara				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	15.5	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	7.8	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.6	
04.	Nitrogen Dioxide (NO2)	μg/m³	80	1.7	
05.	Ammonia (NH₃)	μg/m³	400	3.7	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	9.8	
07.	Carbon Monoxide (CO)	mg/m³	02	0.05	
08.	Lead (Pb)	μg/m³	1.0	0.07	
09.	Nickel (Ni)	ng/m³	20	1.8	
10.	Arsenic (As)	ng/m³	06	1.5	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.7	
12.	Benzo (a) Pyrene	μg/m³	01	0.5	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

AUGUST 2021

**Report no: MEEPL**/SEP/0016/2021-22

Date: 10th September, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand

Country: India

Sample type: AMBIENT AIR QUALITY MONITORING
Marks on Sample: Location: Ropeway Unloading Station

Sample collected on: 04.08.2021

	LOCATION / IDENTIFICATION: Ropeway Unloading Station				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	22.5	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	18.2	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.7	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.8	
05.	Ammonia (NH₃)	μg/m³	400	2.4	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	7.7	
07.	Carbon Monoxide (CO)	mg/m³	02	0.15	
08.	Lead (Pb)	μg/m³	1.0	0.05	
09.	Nickel (Ni)	ng/m³	20	1.6	
10.	Arsenic (As)	ng/m³	06	1.8	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.3	
12.	Benzo (a) Pyrene	μg/m³	01	0.18	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

AUGUST 2021

Report no: MEEPL/SEP/0017/2021-22 Date: 10th September, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: **AMBIENT AIR QUALITY MONITORING** Marks on Sample: Location: **Ropeway Angle Station** 

Sample collected on: 04.08.2021

	LOCATION / IDENTIFICATION: Ropeway Angle Station				
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	21.1	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	12.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.7	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	1.8	
05.	Ammonia (NH3)	μg/m³	400	3.7	
06.	Ozone (O₃)	μg/m³	180	7.4	
07.	Carbon Monoxide (CO)	mg/m³	02	0.18	
08.	Lead (Pb)	μg/m³	1.0	0.04	
09.	Nickel (Ni)	ng/m³	20	1.8	
10.	Arsenic (As)	ng/m³	06	1.6	
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.5	
12.	Benzo (a) Pyrene	μg/m³	01	0.21	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey





# Eco Ventures Pvt. Ltd.

Regd. Office: 2/37, Sarvapriya Vihar, Near IIT Gate, New Delhi-110016
Corporate Office: 7/8 Bhaveshwar Bhuvan, Opp Porthugese Church, Near Dindayal Upadhyay Garden,
Gokhale Road (North), Dadar (West), Mumbai 400 028. Tel: +91 22 24370520 / 6672.

E: ecoventures.mumbai@gmail.com / ecoventures@eco-ventures.in

## Mahabal Enviro Engineers Pvt. Ltd.

At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009

#### BHUSAR BAUXITE MINE - ENVIRONMENTAL MONITORING REPORT

SEPTEMBER 2021

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

SEPTEMBER 2021

## CONTENT

	LOCATION - BHUSAR BAUXITE MINE			
	AMBIENT AIR QUALITY - CORE ZONE			
1	Near View Point 1 (Bhusar Mine Pit I)			
2	Near View Point 2 (Bhusar Mine Pit II)			
3	Near Rest Shelter			
4	Near GTS Point			



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

SEPTEMBER 2021

Date: 15th October, 2021

**Reports no: MEEPL/OCT/0018/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample Location: Near View Point 1 (Bhusar Mine Pit I)

Sample collected on: 04.09.2021

	LOCATION / IDENTIFICATION: Near View Point 1 (Bhusar Mine Pit I)					
Sl. No.			Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	39.7		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	18.4		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.7		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.6		
05.	Ammonia (NH3)	μg/m³	400	5.9		
06.	Ozone (O₃)	μg/m³	180	6.6		
07.	Carbon Monoxide (CO)	mg/m³	02	0.19		
08.	Lead (Pb)	μg/m³	1.0	0.06		
09.	Nickel (Ni)	ng/m³	20	1.9		
10.	Arsenic (As)	ng/m³	06	1.5		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.1		
12.	Benzo (a) Pyrene	μg/m³	01	0.20		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

SEPTEMBER 2021

**Reports no: MEEPL/OCT/0019/2021-22** 

Date: 15th October, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near View Point 2 (Bhusar Mine Pit II)

Sample collected on: 04.09.2021

	LOCATION / IDENTIFICATION: Near View point 2 (Bhusar Mine Pit II)					
Sl. No.	PARAMETERS U		Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	52.6		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	20.5		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.9		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.8		
05.	Ammonia (NH3)	μg/m³	400	6.7		
06.	Ozone (O₃)	μg/m³	180	7.61		
07.	Carbon Monoxide (CO)	mg/m³	02	0.28		
08.	Lead (Pb)	μg/m³	1.0	0.06		
09.	Nickel (Ni)	ng/m³	20	2.1		
10.	Arsenic (As)	ng/m³	06	1.8		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.3		
12.	Benzo (a) Pyrene	μg/m³	01	0.23		

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

SEPTEMBER 2021

**Reports no: MEEPL/OCT/0020/2021-22** 

Date: 15th October, 2021

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING Marks on Sample: Location: Near Rest Shelter

Sample collected on: 04.09.2021

	LOCATION / IDENTIFICATION: Near Rest Shelter					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than $10 \mu m$ ) $PM_{10}$	μg/m³	100	45.2		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	17.5		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	1.9		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.8		
05.	Ammonia (NH₃)	μg/m³	400	4.6		
06.	Ozone (O <sub>3</sub> )	μg/m³	180	5.7		
07.	Carbon Monoxide (CO)	mg/m³	02	0.13		
08.	Lead (Pb)	μg/m³	1.0	0.04		
09.	Nickel (Ni)	ng/m³	20	1.5		
10.	Arsenic (As)	ng/m³	06	0.8		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.5		
12.	Benzo (a) Pyrene	μg/m³	01	0.14		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bhusar

Environmental Monitoring Report

SEPTEMBER 2021

Date: 15th October, 2021

Reports no: MEEPL/OCT/0021/2021-22

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Near GTS Point

Sample collected on: 04.09.2021

	LOCATION / IDENTIFICATION: Near GTS Point					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	36.5		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	12.9		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	3.9		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	1.9		
05.	Ammonia (NH3)	μg/m³	400	6.7		
06.	Ozone (O <sub>3</sub> )	μg/m³	180	7.9		
07.	Carbon Monoxide (CO)	mg/m³	02	0.16		
08.	Lead (Pb)	μg/m³	1.0	0.07		
09.	Nickel (Ni)	ng/m³	20	1.9		
10.	Arsenic (As)	ng/m³	06	1.5		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	0.9		
12.	Benzo (a) Pyrene	μg/m³	01	0.27		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

SEPTEMBER 2021

**Reports no: MEEPL/OCT/0014/2021-22 Date: 15th October, 2021** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: **AMBIENT AIR QUALITY MONITORING**Marks on Sample Location: **Near Daldaliya Village** 

Sample collected on: 03.09.2021

	LOCATION / IDENTIFICATION: Near Daldaliya Village					
Sl. No.			Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	28.2		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	12.1		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	1.9		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	1.5		
05.	Ammonia (NH3)	μg/m³	400	4.9		
06.	Ozone (O₃)	μg/m³	180	5.6		
07.	Carbon Monoxide (CO)	mg/m³	02	0.06		
08.	Lead (Pb)	μg/m³	1.0	0.03		
09.	Nickel (Ni)	ng/m³	20	1.9		
10.	Arsenic (As)	ng/m³	06	1.6		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	2.1		
12.	Benzo (a) Pyrene	μg/m³	01	0.20		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@gmail.com

Hindalco Industries : Bagru Environmental Monitoring Report

SEPTEMBER 2021

Date: 15th October, 2021

**Reports no: MEEPL/OCT/0015/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

**Sample type:** AMBIENT AIR QUALITY MONITORING **Marks on Sample: Location: Aditya School Gangupara** 

Sample collected on: 03.09.2021

	LOCATION / IDENTIFICATION: Aditya School Gangupara					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	31.9		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	10.3		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	1.8		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.9		
05.	Ammonia (NH3)	μg/m³	400	3.6		
06.	Ozone (O <sub>3</sub> )	μg/m³	180	6.9		
07.	Carbon Monoxide (CO)	mg/m³	02	0.05		
08.	Lead (Pb)	μg/m³	1.0	0.03		
09.	Nickel (Ni)	ng/m³	20	1.8		
10.	Arsenic (As)	ng/m³	06	0.9		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.8		
12.	Benzo (a) Pyrene	μg/m³	01	0.15		

 $For \, \textbf{Mahabal} \, \textbf{Enviro} \, \textbf{Engineers} \, \textbf{Pvt.} \, \, \textbf{Ltd.}$ 

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO - RMCC, District - Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru **Environmental Monitoring Report**  SEPTEMBER 2021

Date: 15th October, 2021

**Reports no: MEEPL/OCT/0016/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: [harkhand Country: India

Sample type: AMBIENT AIR QUALITY MONITORING

Marks on Sample: Location: Ropeway Unloading Station

Sample collected on: 03.09.2021

	LOCATION / IDENTIFICATION: Ropeway Unloading Station					
Sl. No.			Standard Limit	Concentration		
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	49.3		
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	22.5		
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.9		
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	3.6		
05.	Ammonia (NH3)	μg/m³	400	5.9		
06.	Ozone (O₃)	μg/m³	180	7.5		
07.	Carbon Monoxide (CO)	mg/m³	02	0.14		
08.	Lead (Pb)	μg/m³	1.0	0.06		
09.	Nickel (Ni)	ng/m³	20	2.9		
10.	Arsenic (As)	ng/m³	06	2.1		
11.	Benzene (C <sub>6</sub> H <sub>6</sub> )	μg/m³	05	1.7		
12.	Benzo (a) Pyrene	μg/m³	01	0.25		

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



At Booty, Near PHED Colony, Behind Pump House, PO – RMCC, District – Ranchi 834009, Mobile No: +91 9431.102.102 / +91 9955.358.262,

E-mail: mahabalranchi@qmail.com

Hindalco Industries : Bagru

**Environmental Monitoring Report** 

SEPTEMBER 2021

Date: 15th October, 2021

**Reports no: MEEPL/OCT/0017/2021-22** 

Sample described by customer: AMBIENT AIR QUALITY MONITORING

Client Name: Hindalco Industries Limited

Client Address: Lohardaga Postal Code: 835203 State: Jharkhand Country: India

Sample Type: **AMBIENT AIR QUALITY MONITORING** Marks on Sample: Location: **Ropeway Angle Station** 

Sample collected on: 03.09.2021

LOCATION / IDENTIFICATION: Ropeway Angle Station					
Sl. No.	PARAMETERS	UNIT	Standard Limit	Concentration	
01.	Particulate Matter (size less than 10 μm) PM <sub>10</sub>	μg/m³	100	39.1	
02.	Particulate Matter (size less than 2.5 μm) PM <sub>2.5</sub>	μg/m³	60	18.5	
03.	Sulphur Dioxide (SO <sub>2</sub> )	μg/m³	80	2.8	
04.	Nitrogen Dioxide (NO <sub>2</sub> )	μg/m³	80	2.3	
05.	Ammonia (NH3)	μg/m³	400	3.5	
06.	Ozone (O <sub>3</sub> )	μg/m³	180	9.4	
07.	Carbon Monoxide (CO)	mg/m³	02	0.15	
08.	Lead (Pb)	μg/m³	1.0	0.07	
09.	Nickel (Ni)	ng/m³	20	2.3	
10.	Arsenic (As)	ng/m³	06	1.6	
11.	Benzene (C₀H₀)	μg/m³	05	2.9	
12.	Benzo (a) Pyrene	μg/m³	01	0.18	

For Mahabal Enviro Engineers Pvt. Ltd.

Vijay Pandey



		Annexure 1					
<b>Piezome</b>	Piezometer reading - Bhusar						
S No	Month	Depth (meter)					
1	Apr-21	34.2					
2	May-21	34.16					
3	Jun-21	34.14					
4	Jul-21	34.11					
5	Aug-21	35.5					
6	Sep-21	35.5					

#### Annexure-2

#### BREAK UP THE COST OF ENVIRONMENTAL MEASURES DURING THE YEAR 2021-22

The composite cost during the year 2021-22 for environmental protection & pollution control by Jharkhand Mines division of M/s Hindalco Industries Ltd & M/s Minerals & Minerals Ltd for implementation of the suggested measures in EC at our all the operating mines in the state of Jharkhand-namely Pakhar (115,13 ha), Pakhar (15.58 ha), Pakhar (109.507 ha), Pakhar (8.09 ha), Pakhar (35.12 ha), Serengdag (140.06 ha), Serengdag (155.81 ha), Jalim & Sanai (12.14 ha), Gurdari (584.19 ha), Amtipani (190.95 ha), Kujam I (80.97 ha) Kujam II (157.38 ha), Bagru (75.41 ha), Hisri New (14.55 ha), Chiro kukud (152.57 ha), Orsa pat (196.36 ha), Bhusar (65.31 ha) and Bimarla Bauxite Mines (134.52 ha).

S No	Description	Budget (in Rupees) FY 2021-22	Actual (in Rupees) FY 2021-22 (From April'21 to September'21)
1	Pollution Control & Environment monitoring	44,21,524.00	38,26,550.78
2	Reclamation/ Back filing & Rehabilitation**	3,91,80,000.00	2,19,87,911.52
3	Green belt, Plantation & Water spraying arrangement	50,25,900.00	19,62,336.16
4	Rural Development	3,10,21,250.00	1,08,93,416.77

<sup>\*\*</sup>Part of OB removed cost.

(Basudev Gangopadhyay) Head (Geology & Environment)



Annexure 3

Date - 06.07.2020

### Office Order

Environmental Cell has been re-constituted at Bhusar Bauxite Mine (Area 65.31 ha) comprising below mentioned team members. The team will ensure compliance of Environment Act, Regulation & Rule in respect of the said mines of Hindalco Industries Limited.

- 1. Mr. Akhilesh Sinha (Coordinator)
- 2. Mr. Rupak Kumar Dubey (Member)
- 3. Mr. Anil Kumar Singh (Member)
- 4. Mr. Abhay Kumar Environment Engineer

The Undersigned is the in charge of above Environment Management Cell constituted for the purpose of ensuring compliances of environmental act rule and regulation for the above mine.

Basudev Gangopadhyay
Senior Executive (Quality & Environment)

# Annexure 4

	Production, M	Mining	Production	d Over Burder	n removal from	n April'21 to	September	'21
S N	Name of the Mines	lease area (ha)	Capacity (MT)*	Lease Period*	Production (MT)	Mined out area (ha)	Back filled	Over burder
2	and a during lattice	75.41	85000	22.01.1974 to 31.03.2030	NIL	NIL	area (ha) NIL	(Cu.M)
3	Bhusar Bauxite Mine Hisri (New) Bauxite	65.31	280000	11.07.1981 to 31.03.2030	60473	0	0	27136.33
4	Mine  Kujam - I Bauxite Mine	14.55	100000	19.07.1981 to 31.03.2030	49451	0.26	0.37	33822.47
5	Kujam - Il Bauxite Mine	80.87	150000	13.03.2006 to 12.03.2056	51620	2.46	0.58	47195.21
6		157.38	300000	24.03.2006 to 23.03.2056	111095	2.9	0.98	104352.49
	Amtipani Bauxite Mine	190.95	150000	13.03.2006 to 12.03.2056	81175	2.51	1.00	157783.250
7	Gurdari Bauxite Mine	584.19	325000	23.03.1985 to 22.03.2035	128785	5.037	4.08	185833.09
8	Shrengdag A Bauxite Mine	155.81	260000	16.10.1974 to 31.03.2030	69525	1.42	1.38	52264.7
	Shrengdag B Bauxite Mine	140.07	100000	04.10.1978 to 31.03.2030	0	0	0	0
2	Jalim & Sanai Bauxite Mine	12.14	50000	16.10.1974 to 31.03.2030	19930	0.34	0.32	14364.7

## Annexure 4

1:	1 Orsapat Bauxite Mine	196.36	200000	17.07.1986 to	NIL	NIL	NIL	NIL
12	Chiro Kukud bauxite	152.57	1000	16.07.2036				INIL.
	Mine	152.57	100000	29.01.1985 to	NIL	NIL	NIL	NIL
13	Pakhar (8.09)	8.09	90000	28.01.2035				
		0.03	80000	16.05.1973 to	NIL	NIL	NIL	NIL
14	Pakhar (35.12)	35.12	200000	31.03.2030				
		20	200000	17.04.1975 to	NIL	NIL	NIL	NIL
15	Pakhar (115.13)	115.13		31.03.2030				
		115.13	300000	19.07.1996 to	95000	0.98	0.97	186006.49
	1 = 1	Minerals & M	linerals Limited	31.03.2030				No. Visitable
16	Pakhar (15.58)	15.58	60000					
			44000	28.04.1965 to	9900	0.15	0.10	13215.18
17	Pakhar (109.507)	109.507	280000	31.03.2030		4.		1-315
•			200000	26.07.2008 to	92100	0.95	1.17	111648.32
18	Bimarla Bauxite Mine	134.37	300000	25.07.2058				
			30000	18.07.2009 to 17.07.2059	51200	1.65	1.00	105411.92

<sup>\*</sup>Static information about the mines included in the above table

Basudev Gangopadhyay Head (Geology & Environment)